

Tropical Tech Automobile Services

BLK 5030 ANG MO KIO AVENUE 3 #01-201 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484

E-mail : tsac303@singnet.com.sg

M/s: **India International Ins Pte Ltd**
64, Cecil Street, #04-00 IOB Bldg,
Singapore 049711

Attn : Motor Claims Department
Tel : 62238122
Fax : 62257743

Estimate bill : TT 45 / 18 / TP / WT

Registration No : SDU888Y

Make / model : MB E250 Coupe

Mileage :

Date : 17 / 09 / 2018

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SHC2505L AND SDU888Y ALONG UPPER CHANGI ROAD EAST ON 15 SEPTEMBER 2018 AT ABOUT 2155 HRS.

1pc	Front grille		\$	1,191.00
1pc	Front bumper		\$	1,709.00
1pc	Rear boot		\$	2,734.00
2pcs	Rear boot license lamp		\$	70.00
1pc	Rear boot licence lamp garnish	(Each \$35.00)	\$	100.00
1pc	Rear boot rubber		\$	200.00
2pc	Rear tail lamp		\$	1,710.00
2pc	Rear tail lamp lower bracket		\$	114.00
1pc	Rear end panel		\$	1,965.00
1pc	Rear end panel top garnish		\$	200.00
1pc	Spare tyre wheelhouse cover		\$	399.00
1pc	Rear bumper		\$	2,136.00
2pcs	Rear bumper side chrome moulding		\$	388.00
1pc	Rear bumper centre chrome moulding	(Each \$194.00)	\$	257.00
4pcs	Rear bumper PDC sensor		\$	1,140.00
4pcs	Rear bumper PDC sensor seal ring	(Each \$285.00)	\$	48.00
1pc	Rear bumper lip	(Each \$12.00)	\$	1,139.00
2pcs	Rear bumper side bracket		\$	98.00
1pc	Rear bumper frame (Top)	(Each \$49.00)	\$	143.00
1pc	Rear bumper reinforcement		\$	1,025.00
	Sub A total :		\$	16,766.00
	Less 10% discount :		\$	1,676.60
	A total :		\$	15,089.40

Special net items :

- 1pc Rear boot emblem
- 1pc Rear boot "E250" designation
- 1pc Rear boot "CGI" designation

B total :

Total amount for Page 1 :

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tropical Tech Automobile Services

BLK 5030 ANG MO KIO AVENUE 3 #01-201 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484

E-mail : tsac303@singnet.com.sg

M / s : **India International Ins Pte Ltd**
64, Cecil Street, #04-00 IOB Bldg,
Singapore 049711

Estimate bill : TT 45 / 18 / TP / WT

Attn : Motor Claims Department
Tel : 62238122
Fax : 62257743

Registration No : SDU888Y

Make / model : MB E250 Coupe

Mileage :

Date : 17 / 09 / 2018

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SHC2505L AND SDU888Y ALONG UPPER CHANGI ROAD EAST ON 15 SEPTEMBER 2018 AT ABOUT 2155 HRS.

Remove and transfer front bumper necessary attachment spare part items.

Remove and transfer rear boot necessary attachment spare part items.

Remove and transfer rear bumper necessary attachment spare part items.

Remove and refit front grille, front bumper, rear boot, rear boot license lamp, rear boot licence lamp garnish, rear boot rubber, rear tail lamp, rear tail lamp lower bracket, rear end panel top garnish, spare tyre wheelhouse cover, rear bumper, rear bumper side chrome moulding, rear bumper centre chrome moulding, rear bumper PDC sensor, rear bumper PDC sensor seal ring, rear bumper lip, rear bumper side bracket, rear bumper frame (Top), rear bumper reinforcement.

Heat / weld / renew rear end panel, heat / weld / beating / pull / straighten / align rear chassis frame by Chassis Alignment Jack.

Diagnostic & reset rear bumper PDC sensor by HHT.

Tuff koff rear damaged portion.

Putty / primer application, spray painting front bumper, rear boot, rear end panel, rear bumper, rear bumper PDC sensor, rear bumper lip.

Balance amount brought from Page 1 :

Grand amount :

12001
\$ 2,200.00

\$ 100.00


\$ 60 150.00

1400
\$ 2,000.00

\$ 15,360.40

\$ 19,810.40

Tropical Tech Automobile Services


(Authorised Signature)
William Tan

