

(5/5/2010)

INS. CASE OWNER:

CC3/CTI1801

7000, Gmbh⁵²

LKK:

IDAC:

Surveyor:

x60

DOI:

ASSIGNMENT

12/1/18

Date / Time:

12/1/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBG 4900R.

Name of Insured:

CO-MIN COMPANY

Insured Tel No.:

HP:

D.O.A:

12/1/18

Excess Sec II :SS

Is driver the owner?

(YES) (NO)

Nature of Accident:

If NO, Driver Name / Age:

FOM HENA HIE

Driver Tel No.:

00614241

(V/T) YES / NO)

Claim No.:

SMH18014503(02/10/18)KAS

Policy No.:

DMVSN705221800

Make / Model:

TOYOTA

Place of Accident:

18 MARKSINGH LANE 1P

OI GIA REPORT:

(YES / NO)

TP GIA REPORT:

YES / NO

Insured Liability:

%

Final ? Yes / No

SHC4932

INSRS:
WSP:
Tel:
Liability:
RMKS:

SMRT

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SHC4932 - 4

GMBH4900R - 4

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Lee Ger

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

NIL

Repair Cost:

SS

2600.00

Loss of Rental (LOR):

SS

834.60

(7.5 days) X

111.28

Loss of Use (LOU):

SS

(S

x

days)

Loss of Income (LOI):

SS

(S

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

7.00

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

2441.60

Global Sum SS: 3440.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

3440.00

Name 1:

SMRT Taxis Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
29/1/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

10/01/14
SYNOPSIS

XPR

REF:

CTi

8369K
C87469

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD: ☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV
To Inspect Vehicle No: _____
at Workshop m/s: **SMRT**
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt.: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **4** days Res.: Yes or No

Lum Sum: **20** % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SHC4493Z** Yr Regn: **10 Sep 2014**
Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make: **Toyota Prius** G.C. **1798**

Colour: **black** A/C: Insured / Std / NI / NA

Sp. Reading: **408714** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **JTDKN364205748905**

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: ☒ N / S/Rim / STD A/Rim or

Tyre Size: F: **195 / 65 R15**

R: **11**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FAUKEN

Front

Rear

R/Bal. **6** mm R/Bal. **6** mm

L/Bal. **6** mm L/Bal. **6** mm

D.O.A. **14/9/18**

D.O.I. **17-09-18**

Survey held at: **w/s**

4:30pm

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21/9/19 confirm 218 \$2600.00 with 4 working days

(Est. \$5484.37
68%.)

Date/Time, File Pass to?

☐ : Prel. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

☐ S+RS ☐ St

☐ Photos

☐ Others

Add Fee: ☐ Site Insp. (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$ _____)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA.TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18017000/Gwb3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 18-09-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 4900R	Veh. Inspected	SHC 4493Z	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	18/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/09/2018	Inspection Date	17/09/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE L #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI18017000/Gwb3

Date: 18.09.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC4493Z


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17.09.2018 at the premises of M/s SMRT Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	8,084.38
Revised Estimate Amount	: S\$	3,014.11
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

XING GUO QIANG
Licensed Appraiser



W. Chan

Section A - Accident Details

Registration Number	SHC4493Z
Case Reference Number	TAX/09/18/2057
Registration Date	10/09/14
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	TENG CHEE HWA
Type of Accident	Others
Accident Date and Time	14/09/18 3:38 PM
Accident Reported Date and Time	14/09/18 4:30 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24097937
Special instruction to ARC, if any	
Prepared Date and Time	14/10/18 12:08 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$400.00
Total Spray Cost	\$1,674.00	\$500.00
Total Spare Part Cost	\$4,500.37	\$1,477.69
Total Other Cost	\$1,065.00	\$230.00
TOTAL COST	\$8,084.37	\$2,607.69
Lump Sum Total	\$8,100.00	\$2,600.00 (L/S)
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Kim Ming Chin	GUO QIANG (LKK) / CHINA TAIPING
ARC / Surveyor Sign Off Date		
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$845.00	\$400.00 ✓
Total Labour	\$845.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00 ✓
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY VIEW MIRROR	\$180.00	\$100.00 ✓
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00 ✓
TO RESPRAY FRONT PILLAR RH	\$180.00	\$0.00
TO RESPRAY REAR DOOR RH	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$1,674.00	\$500.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$60.00 ✓
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$60.00 ✓
TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	\$120.00	\$40.00 ✓
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$40.00 ✓
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$1,065.00	\$230.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			FENDER FRT/RH	1.00	\$723.40 ✓	25.00	\$542.55 ✓	Replace	Replace ✓
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90 ✓	25.00	\$38.93 ✓	Replace	Replace ✓
			FENDER LINER FRT/RH	0.00	\$171.70 X	25.00	\$0.00	Replace	Not Given X
		42611-47140(Frt)	WHEEL DISC. FRONT	0.00	\$1,484.20 X	25.00	\$0.00	Replace	Not Given X
			TYRE	0.00	\$126.74 X	0.00	\$0.00	Replace	Not Given X
			QUATER GLASS FRT/RH	1.00	\$234.90 ✓	25.00	\$176.18 ✓	Replace	Replace ✓
			SEALANT W/SCREEN	0.00	\$37.00 X	0.00	\$0.00	Replace	Not Given X

		DOOR FRT/RH	1.00	\$894.40	/	25.00	\$670.80	/	Replace	Replace	/
		STICKER DECAL SMRT (DOOR)	1.00	\$60.00	/	0.00	\$60.00	/	Replace	Replace	/
		DOOR OUTER HANDLE FRT/RH	1.00	\$370.80	/	25.00	\$278.10	/	Replace	Replace	/
		DOOR HINGE LOWER FRT/RH	0.00	\$80.50	X	25.00	\$0.00		Replace	Not Given	X
		DOOR HINGE UPPER FRT/RH	0.00	\$80.50	X	25.00	\$0.00		Replace	Not Given	X
		CHECK ASSY. FR DOOR	0.00	\$150.30	X	25.00	\$0.00		Replace	Not Given	X
		PILLAR, FR BODY	0.00	\$363.10	X	25.00	\$0.00		Replace	Not Given	X
		MIRROR ASSY, RH	0.00	\$1,307.10	X	25.00	\$0.00		Replace	Not Given	X
	81730-52090	MIRROR LAMP RH	0.00	\$65.30	X	10.00	\$0.00		Replace	Not Given	X
		COVER, OUTER MIRROR, RH	1.00	\$107.40	/	25.00	\$80.55	/	Replace	Replace	/
		DOOR BELT FRT/RH	0.00	\$69.20	X	25.00	\$0.00		Replace	Not Given	X
		DOOR RR/RH	0.00	\$954.50	X	25.00	\$0.00		Replace	Not Given	X
		PIXEL STICKER	0.00	\$60.00	X	0.00	\$0.00		Replace	Not Given	X
Total				\$7,392.94			\$1,847.11				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

~~27479.8~~
~~25%: 1859.85~~

~~2382.8~~
~~25%: 1781.1~~

~~1847.1~~
~~1477.68~~

1847.11 /
- 20%

1477.69
+ 400.00
+ 730.00

2607.69

US \$2600/-

SMRT Accident Taxi Repair Estimates

Section A - To be completed by Claims Advisor/Duty Officer at Accident Reporting Centre

Reg. No. : SHC 4493Z Ref. No. TAX 9 / 18 / 2057

Make / Model : TOYOTA PRIUS Reg. Date : 10/09/2014

Name of Driver : TENG CHEE HWA

Date/Time of Accident : 14/09/2018 15:38

Surveyer is Required ? YES / NO

If Yes, VICOM / LKK / LH Teo / AIS (Please circle one)


Taxi is Towed Back ? YES / NO

Replacement Taxi Issued ? YES / NO

Accident Repair Job Card No. : 2409737

Special Instruction to ARC, if any :

The damages on the Taxi are as indicated in the following diagram :



Signed :

Date :

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U205748905 Mileage :

Date Prepared : 15/09/2018 Repair Completed date/time:

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	\$ <u>845</u>	\$ <u> </u>
Total Spray Painting Charges :	\$ <u>1674</u>	\$ <u> </u>
Total Material Charges :	\$ <u>4500.38</u>	\$ <u> </u>
Other Charges :	\$ <u>1065</u>	\$ <u> </u>
TOTAL :	\$ <u>8084.38</u>	\$ <u> </u> ()
No. of Repair Days :	[<u>6</u>] days	[<u>4</u>] days

Signature :

Prepared by: MING

15/09/2017 17:33

Adjusted by:

Gue Qiang
17/9/18

LKK Auto Consultants hence notify the Repairer of the following:

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

QN No. : Invoice No. :

Signed :

Date :

Invoice Date

Unsupervised Repair
After repair photos

Acknowledged by Repairer

Signature:

Date:

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	845	400
Total Labour	\$ 845.00	\$

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER RH	378	200
TO RESPRAY RIM	180	X NN
TO RESPRAY VIEW MIRROR	180	100
TO RESPRAY FRONT DOOR RH	378	200
TO RESPRAY FRONT PILLAR RH	180	X
TO RESPRAY REAR DOOR RH	378	200 X NN
Total Spray Painting & Panel Beating	\$ 1,674.00	\$

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80	30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100	60
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET) SN	125	X NN
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120	X NN
TO TRANSFER DOOR MECHANISM	240	60
TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	120	40
TO REMOVE AND REFIX WING MIRROR	120	40
TO WASH AND VACUUM	60	X NN
TO REPLACE SUNDRY PARTS	100	X NN
Total Other Costs	\$ 1 065.00	\$

Section D - Details of Repair Estimates

Part 4 - Spare Parts / Material Usage

Ref. No. TAX 9 / 18 / 2057

Reservation No : _____

Page ()

To be completed by Service Advisor, ARC							Surveyor Adj
Part Number	Parts Description	Qty	List Price (\$)	Discount (%)	Final Price (\$)	Repair (R) Replace (/)	Not given (x) Repair (R) Replace (/)
53801-47050	FENDER FRT/RH X ^{BUC}	1	\$723.40	25%	\$542.55	/	
75374-47051	NAME PLATE (HYBRID) X	1	\$51.90	25%	\$38.93	/	
53875-47030	FENDER LINER FRT/RH X ^{NN}	1	\$171.70	25%	\$128.78	/	
42611--47140(Frt)	WHEEL DISC. FRONT X ^{NN}	1	\$1,484.20	25%	\$1,113.15	/	
	TYRE X ^{NN}	1	\$126.74	0%	\$126.74	/	
62110-47021	QUARTER GLASS FRT/RH X ^{NN}	1	\$234.90	25%	\$176.18	/	
	SEALANT W/SCREEN X ^{NN}	1	37.00	0%	37.00	/	
67001-47070	DOOR FRT/RH X ^{NN}	1	\$894.40	25%	\$670.80	/	
	STICKER DECAL SMRT (DOOR) X ^{NN}	1	\$60.00	0%	\$60.00	/	
69210-74030	DOOR OUTER HANDLE FRT/RH X ^{NN}	1	\$370.80	25%	\$278.10	/	
68720-12151	DOOR HINGE LOWER FRT/RH X	1	\$80.50	25%	\$60.38	/	
68710-12151	DOOR HINGE UPPER FRT/RH X	1	\$80.50	25%	\$60.38	/	
68610-47021	CHECK ASSY, FR DOOR, X ^{NN}	1	\$150.30	25%	\$112.73	/	
61131-47030	PILLAR, FR BODY X	1	\$363.10	25%	\$272.33	/	
87910-47330	MIRROR ASSY, RH X	1	\$1,307.10	25%	\$980.33	/	
81730-52090	MIRROR LAMP RH X	1	\$65.30	10%	\$58.77	/	
879157-4010	COVER, OUTER MIRROR, RH X ^{NN}	1	\$107.40	25%	\$80.55	/	
75710-47021	DOOR BELT FRT/RH X	1	\$69.20	25%	\$51.90	/	
67003-47080	DOOR RR/RH X ^{NN}	1	\$954.50	25%	\$715.88	/	
	PIXEL STICKER X ^{NN}	1	\$60.00	0%	\$60.00	/	
TOTAL MATERIALS LUMP SUM 20%					\$4,500.38		

10976.94

Shu Pei (LKKAUTO)

From: Jowyn Tay <jowyn.tay@sg.cntaiping.com>
Sent: Wednesday, 19 September 2018 11:39 AM
To: Shu Pei (LKKAUTO); Vivian Lau (LKKAUTO)
Cc: Admin A; Alfred Toh; Jowyn Tay
Subject: RE: Direct Settlement - Accident Involving GBG4900R (OI : SNM18D04507/C02/0/LKKDS) AND SHC4493Z (TP : LKK REF - CC3/CTI18017000/Gwb3) on 14/09/2018
Attachments: SNM18D04507C02 20180919-TO INSD-APPT LKK AS SETTLEMENT AGENT.pdf; MCHM18120458-GBG4900R.pdf
Importance: High

Dear Vivian &/or Shu Pei,

Refer to your email on 18 Sept 2018.

We attached our insured's accident report and letter for your immediate attention.

Thank you.

Best Regards,

Jowyn Tay

Deputy Claims Executive
Claims Department – Motor Division

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6174

Fax (65) 6224 7175 / 6224 7478

Email: claimsdept@sg.cntaiping.com

Website: www.sg.cntaiping.com



Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAuto) [mailto:shupe@lkkauto.com]

Sent: Tuesday, 18 September, 2018 5:28 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Lucas Lee <lucas.lee@sg.cntaiping.com>; Jowyn Tay <jowyn.tay@sg.cntaiping.com>; Admin A <admin-a@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>

Subject: Direct Settlement - Accident Involving GBG4900R (OI : CTI - TBA) AND SHC4493Z (TP : LKK REF - CC3/CTI18017000/Gwb3) on 14/09/2018

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

This is a TP direct settlement case. We have inspected TP vehicle SHC 4493Z at M/s SMRT Automotive Services Pte Ltd - Woodlands.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079906
Tel: 6389 6111 Fax: 6222 1033
Website: www.ctaiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM18D04507/C02/0**

Date : **19 SEPTEMBER 2018**

via Ordinary & Registered Mail

**CO-HIN COMPANY
BLK 133 JURONG GATEWAY ROAD
#04-299
SINGAPORE 600133**

Dear Sir / Madam

**ACCIDENT INVOLVING GBG4900R AND SHC4493Z ON 14 SEPTEMBER 2018
ALONG B/18 MARSILING LANE (CAR PARK)**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHC4493Z**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : VIVIAN LAU

Ref : CC3/CTI18017000/GWB3

Contact No : 68418625

via Email : vivianlau@lkkauto.com

CC : Agent - (AN0166A) - LQ BUSINESS PTE LTD

F01/LKKDS-2013



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18017000/Gwb3s2

3 ANSON ROAD #16-00

SPRINGLEAF TOWERS SINGAPORE 079909

Date : 03-06-2019



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 4900R	Veh. Inspected	SHC 4493Z
Policy No.	DMCVSN3054291800	Coverage (\$)	0.00
Claim No.	SNM18D04507C02/0	Excess (\$)	0.00
Assign From		Assign Date	17/09/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U205748905	Colour	MAROON
Odometer	408714	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	FALKEN	6 mm
L/H Front Tyre	195/65R15	FALKEN	6 mm
R/H Rear Tyre	195/65R15	FALKEN	6 mm
L/H Rear Tyre	195/65R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/09/2018	Inspection Date	17/09/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4493Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FENDER FRT/RH (DISC 25%)	BUCKLED	723.40	542.55
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.93
1	QUARTER GLASS FRT/RH (DISC 25%)	NECESSARY	234.90	176.18
1	DOOR FRT/RH (DISC 25%)	BENT	894.40	670.80
1	DOOR OUTER HANDLE FRT/RH (DISC 25%)	CUT	370.80	278.10
1	COVER, OUTER MIRROR, RH (DISC 25%)	CUT	107.40	80.55
1	SEALANT W/SCREEN (SN)	NECESSARY	37.00	37.00
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
1	FENDER LINER FRT/RH	NOT NECESSARY	171.70	-
1	WHEEL DISC FRONT	NOT NECESSARY	1,484.20	-
1	TYRE	NOT NECESSARY	126.74	-
1	DOOR HINGE LOWER FRT/RH	NOT NECESSARY	80.50	-
1	DOOR HINGE UPPER FRT/RH	NOT NECESSARY	80.50	-
1	CHECK ASSY, FR DOOR,	NOT NECESSARY	150.30	-
1	PILLAR, FR BODY	NOT NECESSARY	363.10	-
1	MIRROR ASSY, RH	NOT NECESSARY	1,307.10	-
1	MIRROR LAMP RH	NOT NECESSARY	65.30	-
1	DOOR BELT FRT/RH	NOT NECESSARY	69.20	-
1	DOOR RR/RH	NOT NECESSARY	954.50	-
1	PIXEL STICKER	NOT NECESSARY	60.00	-
1	SOLAR FILM (SN)	NOT NECESSARY	125.00	-
			7,517.94	1,884.11
LABOUR				
	PANEL BEATING & BODYWORK.		845.00	400.00
	SPRAY PAINT.		1,674.00	500.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	30.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	60.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	NOT NECESSARY	120.00	-
	TO TRANSFER DOOR MECHANISM.		240.00	60.00
	TO REMOVE & REFIX FRONT LHS/RHS QUARTER GLASS.		120.00	40.00

Report Ref No. CC3/CT118017000/Gwb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIX WING MIRROR.		120.00	40.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
			3,459.00	1,130.00
GRAND TOTAL			10,976.94	3,014.11
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,600.00

Report Ref No. CC3/CT118017000/Gwb3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.