

## SMRT Accident Taxi Repair Estimates

### Section A - To be completed by Claims Advisor/Duty Officer at Accident Reporting Centre

Reg. No. : SHC 4493Z Ref. No. TAX 9 / 18 / 2057

Make / Model : TOYOTA PRIUS Reg. Date : 10/09/2014

Name of Driver : TENG CHEE HWA

Date/Time of Accident : 14/09/2018 15:38

Surveyer is Required ? YES / NO

If Yes, VICOM / LKK / LH Teo / AIS (Please circle one)


Taxi is Towed Back ? YES / NO

Replacement Taxi Issued ? YES / NO

Accident Repair Job Card No. : 2409737

Special Instruction to ARC, if any :

The damages on the Taxi are as indicated in the following diagram :



Signed : \_\_\_\_\_ Date : \_\_\_\_\_

### Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U205748905 Mileage : \_\_\_\_\_

Date Prepared : 15/09/2018 Repair Completed date/time: \_\_\_\_\_

#### Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	\$ <u>845</u>	\$ _____
Total Spray Painting Charges :	\$ <u>1674</u>	\$ _____
Total Material Charges :	\$ <u>4500.38</u>	\$ _____
Other Charges :	\$ <u>1065</u>	\$ _____
<b>TOTAL</b> :	<b>\$ <u>8084.38</u></b>	<b>\$ _____ ( )</b>
No. of Repair Days :	[ <u>6</u> ] days	[ <u>4</u> ] days

Signature : \_\_\_\_\_ Prepared by: MING

15/09/2018 17:33

Adjusted by: Eric Q. ang  
17/9/18

### Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Q/N No. : \_\_\_\_\_ Invoice No. : \_\_\_\_\_

Invoice Date : \_\_\_\_\_

Signed : \_\_\_\_\_ Date : \_\_\_\_\_

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

## Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	845	400
<b>Total Labour</b>	<b>\$ 845.00</b>	<b>\$ -</b>

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER RH	378	<del>378</del> 200
TO RESPRAY RIM	180	X NN
TO RESPRAY VIEW MIRROR	180	<del>180</del> 100
TO RESPRAY FRONT DOOR RH	378	200
TO RESPRAY FRONT PILLAR RH	180	X
TO RESPRAY REAR DOOR RH	378	<del>378</del> X NN
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$ 1,674.00</b>	<b>\$ -</b>

## Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80	<del>80</del> 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100	<del>100</del> 60
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125	X NN
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120	X NN
TO TRANSFER DOOR MECHANISM	240	<del>240</del> 60
TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	120	<del>120</del> 40
TO REMOVE AND REFIX WING MIRROR	120	<del>120</del> 40
TO WASH AND VACUUM	60	X NN
TO REPLACE SUNDRY PARTS	100	X NN
<b>Total Other Costs</b>	<b>\$ 1 065.00</b>	<b>\$ -</b>

## Section D - Details of Repair Estimates

Part 4 - Spare Parts / Material Usage

Ref. No. TAX 9 / 18 / 2057

Reservation No : \_\_\_\_\_

Page ( )

To be completed by Service Advisor, ARC							Surveyor Adj
Part Number	Parts Description	Qty	List Price (\$)	Discount (%)	Final Price (\$)	Repair (R) Replace (/)	Not given (x) Repair (R) Replace (/)
53801-47050	FENDER FRT/RH <del>X</del> <i>BUC</i>	1	\$723.40	25%	\$542.55	/	
75374-47051	NAME PLATE (HYBRID) <del>X</del> <i>RC</i>	1	\$51.90	25%	\$38.93	/	
53875-47030	FENDER LINER FRT/RH <del>X</del> <i>NN</i>	1	\$171.70	25%	\$128.78	/	
42611--47140(Frt)	WHEEL DISC. FRONT <del>X</del> <i>NN</i>	1	\$1,484.20	25%	\$1,113.15	/	
	TYRE <del>X</del> <i>NN</i>	1	\$126.74	0%	\$126.74	/	
62110-47021	QUARTER GLASS FRT/RH <del>X</del> <i>RC</i>	1	\$234.90	25%	\$176.18	/	
	SEALANT W/SCREEN <del>X</del> <i>RC</i>	1	37.00	0%	37.00	/	
67001-47070	DOOR FRT/RH <del>X</del> <i>BT</i>	1	\$894.40	25%	\$670.80	/	
	STICKER DECAL SMRT (DOOR) <del>X</del> <i>RC</i>	1	\$60.00	0%	\$60.00	/	
69210-74030	DOOR OUTER HANDLE FRT/RH <del>X</del> <i>Cut</i>	1	\$370.80	25%	\$278.10	/	
68720-12151	DOOR HINGE LOWER FRT/RH <del>X</del>	1	\$80.50	25%	\$60.38	/	
68710-12151	DOOR HINGE UPPER FRT/RH <del>X</del>	1	\$80.50	25%	\$60.38	/	
68610-47021	CHECK ASSY, FR DOOR, <del>X</del> <i>NN</i>	1	\$150.30	25%	\$112.73	/	
61131-47030	PILLAR, FR BODY <del>X</del>	1	\$363.10	25%	\$272.33	/	
87910-47330	MIRROR ASSY, RH <del>X</del>	1	\$1,307.10	25%	\$980.33	/	
81730-52090	MIRROR LAMP RH <del>X</del>	1	\$65.30	10%	\$58.77	/	
879157-4010	COVER, OUTER MIRROR, RH <del>X</del> <i>Cut</i>	1	\$107.40	25%	\$80.55	/	
75710-47021	DOOR BELT FRT/RH <del>X</del>	1	\$69.20	25%	\$51.90	/	
67003-47080	DOOR RR/RH <del>X</del> <i>NN</i>	1	\$954.50	25%	\$715.88	/	
	PIXEL STICKER <del>X</del> <i>NN</i>	1	\$60.00	0%	\$60.00	/	
TOTAL MATERIALS LUMP SUM 20%					\$4,500.38		