

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR GZ7384B

No.	Qty	List Items				
1	1	Front bumper	\$ CM	706.90	✓	
2	1	Front bumper inner bracket	\$	704.60	?	
3	1	Front inner cross member	\$	407.00	?	
4	2	Headlamp	OLSBu nls my \$ CM	696.40	✓	
5	2	Front side lamp	\$ Bu	369.00	✓	
6	1	Front grille	\$ nls	371.60	✓	
7	1	Front grille centre "NISSAN" logo	\$ nls	65.70	✓	
8	1	Front wiper garnish	\$ Bu	544.10	✓	
9	1	Front wiper garnish "CABSTAR" emblem	\$ Bu	36.30	✓	
10	1	Front RH wiper arm	\$ Su	43.40	X	
11	1	Front LH wiper arm	\$	43.40	?	
12	2	Front wiper blade	\$	31.70	?	
13	1	Front panel	\$ Bu	1,554.00	✓	
14	1	Front windscreen glass	\$ CM	1,160.00	✓	
15	1	Front windscreen rubber	\$ Bu	160.40	50% Su	
16	1	Front LH side mirror complete	\$ R	104.30	X	
17	1	Front RH side mirror complete	\$ R	104.30	X	
18	2	Front corner panel	OLSBu \$	857.80	4	
19	2	Front cabin mounting	\$	170.40	?	
20	1	Front clutch hose	nls Bu \$	54.50	✓	
21	1	Dashboard assy	\$ Bu	1,021.90	✓	
22	1	Air con high pressue hose	\$ Bu	150.00	✓	
23	1	Air con low pressue hose	\$ Bu	165.00	✓	
24	1	Front RH door	Bu \$	1,536.20	✓	
25	1	Front RH door front pillar outer	\$ Bu	1,135.50	✓	
26	1	Front RH door front pillar inner	\$ R	447.20	X	
27	1	Front RH door rear pillar	\$ R	1,034.50	X	
28	1	Front RH door inner lock	\$ Bu	167.70	✓	
29	1	Front RH door glass regulator	\$ Bu	112.00	✓	
30	1	Front RH door glass regulator motor	\$ Bu	524.40	✓	
31	2	Front RH door hinge (Top & bottom)	\$ Bu	260.10	✓	
32	1	Front RH door check	\$ R	67.70	X	
33	1	Front RH door weatherstrip	\$	181.60	?	
34	1	Front RH door inner trim board	\$ CM	794.70	✓	
35	1 set	Front RH door inner trim board clips	\$ Bu	50.00	✓	
36	1	Rear tailgate	\$ Bu	1,399.70	✓	
37	1	Rear deck end panel	\$ Bu	848.60	✓	
38	2	Taillamp bracket	OLSBu \$	114.80	4	
39	2	Taillamp	OLSBu \$	297.40	4	
40	1	Rear number plate bracket	\$ R	48.50	X	
41	1	Rear number plate lamp	\$ Su	71.30	X	
42	1	Rear lower spare tyre carrier chain	\$	240.50	?	
43	1	Rear RH side gate lower lock catch	\$	85.10	?	

Not withain
61 Sep 8?
Money After Repair
18 days

44	1	Rear RH side lower rubber stopper bracket	\$	183.40	—
45	1 set	Rear side lower rubber stopper	\$	8.90	—
			\$	19,132.50	
		Less 10%	\$	1,913.25	
		Total :	\$	17,219.25	

Special Nett Items

46	1	Front wiper linkage	\$	166.60	?
47	1	Front wiper motor	\$	589.50	?
48	1	Front brake booster pump	\$	1,340.10	?
49	1	Front brake booster pump bracket	\$	135.70	?
50	1	Front brake master pump	\$	561.30	?
51	2	Front brake hoses	\$	100.60	?
52	3	Front brake tube	\$	199.50	?
53	1	Steering box	\$	1,879.30	?
54	1	Air con evaporator unit	\$	1,310.60	?
55	1	Air con blower unit	\$	462.20	?
56	1	Front RH door "CABSTAR" emblem	\$	27.40	—
57	1	Front RH door glass	\$	720.70	—
58	1	Front number plate	\$	40.00	205m
59	1	IU bracket	\$	26.00	—
60	1	Rear number plate	\$	40.00	205m
61	1	Rear lower cross member	\$	282.30	?
62	1	Rear lower exhaust pipe	\$	545.50	X
63	1	Rear lower step bar	\$	250.00	?
64	1	Rear lower spare tyre	\$	150.00	?
		Total :	\$	8,827.30	

Labour

1	Towing charges.	\$	60.00	✓
2	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$	2,600.00	2200
3	To putty and spray Spray Paintings charges.	\$	2,400.00	1600
4	To remove, refit front windscreen glass.	\$	120.00	60
5	To check wirings and lightings for front & rear damages.	\$	50.00	40
6	To remove, refit dashboard assy	\$	250.00	✓
7	To remove, refit air con blower/evaporator unit, including refill air con gas.	\$	140.00	100
8	To remove, refit brake booster pump, brake hoses/pipings, clutch hose and bleed systems.	\$	80.00	80
9	To remove, refit front RH door fittings.	\$	80.00	60
10	To remove, refit rear exhaust pipe.	\$	60.00	X
11	To remove, refit rear deck floor bed, inorder to facilitate repair.	\$	500.00	X
12	To mount vehicle on chassis bench, to repair, straighten & adjust to its specification.	\$	280.00	X
13	To supply and apply anti-rust treatment	\$	150.00	✓
	Total :	\$	6,770.00	

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total Parts and Labour : \$ 32,816.55