



PDI TUAS

SUN XIYU  
33 UBI AVENUE 3  
#03-03  
Singapore, 408868  
Singapore

4 Days.  
before paint photos.  
Gua Qiang - 82880282  
21/9/18

PDI TUAS

Phone No.  
Fax No.  
E-Mail

VAT Registration No. M20098505-2  
Tax No. 199101494Z

## Service Quote

Customer No. CV039167  
Quote No. SER/QUO/1801556  
QuoteDate 18/09/18  
Salesperson Maggie Poon  
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

| Make               | Model Description          | Mileage              | Service Advisor |
|--------------------|----------------------------|----------------------|-----------------|
| Volkswagen Passeng | Passat 2.0 TSI Excline 9S8 | 4,165                | Tang Shu Shi    |
| License No.        | VIN                        | Initial Registration | Sales Advisor   |
| SLN29C             | WVWZZZ3CZHE029546          | 23/11/17             | Maggie Poon     |
| Engine Code        | Labor Type                 | Engine No.           | Model Code      |
|                    | 1P                         | CHH 163363           | 3G24MY          |

| No.                        | Description                                            | Qty. | UoM     | Unit Price | Amount           |
|----------------------------|--------------------------------------------------------|------|---------|------------|------------------|
| P B&P MACP LABOUR          | LABOUR                                                 | 2    | 4 UNIT  | 1680       | 3,360.00         |
| P B&P MACP PAINT           | SPRAY PAINT                                            | 4    | 4 UNIT  | 1600       | 3,200.00         |
| P B&P NUMBER PLATE         | B&P NUMBER PLATE -NETT                                 | 1    | pcs     |            | 80.00            |
| P B&P DIAG                 | PROGRAMMING & CALIBRATION<br>COMPULSORY TO DO AFTER AC | 1    | Time Un |            | 480.00           |
| P B&P MECH                 | CHECK WIRE HARNESS, ECU, S<br>Nett                     | 1    | Time Un |            | 280.00           |
|                            | <b>Sum Labor</b>                                       |      |         |            | <b>7,400.00</b>  |
| P 3G0807305T               | REINFORCEMENT ?<br>Predecessor 3G0807305N              | 1    | Pieces  |            | 416.15           |
| P 3G0807521R GRU           | SPOILER                                                | 1    | Pieces  |            | 207.57           |
| P 3G0827469F FOD           | BOOTLID MECHANISM ?<br>Use Predecessor 3G0827469 FO    | 1    | Pieces  |            | 1,726.38         |
| P 3G0827506F               | LATCH ?                                                | 1    | Pieces  |            | 356.92           |
| P 3G0853675AJ2ZZ           | 380 TSI EMBLEM                                         | 1    | Pieces  |            | 54.06            |
| P 3G0853687 2ZZ            | PASSAT EMBLEM                                          | 1    | Pieces  |            | 52.41            |
| P 3G0853835 2ZZ            | CENTRE BUMPER MOLDING                                  | 1    | Pieces  |            | 174.60           |
| P 3G0853841 2ZZ            | LHR BUMPER MOULDING<br>Use Predecessor 3G0807367 9B9   | 1    | Pieces  |            | 134.46           |
| P 3G0853842 2ZZ            | RHR BUMPER MOULDING                                    | 1    | Pieces  |            | 134.46           |
| P 3G0945103A               | LH INNER REFLECTOR ?                                   | 1    | Pieces  |            | 60.17            |
| P 3G0945104A               | RH INNER REFLECTOR ?                                   | 1    | Pieces  |            | 60.17            |
| P 3G0945105A               | LH OUTER REFLECTOR ?                                   | 1    | Pieces  |            | 60.17            |
| P 3G0945106A               | RH OUTER REFLECTOR ?                                   | 1    | Pieces  |            | 60.17            |
| P 3G0998491                | SENSOR BRACKET                                         | 1    | Pieces  |            | 42.62            |
| <b>Sum carried forward</b> |                                                        |      |         |            | <b>10,940.31</b> |

Payments to:

- BBN: - Acc.-No.:



PDI TUAS

SUN XIYU  
33 UBI AVENUE 3  
#03-03  
Singapore, 408868  
Singapore

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PDI TUAS

Phone No.

Fax No.

E-Mail

VAT Registration No. M20098505-2

Tax No. 199101494Z

## Service Quote

Customer No. CV039167  
Quote No. SER/QUO/1801556  
QuoteDate 18/09/18  
Salesperson Maggie Poon  
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

| Make               | Model Description          | Mileage              | Service Advisor |
|--------------------|----------------------------|----------------------|-----------------|
| Volkswagen Passeng | Passat 2.0 TSI Excline 9S8 | 4,165                | Tang Shu Shi    |
| License No.        | VIN                        | Initial Registration | Sales Advisor   |
| SLN29C             | WVWZZZ3CZHE029546          | 23/11/17             | Maggie Poon     |
| Engine Code        | Labor Type                 | Engine No.           | Model Code      |
|                    | 1P                         | CHH 163363           | 3G24MY          |

| Continued        |                                  |          | 10,940.31       |
|------------------|----------------------------------|----------|-----------------|
| P 3G0998492      | SENSOR BRACKET / <i>mc</i>       | 1 Pieces | 36.11           |
| P 3G5807375      | LHR BUMPER BRACKET <i>= 4 mc</i> | 1 Pieces | 30.90           |
| P 3G5807376      | RHR BUMPER BRACKET               | 1 Pieces | 30.90           |
| P 3G5807417 GRU  | REAR BUMPER / <i>DE</i>          | 1 Pieces | 969.81          |
| P 3G5807483      | LHR TAILLIGHT BRACKET ?          | 1 Pieces | 17.88           |
| P 3G5807484      | RHR TAILLIGHT BRACKET ?          | 1 Pieces | 17.88           |
| P 3G5827025A     | BOOT LID / <i>mc</i>             | 1 Pieces | 1,308.09        |
| P 3G5827520A 9B9 | LOCK ?                           | 1 Pieces | 27.85           |
| P 3G5827705E     | BOOT LID SEAL ?                  | 1 Pieces | 255.33          |
| P 3G5945307E     | LH INNER TAILLIGHT ?             | 1 Pieces | 467.22          |
|                  | Predecessor 3G5945307A           |          |                 |
| P 3G5945308D     | RH INNER TAILLIGHT ?             | 1 Pieces | 409.10          |
| P 510853617A FOD | VW SIGN / <i>mc</i>              | 1 Pieces | 63.66           |
| P 5Q0919133 9B9  | SENSOR O RING / <i>mc</i>        | 1 Pieces | 1.32            |
| P 5Q0919275B GRU | SENSOR ?                         | 1 Pieces | 166.62          |
|                  | Use Predecessor 5Q0919275 GR     |          |                 |
| P D 180KU2A1     | 2KADHESIVE / <i>mc</i>           | 1 Pieces | 69.11           |
| P D 822150A1     | BONDAGENT / <i>mc</i>            | 1 Pieces | 49.44           |
| P WHT005263      | POP-RIVET / <i>mc</i>            | 5 Pieces | 5.65            |
|                  | <b>Sum Item</b>                  |          | <b>7,467.18</b> |

Payments to:

- BBN: - Acc.-No.:



PDI TUAS

SUN XIYU  
33 UBI AVENUE 3  
#03-03  
Singapore, 408868  
Singapore

PDI TUAS

Phone No.  
Fax No.  
E-Mail

VAT Registration No. M20098505-2  
Tax No. 199101494Z

## Service Quote

Customer No. CV039167  
Quote No. SER/QUO/1801556  
QuoteDate 18/09/18  
Salesperson Maggie Poon  
Page 3

THIS IS NOT AN OFFICIAL TAX INVOICE

|                    |                            |
|--------------------|----------------------------|
| <b>Make</b>        | <b>Model Description</b>   |
| Volkswagen Passeng | Passat 2.0 TSI Excline 9S8 |
| <b>License No.</b> | <b>VIN</b>                 |
| SLN29C             | WVWZZZ3CZHE029546          |
| <b>Engine Code</b> | <b>Labor Type</b>          |
|                    | 1P                         |

|                             |                        |
|-----------------------------|------------------------|
| <b>Mileage</b>              | <b>Service Advisor</b> |
| 4,165                       | Tang Shu Shi           |
| <b>Initial Registration</b> | <b>Sales Advisor</b>   |
| 23/11/17                    | Maggie Poon            |
| <b>Engine No.</b>           | <b>Model Code</b>      |
| CHH 163363                  | 3G24MY                 |

|                            |                  |
|----------------------------|------------------|
| <b>Sum Labor</b>           | <b>7,400.00</b>  |
| <b>Sum Item</b>            | <b>7,467.18</b>  |
| <b>Total SGD</b>           | <b>14,867.18</b> |
| 7% GST                     | 1,040.71         |
| <b>Total SGD Incl. GST</b> | <b>15,907.88</b> |

### Explanations

P = Proportionately Charged

**Payment Terms** No Credit

Payments to: - BBN: - Acc.-No.: