

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1083/2018/GW
Date : 19-Sep-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Chew Loy Cheow
Address : 17M Lim Tua Tow Road
Singapore 547764
Telephone : HP +65 96163206
Type of Claim : Third Party Claims
Policy No. : SD17V03346/VPC2/R00
Vehicle No : **SJV 575 Z**
Model Code : Audi A4 Sedan 1.4 TFSI
Model / Year : Feb-17
Engine No : CVN 022440
Chassis No : WAUZZZF49HA056422
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-Sep-18
Place of Accident : Blk 232 Serangoon Ave 3 Car park

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SJV 575 Z.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for healdights, horns, outside temperture sensor and headlights washer assy.	S/N \$ 360.00	✓
2	To dismantle rhs fornt door panel trim. To remove and reinstall rhs wing mirror assy.	S/N \$ 300.00	✓
3	To disamantle and renew front bumper, rhs front fender and rhs headlight. Re-organize front crash management components. Reinstall all parts removed.	\$ 2,100.00	1250 .
4	To respray front bumper, rhs front fender and rhs front door.	\$ 2,500.00	1650
5	To carry out diagnostic check .	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,452.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJV 575 Z

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Rehnd</i>	\$ 1,849.00	✓
2	FRONT BUMPER FIXING PARTS <i>He ne</i>	\$ 245.00	X
3	FRONT BUMPER SECURING STRIP <i>He m</i>	\$ 60.00	X
4	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE <i>He m</i>	\$ 180.00	X
5	FRONT BUMPER AIR GUIDE-RH <i>He m</i>	\$ 73.00	X
6	FRONT BUMPER AIR GUIDE GRILLE-RH <i>He m</i>	\$ 118.00	X
7	FRONT BUMPER GUIDE SECTION-RH <i>He m</i>	\$ 32.00	X
8	FRONT FENDER-RH <i>Distorted</i>	\$ 665.00	✓
9	FENDER ATTACHMENT PARTS <i>He ?</i>	\$ 45.00	?
10	FRONT FENDER CLOSING ELEMENT-RH <i>?</i>	\$ 44.00	?
11	FRONT FENDER BRACKET-RH <i>?</i>	\$ 31.00	?
12	FRONT FENDER DEFORMATION BRACKET-RH <i>He ?</i>	\$ 43.00	?
13	FRONT FENDER BRACKET-RH <i>?</i>	\$ 27.00	?
14	FRONT FENDER BRACE-RH <i>?</i>	\$ 103.00	?
15	FRONT FENDER COVER <i>He</i>	\$ 27.00	✓
16	FRONT FENDER TOP COVER <i>He</i>	\$ 20.00	✓
17	FRONT WHEEL HOUSING LINER -RH <i>He m</i>	\$ 209.00	X
18	WHEEL HOUSING LINER ATTACHMENT PARTS <i>He m</i>	\$ 78.00	X
19	FRONT WHEEL SPOILER-RH <i>He m</i>	\$ 63.00	X
20	FRONT FENDER END PLATE-RH <i>?</i>	\$ 31.00	?
SUB-TOTAL SPARE PARTS		\$ 3,943.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJV 575 Z

S/N	Parts Description	Damage Pa S/NETT
21	STONE CHIP GUARD <i>new</i>	\$ 44.00 ✓
22	LED HEADLIGHT-RH <i>lit</i>	\$ 6,973.00 ✓
23	LED HEADLIGHT LIFT CYLINER-RH <i>RLH new</i>	\$ 184.00 ✗
24	SUNDRIES ?	\$ 300.00 ?
TOTAL SPARE PARTS :		\$ 11,444.00
TOTAL LABOUR CHARGES :		\$ 5,452.00
GRAND TOTAL :		\$ 16,896.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 21/09/18.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, OS Rep

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant