

ASS. REC. BY:

REF: CS / FCL 18017017 / G79021 Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): WS Luene Jau of FCL Date/Time: 18/09/2018 3:38pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJS 6346U Insured: SHD 8560G

at Workshop m/s Torque 5 Tel: 6452 4457

of 8 Kaki Bukit Ave 4 #01-50

Policy No: Claim No: D18006868M7SH

Sum Insured: Excess:

Make of Veh: D.O.A. 16092018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS' 19.09.2018

Date/Time: 18/09/2018 4:48pm Person Contacted: Lee Yi H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time Action/Instruction (✓) Estimate

SJS 6346U - C16 / AXA 1300877 / Uhb3XX 209: 090513

SHD 8560G - X

20/9/18 @ 3:07pm revised to Luene by email.

Surveillance XRL

REF: RA

ASSIGNMENT

(-2019)

From: _____ Date: 19/09/2018
Estimated Cost: _____
OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SJS 6346U
at Workshop m/s: Torque 5
of 8 Kaki Pukh ARL4 #01-50
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$223K
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 11 days Res.: Yes or No
Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJS6346U Yr Regn: 26 Aug 2009
Type: ☒ M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Toyota wish C.C. 1797
Colour: white A/C: _____ Insured / Std / NI / NA
Sp. Reading: 131595 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: 2GE 2000 / 2984
Gen. Cond: 8 Good / Fair / Poor / Burnt
Steering: 8 In order / Jammed / Leaked / Burnt or
Brake: 6 In order / Jammed / Leaked / Burnt or
Modi: 0 Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/40ZR18
R: u

BS / DUN / EXNOVA / GY / FS / LIZA / MC / OHTSU / PIR / SUMI /
TOYO / YOKO or memhat

Front		Rear
R/Bal. <u>5</u> mm		R/Bal. <u>5</u> mm
L/Bal. <u>5</u> mm		L/Bal. <u>5</u> mm
D.O.A. _____		D.O.I. <u>19-09-18</u>

Survey held at w/s 4:30pm

Des. of Damages: Frt / 0 Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Final sum \$8600 with lucas. (Red \$77458.30, 76%)</u>

RECEIVED 29 NOV 2018

Date/Time, File Pass to? ☐ Preli. Report
1) 20/11/18 ☐ Final Report
Date/Time, File Return to?

Days Of Repair: 11
Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Invs (\$)
☐ Weekend (\$)

Report Format: TP
Lump Sum / I.B.I. (\$) 8600

Survey Fee 26x15 = 390
Transportation: 170 + 390
50
50 + 50
96
806



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006868MFSH
Our Ref: CS/FCI18017017/Gqb

Date: 20 September 2018

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJS 6346U

Please be informed that we had conducted the inspection of the abovementioned vehicle on 19/09/2018 at the premises of M/s TORQUE 5, and have the following to report:-

Workshop Estimate Amount	: S\$ 35,808.30
Revised Estimate Amount	: S\$ 9,545.80
"Check" Items Amount	: S\$ 3,250.40
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:
The vehicle sustained damages
at the rear portion.



Yours faithfully

Guo Qiang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	17-09-2018	Our Ref No. D18006868MFSH
Accident Date	16-09-2018	Claim Type. Third Party
Insured Vehicle	SHD8560G	Third Party Vehicle. SJS6346U
Survey Location	NO. 8 KAKI BUKIT AVE 4 PREMIER @ KAKI BUKIT#01-50	
Contact Person.	HENG LEE YI	
Contact No.	64524457/ 0	Fax No. 64524584
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TORQUE 5 PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 20 September 2018 3:07 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006868MFSH/1
Attachments: CSFCI18017017Gqb.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SJS 6346U.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 18 September 2018 4:50 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006868MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 18 September, 2018 3:38 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006868MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System

Shiau Chan (LKKAuto)

From: Torque 5 Assessment <assessment@torque5.com>
Sent: Thursday, 20 September 2018 10:05 AM
To: SUR; Guo Qiang (LKKAuto)
Cc: assessment@torque5.com; claims@torque5.com
Subject: SJS 6346 U - Toyota Wish
Attachments: image010.wmz

Dear all,



Kindly confirm that the repair limit for the above mentioned vehicle is capped that \$10K (Max).

Warmest Regards,
Heng Lee Yi
Administrative Assistant | Motor Claims Department

Hotline (65) 6452 4457 Ext:111 | Fax (65) 6452 4584

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875

www.torque5.com



9/17/2018

Used Wish 1.8A Car & Used Cars & Vehicles Singapore - sgCarMart

**Toyota Wish 1.8A (New 5-yr COE)****\$35,600**

\$7,120 /yr

01-Apr-2009

1,794 cc

115,500 km

MPV

Available

Low Mileage, Agent Unit, Service Records.

Posted: 06-Sep-2018 Tags: 2009 Toyota Wish, Toyota Wish, Toyota, Wish, Used Toyota

**Toyota Wish 1.8A X****\$27,000**

\$12,060 /yr

05-Jan-2010

1,797 cc

97,500 km

MPV

Available

Elegant White MPV, Low Mileage Done, Low Maintenance Cost, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In-house Loan Packages Available.

Prime Motor & Leasing

Posted: 03-Sep-2018 Tags: 2010 Toyota Wish, Toyota Wish, Toyota, Wish, Used Toyota

**Toyota Wish 1.8A X (New 10-yr COE)****\$59,800**

\$5,980 /yr

24-Aug-2009

1,797 cc

-

MPV

Available

Original Condition N Paint Work, Careful Owner, Very Well Kept, Accident Free, Beautiful Interior And Exterior, Accident Free, With No Wear And Tear To Be Replaced, Low Mileage, Brand New Tyres, See To ...

Posted: 25-Aug-2018 Tags: 2009 Toyota Wish, Toyota Wish, Toyota, Wish, Used Toyota

**Toyota Wish 1.8A X****\$28,800**

\$12,020 /yr

11-Mar-2010

1,797 cc

108,000 km

MPV

Available

1 Owner. Well Maintained By Previous Owner. Very Spacious And Big Boot Space. Ideal For Those Who Fancy Spacious And Comfort Interior Yet Powerful Drive! Loans And In House Loan Can Be Arranged. Call ...

Posted: 20-Aug-2018 Tags: 2010 Toyota Wish, Toyota Wish, Toyota, Wish, Used Toyota

**Toyota Wish 1.8A X (New 10-yr COE)****\$61,800**

\$6,170 /yr

10-Jul-2009

1,797 cc

-

MPV

Available

10 Years New COE, Well Maintained. Very Spacious And Big Boot Space. Great For Big Family. Ideal For Those Who Fancy Spacious And Comfort Interior Yet Powerful Drive!

Posted: 18-Aug-2018 Tags: 2009 Toyota Wish, Toyota Wish, Toyota, Wish, Used Toyota

**Toyota Wish 1.8A (New 5-yr COE)****\$37,800**

\$7,560 /yr

12-Mar-2009

1,794 cc

-

MPV

Available

10 Years COE Renewal For \$54,800. Up To 90% Flexible Loan. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package With Unrivalled Warranty Complete With Certificate And...

Classic Credit Pte Ltd

Posted: 10-Aug-2018 Tags: 2009 Toyota Wish, Toyota Wish, Toyota, Wish, Used Toyota

Make & Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view **Expired ads**

40 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Wish 1.8A, Wish 1.8A Singapore, used Wish 1.8A Singapore, used Wish 1.8A, used vehicles Singapore or even buy used Wish 1.8A Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

[Compare](#)

► Wish Used Vehicle List (20 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabl
Toyota Wish 1.8A (New 10-yr COE)	\$60,800	\$6,080 /yr	25-Nov-2009	1,797 cc	108,000 km	Karz Konzept	Availat
Down Payment Of \$1800. 2 Owners. Engine All Done Up. New Alternator, New Starter, New Aircon Compressor. No Oil Leak. Car In Superb Condition. No Expenses Spent On By Previous Owner. Call Now To Enqui...							
Office No. - - Tan (No Sms) - 81173333 Kelvin - 82513333							
Toyota Wish 2.0A (New 10-yr COE)	\$66,888	\$6,680 /yr	10-Nov-2009	1,987 cc	90,827 km	ABS Auto Holding Pte Ltd	Availat
We Are The COE Specialist. No Gimmicks, Honest Dealing, 1 Owner With Low Mileage Clock, Car In Good Condition, High Loan With \$6000 Down Paymer Drive Away! 100% Approval. Trade In Welcome, Bank Loan ...							
Office No. - 64753423 Kenny - 98259995 Roy Lee - 83158315 Alex - 82298229 Ken - 91196006							
Toyota Wish 1.8A X (New 10-yr COE)	\$59,800	\$5,980 /yr	24-Aug-2009	1,797 cc	-	Car Design Motor	Availat
Original Condition N Paint Work,Careful Owner, Very Well Kept, Accident Free, Beautiful Interior And Exterior, Accident Free, With No Wear And Tear To I Replaced, Low Mileage, Brand New Tyres,See To ...							
Office No. - 67468820 Dion - 87425596 David Tan - 83338363 Danson - 83186570 Vicky - 85557476							
Toyota Wish 1.8A X (New 10-yr COE)	\$61,800	\$6,170 /yr	10-Jul-2009	1,797 cc	-	GMA Auto Enterprise LLP	Availat
10 Years New COE. Well Maintained. Very Spacious And Big Boot Space. Great For Big Family. Ideal For Those Who Fancy Spacious And Comfort Interior Powerful Drive!							
Office No. - 64531967 Marcus - 90604010 Mike - 91158182 Gibson - 96729559							
Toyota Wish 1.8A Aero Tourer (New 10-yr COE)	\$56,800	\$5,680 /yr	22-Apr-2009	1,794 cc	99,000 km	Ocean Motoring	Availat
Only 1 Owner. Genuine Pearl White Body Color. Aero Tourer Model With All Bodykit Still Intact. \$0 Driveaway. Neat And Clean Interior. Bank Or In House Loan Available. Test Drive Welcome.							
Office No. - - Jason - 90489293 Chan - 90021531							
Toyota Wish 1.8A (New 5-yr COE)	\$35,600	\$7,120 /yr	01-Apr-2009	1,794 cc	115,500 km	New Way Leasing Pte Ltd	Availat
Low Mileage, Agent Unit, Service Records.							
Office No. - 62622030 Hao - 98279436 Vincent - 98295005 Chwee Huat - 82622662							
Toyota Wish 1.8A (New 5-yr COE)	\$37,800	\$7,560 /yr	31-Mar-2009	1,794 cc	-	Mr Benz Traders	Availat
New Paint And New Leather Seats. Worn Parts Replaced At Workshop With Receipts To Show. 6 Months Warranty. Reliable And Easy Maintenance. Good Fuel Consumption. View To Believe. Bank And In House Loan...							
Office No. - - Ansel Tan - 98607949 Stanley - 90012123 Bernard Foong - 96609891 Chester Lee - 90676766							
Toyota Wish 1.8A (New 10-yr COE)	\$53,600	\$5,360 /yr	27-Mar-2009	1,794 cc	-	Car Auto Connection Pte Ltd	Availat
Agent Unit! Excellent Condition! Lowest Price And Depreciation! New Tyres! Nice Exterior And Clean Interior! Nanolux Coated With UV And IR Protected! Good Fuel Consumption! High Loan Available! Do Cal...							
Office No. - 65700023 Julie - 91290002 Jimmy - 91290003							
Toyota Wish 1.8A Aero Tourer (New 5-yr COE)	\$35,800	\$7,160 /yr	24-Mar-2009	1,794 cc	-	Shuang Hup Credit	Availat

Borneo Motors Unit. STA And VICOM Evaluation Welcome. Vehicle In Showroom Condition By Professional Groomer. Elegant Silver With Black Interior.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	1126M

Vehicle Details

Vehicle No.:	SJS6346U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	17 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8X A
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	2ZR0433379
Chassis No.:	ZGE200012984
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$21,895.00
Original Registration Date:	26 Aug 2009
First Registration Date:	26 Aug 2009
Transfer Count:	3
Actual ARF Paid:	\$21,895.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Aug 2019
PARF Rebate Amount:	\$10,947.00

Intended COE Rebate Details

COE Expiry Date:	25 Aug 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$16,290.00
COE Rebate Amount:	\$1,528.00
Total Rebate Amount:	\$12,475.00

The information contained herein is correct as at 17 Sep 2018

OK



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJS6346U
Make & Model : TOYOTA WISH 1.8X A, ZGE200012984
Year of Manufacture : 2009

Estimation No. : E18090012
DOA : 17/09/2018

No	Description	Qty	U/P	Amt
Section: List Items				
1	Rear bumper / <i>Q's</i>	1.00	574.90	574.90 /
2	Rear bumper retainer (LH) / <i>ee</i>	1.00	89.90	89.90 /
3	Rear bumper retainer (RH) / <i>CRA</i>	1.00	89.90	89.90 /
4	Rear bumper bracket (LH) / <i>DT</i>	1.00	79.90	79.90 <i>30</i>
5	Rear bumper bracket (RH) / <i>NN</i>	1.00	79.90	79.90 <i>3X</i>
6	Rear bumper reflector (LH) / <i>MIS</i>	1.00	79.90	79.90 /
7	Rear bumper reflector (RH) / <i>NN</i>	1.00	79.90	79.90 <i>X 1255</i>
8	Bootlid / <i>buc</i>	1.00	1,498.90	1,498.90 / <i>1400</i>
9	Bootlid lock / <i>DT</i>	1.00	398.90	398.90 /
10	Bootlid lock catch / <i>NN</i>	1.00	60.00	60.00 <i>X</i>
11	Bootlid rubber beading / <i>Tw</i>	1.00	362.10	362.10 <i>320</i>
12	Bootlid lamp (LH) / <i>CRA</i>	1.00	294.90	294.90 /
13	Bootlid lamp (RH) / <i>NN</i>	1.00	294.90	294.90 <i>X</i>
14	License lamp chrome garnish / <i>CRA</i>	1.00	227.30	227.30 <i>195</i>
15	License lamp (LH) / <i>NN</i>	1.00	360.00	360.00 <i>X</i>
16	License lamp (RH) / <i>NN</i>	1.00	360.00	360.00 <i>X</i>
17	Bootlid emblem - Logo / <i>bc</i>	1.00	89.90	89.90 <i>268.1</i>
18	Bootlid hinge (LH) / <i>X</i>	1.00	79.90	79.90 <i>X</i>
19	Bootlid hinge (RH) / <i>X</i>	1.00	79.90	79.90 <i>X</i>
20	Bootlid damper (LH) / <i>NN</i>	1.00	268.90	268.90 <i>X</i>
21	Bootlid damper (RH) / <i>NN</i>	1.00	268.90	268.90 <i>X</i>
22	Bootlid lock switch / <i>X</i>	1.00	482.30	482.30 <i>X</i>
23	Bootlid inner trim / <i>CRA</i>	1.00	589.90	589.90 <i>365</i>
24	Bootlid side trim (LH) / <i>NN</i>	1.00	428.00	428.00 <i>X</i>
25	Bootlid side trim (RH) / <i>NN</i>	1.00	428.00	428.00 <i>X</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJ56346U
Make & Model : TOYOTA WISH 1.8X A, ZGE200012984
Year of : 2009
Manufacture

Estimation No. : E18090012
DOA : 17/09/2018

No	Description	Qty	U/P	Amt	
26	Bootlid top trim X	1.00	0.00	0.00	X
27	Rear windscreen X	1.00	1,280.00	1,280.00	X
28	Rear windscreen moulding - MC	1.00	158.90	158.90	90
29	Rear wiper motor X	1.00	365.80	365.80	X
30	Rear wiper arm X	1.00	390.00	390.00	X
31	End panel - BUC	1.00	572.90	572.90	485
32	End panel top garnish R / LL	1.00	298.70	298.70	/
33	Tail lamp (LH) cut R - CFA	1.00	569.20	569.20	288
34	Tail lamp (RH) X	1.00	569.20	569.20	X
35	Tail lamp inner panel (LH) X	1.00	291.70	291.70	X
36	Rear floor panel X repair.	1.00	1,430.90	1,430.90	X
37	Rear floor panel trim X NN	1.00	1,150.00	1,150.00	X
38	Rear fender (LH) - BUC	1.00	838.60	838.60	/
39	Rear fender inner shield (LH) - cut	1.00	79.90	79.90	/
40	Rear fender mud flap (LH) X NN	1.00	0.00	0.00	X
41	Rear fender inner trim R / LL	1.00	690.90	690.90	/
42	Rear fender air vent (LH) - Di's	1.00	120.00	120.00	/
43	Rear fender wheel house (LH) X repair - BUC	1.00	260.00	260.00	X -
44	Fuel lid X	1.00	0.00	0.00	X
45	Fuel lid lock X	1.00	0.00	0.00	X
46	Fuel lid cover X	1.00	120.00	120.00	X
47	Rear door (LH) X repair	1.00	1,618.20	1,618.20	X
48	Rear door lock R - BT	1.00	350.00	350.00	/
49	Rear fender glass X NN	1.00	386.10	386.10	X
50	Rear fender glass moulding - MC	1.00	156.20	156.20	/
51	Rear chassis (LH) X repair.	1.00	386.70	386.70	X

Continue on next page...



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJ56346U
Make & Model : TOYOTA WISH 1.8X A, ZGE200012984
Year of Manufacture : 2009

Estimation No. : E18090012
DOA : 17/09/2018

No	Description	Qty	U/P	Amt
52	Rear axle X	1.00	1,618.30	1,618.30
53	Rear wheel bearing (LH) X	1.00	599.10	599.10

~~7158.8~~ 7563.8
 25%
 Amt \$ 21,948.30
 Discount (0.00%) \$ 0.00
 Subtotal \$ 21,948.30
 5399.1 5672.85

Section: Special Nett Items

54	Rear bumper lower / CRA	1.00	800.00	800.00	450
55	Reverse sensor set / DM	1.00	250.00	250.00	200
56	Rear bumper clip set / MC	1.00	40.00	40.00	/
57	Decal X	1.00	20.00	20.00	X
58	Reverse camera X	1.00	500.00	500.00	X
59	Exhaust bracket (LH) / BT	1.00	200.00	200.00	600
60	Bootlid trim clip set /	1.00	40.00	40.00	/
61	End panel top garnish clip set /	1.00	30.00	30.00	/
62	Rear fender inner trim clip set /	1.00	40.00	40.00	/
63	End panel sealant /	1.00	50.00	50.00	/
64	Rear floor panel sealant X	1.00	50.00	50.00	X
65	Rear fender wheel house sealant X	1.00	50.00	50.00	X
66	Tailgate windscreen sealant /	1.00	50.00	50.00	/
67	Rear fender sealant X	1.00	50.00	50.00	X
68	Rear windscreen tinted X	1.00	200.00	200.00	100
69	Rear fender tinted X	1.00	150.00	150.00	X
70	Rear BC sport adjustable absorber (LH) X	1.00	1,300.00	1,300.00	/
71	Rear BC sport adjustable absorber (RH) X	1.00	1,300.00	1,300.00	/
72	Rear ultra racing struct bar X	1.00	1,200.00	1,200.00	X

Continue on next page...

1060



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJS6346U
Make & Model : TOYOTA WISH 1.8X A, ZGE200012984
Year of : 2009
Manufacture :

Estimation No. : E18090012
DOA : 17/09/2018

No	Description	Qty	U/P	Amt
73	Rear ultra racing antiroll bar X X NN	1.00	900.00	900.00
74	Rear wheel rim (LH) X	1.00	650.00	650.00
75	225/40/18 Rear tyre (LH) X / CA	1.00	200.00	200.00

Floor panel Insulator mat / etc
\$250 150

Amt S\$ 8,070.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 8,070.00

Section: Labour Items

76	To R&R rear bumper reverse sensor	1.00	80.00	80.00
77	To R&R rear windscreen	1.00	180.00	180.00
78	To R&R rear fender glass	1.00	150.00	150.00
79	To R&R rear undercarriage damage parts	1.00	350.00	350.00
80	To R&R rear wheel rim & balancing	1.00	60.00	60.00
81	To R&R rear trims, garnish & seats	1.00	150.00	150.00
82	To R&R fuel tank to cut & welding	1.00	200.00	200.00
83	To straighten rear chassis (LH)	1.00	350.00	350.00
84	To check wiring and lighting system	1.00	80.00	80.00
85	To apply undercoating on affected areas	1.00	80.00	80.00
86	To R&R tailgate mechanism	1.00	160.00	160.00
87	To repair, replace and realign damage areas	1.00	2,000.00	2,000.00
88	To spray painting on affected areas	1.00	1,800.00	1,800.00
89	To check water seepage on affected after repair	1.00	150.00	150.00

11 Days.

Unpsum repair

After repair photos

Cam R: up.

19/9/18.

10762.85

10787.85

20/9/18

8600

Amt S\$ 5,790.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 5,790.00

List Items Subtotal S\$ 21,948.30

Special Nett Items S\$ 8,070.00
Subtotal

Labour Items Subtotal S\$ 5,790.00

Total S\$ 35,808.30



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18017017/Gqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 30-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 8560G	Veh. Inspected	SJS 6346U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006868MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	18/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	ZGE200012984	Colour	WHITE	
Odometer	131595	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 ZR18	MEMBAT	5 mm	
L/H Front Tyre	225/40 ZR18	MEMBAT	5 mm	
R/H Rear Tyre	225/40 ZR18	MEMBAT	5 mm	
L/H Rear Tyre	225/40 ZR18	MEMBAT	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/09/2018	Inspection Date	19/09/2018	
Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		11 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 6346U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DISTORTED	574.90	574.90
1	REAR BUMPER RETAINER (LH)	DEFORMED	89.90	89.90
1	REAR BUMPER RETAINER (RH)	CRACKED	89.90	89.90
1	REAR BUMPER BRACKET (LH)	BENT	79.90	30.00
1	REAR BUMPER BRACKET (RH)	NOT NECESSARY	79.90	-
1	REAR BUMPER REFLECTOR (LH)	MISSING	79.90	79.90
1	REAR BUMPER REFLECTOR (RH)	NOT NECESSARY	79.90	-
1	BOOTLID	BUCKLED	1,498.90	1,400.00
1	BOOTLID LOCK	BENT	398.90	398.90
1	BOOTLID LOCK CATCH	NOT NECESSARY	60.00	-
1	BOOTLID RUBBER BEADING	TWISTED	362.10	320.00
1	BOOTLID LAMP (LH)	CRACKED	294.90	294.90
1	BOOTLID LAMP (RH)	NOT NECESSARY	294.90	-
1	LICENSE LAMP CHROME GARNISH	CRACKED	227.30	195.00
1	LICENSE LAMP (LH)	NOT NECESSARY	360.00	-
1	LICENSE LAMP (RH)	NOT NECESSARY	360.00	-
1	BOOTLID EMBLEM-LOGO	NECESSARY	89.90	68.10
1	BOOTLID HINGE (LH)	NOT NECESSARY	79.90	-
1	BOOTLID HINGE (RH)	NOT NECESSARY	79.90	-
1	BOOTLID DAMPER (LH)	NOT NECESSARY	268.90	-
1	BOOTLID DAMPER (RH)	NOT NECESSARY	268.90	-
1	BOOTLID LOCK SWITCH	NOT NECESSARY	482.30	-
1	BOOTLID INNER TRIM	CRACKED	589.90	365.00
1	BOOTLID SIDE TRIM (LH)	NOT NECESSARY	428.00	-
1	BOOTLID SIDE TRIM (RH)	NOT NECESSARY	428.00	-
1	BOOTLID TOP TRIM (NPA)	NOT NECESSARY	-	-
1	REAR WINDSCREEN	NOT NECESSARY	1,280.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	158.90	90.00
1	REAR WIPER MOTOR	NOT NECESSARY	365.80	-
1	REAR WIPER ARM	NOT NECESSARY	390.00	-
1	END PANEL	BUCKLED	572.90	485.00

Report Ref No. CS/FCI18017017/Gqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	END PANEL TOP GARNISH	DEFORMED	298.70	298.70
1	TAIL LAMP (LH)	CRACKED	569.20	288.00
1	TAIL LAMP (RH)	NOT NECESSARY	569.20	-
1	TAIL LAMP INNER PANEL (LH)	NOT NECESSARY	291.70	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,430.90	-
1	REAR FLOOR PANEL TRIM	NOT NECESSARY	1,150.00	-
1	REAR FENDER (LH)	BUCKLED	838.60	838.60
1	REAR FENDER INNER SHIELD (LH)	CUT	79.90	79.90
1	REAR FENDER MUD FLAP (LH)(NPA)	NOT NECESSARY	-	-
1	REAR FENDER INNER TRIM	DEFORMED	690.90	690.90
1	REAR FENDER AIR VENT (LH)	DISTORTED	120.00	120.00
1	REAR FENDER WHEEL HOUSE (LH)	BUCKLED	260.00	260.00
1	FUEL LID (NPA)	NOT NECESSARY	-	-
1	FUEL LID LOCK (NPA)	NOT NECESSARY	-	-
1	FUEL LID COVER	NOT NECESSARY	120.00	-
1	REAR DOOR (LH)	TO REPAIR SEE LABOUR	1,618.20	-
1	REAR DOOR LOCK	BENT	350.00	350.00
1	REAR FENDER GLASS	NOT NECESSARY	386.10	-
1	REAR FENDER GLASS MOULDING	NECESSARY	156.20	156.20
1	REAR CHASSIS (LH)	TO REPAIR SEE LABOUR	386.70	-
1	REAR AXLE	NOT NECESSARY	1,618.30	-
1	REAR WHEEL BEARING (LH)	NOT NECESSARY	599.10	-
	LESS 25% DISCOUNT		-	-1,890.95
			21,948.30	5,672.85
	SPECIAL NETT ITEMS			
1	REAR BUMPER LOWER (SN)	CRACKED	800.00	450.00
1	SET REVERSE SENSOR (SN)	DAMAGED	250.00	200.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	40.00	40.00
1	DECAL (SN)	NOT NECESSARY	20.00	-
1	REVERSE CAMERA (SN)	NOT NECESSARY	500.00	-
1	EXHAUST BRACKET (LH)(SN)	BENT	200.00	60.00

Report Ref No. CS/FCI18017017/Gqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BOOTLID TRIM CLIP (SN)	NECESSARY	40.00	40.00
1	SET END PANEL TOP GARNISH CLIP (SN)	NECESSARY	30.00	30.00
1	SET REAR FENDER INNER TRIM CLIP (SN)	NECESSARY	40.00	40.00
1	END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR FLOOR PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
1	REAR FENDER WHEEL HOUSE SEALANT (SN)	NOT NECESSARY	50.00	-
1	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR FENDER SEALANT (SN)	NOT NECESSARY	50.00	-
1	REAR WINDSCREEN TINTED (SN)	NECESSARY	200.00	100.00
1	REAR FENDER TINTED (SN)	NOT NECESSARY	150.00	-
1	REAR BC SPORT ADJUSTABLE ABSORBER (LH)(SN)	NOT NECESSARY	1,300.00	-
1	REAR BC SPORT ADJUSTABLE ABSORBER (RH)(SN)	NOT NECESSARY	1,300.00	-
1	REAR ULTRA RACING STRUCT BAR (SN)	NOT NECESSARY	1,200.00	-
1	REAR ULTRA RACING ANTIROLL BAR (SN)	NOT NECESSARY	900.00	-
1	REAR WHEEL RIM (LH)(SN)	NOT NECESSARY	650.00	-
1	225/40/18 REAR TYRE (LH)(SN)	CUT	200.00	160.00
1	FLOOR PANEL INSULATOR MATT (SN)	NECESSARY	250.00	150.00
			8,320.00	1,370.00
	LABOUR			
	TO R&R REAR BUMPER REVERSE SENSOR.		80.00	40.00
	TO R&R REAR WINDSCREEN.		180.00	100.00
	TO R&R REAR FENDER GLASS.		150.00	60.00
	TO R&R REAR UNDERCARRIAGE DAMAGE PARTS.	NOT NECESSARY	350.00	-
	TO R&R REAR WHEEL RIM & BALANCING.		60.00	30.00
	TO R&R REAR TRIMS,GARNISH & SEATS.		150.00	60.00
	TO R&R FUEL TANK TO CUT & WELDING.		200.00	60.00
	TO STRAIGHTEN REAR CHASSIS (LH).		350.00	200.00
	TO CHECK WIRING AND LIGHTING SYSTEM.		80.00	30.00
	TO APPLY UNDERCOATING ON AFFECTED AREAS.		80.00	80.00
	TO R&R TAILGATE MECHANISM.		160.00	60.00
	TO REPAIR,REPLACE AND REALIGN DAMAGE AREAS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL,REAR DOOR (LH) AND REAR CHASSIS (LH).		2,000.00	1,600.00

Report Ref No. CS/FCI18017017/Gqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINTING ON AFFECTED AREAS.	NOT NECESSARY	1,800.00	1,400.00
	TO CHECK WATER SEEPAGE ON AFFECTED AFTER REPAIR.		150.00	-
			5,790.00	3,720.00
GRAND TOTAL			36,058.30	10,762.85
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,600.00

Report Ref No. CS/FCI18017017/Gqbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.