



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### General Details

Involving	TPVD HONDA CRZ (SLS9720D)
Date of Loss	15 September 2018
Time of Loss	23.45
Loss Description	SFB5166R (INSD) HIT INTO REAR SLS9720D(TP)
Comment	<input type="text"/>

### Workshop Details

Total Rebate Amount	<input type="text" value="0"/>
Nett Loss Amount	\$45,000.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	<input type="text" value="20"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

## Vehicle &amp; Driver Details

Vehicle Registration# SLS9720D

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date \*

19/09/2012



Mileage



Age of Vehicle

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2007	2012
Make	TOYOTA	HONDA
Model	ESTIMA 2.4	CR-Z 1.5L CVT

## Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	SIM SIANG BOON REUEL	
Date of Birth	9 March 1993	dd/mm/yyyy
Age	25	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		<input type="text" value="▼"/>
Type of Paint		<input type="text"/>
Chassis No	ACR500029328	<input type="text" value="JHMZF1420CS202396"/>
Engine No	2AZF007347	<input type="text" value="LEA12006137"/>
Engine Capacity		<input type="text" value="1497"/>
Sum Insured	0	<input type="text" value="0"/>
Market Value	0	<input type="text" value="45000"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text"/>
Education Qualification	Other	<input type="text" value="▼"/>
Driving Experience	0	
Driver License #		<input type="text"/>
License Type		<input type="text" value="▼"/>
License Issue Date		<input type="text" value="dd/mm/yy"/> 
License Expiration Date		<input type="text" value="dd/mm/yy"/> 
Address	70 SENGKANG SQUARE, #01-46, 544705, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="▼"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	<input type="text"/>
Marital status	Unknown	<input type="text"/>
Identification #	S9308181A	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

## Detailed Assessment

Inspection Date \*

19/09/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/  
Unnamed Driver Excess

0

Other Excess

## Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

## Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

195/55R16

Rear Tyre Size

195/55R16

Front left side

YOKOHAMA6mm

Rear left side

YOKOHAMA6mm

Front right side

YOKOHAMA6mm

Rear right side

YOKOHAMA6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

### Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

100

### Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD		Ref: CS3/ASM18017024/Gcbe2		
8 SHENTON WAY #24-01		Date: 24-09-2018		
AXA TOWERSINGAPORE 068811				
ATTN : CYNTHIA LOH		Code: ASM		
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	SFB 5166R	Veh. Inspected	SLS 9720D	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00VOR	Excess (\$)	0.00	
Assign From	CYNTHIA LOH	Assign Date	18/09/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA CR-Z	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	JHMZF1420CS202396	Colour	SILVER	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/55 R16	YOKOHAMA	6 mm	
L/H Front Tyre	195/55 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	195/55 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	195/55 R16	YOKOHAMA	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.				
<b>5. General Information</b>				
Accident Date	15/09/2018	Inspect Date / Time	19/09/2018 ( 04:00 PM )	
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/ASM18017024/Gcbe2

**Inspected By**

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.