

ASS. REC. BY:

REF: CS/FCL18017028/K96⁷²

Special Instruction:

Supervisor:

ASSIGNMENT (Office)

From (Person): CWS Eileen Lee of FCL Date/Time: 17/05/2018 5:50pm

Estimated Cost: _____ Bill to: _____

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLV 5592S Insured: SHA 5988S

at Workshop m/s: Ready Auto Tel: 6481 0304

of Blk 10 Amk Ind Park JA #03-06

Policy No: _____ Claim No: 018006336MTSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 11.07.2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement: _____

Date/Time: 18/09/2018 9:28am Person Contacted: Sulyn Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLV 5592S - X
	SHA 5988S - CC3/ALH 18011613/K1W03 POA: 20618
20/7/18 @	2.56pm revised to Eileen Lee by email.
	6/1 Pm @ 1100L Confirm by email (Red \$875,44/-)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006836MFSH

Date: 20 September 2018

Our Ref: CS/FCI18017028/Kqb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLV 5592S

Please be informed that we had conducted the inspection of the abovementioned vehicle on 19/09/2018 at the premises of M/s READY AUTO, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>1,975.00</u>
Revised Estimate Amount	: S\$ <u>1,525.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the o/s front portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	14-09-2018	Our Ref No. D18006836MFSH
Accident Date	11-09-2018	Claim Type. Third Party
Insured Vehicle	SHA5988S	Third Party Vehicle. SLV5592S
Survey Location	BLK 10 #03-06 ANG MO KIO AUTO POINT ANG MO KIO AVE 5 IND PARK 2A	
Contact Person.	SULYM	
Contact No.	64810304/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	READY AUTO CARE PTE LTD	Attention. NIL
Cc : TP Solicitor	CATHERINE LIM LLC	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 20 September 2018 2:56 PM
To: 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006836MFSH/1
Attachments: CSFC118017028Kqb.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SLV 5592S.

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 18 September 2018 9:29 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006836MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin
LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 17 September, 2018 5:50 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006836MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Ready Auto Care Pte Ltd - We Care For All Your Car Needs

Blk 10 # 03-06 AMK Auto Point, Ang Mo Kio Ind Park 2A, Ang Mo Kio Ave 5. Singapore 568047

Tel : 64810304 Fax : 64815587 Reg No : 200600989K GST No : 200600989k

First Capital Insurance Limited

Motorcar Claim Department
Attn Officer In Charge

*Not Withheld
Mummy B&P 1.B.1*


Estimate Repair

Date : 18/9/2018

Accident Involving SLV5592S & SHA5988S On 11/09/2018 Along Upper Paya Lebar Rd

Item	Descriptions	Amount
1	Front Right Fender	<i>Per</i> \$ 685.00 ✓
2	Front Bumper Repair	\$ -
Total For Parts		\$ 685.00
S/N Item (s)		
1	Front Right Sport Rim	<i>Per</i> \$ 80.00 <i>50sn</i>
Total For S/N		\$ 80.00
Labour & Misc		
1	To Remove All Damaged Parts, Knock Out Dents, Jack Out Damaged Panel Panel, Adjust, Replace, Reshape, Cut, Weld, Refix & Realign Body Structure	\$ 450.00 <i>30gl</i>
2	Spray Painting For New And Repair Parts Including Supply Of Paints Materials	\$ 650.00 <i>400d</i>
3	Computerise 4 Wheels Alignment	\$ 60.00 ✓
4	Cavity Preservation On All Affected Areas	\$ 50.00 <i>3ol</i>
Total For Labour & Misc		\$ 1,210.00
Total For Parts & Labour		\$ 1,975.00
No Of Days For Repair		3 Days ✓

Ready Auto Care Pte Ltd
Sulynn 96606551



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18017028/Kqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 11-10-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 5988S	Veh. Inspected	SLV 5592S
Policy No.		Coverage (\$)	0.00
Claim No.	D18006836MFSH	Excess (\$)	0.00
Assign From	EILEEN	Assign Date	17/09/2018
2. Vehicle Particulars & Condition			
Make & Model	mitsubishi space star (A)	c.c	1193
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	MMCXTA03AJH005944	Colour	METALLIC RED
Odometer	10752	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175/55 R15	YOKOHAMA	9 mm
L/H Front Tyre	175/55 R15	YOKOHAMA	9 mm
R/H Rear Tyre	175/55 R15	YOKOHAMA	9 mm
L/H Rear Tyre	175/55 R15	YOKOHAMA	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/09/2018	Inspection Date	19/09/2018
Survey held at	READY AUTO CARE PL BLK 10 #03-06, AMK AUTOPOINT, ANG MO KIO AVE 5, INDUSTRIAL PARK 2A, SINGAPORE 568047		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 5592S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT RIGHT FENDER	BUCKLED	685.00	685.00
1	FRONT BUMPER (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-	-68.50
			685.00	616.50
SPECIAL NETT ITEMS				
1	FRONT RIGHT SPORT RIM (SN)	SCRATCHED	80.00	50.00
			80.00	50.00
LABOUR				
	TO REMOVE ALL DAMAGED PARTS, KNOCK OUT DENTS, JACK OUT DAMAGED PANEL PANEL, ADJUST, REPLACE, RESHAPE, CUT, WELD, REFIX & REALIGN BODY STRUCTURE. INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		450.00	300.00
	SPRAY PAINTING FOR NEW AND REPAIR PARTS INCLUDING SUPPLY OF PAINTS METERIALS.		650.00	400.00
	COMPUTERISE 4 WHEELS ALIGNMENT.		60.00	60.00
	CAVITY PRESERVATION ON ALL AFFECTED AREAS.		50.00	30.00
			1,210.00	790.00
GRAND TOTAL			1,975.00	1,456.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,100.00

Report Ref No. CS/FC18017028/Kqbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.