

Surveyor: RAGNE ASS/MENT 17035 Date / Time: 18/09/18
Registered in Merimen: 18/09/18

Pre-assign / CCU / FTE



Insured Vehicle No. SHC 8522 Y

Name of Insured CIM

Insured Tel No. HP: 16/09/18

Excess Sec II : S\$ D.O.A: 16/09/18

Is driver the owner? (YES ☒ NO) Nature of Accident :

If NO, Driver Name / Age: CHIA NH Hock

Driver Tel No. : 97344874 (V/L: YES / NO)

Claim No. : 62

Policy No. : Micomark

Make / Model : H-160

Place of Accident : PIE

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SHC 2038 M



INSRS:

WSP: prime

Tel: Auto

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time		STAGE	DATE / PIC
<u>11/10/18</u>	<u>SHC 2038 M - NPA/ins 1 672064/11 ; 00A: 20/1/18</u>	Non-Reporting ltr (1st):	
	<u>CHIA NH Hock 12005426 / 26/1/18 ; 00A: 23/1/18</u>	Non-Reporting ltr (2nd):	
	<u>SHC 8522 Y - NPA/ins 1 672064/11 ; 00A: 1/1/18</u>	Non-Reporting ltr (Final):	
	<u>NT/ins 1 7015259 / 1/1/18 ; 00A: 5/1/18</u>	Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
		Documentation Check List:	Handler Typist
<u>1/10/18</u>	<u>Email From III reject TP claim.</u>	Notification ltr (if non-pickup)	<input type="checkbox"/>
<u>1/10/18</u>	<u>Email to workshop reject IP claim.</u>	After call ltr to OI:	<input type="checkbox"/>
<u>1/10/18</u>	<u>Base on CAD video, TP cut into CDD'S lane</u>	Authorisation To Act:	<input type="checkbox"/>
		Release Voucher:	<input type="checkbox"/>
		Final Repair Bill:	<input type="checkbox"/>
		Car Rental Invoice:	<input type="checkbox"/>
		Towing Invoice:	<input type="checkbox"/>
		LTA / GIA:	<input type="checkbox"/>
		Medical Bill:	<input type="checkbox"/>
		PIR:	<input type="checkbox"/>
		Mandate/Reject Instruction:	<input type="checkbox"/>
		LOD	<input type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/>
		Others:	<input type="checkbox"/>

PRELIMINARY ADVICE		Date/Time:	Sent By:	Confirm with:	Confirm by:
FINALIZATION		Date/Time:	Confirm with:	Confirm by:	
Repair Cost:	S\$	(days)	Reduction:	%	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT		Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>	
Final Liability:	%	(Agreed / Assessed)	BOLA S/N No. :	If NO or B 28, Ass. Lia :	
Repair Cost:	S\$				
Loss of Rental (LOR):	S\$	(days)			
Loss of Use (LOU):	S\$	(\$ x days)			
Loss of Income (LOI):	S\$	(\$ x days)			
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]				
GIA/LTA Search	S\$				
Medical	S\$				
Disbursement:	S\$	(e.g. Tow/ Independent)			
Legal Cost	S\$				
Total:	S\$		Global Sum S\$:		
FINAL PAYMENT		Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>	
Payee 1:	S\$	Name 1:			
Payee 2: (Strike if N.A.)	S\$	Name 2:			
Payee 3: (Strike if N.A.)	S\$	Name 3:			

COPY SENT

1) Claim status: Normal/Reject/Private Settle
2) Report Format: paper
3) Survey fee: \$250.00

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKD 2038Mat Workshop m/s PRIME AUTOof 6, hani placeInsured: W/ up

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKD 2038M Yr Regn: 2014 / OUTType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIUS HYBRID 1.8L c.c. 1797Colour: Brown A/C Insured / Std / NI / NASp. Reading: 290061 T/Radio: Insured / Std / NI / NA

Eng/No _____

C/No: ZUW301833506Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: 2.0 / S/Rim / STD A/Rim orTyre Size: F: 185/65R15R: 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or GOODRIDE

Front

Rear

R/Bal: 5 mm R/Bal: 5 mmL/Bal: 5 mm L/Bal: 5 mmD.O.A: 16/09/18 D.O.I: 18/09/18Survey held at: PRIME AUTO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt & N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11/10/18 Confirm U/S \$2700.00 with 8 working days(Red. \$1625.60
38%)

Date/Time: File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time: File Return to?

Survey Fee:

2)

Transportation:

Add Fee: ☐ Site Insp (\$

) \$ + R5.00

☐ Interview (\$

) Photos

☐ Tech. Invs (\$

) Office

☐ Weekend (\$

)

Report Format :

Lump Sum / I.B.I.: (\$

TOTAL



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 18.09.2018

India International Insurance Pte Ltd
64 Cecil Street #04/#05
IOB Building
Singapore 049711

Attn: Motor Claims Dept

RE: COST OF REPAIR TO VEHICLE SHD2038M TOYOTA PRIUS HYBRID 1.8L (2014)

To Supply

1)	1pc	Front bumper	\$	1,230.00	DE
2)	1set	Front bumper clips	\$	30.00	na
3)	1pc	Front bumper left side retainer	\$	82.40	? Xsu
4)	1pc	Left front fender	\$	776.00	repair X
5)	1pc	Left front fender "Hybrid" emblem	\$	52.40	na
6)	1pc	Left front fender cowling	\$	290.00	? Xsu
7)	1pc	Left front fender cowling clip	\$	20.00	na
8)	1pc	Left side mirror assy.	\$	720.00	Br
9)	1pc	Left side mirror outer cover	\$	40.00	na

Sub total parts	\$	3,240.80	2092.40
Less: 25% discount	\$	(810.20)	-523.10
	\$	2,430.60	1569.30

To Supply S.Nett Parts

- 1) 1pc "Dial-A-Cab" sticker

	\$	55.00	na
Sub total S.Nett Parts	\$	55.00	

L/charge

- 1) To tuff-kote \$ 50.00
- 2) To remove front bumper & left front fender. Knock & repair left front door, left rear door & left rear fender. Replace the above parts. Align & adjust left front door, left rear door and rear bumper. \$ 800.00 700

3) To putty, respray painting front bumper, left front fender, left front door, left rear door, left rear fender & left side mirror cover. To polish

\$ 1,000.00

Sub total L/charges	\$	1,850.00	1750.00
Estimated Grand Total	\$	4,335.60	3374.30

less 80% LS - 674.86
2699.44

Repair

HP 90010068

LS 2,700

8 days

LS

8 days

18/01/15 @ 1510

Respray after repair

LKK Auto Consultants hereby certify the Repair the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 18.09.2018

India International Insurance Pte Ltd
64 Cecil Street #04/#05
IOB Building
Singapore 049711

Attn: Motor Claims Dept

RE: COST OF REPAIR TO VEHICLE SHD2038M TOYOTA PRIUS HYBRID 1.8L (2014)

To Supply

1)	1pc	Front bumper	\$	1,230.00	DE-
2)	1set	Front bumper clips	\$	30.00	na -
3)	1pc	Front bumper left side retainer	\$	82.40	?
4)	1pc	Left front fender	\$	776.00	repair
5)	1pc	Left front fender "Hybrid" emblem	\$	52.40	na -
6)	1pc	Left front fender cowling	\$	290.00	?
7)	1pc	Left front fender cowling clip	\$	20.00	na -
8)	1pc	Left side mirror assy.	\$	720.00	3Rs ✓
9)	1pc	Left side mirror outer cover	\$	40.00	ms ✓

Sub total parts	\$	3,240.80
Less: 25% discount	\$	(810.20)
	\$	2,430.60

To Supply S.Nett Parts

1)	1pc	"Dial-A-Cab" sticker	\$	55.00	na ✓
Sub total S.Nett Parts			\$	55.00	

L/charge

1)	To tuff-kote	\$	50.00	✓
2)	To remove front bumper & left front fender. Knock & repair left front door, left rear door & left rear fender. Replace the above parts. Align & adjust left front door, left rear door and rear bumper.	\$	800.00	700 ✓

3) To putty, respray painting front bumper, left front fender, left front door, left rear door, left rear fender & left side mirror cover. To polish

\$ 1,000.00

Sub total L/charges	\$ 1,850.00
Estimated Grand Total	\$ 4,335.60

Let Auto Consultants, Inc. survey
and repair the following:

- To resurvey body after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Resur
HP 90010068

8 days

HS

18/04/18 @ 1510

Resurvey after repair

Vivian Lau (LKKAuto)

From: Vivian Lau (LKKAuto)
Sent: Monday, 1 October, 2018 12:06 PM
To: 'Alice Leong'
Cc: Admin A
Subject: RE: ACCIDENT ON 16.09.2018 INVOLVING VEHICLES SHD2038M & SHC8522Y
Attachments: Sketch Plan .pdf, SHC 8522Y.MP4

WITHOUT PREJUDICE

Your Ref: SHD 2038M
Our Ref: CC4/III18017035/R1wa3

Dear Sir/Madam,

ACCIDENT ON 16.09.2018 INVOLVING SHD2038M & SHC8522Y

We refer to the above matter

Our insured driver has reiterated that the accident was caused due to the entire negligence of your client. Your client encroached into OID's lane

We attached herewith our insured's accident report and video footage for your perusal.

Under such circumstances, we have our principal's instruction to deny liability of your client's claim.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Alice Leong [<mailto:aliceleong@primeautoclaims.com>]
Sent: Thursday, 27 September, 2018 10:23 AM
To: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>

Subject: FW: ACCIDENT ON 16.09.2018 INVOLVING VEHICLES SHD2038M & SHC8522Y
Importance: High

Hi Vivian,

URGENT ATTENTION

Our below e-mail referred.

Please let us have your reply on urgent basis to facilitate our us to advise our client to make decision

Regards

Alice Leong
Manager, Motor Claims

Prime Auto Claims Service Pte Ltd
6 Benoi Place Singapore 629927
T (65): 6861 0908 | F (65) 6515 2948
HP (65) 9818 4304

A member of the Prime Group

Disclaimer

This e-mail (including all attachment) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intend recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Alice Leong [<mailto:aliceleong@primeautoclaims.com>]
Sent: 20 September, 2018 11:44 AM
To: 'Vivian Lau (LKKAUTO)' <vivianlau@lkkauto.com>
Cc: 'Admin A' <admin-a@lkkauto.com>
Subject: RE: ACCIDENT ON 16.09.2018 INVOLVING VEHICLES SHD2038M & SHC8522Y
Importance: High

Hi Vivian,

Your insured reported he has video footage. We would be greatly appreciate if you could kindly furnish us your insured video footage for our viewing ?

Regards

Alice Leong
Manager, Motor Claims

Prime Auto Claims Service Pte Ltd
6 Benoi Place Singapore 629927
T (65): 6861 0908 | F (65) 6515 2948
HP (65) 9818 4304

A member of the Prime Group

Disclaimer

This e-mail (including all attachment) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intend recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Vivian Lau (LKKAUTO) [<mailto:vivianlau@lkkauto.com>]
Sent: 20 September, 2018 11:32 AM
To: Alice Leong <aliceleong@primeautoclaims.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: ACCIDENT ON 16.09.2018 INVOLVING VEHICLES SHD2038M & SHC8522Y

WITHOUT PREJUDICE

Dear Sir/Madam,

ACCIDENT ON 16.09.2018 INVOLVING VEHICLES SHD2038M & SHC8522Y

We refer to the above matter

We are of the opinion that this is a case of **conflicting versions**. There is no conclusive evidence to substantiate either's parties version. Enclosed herewith a copy of our insured's accident report for your perusal.

Meanwhile, kindly forward to us with any evidence (if any) to support your claim

Kindly take note that the case handler in-charge is Vivian and she can be contacted at her DID 6841 8625.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Alice Leong [<mailto:aliceleong@primeautoclaims.com>]

Sent: Thursday, 20 September, 2018 10:57 AM

To: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: ACCIDENT ON 16.09.2018 INVOLVING VEHICLES SHD2038M & SHC8522Y

Importance: High

Hi Vivian,

URGENT

Your appointed surveyor Mr. Rasul had surveyed our client's vehicle on 18.09.2018

For swift & amicable settlement, please establish liabilities as we have to define hirer's accident excess within limited period.

Regards

Alice Leong

Manager, Motor Claims

Prime Auto Claims Service Pte Ltd

6 Benoi Place Singapore 629927

T (65): 6861 0908 | F (65) 6515 2948

HP (65) 9818 4304

A member of the Prime Group

Disclaimer

This e-mail (including all attachment) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intend recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

View Received Message

This mail is associated with :

***SHD2038M (MCT18090441)
[SHC8522Y]**

TP
PRIME CAR RENTAL & TAXI SERVICES PTE LTD
Sep 16 2018 1:00AM

Prime Auto Claims Service Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 24/09/2018 16:14 PM.
To LKK_HQ
Subject Alert - Adj Mandate Maintained - SHD2038M - Claim Handler: Sherini Pillai

Maintained:Based on video uploaded, TP had clearly enroached into QID's lane. Please reject.

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Sep 2018 Edit Reg		18 Sep 2018 00:00 Edit Adj Rpt	S\$2,700.00 Edit Estimates	S\$2,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	PRIME CAR RENTAL & TAXI SERVICES PTE LTD, Co. Reg. No.: 199606293Z								
Vehicle Reg. No.:	SHD2038M	Date of Loss:	16/09/2018 01:00 - :59 [47 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18090441	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHC8522Y	Policy No. (Claimant):	5068045737-03						
		Excess:							
Repairer:	Prime Auto Claims Service Pte Ltd (HQ) 6 Benoi Place, 629927 Pioneer - Tel: 68610908								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 27/09/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (24/09/2018): Alert - Adj Mandate Maintained - SHD2038M - Claim Handler: Sherini Pillai 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHD2038M (MCT18090441)
 [SHC8522Y]
 TP
 PRIME CAR RENTAL & TAXI SERVICES PTE LTD
 Sep 16 2018 1:00AM
 [COMFORT TRANSPORTATION PTE LTD]
 Prime Auto Claims Service Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Video

1 per page

No

Finalized On

India International Insurance Pte Ltd (HQ)

Thumbnail

Print

1

24/09/18 16:13

Video - OID

Load MP4

Photos/Images

3 per page

No

Relabel/Reorder

LKK Auto Consultants Pte Ltd (HQ)

Thumbnail

Print

1

01/10/18 12:09

General View

Load JPG

2

01/10/18 12:09

General View

Load JPG

3

01/10/18 12:09

General View

Load JPG

4

01/10/18 12:09

General View

Load JPG

5

01/10/18 12:09

General View

Load JPG

6

01/10/18 12:09

General View

Load JPG

7

01/10/18 12:09

General View

Load JPG

8

01/10/18 12:09

General View

Load JPG

9

01/10/18 12:09

General View

Load JPG

10

01/10/18 12:09

General View

Load JPG

11

01/10/18 12:09

General View

Load JPG

12

01/10/18 12:09

General View

Load JPG

13

01/10/18 12:09

General View

Load JPG

14

01/10/18 12:09

General View

Load JPG

15

01/10/18 12:09

General View

Load JPG

16

01/10/18 12:09

General View

Load JPG

17

01/10/18 12:09

General View

Load JPG

18

01/10/18 12:09

General View

Load JPG

19

01/10/18 12:09

General View

Load JPG

20

01/10/18 12:09

General View

Load JPG

21

01/10/18 12:09

General View

Load JPG

22

01/10/18 12:09

General View

Load JPG

23

01/10/18 12:09

General View

Load JPG

24

01/10/18 12:09

General View

Load JPG

25

01/10/18 12:09

General View

Load JPG

26

01/10/18 12:09

General View

Load JPG

27

01/10/18 12:09

General View

Load JPG

28

01/10/18 12:09

General View

Load JPG

29

01/10/18 12:09

General View

Load JPG

30

01/10/18 12:09

General View

Load JPG

31

01/10/18 12:09

Reinspection Photo

Load JPG

32

01/10/18 12:09

Reinspection Photo

Load JPG

33

01/10/18 12:09

Reinspection Photo

Load JPG

34

01/10/18 12:09

Reinspection Photo

Load JPG

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	01/10/18 12:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	01/10/18 12:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	01/10/18 12:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/09/18 20:01	ACKNOWLEDGEMENT EMAIL TO III DD 18.09.2018	 Load PDF	
2	18/09/18 20:01	TP GIA REPORT	 Load PDF	
3	21/09/18 13:27	TP ESTIMATE - MARKED	 Load PDF	
4	01/10/18 12:08	Email to wkshop reject TP claim 1.10.18	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	19/09/18 09:00	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18017035/R1WA3Q2

Date: 03/10/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle No : SHD2038M

Insured Vehicle No : SHC8522Y

Date of Loss: 16/09/2018

Nature of Claim:

TP

Claim No: MCT18090441

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD2038M

Make & Model: TOYOTA PRIUS HYBRID, 1.8 (A)

Engine No: 3JM1405130813A

Reg. Date: 13/10/2014 (Man. Year: 2014)

Chassis No: ZVW301833506

Colour: Brown

Odometer: 290061 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Goodride 5 mm

Rear Left Side: Goodride 5 mm

Front Right Side: Goodride 5 mm

Rear Right Side: Goodride 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,485.60	1,624.30	861.30	34.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,750.00	100.00	5.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,335.60	3,374.30	961.30	22.17
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	4,335.60	2,700.00	1,635.60	37.72
+ GST 7.00/7.00% (S\$)	303.49	189.00	114.49	37.72
Nett Amount (S\$)	4,639.09	2,889.00	1,750.09	37.72
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 18/09/2018

Date Inspected: 18/09/2018 Inspected At:

Prime Auto Claims Service Pte Ltd (HQ)

6 Benoi Place

Singapore 629927

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL**Manager:** VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 02 Oct 2018)
Parts: 144	TOYOTA PRIUS HYBRID 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHD2038M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,230.00 FL	*1,230.00 FL
2	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	1		*FRONT BUMPER LEFT SIDE RETAINER	Serviceable	82.40 FL	*- FL
4	1		*LEFT FRONT FENDER	Repair	776.00 FL	*- FL
5	1		*LEFT FRONT FENDER HYBRID EMBLEM	Necessary	52.40 FL	*52.40 FL
6	1		*LEFT FRONT FENDER COWLING	Serviceable	290.00 FL	*- FL
7	1		*LEFT FRONT FENDER COWLING CLIP	Necessary	20.00 FL	*20.00 FL
8	1		*LEFT SIDE MIRROR ASSY	Broken	720.00 FL	*720.00 FL
9	1		*LEFT SIDE MIRROR OUTER COVER	Missing	40.00 FL	*40.00 FL
10	1		*DIAL -A-CAB STICKER	Necessary	55.00 FS	*55.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,295.80	2,147.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	810.20	523.10
Total Parts (\$\$)	2,485.60	1,624.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TUFF-KOTE	New	50.00	50.00
2	TO REMOVE FRONT BUMPER & LEFT FRONT FENDER .KNOCK & REPAIR LEFT FRONT DOOR ,LEFT REAR DOOR &LEFT REAR FENDER .REPLACE THE ABOVE PARTS .ALIGN & ADJUST LEFT FFRONT DOOR ,LEFT REAR DOOR AND REAR BUMPER	New	800.00	700.00
3	TO PUTTY ,RESPRAY PAINTING FRONT BUMPER ,LEFT FRONT FENDER ,LEFT FRONT DOOR ,LEFT REAR DOOR ,LEFT REAR FENDER & LEFT SIDE MIRROR COVER .TO POLISH	New	1,000.00	1,000.00
Gross Labour Cost (\$\$)			1,850.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >