

Prime Auto Claims Service Pte Ltd

GST Reg. No: 201606560M 6 Benoi Place Singapore 629927 Tel: 6861 0908 Fax: 6515 2948

Date: 18.09.2018

India International Insurance Pte Ltd 64 Cecil Street #04/#05 IOB Building Singapore 049711

Attn: Motor Claims Dept

RE: COST OF REPAIR TO VEHICLE SHD2038M TOYOTA PRIUS HYBRID 1.8L (2014)

To Supply

1)	1pc	Front bumper		\$	1,230.00 DE-
2)	1set	Front bumper clips		\$	30.001
3)	1pc	Front bumper left side retainer		\$	82.40 ?
4)	1pc	Left front fender		\$	776.00 repair
5)	1pc	Left front fender "Hybrid" emblem		\$	52.40me -
6)	1pc	Left front fender cowling		\$	290.00 ?
7)	1pc	Left front fender cowling clip			20.00 re-
8)	1pc	Left side mirror assy.		\$ \$ \$	720.00 BR
9)	1pc	Left side mirror outer cover		\$	40.00ms
			Sub total parts	\$	3,240.80
			Less: 25% discount		(810.20)
				\$	2,430.60
To Su	pply S.Nett	Parts			AST -
1)	1pc	"Dial-A-Cab" sticker		\$	55.00
		S	ub total S.Nett Parts	\$	55.00
L/char	ge				
	1) To tuff-kote			\$	50.00
2)	door, left	rear door & left front fender. Knock & representations of the second sec		\$	50.00 800.00 70 U
	& adjust	left front door, left rear door and rear bumper.			

To putty, respray painting front bumper, left front fender, left front door, left rear door, left rear fender & left side mirror cover. To polish

1,000.00 \$

Sub total L/charges	\$ 1,850.00
Estimated Grand Total	\$ 4,335.60

LKK Auto Consultants hence notify the Repaire the following:

To resurvey before/after spray painting

ndisplay damaged part(s) during resurvey

· Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

. No illegal modification(s) is allowed

· Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resurs after regain