

ASS. REC. BY:

REF: CS/FCI18017039/Ktd3nt Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

CWS

Eileen Lee

of

FCI

Date/Time: 19/9/18 @ 9:22am

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJP 5891J

Insured:

SHC 3758S

at Workshop m/s

Chew Goon Motor

Tel:

64641626

of

Blk 10, Amk Ind. Park 2A Ave 5 #01-15/16

Policy No:

Claim No:

D18006910 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15/09/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time: 9:34am @ 19/9/18

Person Contacted:

Grace

Vehicle ~~IN~~ OUT

Date/Time

Action/Instruction (✓) Estimate

SJP 5891J - X

SHC 3758S - NA / INC 16061027 / d2

DOA: 16/01/16

20/9/18 @

1.46pm revised to Eileen Lee by email.

V/Lyn 8 & 500k email (Red: 6200.281, 59%)

REF: FCI

ASSIGNMENT

From: Date: 19/09/18

Estimated Cost:

OD: ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s:

of BLK 10, Amk Ind Park 2A Ave 5 # 01-15

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. 1-24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

20/9

File pass to Catherine

MV: 10,000

LTA: 1,334

NV: 86631-

RECEIVED 20 DEC 2018

Date/Time, File Pass to?

20/9 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) 4500

☐
☒

Preli. Report

Final Report

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee:

☐
☐
☐
☐

Site Insp (\$)

Interview (\$)

Tech Insp (\$)

Weekend (\$)

Survey Fee:

Transportation

S + RS \$

Photos

Others

TOTAL

170+15

50

50

28

313

Veh No: STP 58913 Yr Regn: 03 09

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda: Avante S 1591

Colour:

M. Red A/C: Insured / Std / NI / NA

Sp. Reading:

12339, T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNH0U41BR9U 718544

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal.

6 mm

R/Bal.

7 mm

L/Bal.

6 mm

L/Bal.

7 mm

D.O.A.

15/19/18

D.O.I.

19/19/18

Survey held at

Des. of Damages: ☒ Frt / ☐ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18017039/Ktd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 19-09-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3758S	Veh. Inspected	SJP 5891J
Policy No.		Coverage (\$)	0.00
Claim No.	D18006910MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	19/09/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	15/09/2018	Inspection Date	19/09/2018
Survey held at	CHEW GOON MOTOR BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006910MFSH

Date: 20 September 2018

Our Ref: CS/FCI18017039/Ktd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJP 5891J

Please be informed that we had conducted the inspection of the abovementioned vehicle on 19/09/2018 at the premises of M/s CHEW GOON MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ 11,200.28 .
Revised Estimate Amount	: S\$ 6,844.52 .
"Check" Items Amount	: S\$ 3,133.76 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the front portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	18-09-2018	Our Ref No. D18006910MFSH
Accident Date	15-09-2018	Claim Type. Third Party
Insured Vehicle	SHC3758S	Third Party Vehicle. SJP5891J
Survey Location	BLK 10, ANG MO KIO INDUSTRIAL PARK 2A AVE 5 #01-15,16,17 & #03-05AMK AUTOPOINT	
Contact Person.	GRACE	
Contact No.	64841626/ 0	Fax No. 64840465
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHEW GOON MOTOR	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/244332)



PRI Documents



Close



PRI Header Details

Claim No	D18006910MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & CHEW GO
Workshop Name	CHEW GOON MOTOR (Contact Person : GRACE)	Survey Location & Contact Details	BLK 10, ANG MO KIO INDUSTRIAL PARK 2A AVE 5 #01-AUTOPOINT Mobile: 0 , Phone: 64841626 , Fax: 64840465 EmailId: AD3@CHEWGOONMOTOR.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: LIABILITY UNCLEAR:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC3758S	TP Vehicle No	SJP5891J
PRI Recieved Date	18-09-2018 10:29:58 PM	Surveyor Appointed Date	19-09-2018 09:21:05 AM	Surveyor Accept Date	19-09-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	19-09-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	--	----------------------	------------	-------------------------	--------------------------------------------

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

<input type="button" value="Upload Multiple Documents"/>	
File Name	Action

Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
---------	----------------------	-------------------------------------

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 20 September 2018 1:46 PM
To: 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006910MFSH/1
Attachments: CSFCI18017039Ktd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SJP 5891J.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 19 September 2018 9:38 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006910MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 19 September 2018 9:21 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006910MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 0300A

Vehicle Details

Vehicle No.: SJP5891J

Vehicle to be Exported: No

Intended Deregistration Date: 15 Sep 2018

Vehicle Make: HYUNDAI

Vehicle Model: HD AVANTE 1.6 A

Primary Colour: Red

Manufacturing Year: 2009

Engine No.: G4FC9U622485

Chassis No.: KMH DU41BR9U718544

Maximum Power Output: 89.7 kW (120 bhp)

Open Market Value: \$11,974.00

Original Registration Date: 30 Mar 2009

First Registration Date: 30 Mar 2009

Transfer Count: 1

Actual ARF Paid: \$2,567.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Mar 2019

PARF Rebate Amount: \$1,283.00

Intended COE Rebate Details

COE Expiry Date: 29 Mar 2019

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$643.00

COE Rebate Amount: \$54.00

Total Rebate Amount: \$1,337.00

The information contained herein is correct as at 15 Sep 2018

OK

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9013769G



Name
JONATHAN CHIA ZIXIN

謝子信

Race
CHINESE

Date of birth
14-04-1990

Sex
M

Country of birth
SINGAPORE

S9013769G

REPUBLIC OF SINGAPORE DRIVING LICENCE

S9013769G

JONATHAN CHIA ZIXIN

Date of birth: 14 Apr 1990

Valid Date: 02 Jun 2018

002809069C

4016031



NRIC No. S9013769G



Date of issue
14-03-2007

APT BLK 22 HOUGANG AVENUE 3 #09-253
SINGAPORE 530022

NRIC No: S9013769G

Date: 17-02-2011 (R)

No: 6725446

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

EFFECTIVE DATE

Class 3 Motor cars with unladen weight $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq 2500\text{kg}$ 30 May 2009

Licence No: S9013769G

NP 428A

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5098873070

Cover : drivo CLASSIC

1. Index mark and Registration Number of Vehicle : **SJP5891J**
Chassis Number : KMH DU41BR9U718544
2. Name of Policyholder : JCK ELECTRIC MACHINERY & TRADING
3. Effective Date of Insurance : 30 Mar 2018
4. Expiry Date of Insurance : 29 Mar 2019
5. Persons or Classes of Persons entitled to drive#
(a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use#
(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business.

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
 - (b) Use for the carriage of goods (other than samples) in connection with any trade or business.
 - (c) Use for any purpose in connection with the Motor Trade.
- # Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$2,000
EXCESS (SECTION 2)	: S\$1,500
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: N/A
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: MAYBANK
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)


Agency : SOON WAN YONG (00000573605)
Date of Issue : 28 Mar 2018 11:20 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Authorized
61km @ 500k Max
Resony After Pain
Today

To: First Capital Insurance Limited

Policy No: _____

Third Party

Date: 18.09.2018

Accident Date : 15.09.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Hyundai Avante" Reg. No. SJP5891J Claiming Against Your Insured Veh. No. SHC3758S			
1pc	Bonnet		<i>R1</i> 1,792.40 ✓
2pcs	Bonnet Hinges	59.60	<i>DR1/R2</i> 119.20 ✓
1pc	Bonnet Rubber Seal		<i>GR</i> 16.20 ✓
1pc	Bonnet Lock		<i>DR1</i> 49.30 ✓
1pc	Bonnet Stopper LH		<i>DR1</i> 7.00 ✓
10pcs	Bonnet Insulator Clips	3.00	<i>DR</i> 30.00 ✓
1pc	Grille		<i>CM</i> 402.00 ✓
1pc	Grille Emblem		<i>DR</i> 25.00 ✓
2pcs	Headlamps Assy	530.00	1,060.00 ✓
1pc	Headlamps Lower Bracket LH		<i>R1</i> 32.70 ✓
1pc	Front Bumper		<i>R2</i> 452.00 ✓
10pcs	Front Bumper Clips	3.00	<i>DR</i> 30.00 ✓
2pcs	Front Bumper Brackets	63.00	<i>R</i> 126.00 ✓
1pc	Front Bumper Sponge		<i>CM</i> 124.00 ✓
2pcs	Front Bumper Top Retainers	20.50	<i>DR1/DR2</i> 41.00 ✓
1pc	Front Bumper Reinforcement		<i>R1</i> 279.00 ✓
1pc	Front Bumper Center Air Grille		<i>DR1</i> 51.50 ✓
2pcs	Front Bumper Fog Lamps	150.00	300.00 ✓
2pcs	Front Bumper Corner Holders	32.00	<i>DR1/DR2</i> 64.00 ✓
1pc	Front Bumper Lower Rubber Guard		<i>DR1</i> 48.00 ✓
1pc	Front Bumper Lower Splash Shield		<i>DR</i> 47.50 ✓
1pc	Front Fender LH		<i>R1</i> 477.60 ✓
1pc	Front Fender Badge "VVT"		<i>DR</i> 20.00 ✓
2pcs	Front Fender Shields	52.00	<i>CM</i> 104.00 ✓
10pcs	Front Fender Shield Clips	3.00	<i>DR</i> 30.00 ✓
1pc	Support Panel		<i>DR</i> 860.00 ✓
1pc	Air Con Condenser		<i>DR1/DR2</i> 1,070.00 ✓
1pc	Air Con Condenser Side Air Guide		<i>CM</i> 16.00 ✓
1pc	Radiator		<i>DR</i> 647.00 ✓
1pc	Radiator Fan Assy		<i>CM</i> 624.00 ✓
1pc	Battery Tray		<i>DR</i> 37.20 ✓
1pc	Main Fuse Box LH		<i>DR</i> 876.00 ✓
1pc	Air Cleaner Box		<i>CM</i> 197.00 ✓
1pc	Front Wiper Garnish		<i>DR</i> 92.00 ✓
1pc	Front Wiper Garnish End Cover LH		<i>DR1</i> 59.00 ✓
	Less 20%		10,206.60 2,041.32 8,165.28
		C/F	8,165.28

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

To: **First Capital Insurance Limited**

Policy No: _____ **Third Party**

Date: **18.09.2018**

Accident Date : 15.09.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Hyundai Avante" Reg. No. SJP5891J Claiming Against Your Insured Veh. No. SHC3758S		
		B/F	8,165.28
1pc	Front Number Plate		45.00 SN ✓
1pc	Battery	50%	160.00 SN 50%
	To Conduct Front Electrical Check, Locking System, Adjust, Focus Headlamp etc		30.00 20%
	To Remove / Refit Air Con Condenser & Refill Gas		120.00 100%
	To Remove / Refit, Radiator System, Bleed, Refill Coolant		60.00 50%
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		50.00 ✓
	To Provide Transportation (Towing)		70.00 50%
	Labour Charge - Panel Beating, Repairing Of 2 x Front Chassis Member, Inner Panel, O/S Fender, N/S Fender Inner Panel, Front Door Cnt, Weld Support and Parts Replacement		1,300.00 70%
	To Respray Affected Areas		1,200.00 80%
		Total :	11,200.28

LKK Auto Consultants hence notify
the Reparer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company
Acknowledged by Reparer
Signature:
Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18017039/KId3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 28-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3758S	Veh. Inspected	SJP 5891J	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18006910MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	19/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI AVANTE S (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	KMH DU41BR9U718544	Colour	METALLIC RED	
Odometer	123391	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	KUMHO	6 mm	
L/H Front Tyre	195/65 R15	KUMHO	6 mm	
R/H Rear Tyre	195/65 R15	KUMHO	7 mm	
L/H Rear Tyre	195/65 R15	KUMHO	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/09/2018	Inspection Date	19/09/2018	
Survey held at	CHEW GOON MOTOR BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 5891J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	BENT	1,792.40	1,792.40
2	BONNET HINGES @\$59.60	DISTORTED / BENT	119.20	119.20
1	BONNET RUBBER SEAL	CUT	16.20	16.20
1	BONNET LOCK	DISTORTED	49.30	49.30
1	BONNET STOPPER LH	MISSING	7.00	7.00
10	BONNET INSULATOR CLIPS @\$3.00	NECESSARY	30.00	30.00
1	GRILLE	CRACKED	402.00	402.00
1	GRILLE EMBLEM	NECESSARY	25.00	25.00
2	HEADLAMPS ASSY @\$530.00	O/S MTG CRACKED / N/S CRACKED	1,060.00	1,060.00
1	HEADLAMPS LOWER BRACKET LH	BENT	32.70	32.70
1	FRONT BUMPER	BENT	452.00	452.00
10	FRONT BUMPER CLIPS @\$3.00	NECESSARY	30.00	30.00
2	FRONT BUMPER BRACKETS @\$63.00	TO REPAIR SEE LABOUR	126.00	-
1	FRONT BUMPER SPONGE	CRACKED	124.00	124.00
2	FRONT BUMPER TOP RETAINERS @\$20.50	N/S DISTORTED	41.00	20.50
1	FRONT BUMPER REINFORCEMENT	BENT	279.00	279.00
1	FRONT BUMPER CENTER AIR GRILLE	DISTORTED	51.50	51.50
2	FRONT BUMPER FOG LAMPS @\$150.00	N/S MISSING	300.00	150.00
2	FRONT BUMPER CORNER HOLDERS @\$32.00	N/S MISSING	64.00	32.00
1	FRONT BUMPER LOWER RUBBER GUARD	DISTORTED	48.00	48.00
1	FRONT BUMPER LOWER SPLASH SHIELD	TORN	47.50	47.50
1	FRONT FENDER LH	BENT	477.60	477.60
1	FRONT FENDER BADGE "VVT"	NECESSARY	20.00	20.00
2	FRONT FENDER SHIELDS @\$52.00	CRACKED	104.00	104.00
10	FRONT FENDER SHIELD CLIPS @\$3.00	NECESSARY	30.00	30.00
1	SUPPORT PANEL	BUCKLED	860.00	860.00
1	AIR CON CONDENSER	BENT / PUNCTURE	1,070.00	1,070.00
1	AIR CON CONDENSER SIDE AIR GUIDE	CRACKED	16.00	16.00
1	RADIATO	PUNCTURE	647.00	647.00

Report Ref No. CS/FCI18017039/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR FAN ASSY	CRACKED	624.00	624.00
1	BATTERY TRAY	SERVICEABLE	37.20	-
1	MAIN FUSE BOX LH	SERVICEABLE	876.00	-
1	AIR CLEANER BOX	CRACKED	197.00	197.00
1	FRONT WIPER GARNISH	DENTED	92.00	92.00
1	FRONT WIPER GARNISH END COVER LH	DISTORTED	59.00	59.00
	LESS 20% DISCOUNT		-2,041.32	-1,792.98
			8,165.28	7,171.92
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	MISSING	45.00	45.00
1	BATTERY (50%)(SN)	DENTED	160.00	80.00
			205.00	125.00
	LABOUR			
	TO CONDUCT FRONT ELECTRICAL CHECK, LOCKING SYSTEM, ADJUST, FOCUS HEADLAMP ETC.		30.00	20.00
	TO REMOVE/REFIT AIR CON CONDENSER & REFILL GAS.		120.00	100.00
	TO REMOVE/REFIT, RADIATOR SYSTEM, BLEED, REFILL COOLANT.		60.00	50.00
	TO APPLY RUST PROOFING/RESEAL TUFF COATING TREATMENT TO RESPRAY/REPLACED/REPAIR PANEL.		50.00	50.00
	TO PROVIDE TRANSPORTATION (TOWING).		70.00	50.00
	LABOUR CHARGE-PANEL BEATING, REPAIRING OF 2X FRONT CHASSIS MEMBER, INNER PANEL, O/S FENDER, N/S FENDER INNER PANEL, FRONT DOOR CNT, WELD SUPPORT AND PARTS REPLACEMENT. INCLUSIVE OF THE REPAIR OF FRONT BUMPER BRACKETS.		1,300.00	700.00
	TO RESPRAY AFFECTED AREAS.		1,200.00	800.00
	-		-	-
	-		-	-
	-		-	-
			2,830.00	1,770.00
GRAND TOTAL			11,200.28	9,066.92



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,500.00
-------------------------------------------------------------------------	--	--	----------

Report Ref No. CS/FCI18017039/Ktd3n2

MARKET VALUE: \$10,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$1,337.00=NETT VALUE: \$8,663.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.