

ASS. REC. BY:

REF:

*TP/1*

*CS/TP18017042/Krbnz*

*Mcneeth*

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Trans Cob

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: S1TB 7987B Yr Regn: 01, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / TaxP / Prime Mover /

Truck / Traller or

Make: Chevrolet <sup>A</sup> Epice c.c. 1991

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 776489 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KL11A6PRJBB 12 4317

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inopdr / Jammed / Leaked / Burnt or

Brake: Inopdr / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 14/9/18

Rear

R/Bal. 9 mm

L/Bal. 9 mm

D.O.I. 17/9/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

NIS body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/9 File pass to Catherine

L1 by B43501 (Red 1st 50.07, 80%)

19/9 To submit independent

S1TB 7987B CS/AXA 16018919 / 011016

DA: 01.10.16

RECEIVED 15 OCT 2018

Date/Time, File Pass to?

: Prell. Report

1)

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trlp: \_\_\_\_\_

12x15: 180

Add Fee:  : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Survey Fee:

Transportation:

S - RS, SI

Fixtos

Others

TOTAL

170+180

50

24

80

504

Report Format: TP

Lump Sum / I.B.I: (\$ 4,350)



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/09/2018 10:01
Date Of Accident	14/09/2018 02:00
Exact Location Of Accident	RIVER VALLEY ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB7987B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

### Vehicle Particulars

Manufacturer	CHEVROLET
Model	EPICA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	ABU BAKAR BIN MOHAMED ALWI
NRIC No	S0148311J
Date Of Birth	16/02/1951
Occupation	OUTDOOR
Date Of Driving Pass	09/03/1984
Driving Experience	34 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91089961
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 168 PETIR ROAD #10-126
Postcode	670168
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - OPENING DOOR OF VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON 14/09/18 AT ABOUT 0200HRS I WAS TRAVELLING STRAIGHT ALONG THE SECOND LANE OF RIVER VALLEY ROAD. SUDDENLY I FELT AND IMPACT FROM THE LEFT SIDE OF MY TAXI, THE PASSENGER OF VEHICLE B(SHA91L) DID NOT CHECK FOR ONCOMING VEHICLES AND OPENED THE DOOR AND HIT ONTO MY TAXI'S LEFT SIDE PORTION.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

## Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to GIA Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

*Abner*  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*Zhenwei*  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 7987B**

**AAD1809-127**

*Not Notarised  
61 Sep @ 4350/*

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :

**SHB 7987B**  
KL1LA69RJB124317  
CHEVROLET  
EPICA 2.0  
14.9.2018  
**III**

**PART**

**LIST**

QTY	PART	UNIT	PRICE	TOTAL	STATUS
1	Front Fender LH	\$	837.60	837.60	✓
2	Front Fender Liner LH	\$	47.00	47.00	X
3	Front Fender Inner Wheel House Panel LH	\$	1,437.00	1,437.00	X
4	Front Shock Absorber Assy LH	\$	216.17	216.17	X
5	Front Shock Absorber Top Mounting LH	\$	48.32	48.32	X
6	Front Lower Arm LH	\$	283.00	283.00	X
7	Front Knuckle Arm LH	\$	230.00	230.00	X
8	Front Door LH	\$	1,133.00	1,133.00	✓
9	Front Door Glass Guide RH Chrome Moulding	\$	60.00	60.00	X
10	Front Door Outer Moulding	\$	220.00	220.00	✓
11	Front Door Outer Handle	\$	125.00	125.00	} X
12	Front Door Handle Support	\$	3.00	3.00	
13	Front Door outer handle inner seal	\$	89.15	89.15	
14	Front Door outer key lock	\$	25.00	25.00	
15	Front Door Hinge Upper	\$	65.00	65.00	
16	Front Door Hinge Lower	\$	65.00	65.00	
17	Front Door inner lock	\$	586.00	586.00	
18	Front Door Inner Lock Latch LH	\$	206.00	206.00	
19	Front Door Check / Arrestor	\$	67.50	67.50	
20	Front Door Weatherstrip LH	\$	138.79	138.79	
21	Front Door glass channel weatherstrip	\$	160.00	160.00	
22	Front Door inner trim board	\$	455.69	455.69	
23	Front Door window glass	\$	456.12	456.12	
24	Front Door Power Window Motor (Master) LH	\$	284.97	284.97	
25	Front Door power window motor switch	\$	145.00	145.00	
26	Front Door Window Regulator Gear LH	\$	84.58	84.58	
27	Front Door Outer Pillar Panel LH	\$	715.00	715.00	✓
28	Front Door Pillar Inner Panel LH	\$	850.00	850.00	X
29	Front Door Center Pillar Panel LH	\$	698.15	698.15	X

**Trans-cab Auto Services Pte Ltd**

AAD1809-127

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 7987B**

30	1	Front Side View Mirror Assy LH	\$	<i>Ad/ly</i> 1,191.00 ✓
31	1	Front Side Rocker Panel Garnish LH	\$	<i>Sm</i> 236.40 X
32	1	Front Side Rocker Panel Outer LH	\$	<i>n</i> 600.00 X
33	1	Front Side Rocker Panel Inner LH	\$	<i>n</i> 519.30 X

<b>TOTAL</b>	\$	<b>12,278.74</b>
<b>10%</b>	\$	<b>1,227.87</b>
	\$	<b>11,050.87</b>

**Special Nett**

1 Set	Front Fender Liner clip	\$	<i>Sm</i> 30.00 X
1	Front Fender RR Bracket LH	\$	<i>n</i> 7.10 X
1	Front Wheel Rim Hub Cap LH	\$	<i>Sm</i> 166.30 X
1	Front Tyre LH	\$	<i>Sm</i> 180.00 X
1	Front Tyre Rim LH	\$	<i>Sm</i> 126.00 X
1	Front left door sticker 'Trans-cab'	\$	<i>me</i> 80.00 <i>60sm</i>

<b>TOTAL</b>	\$	<b>589.40</b>
--------------	----	---------------

<b>TOTAL PARTS</b>	\$	<b>11,640.27</b>
--------------------	----	------------------

**LABOUR**

To Check Electrical Lighting Concerned.	\$	170.00 <i>201</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00 <i>6001</i>
Putty and spray painting of the affected portion.	\$	4,000.00 <i>8601</i>
Towing Fees.	\$	<i>na</i> 120.00 X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>na</i> 380.00 X

**Trans-cab Auto Services Pte Ltd**

**AAD1809-127**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 7987B**

To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00 <i>X</i>
To rust-proofing of the affected areas.	\$	170.00 <i>bol</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00 <i>X</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 <i>bol</i>
To transfer of fender fittings, attachment and perform water seepage test.	\$	170.00 <i>bol</i>

**TOTAL \$ 10,460.00**

**Over All Total \$ 22,100.27**

**Repair Days (Lump Sum)**

*15 days*

*5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
TRANS-CAB AUTO SERVICES PTE LTD		Ref : CS/TP18017042/Krbn2	
NO.2 ANG MO KIO STREET 63SINGAPORE 569111		Date : 25-10-2018	
		Code : TP378	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.		Veh. Inspected	SHB 7987B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	17/09/2018
2. Vehicle Particulars & Condition			
Make & Model	CHEVROLET EPICA (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	KL1LA69RJBB124317	Colour	WHITE / RED
Odometer	776489	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	GITI	9 mm
L/H Front Tyre	195/65 R15	GITI	9 mm
R/H Rear Tyre	195/65 R15	GITI	9 mm
L/H Rear Tyre	195/65 R15	GITI	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/09/2018	Inspection Date	17/09/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 7987B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT FENDER LH	BENT	837.60	837.60
1	FRONT FENDER LINER LH	SERVICEABLE	47.00	-
1	FRONT FENDER INNER WHEEL HOUSE PANEL LH	TO REPAIR SEE LABOUR	1,437.00	-
1	FRONT SHOCK ABSORBER ASSY LH	SERVICEABLE	216.17	-
1	FRONT SHOCK ABSORBER TOP MOUNTING LH	SERVICEABLE	48.32	-
1	FRONT LOWER ARM LH	SERVICEABLE	283.00	-
1	FRONT KNUCKLE ARM LH	SERVICEABLE	230.00	-
1	FRONT DOOR LH	BENT	1,133.00	1,133.00
1	FRONT DOOR GLASS GUIDE RH CHROME MOULDING	SERVICEABLE	60.00	-
1	FRONT DOOR OUTER MOULDING	DENTED	220.00	220.00
1	FRONT DOOR OUTER HANDLE	SERVICEABLE	125.00	-
1	FRONT DOOR HANDLE SUPPORT	SERVICEABLE	3.00	-
1	FRONT DOOR OUTER HANDLE INNER SEAL	SERVICEABLE	89.15	-
1	FRONT DOOR OUTER KEY LOCK	SERVICEABLE	25.00	-
1	FRONT DOOR HINGE UPPER	TO REPAIR SEE LABOUR	65.00	-
1	FRONT DOOR HINGE LOWER	TO REPAIR SEE LABOUR	65.00	-
1	FRONT DOOR INNER LOCK	TO REPAIR SEE LABOUR	586.00	-
1	FRONT DOOR INNER LOCK LATCH LH	TO REPAIR SEE LABOUR	206.00	-
1	FRONT DOOR CHECK/ARRESTOR	SERVICEABLE	67.50	-
1	FRONT DOOR WEATHERSTRIP LH	SERVICEABLE	138.79	-
1	FRONT DOOR GLASS CHANNEL WEATHERSTRIP	SERVICEABLE	160.00	-
1	FRONT DOOR INNER TRIM BOARD	SERVICEABLE	455.69	-
1	FRONT DOOR WINDOW GLASS	SERVICEABLE	456.12	-
1	FRONT DOOR POWER WINDOW MOTOR (MASTER) LH	SERVICEABLE	284.97	-
1	FRONT DOOR POWER WINDOW MOTOR SWITCH	SERVICEABLE	145.00	-
1	FRONT DOOR WINDOW REGULATOR GEAR LH	TO REPAIR SEE LABOUR	84.58	-
1	FRONT DOOR OUTER PILLAR PANEL LH	BENT	715.00	715.00
1	FRONT DOOR PILLAR INNER PANEL LH	TO REPAIR SEE LABOUR	850.00	-
1	FRONT DOOR CENTER PILLAR PANEL LH	TO REPAIR SEE LABOUR	698.15	-

Report Ref No. CS/TP18017042/Krbn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SIDE VIEW MIRROR ASSY LH	DENTED / CUT	1,191.00	1,191.00
1	FRONT SIDE ROCKER PANEL GARNISH LH	SERVICEABLE	236.40	-
1	FRONT SIDE ROCKER PANEL OUTER LH	TO REPAIR SEE LABOUR	600.00	-
1	FRONT SIDE ROCKER PANEL INNER LH	TO REPAIR SEE LABOUR	519.30	-
	LESS 10% DISCOUNT		-1,227.87	-409.66
			11,050.87	3,686.94
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT FENDER LINER CLIP (SN)	SERVICEABLE	30.00	-
1	FRONT FENDER RR BRACKET LH (SN)	TO REPAIR SEE LABOUR	7.10	-
1	FRONT WHEEL RIM HUB CAP LH (SN)	SERVICEABLE	166.30	-
1	FRONT TYRE LH (SN)	SERVICEABLE	180.00	-
1	FRONT TYRE RIM LH (SN)	SERVICEABLE	126.00	-
1	FRONT LEFT DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	60.00
			589.40	60.00
	<b><u>LABOUR</u></b>			
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRONT FENDER INNER WHEEL HOUSE PANEL LH, FRONT DOOR HINGE UPPER, FRONT DOOR HINGE LOWER, FRONT DOOR INNER LOCK, FRONT DOOR INNER LOCK LATCH LH, FRONT DOOR WINDOW REGULATOR GEAR LH, FRONT DOOR PILLAR INNER PANEL LH, FRONT DOOR CENTER PILLAR PANEL LH, FRONT SIDE ROCKER PANEL OUTER LH, FRONT SIDE ROCKER PANEL INNER LH AND FRONT FENDER RR BRACKET LH.		4,500.00	600.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,000.00	860.00
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00

Report Ref No. CS/TP18017042/Krbn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO TRANSFER OF DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
			10,460.00	1,660.00
	<b>GRAND TOTAL</b>		<b>22,100.27</b>	<b>5,406.94</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,350.00</b>

Report Ref No. CS/TP18017042/Krbn2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.