

POLY CASE OWNER:

4, PWD 180 17043, Nea3

LIC:  
DAD:

Surveyor:

NAZ

ASSIGNMENT

C/O:

20/6/18

Date / Time:

19/6/18

Registered in Merimen:

26/9/18

Pre-assign / CCU / FTE

S 9304 CD



Insured Vehicle No.:

Claim No.:

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Express Sec II :SS

D.O.A: 31-8-18

Place of Accident:

Is driver the owner? (YES/NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES/NO)

OI GIA REPORT: YES/NO ; TP GIA REPORT: YES/NO

Insured Liability: % Final ? Yes / No

FBM 9230 B



INSRS:

WSP:

Tel:

Liability:

RMKS:

Like Production



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

21/10

gaw

29-10-18

FBM 9230 B - X ; S 9304 CD - X

Ends near liability close.

29-11-18 File PASS TO TYPST TO PREPARE REPORT.

\* OI's name as Merimen.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (If non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (If non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: h/g

Repair Cost: 1/3 S\$3,400

( 3 days) Reduction: 45 %

FINAL SETTLEMENT

Date/Time: 15-11-18

Confirm with: h/g

Email: ☒ Call: ☐

Final Liability: 1/3 100 %

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia: 100%

Repair Cost: 4/51: S\$3,400.00

Loss of Rental (LOR): S\$ -

( days)

Loss of Use (LOU): S\$ 200.00

(\$ 40 x 5 days)

Loss of Income (LOI): S\$ -

(\$ x days)

LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search: S\$ -

Medical: S\$ -

Disbursement: S\$ -

Legal Cost: S\$ -

(e.g. Tow / Independent)

Total: S\$ 3,838.00

Global Sum S\$:

FINAL PAYMENT

Date/Time: 15-11-18

Confirm with: h/g

Email: ☒ Call: ☐

Payee 1: S\$ 3,838.00

Name 1: LIKE PRODUCTION PTE LTD

Payee 2: (Strike if N.A.) S\$ -

Name 2:

Payee 3: (Strike if N.A.) S\$ -

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: 2500

4/1/18

**total**

22/03/2001

ASS. REC BY:

REF:

CS/FWD18017043/N/d3

Special Instruction:

Surveyor:

Naz

ASSIGNMENT (Office)

From (Person):

Josey Jdn

of

FWD

Date/Time:

19/9/18 @ 9.55am

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBM 9230B

Insured:

S 9304CD

at Workshop m/s:

Bike Production

Tel:

639 22555

of

610 Serangoon Rd

Policy No:

Claim No:

1201800011436

Sum Insured:

Excess:

Make of Veh:

D.O.A.

31/08/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

9.55am @ 19/9/18

Person Contacted:

wendy

Vehicle ~~IN~~ OUT

Date/Time

Action/Instruction

(✓)

Estimate

FBM 9230B - X

S 9304CD - X

**BIKE PRODUCTION PTE LTD**

610, Serangoon Road S(218216)

Tel: 63922555, 62995177 Fax: 62975400

ROC/ GST Reg No.: 200007407G

Date: 1 Sept 2018

**ASSESSMENT FOR REPAIR: YAMAHA SNIPER T150 - FBM9230B**

Chassis No.: MH3UG0740J0101700

Engine No.: G3E6E0384678

Qty	Description	Estimate
1 pc	Front disk	<del>\$205.00</del> X SVL
1 pc	Front wheel axle	<del>\$95.00</del> X SVL
1 pc	Front mudguard	140 <del>\$20</del> \$195.00 / SCR
1 pc	Left fork assembly	<del>\$750.00</del> X SVL
1 pc	Right fork assembly	<del>\$750.00</del> X SVL
1 pc	Headlight cover ambler	\$45.00 / SCR
1 pc	Headlight cover	280 <del>\$250</del> \$145.00 / SCR
1 pc	Headlight assy	CRA ✓ \$450.00 X SVL / SCR
1 pc	Front fairing cover	\$330.00 X SVL / SCR
1 pc	Left fairing assembly	\$225.00 / CRA
1 pc	Fairing ambler	\$20.00 / ALL
2 pcs	Steering stem bearing @ \$45.00	760 <del>\$90.00</del> X SVL / ALL
1 pc	Steering stem bracket assembly	<del>\$350.00</del> X SVL
1 pc	Steering stem underbracket	<del>\$350.00</del> X SVL
1 pc	Handle bar	110 <del>\$500</del> \$165.00 / BT
1 pc	Clutch lever	\$45.00 / SCR
1 pc	Left view mirror	\$70.00 / MIS
1 pc	Left balancer	\$45.00 / SCR
1 pc	Left rear signal	\$85.00 / DISCLODGE
1 pc	Left engine cover	\$390.00 X R
1 pc	Left engine cover gasket	720 <del>\$20</del> \$55.00 / ALL
1 pc	Left front footrest holder assembly	70 <del>\$250</del> \$255.00 / BT
1 pc	Main stand	<del>\$200.00</del> X SVL
1 pc	Left front footrest	\$45.00 / SCR
1 pc	Gear pedal assembly	\$145.00 / SCR
1 pc	Rear swing arm assy	\$330.00 / BT
1 pc	Rear wheel axle	\$95.00 / DD
1 pc	Chain guard	\$55.00 / BT
1 pc	Left rear cover	3100 <del>\$220.00</del> X SVL / SCR
1 pc	Rear handle	\$50.00 / SCR
1 pc	Mainstand	<del>\$145.00</del> X SVL
1 pc	Side stand	<del>\$65.00</del> X SVL
		<hr/>
		\$2,640
		\$264
		\$2,376
	Less discount 10%	<hr/>
		\$6,460.00
		\$646.00
		\$5,814.00
	<b>Special nett items</b>	
1 pc	Front sport rim	<del>\$480.00</del> X SVL
1 pc	Rear sport rim	\$157.00 X SVL / SCR
1 pc	Rear tyre	\$330.00 X SVL
1 pc	Engine oil	\$330.00 / ALL
1 pc	Front number plate	\$20.00 / ALL
1 pc	Rear number plate	\$30.00 / ALL
1)	Towing charges	302 <del>\$25</del> \$80.00 / ALL

2)	Dismantle, replace, realign and adjust above damaged parts	\$700.00	300
4)	To knock, straighten chassis & body balancing	\$380.00	150
5)	To remove/refit, replace (if damage) check and straighten front fork tubes	<del>\$180.00</del>	2 x 11
6)	To remove/refit, replace (if damage) check and replace <sup>rear</sup> sport rim	\$180.00	2 x 2
7)	Spray painting	\$300.00	200
	<b>Total Estimate</b>	<u>\$780</u>	<u>\$8,981.00</u>

Note: The above estimate is subjected to the prevailing GST of 7%



For Bike Production Pte Ltd

NAZ LK  
20/9/18 1445  
LIS  
3 days  
After repair RD.

LR (and controller) is deemed to notify the insurer of the following:

- Insured vehicle is being repaired
- Details of damage/repairs during repair
- Estimated cost of repairs
- Third party claim is on a "Without Prejudice" basis
- No other medical claim is allowed
- Supplementary claim(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**BIKE PRODUCTION PTE LTD**  
 610, Serangoon Road S(218216)  
 Tel: 63922555, 62995177 Fax: 62975400  
 ROC/ GST Reg No.: 200007407G

Date: 21 Sept 2018

**ASSESSMENT FOR REPAIR: YAMAHA SNIPER T150 - FBM9230B**

Chassis No.: MH3UG0740J0101700

Engine No.: G3E6E0384678

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Headlight black cover	40 \$125.00 / BT
1 pc	Inner meter cover	\$115.00 / S.W
1 pc	Rear brake disk	<del>\$70</del> \$185.00 / BT
1 pc	Chain adjuster	120 \$88.00 / BT
1 pc	Rear fender	\$255.00 / BT
1 pc	Rear wheel hub	<del>\$400</del> \$195.00 / net
		<u>\$753</u> \$963.00
	Less discount 10%	+ 75.3 \$96.30
		<u>\$677.7</u> \$866.70
	<b><u>Special nett items</u></b>	
	<b>Total Estimate</b>	<u><u>\$866.70</u></u>

Note: The above estimate is subjected to the prevailing GST of 7%



For Bike Production Pte Ltd

**BIKE PRODUCTION PTE LTD**

610, Serangoon Road S(218216)

Tel: 63922555, 62995177 Fax: 62975400

ROC/ GST Reg No.: 200007407G

Date: 1 Sept 2018

**ASSESSMENT FOR REPAIR: YAMAHA SNIPER T150 - FBM9230B**

Chassis No.: MH3UG0740J0101700

Engine No.: G3E6E0384678

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front disk	<del>\$205.00</del> X SVL
1 pc	Front wheel axle	<del>\$95.00</del> X SVL
1 pc	Front mudguard	\$195.00 / SCR
1 pc	Left fork assembly	<del>\$750.00</del> X SVL
1 pc	Right fork assembly	<del>\$750.00</del> X SVL
1 pc	Headlight cover amblem	\$45.00 / SCR
1 pc	Headlight cover	\$145.00 / SCR
1 pc	• Headlight assy	\$450.00 X SVL / SCR
1 pc	• Front fairing cover	CRA ✓ \$330.00 X SVL / SCR
1 pc	Left fairing assembly	\$225.00 / CRA
1 pc	Fairing amblem	\$20.00 / ALL
2 pcs	Steering stem bearing @ \$45.00	<del>\$90.00</del> X SVL
1 pc	Steering stem bracket assembly	<del>\$350.00</del> X SVL
1 pc	Steering stem underbracket	<del>\$350.00</del> X SVL
1 pc	• Handle bar	\$165.00 X SVL
1 pc	Clutch lever	\$45.00 / SCR
1 pc	Left view mirror	\$70.00 / MIS
1 pc	Left balancer	\$45.00 / SCR
1 pc	Left rear signal	\$85.00 / DISCLODGE
1 pc	✗ Left engine cover	\$390.00 X R
1 pc	Left engine cover gasket	\$55.00 / ALL
1 pc	• Left front footrest holder assembly	\$255.00 B / BT
1 pc	Main stand	<del>\$200.00</del> X SVL
1 pc	Left front footrest	\$45.00 / SCR
1 pc	Gear pedal assembly	\$145.00 / SCR
1 pc	Rear swing arm assy	\$330.00 / BT
1 pc	Rear wheel axle	\$95.00 / DD
1 pc	Chain guard	\$55.00 / BT
1 pc	• Left rear cover	X \$220.00 X SVL / SCR
1 pc	Rear handle	\$50.00 / SCR
1 pc	Mainstand	<del>\$145.00</del> X SVL
1 pc	Side stand	<del>\$65.00</del> X SVL
		<hr/>
		\$6,460.00
	Less discount 10%	\$646.00
		<hr/>
		\$5,814.00
	<b><u>Special nett items</u></b>	
1 pc	Front sport rim	<del>\$480.00</del> X SVL
1 pc	Rear sport rim	\$157.00 X SVL / SCR
1 pc	✗ Rear tyre	\$330.00 X SVL
1 pc	Engine oil	\$330.00 / ALL
1 pc	Front number plate	\$20.00 / ALL
1 pc	Rear number plate	\$25 \$30.00 / BT CRA
1)	Towing charges	\$80.00 / ALL

610, Serangoon Road S(218216)  
Tel: 63922555, 62995177 Fax: 62975400  
**ROC/ GST Reg No.: 200007407G**

ASSESSMENT FOR REPAIR: YAMAHA SNIPER T150 - FBM9230B

Engine No.: G3E6E0384678

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Headlight black cover	\$125.00 ✓ BT
1 pc	Inner meter cover	\$115.00 ✓ SUE
1 pc	Rear brake disk	\$185.00 ✓ BT
1 pc	Chain adjuster	\$88.00 ✓ BT
1 pc	Rear fender	\$255.00 ✓ BT
1 pc	Rear wheel hub	\$195.00 ✓ net
		<hr/>
		\$963.00
	Less discount 10%	\$96.30
		<hr/>
		\$866.70
	<u>Special nett items</u>	
	<b>Total Estimate</b>	<hr/>
		\$866.70

**Note: The above estimate is subjected to the prevailing GST of 7%**



For Bike Production Pte Ltd



**BIKE PRODUCTION PTE LTD**  
 610, Serangoon Road S(218216)  
 Tel: 63922555, 62995177 Fax: 62975400  
**ROC/ GST Reg No.: 200007407G**

Date: 1 Sept 2018

**ASSESSMENT FOR REPAIR: YAMAHA SNIPER T150 - FBM9230B**

Chassis No.: MH3UG0740J0101700

Engine No.: G3E6E0384678

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front disk	\$205.00 X SVL
1 pc	Front wheel axle	\$95.00 X SVL
1 pc	Front mudguard	\$195.00 / SCR
1 pc	Left fork assembly	\$750.00 X SVL
1 pc	Right fork assembly	\$750.00 X SVL
1 pc	Headlight cover amblem	\$45.00 / SCR
1 pc	Headlight cover	\$145.00 / SCR
1 pc	Headlight assy	\$450.00 X SVL
1 pc	Front fairing cover	\$330.00 X SCR
1 pc	Left fairing assembly	\$225.00 / SCR
1 pc	Fairing amblem	\$20.00 / ALL
2 pcs	Steering stem bearing @ \$45.00	\$90.00 X SVL
1 pc	Steering stem bracket assembly	\$350.00 X SVL
1 pc	Steering stem underbracket	\$350.00 X SVL
1 pc	Handle bar	\$165.00 ?
1 pc	Clutch lever	\$45.00 / SCR
1 pc	Left view mirror	\$70.00 / MIS
1 pc	Left balancer	\$45.00 / SCR
1 pc	Left rear signal	\$85.00 / DISCLOGE
1 pc	Left engine cover	\$390.00 X R
1 pc	Left engine cover gasket	\$55.00 / ALL
1 pc	Left front footrest holder assembly	\$255.00 ?
1 pc	Main stand	\$200.00 X SVL
1 pc	Left front footrest	\$45.00 / SCR
1 pc	Gear pedal assembly	\$145.00 / SCR
1 pc	Rear swing arm assy	\$330.00 / RT
1 pc	Rear wheel axle	\$95.00 / DD
1 pc	Chain guard	\$55.00 / RT
1 pc	Left rear cover	\$220.00 X SVL
1 pc	Rear handle	\$50.00 / SCR
1 pc	Mainstand	\$145.00 X SVL
1 pc	Side stand	\$65.00 X SVL
		<hr/>
		\$6,460.00
Less discount 10%		\$646.00
		<hr/>
		\$5,814.00
<b><u>Special nett items</u></b>		
1 pc	Front sport rim	\$480.00 X SVL
1 pc	Rear sport rim	\$157.00 / SCR
1 pc	Rear tyre	\$330.00 X AN
1 pc	Engine oil	\$330.00 / ALL
1 pc	Front number plate	\$20.00 / ALL
1 pc	Rear number plate	\$30.00 / CRP
1)	Towing charges	\$80.00 / ALL

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Lionel Tan

Date: 30 Oct 2018

## Preliminary Advice

Insured Vehicle No	: S9304CD	Accident Date	: 31/08/2018
TP Vehicle No	: FBM9230B	Assignment Date	: 26/09/2018
Make	: YAMAHA SNIPER T150	Est. Duration of Repair	: 3 days
Date of Inspection	: 20/09/2018		
Inspection At	: Bike Production Pte Ltd (HQ) 610 SERANGOON ROAD Singapore 218216		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages ....N/S.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,847.70
Revised Amount	:S\$	4,793.20
Check Items (Estimated)	:S\$	148.50
Total	:S\$	4,941.70

Lump Sum Repair :S\$

### Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : We have not authorized repairs.

**Asher Sng (LKKAuto)**

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Monday, 29 October 2018 3:35 PM  
**To:** 'sbk5643e@yahoo.com'  
**Subject:** Re: URGENT!!!!Fw: RESENT!!!! RE: PRI FOR CLAIM AGAINST YOUR INSURED - S9304CD ON 31 AUG 2018 (Our Ref: 1201800011436/LT)

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (**LKK**) to proceed on negotiate settlement.

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1 #02-25 | S(408933)

-----Original Message-----

From: Sbk E [mailto:[sbk5643e@yahoo.com](mailto:sbk5643e@yahoo.com)]

Sent: Sunday, 28 October, 2018 6:45 PM

To: Motor Claims SG - SG Common

Subject: Fw: ATTN: LIONEL, Re: URGENT!!!!Fw: RESENT!!!! RE: PRI FOR CLAIM AGAINST YOUR INSURED - S9304CD ON 31 AUG 2018

Regards,

Kwan S. H.  
Director  
Bike Production Pte Ltd

--- On Sun, 10/28/18, Sbk E <sbk5643e@yahoo.com> wrote:

> From: Sbk E <sbk5643e@yahoo.com>  
> Subject: ATTN: LIONEL, Re: URGENT!!!!Fw: RESENT!!!! RE: PRI FOR CLAIM  
> AGAINST YOUR INSURED - S9304CD ON 31 AUG 2018  
> To: contact.sg@fwd.com  
> Date: Sunday, October 28, 2018, 6:33 PM [Without Prejudice]

>  
> Dear Lionel,  
>  
> Good Day, Please refer to our  
> conversation that liability is down with your insured and you are good  
> for direct settlement for property damage.  
> Please confirm. Thanks.

>  
> Regards,  
>  
> Kwan S. H.  
> Director  
> Bike Production Pte Ltd

>  
> -----  
> On Thu, 10/18/18, Sbk E <sbk5643e@yahoo.com>  
> wrote:

>  
> Subject: URGENT!!!!Fw: RESENT!!!! RE:  
> PRI FOR CLAIM AGAINST YOUR INSURED - S9304CD ON 31 AUG 2018  
> To: contact.sg@fwd.com  
> Date: Thursday, October 18, 2018,  
> 11:24 AM

>  
> Dear Sir,  
>  
> Please refer email below and assist  
> on  
> urgent basis. Thanks.

>  
> Regards,  
>  
> Kwan S. H.  
> Director  
> Bike Production Pte Ltd

>  
>  
> --- On Wed, 10/17/18, Sbk E <sbk5643e@yahoo.com>  
> wrote:

>

> > From: Sbk E <sbk5643e@yahoo.com>  
 > > Subject: RESENT!!!! RE: PRI FOR  
 > CLAIM AGAINST YOUR INSURED - S9304CD  
 > ON 31 AUG 2018  
 > > To: motorclaims.sg@fwd.com  
 > > Date: Wednesday, October 17,  
 > 2018,  
 > 8:47 AM  
 > > RESENT!!!!  
 > >  
 > > Regards,  
 > >  
 > > Kwan S. H.  
 > > Director  
 > > Bike Production Pte Ltd  
 > >  
 > >  
 > >  
 > -----  
 > > On Wed, 9/26/18, Sbk E <sbk5643e@yahoo.com> > wrote:  
 > >  
 > > Subject: RE: PRI FOR CLAIM  
 > AGAINST  
 > > YOUR INSURED - S9304CD ON 31 AUG  
 > 2018  
 > > To: motorclaims.sg@fwd.com  
 > > Date: Wednesday, September  
 > 26, 2018,  
 > > 1:07 PM  
 > >  
 > > [Without Prejudice]  
 > >  
 > > Dear Sir,  
 > >  
 > > Please confirm if direct  
 > settlement  
 > > for  
 > > property damage is possible  
 > and help  
 > > to link up the claim  
 > > officer for this case.  
 > Thanks.  
 > >  
 > > Regards,  
 > >  
 > > Kwan S. H.  
 > > Director  
 > > Bike Production Pte Ltd  
 > >  
 > >  
 > >  
 > >  
 >

> -----  
> > On Tue, 9/18/18, Sbk E  
> > <sbk5643e@yahoo.com>  
> > wrote:  
> >  
> > Subject: RE: PRI FOR CLAIM  
> > AGAINST  
> > YOUR INSURED - S9304CD ON 31  
> > AUG 2018  
> > To: motorclaims.sg@fwd.com  
> > Date: Tuesday, September 18,  
> > 2018,  
> > 7:31 PM  
> >  
> > Dear Sir,  
> >  
> > Please refer to the attached  
> > file for  
> > your necessary action.  
> > Thanks.  
> >  
> > Regards,  
> >  
> > Kwan S. H.  
> > Director  
> > Bike Production Pte Ltd  
> >  
> >

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	26 Sep 2018 14:08	<b>Cim Veh Model Changed</b>	(201316) YAMAHA YZ125 124cc (M).	[A] Nivitha Govindasamy
2	26 Sep 2018 14:08	<b>Cim Created</b>	Reg No: FBM9230B, Acct Date: 2018/08/31. Claim Type: TP. Insurer: FWD Singapo re Pte. Ltd. (HQ). Workshop: Bike Production Pie Ltd (HQ)	[A] Nivitha Govindasamy
3	26 Sep 2018 14:08	<b>Adj Co Assigned</b>	LKK Auto Consultants Pte Ltd (HQ); RR Region: FWD - Ext Auto Adj Assignment. Suggested Adj. : VICOM Ltd.	[A] Nivitha Govindasamy
4	26 Sep 2018 14:08	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2018/10/05	[A] Nivitha Govindasamy
5	26 Sep 2018 14:08	<b>Adj Mandate Set</b>	Approved:0.00.Reinsp:Adj decides.	[A] Nivitha Govindasamy
6	26 Sep 2018 14:09	<b>Adj Adjuster Assigned</b>	[None] -> Muhammad Nazril Bin Abdullah	[A] Nivitha Govindasamy
7	26 Sep 2018 14:54	<b>Cim Registration Modified</b>	Pol No:->PNPV2018-00011083.	[I] Josey Loh
8	26 Sep 2018 14:54	<b>Cim Registration Modified</b>	Excess: -> 500.00.	[I] Josey Loh
9	26 Sep 2018 14:54	<b>Cim Registration Modified</b>	Acct Time:00:00:00->21:00:00.	[I] Josey Loh
10	30 Oct 2018 11:24	<b>Cim Veh Model Changed</b>	(201316) -> (205272) YAMAHA SNIPER T150 150cc.	[A] HOW MEI KWAN
11	30 Oct 2018 11:24	<b>Cim Registration Modified</b>	Rep:204655->203419.	[A] HOW MEI KWAN
12	30 Oct 2018 11:33	<b>Adj Im. Advice Submitted</b>	Next Rpt:Final Rpt.Due Date:2018/10/05	[A] HOW MEI KWAN
13	03 Dec 2018 11:18	<b>Adj Rpt Initiated</b>		[A] JOANNE LEE KHANG MIN
14	03 Dec 2018 11:18	<b>Cim Dtl Modified</b>	JPJ Reg. Date: -> 2018/05/24.	[A] JOANNE LEE KHANG MIN
15	03 Dec 2018 11:18	<b>Cim Details Notified</b>		[A] JOANNE LEE KHANG MIN
16	05 Dec 2018 12:43	<b>Label Added</b>	(20005):Direct Settlement .	[A] Asher Sng Rang Yi
17	05 Dec 2018 12:47	<b>Adj Mandate Request</b>	Cur.Reg:3838.00:LIABILITY: 100% B:28 3VEH CC OI LAST QUANTUM: (a) COR w/G ST: \$3,638.00 + (b) LOU: \$200.00 (5days x \$40) Total: a+b = \$3,838.00 PLEASE REVERT WITH YOUR APPROVAL / MANDATE / INSTRUCTIONS, IF ANY.	[A] Asher Sng Rang Yi

Date From  Date To  Audit Type

### ACTIVITY

No record

### Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1960105	30/10/2018 11:33	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	FBM9230B	S9304CD	10.70

## Print Received Message

This mail is associated with :

**\*FBM9230B (1201800011436)**  
**[S9304CD]**

TP

RAZALI BIN ATAN

Aug 31 2018 9:00PM

[SILVINO SCHLICKMANN JUNIOR]

Bike Production Pte Ltd

**From** FWD Singapore Pte. Ltd. (HQ) (FWD\_SG), sent on 10/12/2018 18:54 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$3838.00) - FBM9230B - Claim Handler: Lionel Tan

Approved:3838.00.



FWD SINGAPORE PTE LTD

Attn: Motor Claims Dept

Dear Sir/ Madam

ACCIDENT INVOLVING VEHICLE NO F8M9230B AND S9304C1  
ALONG BURNA VISTA ON 21/8/2018

We understand that you are the insurer of S9304C1 vehicle.

I/We wish to inform you that my/our vehicle F8M9230B have been completed repairs to my/our satisfaction by M/s RIKE PRODUCTION. I/We therefore propose to claim from your as follows: PTE LTD

1.	Cost of Repairs	S\$ <u>3638</u>
2.	Loss of Use/Rental(S\$ <u>40</u> x <u>5</u> days)	S\$ <u>200</u>
3.	LTA Search Fee/GIA Reports	S\$ <u>7.49</u>
TOTAL		S\$ <u>3845.49</u>

Please let us have your reply soonest possible.

Thank you.

Yours faithfully



Razali Bin Atan  
Blk 202 Bedok North Street 1  
#08-475  
Singapore 460202

Date: 1 Sept 2018

To: Who it may concern  
&  
Mr Kwan Say Hwee  
Bike Production Pte Ltd  
610, Serangoon Road  
Singapore 218216

Dear Sir,

**RE: LETTER OF AUTHORIZATION TO ACT ON BEHALF AND REPAIR FOR  
VEHICLE NO.: FBM9230B**

I, Razali Bin Atan, NRIC No.: S7513426F, registered owner of vehicle No.: FBM9230B hereby authorize Mr. Kwan Say Hwee, NRIC No.: S7722209Z, of Bike Production Pte Ltd, ROC Reg No.: 200007407G to act on my behalf regarding all accident claims issues including repairs for my vehicle-- FBM9230B.

All claims settlement payment for property damage shall be paid directly to Bike Production Pte Ltd as I have not made any payment for the repairs of my vehicle FBM9230B.

In the event of any cancellation of this claim authorization, I agree to pay Bike Production Pte Ltd SGD 500.00 subjected to the prevailing GST. I also agree to pay for all costs and expenses incurred including legal costs on a full indemnity basis. Thank you very much for your attention.

Yours faithfully,



Razali Bin Atan

my execution of this Discharge Voucher is only for my claim for property damage and not prejudicial to any other claims arising from the same accident

#### RELEASE

Claim Reference:	1201800011436
Surveyor's Reference:	CC4/FWD18017043/Nea3
TP Reference:	FBM 9230B

We, BIKE PRODUCTION PTE LTD ("Workshop") hereby agree and confirm that we are authorized by the owner ("Claimant") of motor vehicle FBM 9230B ("Vehicle") to accept the sum of \$3,838.00, being the amount claimed for \$3,638.00 (repair costs), \$200.00 (loss of ~~rental~~ use), \$ - (loss of income), \$ - (search fees) as compensation for the loss of or damage to the Vehicle, as a result of an accident ("Accident") which occurred on 31/08/2018 (date of accident) at / along BUONA VISTA (location) involving vehicle no/s. FBM 9230B and S 9304CD.

This is pursuant to the inspection conducted on 20/09/2018 (date) at the Workshop.

We confirm that this acceptance is in full and final settlement of all claims arising from the damage to the Vehicle (whether now or hereafter to become manifest), to the intent that FWD Singapore Pte. Ltd. and all other persons, in particular the driver of S 9304CD be absolutely and finally exonerated and discharged from all claims of every nature and kind whatsoever which have been made or which may be made in respect of this Accident.

We also declare that we are authorized by the Claimant to receive the above compensation and we have full authority to make the claim as set out above and to settle the matter on behalf of the Claimant in any manner we deem fit.

This settlement is reached on a without prejudice and without admission of liability basis. As such, this Release is not to be construed as an admission of liability on the part of FWD Singapore Pte Ltd, their policyholder and / or authorised driver and shall not be used as evidence in any claims and / or action which may be lodged by any of them.

Dated this 02 day of 01 2019

CLAIMANT

[Signed by the "Workshop" with Co. Stamp]

For and on behalf of the "Claimant"



NAZ

[FWD's appointed surveyor with Co. Stamp]

For and on behalf of FWD Singapore Pte. Ltd.

# BIKE PRODUCTION PTE. LTD.

610, Serangoon Road Singapore 218216  
Tel: 6392 2555 Fax: 6297 5400

## TAX INVOICE

Co. Registration No. 200007407G  
GST Reg. No: 200007407G  
GST Inclusive

No: 5754

Name: FWD SINGAPORE PTE LTD Date: 24/12/2018  
PACIFIC INSURANCE PTE LTD  
Address: 6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4 SE038986  
78 SHERATON WAY #07-16 AIR BUILDING SE 0371205  
I/C No: 6327 5700 Occupation: 6327 5799 DOB: 6327 5799  
Tel: 6327 5700 (FAX) 6327 5799 Driving Licence: 6327 5799

Particulars	Amount
Reg. No: <u>FBM9230B</u> Selling Price	<u>\$3,638.00</u>
Make & Model: <u>YAMAHA SNIPER T150</u> + Insurance	<u>\$ 0</u>
Engine No: <u>G3E6E 0384678</u> + Retention	<u>\$ 0</u>
Chassis No: <u>MH3UG 0740J0101700</u> TOTAL PRICE	<u>\$3,638.00</u>
Insurance Type: <input type="checkbox"/> Comprehensive <input type="checkbox"/> Third Party Fire Theft <input type="checkbox"/> Third Party Only	
Colour: <u>BLACK</u> LUMP SUM REPAIRS Downpayment	<u>\$ 3,400.00</u>
NO OF REPAIR DAYS: <u>3+2 = 5 DAYS</u> GST 7%	<u>\$ 238.00</u>
Loan Amount _____ Interest rates _____ p.a.	<u>\$3,638.00</u>
Terms: ( _____ Monthly Instalments of \$ _____ )	
N/R: _____ TEL: _____	
GTR: _____ TEL: _____	
COE NO: _____ TR	

### Note:

- Above prices do not include ERP IU.
- Deposit is not refundable.
- Balance amount must be cleared within 3 days of the invoice date. Deposit will be forfeited if the buyer fails to clear the full balance amount within the stated period.
- Title to the above-mentioned goods will not be handed to the buyer until the full amount and/or changes are paid
- All cheque payments are to be crossed and made payable to **Bike Production Pte Ltd**. If cheque dishonoured, the buyer has to pay **Bike Production Pte Ltd** by cash and a service charge of S\$30.00 plus prevailing GST.
- Bike Production Pte Ltd** will have full rights to repossess the above-mentioned goods without notice in case of default in payment.
- The buyer shall inspect the above-mentioned goods immediately on notification that goods are due and ready for collection. The buyer shall give notice in writing to the seller of any matter or thing by reason whereof he alleges that the goods are not in acceptable conditions. If the buyer fails to give notice, the above-mentioned goods shall be deemed to be in accordance with the contract and the buyer shall be bound to accept and pay for the same accordingly.
- For hire purchase, no alteration of the hire-purchase agreement and its terms, including down payment and installment period, is allowed once the hire-purchase agreement is made. In the event of cancellation, the buyer shall compensate **Bike Production Pte Ltd** 20% of the total price plus prevailing GST and the deposit shall be forfeited.
- For hire purchase, a Singaporean guarantor between 21 year & 60 year of age and with a different residential address from the buyer is required before the collection of the above-mentioned goods. The guarantor shall not be an undischarged bankrupt and is subject to financial approval.
- I confirm that the information I have provided is my personal data and, where it is not my personal data, that I have the consent of the owner of such personal data to provide such information. By providing this information I understand and give my consent for **Bike Production Pte Ltd** to collect, use, store, transfer and / or disclose personal data about me or us and those whose personal data I or we have provided from sources other than myself or us for the purposes.

For **Bike Production Pte Ltd**

I accept the above terms and conditions

Razali Bin Atan  
Blk 202 Bedok North Street 1  
#08-475  
Singapore 460202

PROFORMA INVOICE : BP/11028/18  
DATE : 20th November 2018  
GST REGN NO : 200007407G  
COMPANY REGN NO : 200007407G

[illegible]

3,400.00  
238.00

FOR BIKE PRODUCTION PTE LTD

3,638.00

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

































## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Sep 2018 <a href="#">Edit Reg</a>		19 Sep 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$3,400.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,400.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>SILVINO SCHLICKMANN JUNIOR</b> , ID: G1451968N								
Main Claimant:	<b>RAZALI BIN ATAN</b> , ID: S7513426F								
Vehicle Reg. No.:	<b>FBM9230B</b>	Date of Loss:	31/08/2018 21:00 - :59 [3 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 1201800011436</b>	Policy/Cover Note No.:	PNPV2018-00011083 (Comprehensive) Coverage: 22/08/2018 - 21/08/2019						
Vehicle Reg. No. (Insured):	<b>S9304CD</b>	Policy No. (Claimant):	VMX/P2145397						
		Excess:	S\$500.00						
Repairer:	<b>Bike Production Pte Ltd (HQ)</b> 610 SERANGOON ROAD, 218216 Serangoon - Tel:								
Handling Insurer:	<b>FWD Singapore Pte. Ltd. (HQ)</b> - Tel: 6727 5700 ... [Handled by <b>Lionel Tan</b> ]								
Claimant's Insurer:	<b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Muhammad Nazril Bin Abdullah</b> ] ... [Final Rpt due 05/10/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• FWD_SG (10/12/2018): Alert - Adj Mandate Approved (S\$3838.00) - FBM9230B - Claim Handler: Lionel Tan									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*FBM9230B (1201800011436)  
[S9304CD]  
TP  
RAZALI BIN ATAN  
Aug 31 2018 9:00PM  
[SILVINO SCHLICKMANN JUNIOR]  
Bike Production Pte Ltd

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>		
<b>Letters/Correspondences</b>			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown	 Edit		
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	30/10/18 11:33	Adjuster Immediate Advice	 Load HTM		
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
2	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
3	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
15	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
16	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
17	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
18	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
19	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
20	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
21	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
22	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
23	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
24	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
25	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
26	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
27	05/12/18 12:44	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>	
28	05/12/18 12:44	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>	
29	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
30	05/12/18 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	05/12/18 12:44	General View	Load JPG	<input checked="" type="checkbox"/>
32	05/12/18 12:44	General View	Load JPG	<input checked="" type="checkbox"/>
33	05/12/18 12:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
34	05/12/18 12:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
35	05/12/18 12:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	05/12/18 12:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	05/12/18 12:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	05/12/18 12:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	05/12/18 12:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	05/12/18 12:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	05/12/18 12:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	05/12/18 12:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	05/12/18 12:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	05/12/18 12:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	05/12/18 12:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	05/12/18 12:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	05/12/18 12:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	05/12/18 12:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	05/12/18 12:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	05/12/18 12:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	05/12/18 12:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	05/12/18 12:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	05/12/18 12:45	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
54	05/12/18 12:45	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
55	05/12/18 12:45	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/10/18 11:34	ACKNOWLEDGEMENT EMAIL TO FWD DD 19.09.2018	Load PDF	
2	30/10/18 11:34	NOTIFICATION FROM LAWYER	Load JPG	<input checked="" type="checkbox"/>
3	30/10/18 11:50	TP ESTIMATE - MARKED	Load PDF	
4	03/12/18 11:32	LOD	Load PDF	
5	07/01/19 09:21	WORKSHOP INVOICE	Load PDF	
6	07/01/19 09:21	AUTHORISATION TO ACT FORM	Load PDF	
7	07/01/19 09:21	Release Voucher	Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	26/09/18 15:11	Insured GIA	Load PDF	
2	29/10/18 15:30	TP GIA Report	Load PDF	
3	29/10/18 15:31	1st Car GIA Report	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			





NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	S9304CD (Insd veh)	Model:	YAMAHA SNIPER T150
	FBM9230B (TP veh)		150CC
Date of Accident:	31/08/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	10,537.04
Final Repair Cost	:	\$	3,638.00
Loss of Use	:	\$	200.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,838.00

5.00 days at \$40.00 per day  
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_\_ 100 \_\_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ 100 \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Bike Production Pte Ltd	:	\$ 3,838.00
2)		:	\$

JOANNE LEE KHANG MIN

07 Jan  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD18017043/NEA3Q2

Date: 07/01/2019

### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00011083  
**Claimant Vehicle No :** FBM9230B **Insured Vehicle No :** S9304CD  
 Date of Loss: 31/08/2018 Nature of Claim: TP Claim No: 1201800011436

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBM9230B**  
 Make & Model: YAMAHA SNIPER T150, 150cc Engine No: G3E6E0384678  
 Reg. Date: 24/05/2018 (Man. Year: 2018) Chassis No: MH3UG0740J0101700  
 Colour: Yellow Odometer: 4201 km  
 Engine Capacity: 150 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 80/80 R17 Rear Tyre Size: 120/70 R17  
 Front Left Side: Platinum 5 mm Rear Left Side: Platinum 5 mm  
 Front Right Side: Platinum 5 mm Rear Right Side: Platinum 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,027.70	3,454.70	4,573.00	56.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,820.00	780.00	1,040.00	57.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,847.70</b>	<b>4,234.70</b>	<b>5,613.00</b>	<b>57.00</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,400.00</b>		
(S\$)	9,847.70	3,400.00	6,447.70	65.47
<b>+ GST 7.00/7.00% (S\$)</b>	689.34	238.00	451.34	65.47
<b>Nett Amount (S\$)</b>	<b>10,537.04</b>	<b>3,638.00</b>	<b>6,899.04</b>	<b>65.47</b>
<b>+ Loss of Use (5.0 x S\$40.00/day) (S\$)</b>		200.00		
<b>Nett Liability (S\$)</b>		<b>3,838.00</b>		

### INSPECTION

Date of Assignment: 19/09/2018  
 Date Inspected: 20/09/2018 Inspected At: Bike Production Pte Ltd (HQ)  
 610 SERANGOON ROAD  
 Singapore 218216  
 Estimated Period of Repair: 3.0 days

---

**Adjuster:** Muhammad Nazril Bin Abdullah**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 03 Dec 2018)	
<b>Parts:</b>	N/A	YAMAHA SNIPER T150 150cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBM9230B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DISK	Serviceable	205.00 FL	*- FL
2	1		*FRONT WHEEL AXLE	Serviceable	95.00 FL	*- FL
3	1		*FRONT MUDGUARD	Scratched	195.00 FL	*140.00 FL
4	1		*LEFT FORK ASSEMBLY	Serviceable	750.00 FL	*- FL
5	1		*RGHT FORK ASSEMBLY	Serviceable	750.00 FL	*- FL
6	1		*HEADLIGHT COVER EMBLEM	Scratched	45.00 FL	*45.00 FL
7	1		*HEADLIGHT COVER	Scratched	145.00 FL	*145.00 FL
8	1		*HEADLIGHT ASSY	Scratched	450.00 FL	*280.00 FL
9	1		*FRONT FAIRING COVER	Cracked	330.00 FL	*330.00 FL
10	1		*LEFT FAIRING ASSEMBLY	Cracked	225.00 FL	*225.00 FL
11	1		*FAIRING EMBLEM	Necessary	20.00 FL	*20.00 FL
12	2		*STEERING STEM BEARING	Necessary	90.00 FL	*60.00 FL
13	1		*STEERING STEM BRACKET ASSEMBLY	Serviceable	350.00 FL	*- FL
14	1		*STEERING STEM UNDERBRACKET	Serviceable	350.00 FL	*- FL
15	1		*HANDLE BAR	Bent	165.00 FL	*110.00 FL
16	1		*CLUTCH LEVER	Scratched	45.00 FL	*45.00 FL
17	1		*LEFT VIEW MIRROR	Missing	70.00 FL	*70.00 FL
18	1		*LEFT BALANCER	Scratched	45.00 FL	*45.00 FL
19	1		*LEFT REAR SIGNAL	Dislodged	85.00 FL	*85.00 FL
20	1		*LEFT ENGINE COVER	Repair	390.00 FL	*- FL
21	1		*LEFT ENGIEN COVER GASKET	Necessary	55.00 FL	*20.00 FL
22	1		*LEFT FRONT FOOTREST HOLDER ASSEMBLY	Bent	255.00 FL	*170.00 FL
23	1		*MAIN STAND	Serviceable	200.00 FL	*- FL
24	1		*LEFT FRONT FOOTREST	Scratched	45.00 FL	*45.00 FL
25	1		*GEAR PEDAL ASSEMBLY	Scratched	145.00 FL	*145.00 FL
26	1		*REAR SWING ARM ASSY	Bent	330.00 FL	*330.00 FL
27	1		*REAR WHEEL AXLE	Dented	95.00 FL	*95.00 FL
28	1		*CHAIN GUARD	Bent	55.00 FL	*55.00 FL
29	1		*LEFT REAR COVER	Scratched	220.00 FL	*200.00 FL
30	1		*REAR HANDLE	Scratched	50.00 FL	*50.00 FL
31	1		*MAINSTAND	Serviceable	145.00 FL	*- FL
32	1		*SIDE STAND	Serviceable	65.00 FL	*- FL
33	1		*FRONT SPORT RIM	Serviceable	480.00 FS	*- FS
34	1		*REAR SPORT RIM	Scratched	157.00 FS	*157.00 FS
35	1		*REAR TYRE	Not Necessary	330.00 FS	*- FS
36	1		*ENGINE OIL	Necessary	330.00 FS	*100.00 FS
37	1		*FRONT NUMBER PLATE	Necessary	20.00 FS	*20.00 FS
38	1		*REAR NUMBER PLATE	Cracked	30.00 FS	*25.00 FS
39	1		*HEADLIGHT BLACK COVER	Bent	125.00 FL	*125.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*INNER METER COVER	Scratched	115.00 FL	*115.00 FL
41	1		*REAR BRAKE DISK	Bent	185.00 FL	*90.00 FL
42	1		*CHAIN ADJUSTER	Bent	88.00 FL	*88.00 FL
43	1		*REAR FENDER	Bent	255.00 FL	*255.00 FL
44	1		*REAR WHEEL HUB	Necessary	195.00 FL	*120.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>8,770.00</b>	<b>3,805.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	<b>742.30</b>	<b>350.30</b>

<b>Total Parts (S\$)</b>	<b>8,027.70</b>	<b>3,454.70</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING CHARGES	New	80.00	80.00
2	DISMANTLE ,REOKACE ,REALIGN AND ADJUST ABOVE DAMAGED PARTS	New	700.00	300.00
3	TO KNOCK ,STRAIGHTEN CHASSIS & BODY BALANCING	New	380.00	150.00
4	TO REMOVE/REFIT ,REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES	New	180.00	0.00
5	TO REMOVE /REFIT ,REPLACE (IF DAMAGE) CHECK AND REPLACE REAR SPORT RIM	New	180.00	50.00
6	SPRAY PAINTING	New	300.00	200.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,820.00</b>	<b>780.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >