

Vehicle Registration Number

SGU698T


Vehicle Make/Model/Colour

Name of Driver

Insurance Company Name

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON. 7-8-2018 @ 06.45 hr I VEH A
 was driving along the above location..
 I. Suddenly VEH B slow down and
 stop I VEH A cannot stop in time
 I manage VEH A stop due to the road was
 wet and it stuck and hit VEH B Rear.
 no passing on VEH B..

DECLARATION

I/We declare the foregoing particulars are true in every respect.

OMFORT TRANSPORTATION P.I. =
 CO REG NO 109303821R

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)

Reporting Centre Personnel's Signature
 Name:

Sketch Plan Pg. 2

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE. LTD.
CO. REG. NO. 199701221P

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


Accident Photo



Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo





**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-131431
Date of Request: 27/08/2018

Your Ref No: INS-D11-107584-18-ER

VISION LAW LLC
133 New Bridge Road #18-01/02
Chinatown Point
Singapore 059413

Dear Sir/Madam,

Date of Accident: 07/08/2018
Vehicle No: SGU698T
Place of Accident: SIMS AVE > LOR 1 GEYLANG
Involving Vehicle No: SHC3945T

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SHC3945T	SIMS AVE > LOR 1 GEYLANG	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

GIRO Cash Cheque



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
 6 Raffles Quay #18-00, Singapore 048580
 Phone: +65 6224 0010 Fax: +65 6224 0030
 Operating Hours: Monday to Friday 9am to 5pm
 GST Registration No: M400017735

SEARCH RESULTS

Our Ref No: GR-18-131427
 Date of Request: 27/08/2018

Your Ref No: INS-D11-107584-18-ER

VISION LAW LLC
 133 New Bridge Road #18-01/02
 Chinatown Point
 Singapore 059413

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 07/08/2018
 Place of Accident: SIMS AVENUE
 Client Vehicle No: SGU698T

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
SHC3945T	KALLANG RD TWDS SIMS AVE	07/08/2018 06:45

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



**GENERAL
INSURANCE
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-131427
Date of Request: 27/08/2018

Your Ref No: INS-D11-107584-18-ER

VISION LAW LLC
133 New Bridge Road #18-01/02
Chinatown Point
Singapore 059413

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 07/08/2018
Place of Accident: SIMS AVENUE
Client Vehicle No: SGU698T

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

GIRO Cash Cheque

Enquire Vehicle & Owner Information (Vehicle No. SHC3945T As At 07 Aug 2018 / 07:05:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: D11

Current Owner Details

Owner ID Type: Company

Owner ID: 199303821R

Owner Name: COMFORT TRANSPORTATION PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 383

Registered Street Name: SIN MING DRIVE

Registered Unit No.: -

Registered Building Name: GAS BUILDING

Registered Postal Code: 575717

Current Vehicle Details

Vehicle No.: SHC3945T

Make Description/Model: HYUNDAI / I40 1.7L CRDI AT ABS AIRBAG 4DR

Insurance Company Name: INDIA INT'L INS PTE LTD



Bik 9002 Tampines Street 93 #01-72 Tampines Ind. Park A Singapore 528836

Tel: 6784 0602 Fax: 6787 0105

Email: derrickmotor@gmail.com

Name : Lim Chun Khim
Address : c/o Blk 9002 Tampines Street 93
#01-72 Tampines Ind Park A
Singapore 528836

Date : 23-Aug-18

Model : Mercedes Benz C180

Final repair bill for **Mercedes Benz C180** no. **SGU 698 T**

To supply and replace parts, labour charges for
repairing, knocking, welding and to respray painting
(Lump Sum Repair)

\$ 6,400.00

Dollars : Six Thousand Four Hundred Only

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Billing Name & Address

Lim Chun Khim
c/o Blk 9002 Tampines Street 93
#01-72 Tampines Ind Park A
Singapore 528836

Invoice No 08-18006/DY

Date 23 Aug 2018

Vehicle No : SGU 698 T

Model : Mercedes Benz C180

Item	Descriptions	Amount S\$
1	Date of inspection : <u>8 Aug 2018</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Purchase of films, develop negatives - Storage of negatives - Submission of photographs <u>78</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 678.00</u>
	SDLS : SIX HUNDRED AND SEVENTY-EIGHT ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Pal's Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O E

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference : **TP / 08-18006/DY / 2018**
Date of Report : **23 Aug 2018**

Lim Chun Khim
c/o Blk 9002 Tampines Street 93
#01-72 Tampines Ind Park A
Singapore 528836

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 7 Aug 2018

As per your instruction dated **8 Aug 2018** with regard to the above matter. We have carried out a physical inspection on the said vehicle **SGU 698 T**. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SGU 698 T
Model : Mercedes Benz C180
Year / Capacity : 2013/1595
Chassis No : WDD2043312G063561
Engine No : 27491030036439
Mileage : 88369
Colour : White

2. TYRES CONDITION

		<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	: 225/45 R17	Michelin	6.00	mm	Sport
REAR	O/S	: 225/45 R17	Michelin	6.00	mm	Sport
FRONT	N/S	: 225/45 R17	Michelin	6.00	mm	Sport
REAR	N/S	: 225/45 R17	Michelin	6.00	mm	Sport

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Derrick Motor Works
Blk 9002 Tampines Street 93
#01-72 Tampines Ind Park A
Singapore 528836
5. Estimated normal period of repair : 5 working days to complete.
6. Enclosed number of photograph : 78 copies.
7. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
8. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: **SGU 698 T**
 Report No: **TP/ 08-18006/DY / 2018**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
	<u>Nett Items</u>			
1	Boot lid	Repair	\$ 1485.00	\$
1	Rear taillamp	Damage	\$ 426.00	\$ ✓ 426.00 CRV
1	Rear taillamp lower bracket	Damage	\$ 42.00	\$ ✓ 42.00 CRV
1	Rear taillamp side cover	Damage	\$ 32.00	\$ ✓ 32.00 CRV
1	Rear end panel	Damage	\$ 805.00	\$ 805.00 RX
1	Rear end panel inner garnish	Damage	\$ 123.00	\$ 123.00 BRV
1	Rear bumper	Damage	\$ 1422.00	\$ ✓ 1422.00 DDV
1	Rear bumper chrome moulding - centre	Damage	\$ 248.00	\$ ✓ 248.00 SCR
1	Rear bumper reinforcement	Damage	\$ 665.00	\$ ✓ 665.00 BTV
3	Rear bumper reverse sensors	Damage	\$ 714.00	\$ 240.00 714.00 SCR
1	Rear exhaust silencer	Damage	\$ 1428.00	\$ 1428.00
2	Rear exhaust silencer mountings	Necessary	\$ 56.00	\$ 56.00
1	Rear exhaust silencer chrome tail pipe	Damage	\$ 105.00	\$ 105.00 } NWX
			<u>\$ 7551.00</u>	<u>\$ 6066.00</u>

Spare Parts Total \$ 7551.00 \$ 6066.00

Vehicle No: **SGU 698 T**
 Report No: **TP/ 08-18006/DY / 2018**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 7551.00	\$ 6066.00
1	To disconnect and reconnect, check electrical wiring, harness wires, sockets, replace damaged parts.	\$ 50.00	\$ 40.00
2	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 110.00	\$ 80.00
3	To remove and refit rear bumper sensor.	\$ 200.00	\$ 120.00 ^{60.00}
4	To remove and refit, straighten and re-adjust exhaust pipe and replace rear exhaust silencer and mountings.	\$ 200.00	\$ 120.00 ^{80.00} X
5	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 900.00	\$ 750.00 ^{400.00}
6	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 900.00	\$ 750.00 ^{400.00}
7	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 110.00	\$ 60.00
Total		<u>\$ 10021.00</u>	<u>\$ 7986.00</u>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 6400.00

SDLS: SIX THOUSAND FOUR HUNDRED ONLY


 Qualified Appraiser

Repair days 4.

TGGM
 ML
 21/9/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III18014453/Bvbs2-1

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 26-09-2018



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3945T	Veh. Inspected	SGU 698T
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT18080200	Excess (\$)	0.00
Assign From	JOEL NAH	Assign Date	18/09/2018

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WDD2043312G063561	Colour	WHITE
Odometer	88387	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45ZR17	MICHELIN	6 mm
L/H Front Tyre	225/45ZR17	MICHELIN	6 mm
R/H Rear Tyre	225/45ZR17	MICHELIN	6 mm
L/H Rear Tyre	225/45ZR17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/08/2018	Inspection Date	10/08/2018
Survey held at	DERRICK MOTOR WORKS BLK 9002 #01-72 TAMPINES ST 93 SINGAPORE 528836		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGU 698T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOT LID (N)	TO REPAIR SEE LABOUR	1,485.00	-
1	REAR TAILLAMP (N)	CRACKED	426.00	426.00
1	REAR TAILLAMP LOWER BRACKET (N)	CRACKED	42.00	42.00
1	REAR TAILLAMP SIDE COVER (N)	CRACKED	32.00	32.00
1	REAR END PANEL (N)	TO REPAIR SEE LABOUR	805.00	-
1	REAR END PANEL INNER GARNISH (N)	BROKEN	123.00	123.00
1	REAR BUMPER (N)	DENTED	1,422.00	1,422.00
1	REAR BUMPER CHROME MOULDING - CENTRE (N)	SCRATCHED	248.00	248.00
1	REAR BUMPER REINFORCEMENT (N)	BENT	665.00	665.00
3	REAR BUMPER REVERSE SENSORS (N)	SCRATCHED	714.00	240.00
1	REAR EXHAUST SILENCER (N)	NOT NECESSARY	1,428.00	-
2	REAR EXHAUST SILENCER MOUNTINGS (N)	NOT NECESSARY	56.00	-
1	REAR EXHAUST SILENCER CHROME TAIL PIPE (N)	NOT NECESSARY	105.00	-
	LESS 10% DISCOUNT		-	-319.80
			7,551.00	2,878.20
LABOUR				
	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING, HARNESS WIRES, SOCKETS, REPLACE DAMAGED PARTS.		50.00	40.00
	TO REMOVE AND REFIT INNER TRIMS, INNER GARNISHES, TO FACILITATE THE REPAIRS.		110.00	80.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		200.00	60.00
	TO REMOVE AND REFIT, STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REPLACE REAR EXHAUST SILENCER AND MOUNTINGS.	NOT NECESSARY	200.00	-
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF BOOT LID AND REAR END PANEL.		900.00	400.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		900.00	400.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		110.00	60.00
			2,470.00	1,040.00
GRAND TOTAL			10,021.00	3,918.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,150.00

Report Ref No. CS3/III18014453/Bvbs2-1

LIM TEOW GUAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.