



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

INDIA INTERNATIONAL INSURANCE PL	Ref : CS3/III18014453/Bvbs2-1
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711	Date : 26-09-2018
	Code : III2



**1. Policy Particulars :- THIRD PARTY CLAIM**

<b>Insured Veh.</b>	SHC 3945T	<b>Veh. Inspected</b>	SGU 698T
<b>Policy No.</b>	MCOM0015	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MCT18080200	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	JOEL NAH	<b>Assign Date</b>	18/09/2018

**2. Vehicle Particulars & Condition**

<b>Make &amp; Model</b>	MERCEDES BENZ C180	<b>c.c</b>	1595
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2013
<b>Chassis No.</b>	WDD2043312G063561	<b>Colour</b>	WHITE
<b>Odometer</b>	88387	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
<b>R/H Front Tyre</b>	225/45ZR17	MICHELIN	6 mm
<b>L/H Front Tyre</b>	225/45ZR17	MICHELIN	6 mm
<b>R/H Rear Tyre</b>	225/45ZR17	MICHELIN	6 mm
<b>L/H Rear Tyre</b>	225/45ZR17	MICHELIN	6 mm

**4. Description of Damages**

	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  DAMAGES SEE DETAILS.
--	--

**5. General Information**

<b>Accident Date</b>	07/08/2018	<b>Inspection Date</b>	10/08/2018
<b>Survey held at</b>	DERRICK MOTOR WORKS BLK 9002 #01-72 TAMPINES ST 93 SINGAPORE 528836		

**5a. Remarks**

	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--	--

**5b. Estimate Days of Repair**

	ESTIMATED NORMAL PERIOD FOR REPAIR: <b>4 Working Days</b>
--	---