



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 171C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	PNL COMPL DR R WLH (N) (CONSISTENT)	BENT	888.00	888.00
1	WSTR OUT DR R WLH (N) (CONSISTENT)	NECESSARY	121.72	121.72
1	WSTR DR R W LH (N) (CONSISTENT)	NECESSARY	156.49	156.49
1	COVER B PLR AY R LH (N) (CONSISTENT)	NECESSARY	25.92	25.92
1	COVER C PLR AY R LH (N) (CONSISTENT)	NECESSARY	22.36	22.36
1	TAPE DR SASH R M WLH (N) (CONSISTENT)	NECESSARY	7.45	7.45
1	SD SPOILER LH (SKIRT) (N) (CONSISTENT)	NOT NECESSARY	612.00	-
	LESS 20% DISCOUNT		-366.79	-244.39
			1,467.15	977.55
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	100.00	20.00
			100.00	20.00
	<b><u>LABOUR</u></b>			
	REPLACE REAR LHS DOOR PANEL AND RELATED DOOR TAPE ,REPLACE LHS SIDE SKIRT.		1,160.00	840.00
	RESPRAY REAR LHS DOOR PANEL AND LHS SIDE SKIRT .		960.00	920.00
			2,120.00	1,760.00
	<b>GRAND TOTAL</b>		<b>3,687.15</b>	<b>2,757.55</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>2,757.55</b>

Report Ref No. CC4/ASM18017054/T1ga3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.