

Trans-cab Auto Services Pte Ltd

AAD1809-140

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 272R

Not Notified
Resumy Bepaint

| | |
|-----------------------|-------------------|
| Vehicle No.: | SHD 272R |
| Chassis No.: | VF1ABL15AUC282421 |
| Vehicle Make: | RENAULT |
| Vehicle Model: | LATITUDE |
| Date of Accident : | 14.9.2018 |
| Third Party Insurer : | AXA |

| PART | LIST |
|-------------------------------|----------------------------|
| 1 DOOR PANEL FRT LH | \$ <i>B</i> 2,844.66 ✓ |
| 1 DOOR HINGE UPPER LH | \$ <i>n</i> 261.28 |
| 1 DOOR HINGE LOWER LH | \$ <i>n</i> 300.55 |
| 1 DOOR CHECK FRT LH | \$ <i>Sn</i> 194.77 |
| 1 DOOR LOCK FRT LH | \$ <i>n</i> 908.75 |
| 1 DOOR CATCH FRT LH | \$ <i>Sn</i> 131.23 |
| 1 DOOR HANDLE OUTER FRT LH | \$ <i>Sn</i> 477.76 |
| 1 DOOR HANDLE COVER FRT LH | \$ <i>Sn</i> 13.22 |
| 1 DOOR HANDLE MODULE FRT LH | \$ <i>Sn</i> 133.60 |
| 1 DOOR REGULATOR FRT LH | \$ <i>B</i> 505.19 |
| 1 DOOR REGUALTOR MOTOR FRT LH | \$ <i>n</i> 796.46 |
| 1 DOOR REGULATOR GUIDE FRT LH | \$ <i>Sn</i> 120.97 |
| 1 DOOR MIRROR ASSY LH | \$ <i>Bro</i> 1,483.40 ✓ |
| 1 DOOR METAL CHROME | \$ <i>Not</i> 90.70 ✓ |
| 1 DOOR FINISHER INNER FRT RH | \$ <i>Sn</i> 323.44 X |
| 1 DOOR MOULDING FRT RH | \$ <i>Sn</i> 176.82 X |
| 1 DOOR GLASS FRT LH | \$ <i>Shotton</i> 625.96 ✓ |
| | <hr/> |
| | \$ 9,388.77 |
| 10% | \$ 938.88 |
| | <hr/> |
| | \$ 8,449.89 |

Specical Nett

| | |
|----------------------------------|--------------------------------|
| 1 FRONT DOOR STICKER 'Trans-cab' | \$ <i>na</i> 80.00 <i>60sn</i> |
| 1 FRONT DOOR STICKER 'Chassis' | \$ <i>na</i> 50.00 <i>30sn</i> |
| 1 DOOR CHECK BOLT | \$ <i>na</i> 22.69 X |
| 1 DOOR GUIDE SCREW | \$ <i>na</i> 10.85 X |
| 1 DOOR HINGE BOLT | \$ <i>na</i> 10.85 X |

Trans-cab Auto Services Pte Ltd

AAD1809-140

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 272R

| | | | | |
|---|-----------------------|----|----------|---|
| 1 | DOOR HINGE NUT RH | \$ | SH 14.60 | X |
| 1 | DOOR CHECK BOLT | \$ | SH 22.69 | X |
| 1 | DOOR CHECK NUT | \$ | SH 3.75 | X |
| 1 | DOOR LOCK SCREW L70Y | \$ | SH 6.12 | X |
| 1 | DOOR CATCH SCREW L70Y | \$ | SH 10.06 | X |

| | | |
|--------------|-----------|---------------|
| TOTAL | \$ | 231.63 |
|--------------|-----------|---------------|

| | | |
|--------------------|-----------|-----------------|
| TOTAL PARTS | \$ | 8,681.52 |
|--------------------|-----------|-----------------|

LABOUR

| | | |
|---|----|----------------------------------|
| Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | \$ | 2501 2801 3,000.00 |
| Putty and spray painting of the affected portion. | \$ | 3,000.00 2801 |
| To rust-proofing of the affected areas. | \$ | 170.00 301 |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. | \$ | nn 380.00 X |
| To check steering geometry and computer wheel alignment | \$ | nn 220.00 X |
| To transfer of front bumper fittings, attachment and perform water seepage test. | \$ | nn 380.00 X |
| To transfer of tire, rim and on wheel balancing. | \$ | nn 170.00 X |
| To Check Electrical Lighting Concerned. | \$ | 170.00 201 |
| To transfer of front fender fittings, attachment and perform water seepage test. | \$ | SH 380.00 X |
| To transfer of front door fittings, attachment and perform water seepage test. | \$ | 380.00 601 |

Trans-cab Auto Services Pte Ltd

AAD1809-140

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 272R

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.

\$ *nn* 380.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *nn* 380.00 X

TOTAL \$ 9,010.00

Over All Total \$ 17,691.52

LUMP SUM (REPAIR DAY)

10 DAYS

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: