



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18017064/T1sd3e2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 16-01-2019



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SHD 8879M	<b>Veh. Inspected</b>	SMD 1733L
<b>Policy No.</b>	D-18088937MFSH	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	D18006901MFSH	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	LURENE JAW	<b>Assign Date</b>	19/09/2018

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA ALPHARD	<b>c.c</b>	2494
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2018
<b>Chassis No.</b>	JTNGF3DH708015607	<b>Colour</b>	BLACK
<b>Odometer</b>	4593	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	235/50 R18	TOYO	6 mm
<b>L/H Front Tyre</b>	235/50 R18	TOYO	6 mm
<b>R/H Rear Tyre</b>	235/50 R18	TOYO	6 mm
<b>L/H Rear Tyre</b>	235/50 R18	TOYO	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	16/09/2018	<b>Inspection Date</b>	26/09/2018
<b>Survey held at</b>	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705		

### 5a. Remarks

A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS.  
 B)DAMAGES CONSISTENT TO ACCIDENT REPORT.  
 C)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
 D)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**