

ESTIMATE RC AUTO

*Not Authorized
1/1mp & ?
Recovery After Paint
8 days*

Blk 18, Sin Ming Industrial Estate Sector A #01-43, Singapore 575676
Tel : 97619383 Email: engshing@hotmail.sg
Reg. No. 53199168K

SJK 8798 C

Date : 18/9/2018

Quantity	Description/Particular	Unit Price	Amount	
1 pc	Rear Tailgate	B ₁ \$	1515	50 ✓
1 pc	Rear Bumper	B ₁ \$	588	70 ✓
1 pc	Rear Bootlid Emblem	M ₁ \$	57	00 ✓
2 pcs	Rear Bumper Retainer@42	NIS D.V \$	84	00 ✓
2 pcs	Rear Bumper bracket@55	NIS B ₁ \$	110	00 ✓
1 pc	Rear Panel	\$ B ₁	566	00 ✓
1 pc	Rear valvematic emblem	M ₁ \$	31	00 ✓
1 pc	Rear Tailgate Inner Ganish	\$	433	00 ?
1 PC	Rear Tailgate reflector	\$	290	00 ?
1 pc	Rear Lamp	\$	380	00 ?
1 pc	Rear Bootlid lock	M ₁ \$	322	00 ✓
1 pc	Rear Bootlid rubber	D ₁ M ₁ \$	170	00 50% ✓
1 pc	Rear FENDER	\$ B ₁	890	20 ✓
		TOTAL \$	5437	40
		LESS 30	3806	18
	Spray painting(pearl)		800	00 ✓
	Reverse sensor	M ₁	250	00 200% ✓
	ANTI RUST		80	00 ✓

Received the above goods in good order and condition

for RC AUTO

Received by

E.&.O.E.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

RC AUTO

Blk 18, Sin Ming Industrial Estate Sector A #01-43, Singapore 575676

Tel : 6458 8878 Fax : 6458 2246

Reg. No. 53199168K

SJK 8798 C

Date : 18/9/2018

Quantity	Description/Particular	Unit Price	Amount	
	To install tailgate accessories		80	00
	To replace above parts		800	00
		Total \$	5816	18
		\$	288	00

Received the above goods in good order and condition

for RC AUTO

Received by

E.&O.E.

Authorised Signature