

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8339K

DATE 17/9/2018 14:18

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper			\$ 553.00	
	Rear Bumper Clip 10 pcs			\$ 22.00	
	<i>Rear Tail lamp (RH)</i>				
	SUB TOTAL			\$ 575.00	
	LESS 20%			\$ 115.00	
	DISCOUNTED TOTAL			\$ 460.00	
	Rear Bumper Rubber Mat			\$ 50.00	Nett
	Rear Bumper Advertisement Logo			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00	Nett
				\$ 300.00	
	Labour Charge				
	Panel Beating			\$ 350.00	
	Spray Painting Charge			\$ 250.00	200
	Wiring Charge			\$ 50.00	20
	Remove/Refix Reverse Sensor			\$ 120.00	30
	TOTAL LABOUR			\$ 770.00	
	ESTIMATE TOTAL			\$ 1,530.00	
<i>18/9/18 10506</i> <i>200</i> <i>40</i> <i>After Repair photo</i> KK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					