

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 7662B

DATE 18/9/2018 13:16

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>X repair</i>			\$ 553.00
	Rear Bumper Reinforcement <i>X su</i>			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) <i>X su</i>		\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs <i>X su</i>			\$ 22.00
	Rear Bumper Bracket <i>X su</i>		\$ 35.60	\$ 71.20
	Rear Bumper Sponge <i>X su</i>			\$ 103.50
	Rear Bumper Under Cover <i>X su</i>			\$ 228.00
	SUB TOTAL			\$ 1,566.70
	LESS 20%			\$ 313.34
	DISCOUNTED TOTAL			\$ 1,253.36
	Rear Bumper Rubber Mat <i>X su</i>			\$ 50.00
	Rear Bumper Advertisement Logo <i>su</i>			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) <i>su</i>		\$ 100.00	\$ 200.00
	Rear Bumper Reverse Sensor <i>X su</i>			\$ 135.70
				\$ 435.70
	Labour Charge			
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 250.00
	Wiring Charge			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 770.00
	ESTIMATE TOTAL			\$ 2,459.06

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to "no prejudice" basis
- Third party survey is on a "no prejudice" basis
- No illegal modification is allowed
- Supplementary work must be approved and subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kalvin LKK/
19/9/18 1030h
2 hrs
4/5
After Repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.