

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

No. : 30036

Vehicle Insured : SJC 2913 T
Accident Date : 17-Sep-2018

Date : 17-Sep-2018

Our Ref : 180594 (FWD) / SHUMAN

PAGE : 1

CDS CAR RENTAL PTE LTD
Singapore

ESTIMATED COST OF REPAIR FOR TOYOTA HIACE DIESEL 2986cc (2004) GX4708G
=====

1 pc tailgate	R 1,305.00	✓
1 pc tailgate lock	Tr 235.00	✓
1 pc tailgate lock catch	DI 55.00	✓
1 pc tailgate weatherstrip	295.00	?
1 pc tailgate glass rubber	Na 345.00	50km
1 pc tailgate logo	Na 60.00	✓
1 pc rear bumper	Bu 568.00	✓
2 pcs rear bumper side bracket (lh/rh)	@ S\$ 20.00 DI 40.00	✓
8 pcs rear bumper clips	@ S\$ 5.00 Na 40.00	✓
1 pc rear bumper centre beam	R 260.00	✓
1 pc rear end panel-outer	Na 385.00	✓
1 pc rear end panel top moulding	75.00	?
2 pcs rear bumper lower bracket	@ S\$115.00 230.00	?
	3,893.00	
	Less 25% : -973.25	
	2,919.75	
1 pc tailgate '70km/h' sticker	Na 25.00	15km
1 pc tailgate '6pax' sticker	Na 25.00	sn 15km
1 pc reverse sensor assy	CM 200.00	sn
To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.	800.00	600
To remove and refit reverse sensor assy.	60.00	50

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a Without Prejudice basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 2 ...



CO. REG. NO: 199402370D

GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : SJC 2913 T
Our Ref : 180594

Page : 2
No. : 30036

To remove and refit rear windscreen
glass and conduct water leak test

120.00 *bol*

To transfer tailgate's fittings

80.00 *bol*

To putty and respray on affected
portions.

800.00 *500*

Total : S\$ 5,049.75
=====

Singapore Dollars Five Thousand and Forty Nine
and Cents Seventy Five Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.