

SFV8/61D

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No.	: b1 48453	Page No. : 1 of 5
Date Estimated	: 17/09/2018	
Prepared By	: Han Kwan Yong	

- ESTIMATE REPAIR FOR - Tan Wan Chye 4A Rochalie Drive Singapore 248261	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFV8161D	G764249	25/05/2017	740Li	0

DESCRIPTION	VALUE
To replace rear bumper & attachments, rear right fender, right trunk floor panel including to knock out dented area caused by the accident	No trunk - 5525 10,200.00 Repair Trunk - 7650 Replace Trunk - 8500 4284 4,766.00
To respray rear bumper, rear right fender, tail panel, right roof frame, right running board panel and boot compartment	451 531.00
To carry out body cavity preservation. (For cut panel).	photo 451 531.00
To remove and install fuel tank to facilitate repairs including extract fuel and conduct leak tests.	✓ 451 531.00
To supply and install rear windscreen solar film.	451 531.00
To check steering geometry and conduct wheel alignment according to BMW specification (1x)	80 94.00
To replace tyre and wheel rim including balancing. (1x).	451? 531.00
To remove and install wire harness, control units and battery at the rear section to facilitate panel replacement.	150 177.00
To check electrical wiring systems and lightings at the rear section for proper function.	? 150.00
Sundries.	
Total Labour 1:	18,042.00

DESCRIPTION	QTY	PRIC	VALUE
# ALLOY RIM 9.5X19 DOUBLE SPK	1	1,401.50	inf 1,401.50
HUB CAP WITH CHROME EDGE	1	35.75	? 35.75
# TRUNK FLOOR	1	290.45	? 290.45

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : **b1 48453**
Date Estimated : **17/09/2018**
Prepared By : **Han Kwan Yong**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFV8161D	G764249	25/05/2017	740Li	0

DESCRIPTION	QTY	PRIC	VALUE
# RR RH FENDER	1	2,721.50	bt ✓ 2,721.50
# Mount for SC	1	38.50	? 38.50
REAR BUMPER CENTRE GUIDE	1	51.50	? 51.50
# REAR RH MOUNT LATERAL	1	160.55	re ✓ 160.55
REAR RH MOULDING ROCKER PANEL	1	51.50	? 51.50
BUMPER GUARD REAR	1	102.95	? 102.95
RH RUBBER STRIP	1	85.05	? 85.05
REAR BUMPER COVER	1	107.05	x 107.05
REAR BUMPER PANEL PRIMED (PDC/PMA)	1	1,586.85	de ✓ 1,586.85
PLASTIC NUT	5	0.85	re ✓ 4.25
REAR WINDOW GREEN (ESG)	1	1,271.35	? 1,271.35
EXPANDING RIVET D=8MM	10	1.05	re ✓ 10.50
# RR RH WHEEL HOUSING COVER	1	180.00	? 180.00
REAR DIFFUSER	1	139.75	? 139.75
EXPANDING NUT	10	0.55	? 5.50
REAR RH REAR REFLECTOR	1	36.25	x 36.25
# REAR RH LIGHT IN TRUNK LID	1	473.65	? 473.65
# RH WATER CHANNEL	1	37.95	? 37.95
REAR RH LIGHT IN THE SIDE PANEL	1	735.95	one ✓ 735.95
DECOUPING RING PDC TORQUE CONVERTER	2	5.05	re ✓ 10.10
ULTRASONIC SENSOR MINERALWEISS(WA96	2	368.80	? 737.60
CAVITY PROTECTION WAX REMOVER 500ML	1	18.45	re ✓ 18.45
BLIND RIVET AVIBVLB	40	0.55	re ✓ 22.00
SCREW (SF PLUS M5X15)	10	0.55	re ✓ 5.50
(DG/SL) BODY ADHESIVE K5B (195ML)	1	281.55	re ✓ 281.55
PUNCH RIVET N5	10	0.55	re ✓ 5.50
(DG) BODYWORK ADHESIVE K5A (50ML)	1	118.35	re ✓ 118.35
(DG) CLEANER R1 (100ML)	1	26.15	re ✓ 26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	re ✓ 263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	re ✓ 27.85
(S/L) SEAM SEAL 300ML	3	33.80	re ✓ 101.40

Total Parts : 11,145.85

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No.	Claim No.
Date & Time 19/9/18 @ 1245	Excess \$
Surveyor's Name Tan Jiah	Sign
Surveyor's Tel 97498749	Authorised Yes / No
Authorised Date	Time
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No	PML Yes / No
Surveyor's E-mail tanjiah@khand.com	
No. of Working Days Recommend 10-14 days	

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplemental work(s) must be resurveyed and

is subject to final approval from Insurance Company

Total GST @ 7%

Acknowledged by Repairer

Signature: Grand Total

Date:

18,042.00

11,145.85

0.00

0.00

2,043.15

31,231.00

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **