



Bedok Motor Engineering Pte Ltd
 30, Defu Land 9, Singapore 539270
<http://www.bedokmotor.com>
enquire@bedokmotor.com
 6286 3032

Not Authorised
Lila
marcus
21/9/18
2 hep. At the top
1/5 = 270sf
Hdy.

Estimate To Repair CB6375H TOYOTA HIACE VAN
 Chassis No : LH172-0046912

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
1	1pc	Front door R/h <i>Bed</i>	\$ 1,459.40
2	1pc	Front door hinge top <i>17</i>	\$ 124.70
3	1pc	Front door hinge bottom <i>17</i>	\$ 124.70
4	1pc	Front door checker <i>17</i>	\$ 165.10
5	1pc	Front door weatherstrip <i>neu</i>	\$ 244.50
6	1pc	Front door step garnish <i>70-11</i>	\$ 168.00
7	1pc	Front door step panel <i>Bed</i>	\$ 124.00
8	1pc	Front door power window motor <i>17</i>	\$ 299.70
9	1pc	Front door regulator <i>17</i>	\$ 161.70
10	1pc	Front bumper <i>CU7</i>	\$ 488.70
11	1pc	Front bumper side retainer <i>neu</i>	\$ 120.00
12	1pc	Head lamp R/h <i>17</i>	\$ 579.00
13	1pc	Side lamp R/h <i>neu</i>	\$ 193.70
14	1pc	Front Indication light <i>neu</i>	\$ 153.10
15	1pc	Front door window glass channel weatherstrip <i>17</i>	\$ 396.70
			\$ 4,803.00
			Less 25%
			\$ 1,200.75
			\$ 3,602.25
<u>SPECIAL NETT ITEAMS</u>			
16	1pc	Front door school bus sticker <i>neu</i>	\$ 30.00
			\$ 30.00
<u>LABOUR & MISC CHARGE</u>			
1		Panel beating.	\$ 800.00
2		Spray painting.	\$ 700.00
3		Check lighting and focussing of head lamp.	\$ 60.00
4		Rust proof the affected.	\$ 150.00
			\$ 1,710.00
Total			\$ 5,342.25

2951.4
2213.55
500
600
20
30

Bedok Motor Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To inspect damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: