

Motor Accident Advice Form Pg. 1



中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #10-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.ag.chinataiping.com
Co. Reg. No. 200208384E

MOTOR ACCIDENT ADVICE FORM (Applicable to Windscreen Claim)					
Agency	Vitesse Solutions			Claim No	
1) PARTICULARS OF INSURED					
Name	Ng Sik Suan		Policy No	DMPCSN3086821702	
Address	4 Kingsmead Road			Contact Nos (H) (HP)	9001 8361
Occupation	Director of Special Projects	Registration No	SJZ 6296T	Make	Mercedes Benz E250
Year Model	2010	C.C./ Tonnage	1796	Amount Insured	
2) ACCIDENT INFORMATION					
Date of Accident	15 September 2018			Time	0630
Place	Coronation Road, just after Prince Road			Approximate Speed	40-45km/h
Name of Police Station Reported To	NA				
3) PARTICULARS OF DRIVER					
Name of Person driving your vehicle	Valerie Ng Zhi-Yan	Age	31	Address	4 Kingsmead Road
Licence No	S8701665Z	Date of Expiry	NA	Relationship to owner	Daughter
If Assured was not driving, does driver own a motor vehicle? If so, please state:				Contact Nos	
Your Car No	Name of Insurance Co	Occupation of Driver		(H)	
SJZ 6296T	China Taiping	Doctor		(HP)	9456 7242
4) DETAILS OF DAMAGE TO YOUR VEHICLE					
Left-front rim and left-back rim damaged					
Left-back panel dented and boot cannot open					
5) DAMAGES TO THIRD PARTY PROPERTY					
a. Registration Number(s) and details of damage to the other vehicle(s) involved					
NA					
b. Any other property					
6) INJURY TO PERSONS					
Name		Address		Extend of Injury	
7) WITNESS					
Passenger's Name		Address		Other Witness Name	
8) Have you obtained an estimate for repair? If so, give name of repairers and amount of estimate.					
No liability attaches this Company UNLESS the vehicle is inspected after accident and the estimate for the cost repairs approved.					

Motor Accident Advice Form Pg. 2




中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #10-00 Springleaf Tower Singapore 079909
Tel: 6388 8111 Fax: 6222 1033
Website: www.sg.ontaiiping.com
Co. Reg. No. 200208394E

DETAIL OF ACCIDENT

PLEASE EXPLAIN CLEARLY THE CIRCUMSTANCES UNDER WHICH THE ACCIDENT TOOK PLACE.

SKETCH:



15 September around 6:30 a.m. I was driving along Coronation Road, just after Prince Road, where there is a right-hand bend.

As I turned the bend, a stray animal suddenly dashed across the road.

To avoid hitting it, I swerved to the left and my left front tyre hit the curb and I mounted the curb.

At this moment, I steered back onto the road, and the left back of my car hit a tree in the process.

NOTE:- Every communication you receive in connection with this matter should be forwarded to the Company without delay.

DATA PRIVACY STATEMENT

In accordance with the Personal Data Protection Act 2012, I consent to the collection, use, disclosure of and/or process of my personal data (whether contained in the Claim Form or otherwise obtained) by China Taiping Insurance (Singapore) Pte Ltd, its affiliates and service providers (within or outside Singapore), for the purpose relating to the evaluation of the claim and to provide advice and information relating to the claim to me by Short Message Service (SMS), Multimedia Messaging Service (MMS) and fax messages (notwithstanding the registration of my telephone or mobile number in the Singapore's Do Not Call Registry)

Yes, I have read and agreed to the above Data Privacy Statement.

Signature of Claimant

Name:
NRIC/FIN/Passport No

17 September 2018

Date

Insured Signature

Driver Signature

FOR OFFICE USE ONLY

NAMED DRIVERS:-

- a. _____
- b. _____
- c. _____
- d. _____

ENDORSEMENTS:-

- a. _____
- b. _____
- c. _____

PERIOD OF INSURANCE:-

FROM: _____ TO: _____

EXCESS:-

- a. Section I :-
- Section II :-
- b. Unnamed Driver :-
- TOTAL =
- NO CLAIM BONUS =



Mercedes-Benz

Cycle
Industri
Authoris
Compar
GST Reg

ESTIMATE FOR SJZ6296T

Mr NG SIK SUAN
 4 Kingsmead Road
 Singapore 267959
 Mobile: 90018361

Vehicle & Document
 WIP No 26912
 Reg No/Reg Date SJZ6296T / 15/
 Date In/Mileage 0th
 Chassis No SWDD2120472A34
 Engine No 27186030157361
 Make/Model MB/E 250 CGI SEDAI
 Colour/Trim 024 497 Cuprite Bl

Account No	Terms	Date/Time Printed	CSE	Operator	
CSM00128	Cash	17/09/2018/ 13:53	K0	305 / Alan Quek A1 Lun	
Description of Goods / Services				Qty	Unit

Z REQUEST
 Customer Request
 MBPNSUN

THIS IS NOT AN OFFICIAL TAX ESTIMATE

POLICY NO/ACC DATE : // 14/09/2018
 TOWED IN/EXCESS : 15/09/2018 //
 DATE IN/DATE SURVEY:
 BY/AUTHORIZED ON :

- A BPILAB STRAIGHTEN, REMOVE SUPPORT ASSY FROM FRAME IMPACT DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.
- A BPIRES RESPRAY FRONT BUMPER, LH/ RUNNING BOARD, LH/ REAR DOOR, LH/ REAR FENDER, BOOT LID, REAR BUMPER, END PANEL & LH/ WHEELHOUSE.
- A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT
- A BPILAB PLACE VEHICLE ON-TO CELLETTE BENCH & CONDUCT CHASSIS ALIGNMENT. NETT
- A BPILAB CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT
- A BPILAB REMOVE & INSTALL INTERIOR SEATS, CARPET, GARNISH UNHOLSTRY ETC FOR NECESSARY REPAIR.
- A BPILAB REMOVE & REPLACE REAR GLASS WITH INSTALL . NETT
- A BPILAB REMOVE CARRIAGE ASSY FROM FRAME, IMPACT.REPLACE AND ASSEMBLE WHEEL BAS FRONT PORTION
- A BPILAB REMOVE CARRIAGE ASSY FROM FRAME, IMPACT.REPLACE AND ASSEMBLE WHEEL BAS REAR PORTION
- A BPILAB TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include work required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan I
 188 Pan
 Singapo
 Tel: 677
 Fax: 677
 www.me

Insurance Certificate Pg. 1



中国太平保險(新加坡)有限公司
 CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
 Co. Reg. No. 200206384E

MCLE
 R SN
 AN0421A
 Cov.Type: C

MOTOR PRIVATE CAR

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
 Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
 Road Transport Act, 1987 (Malaysia)
 Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

ORIGINAL

CERTIFICATE No.	DMPCSN3086821702	Engine No :27186030157361 ChaNo:WDD2120472A347221
1. Index Mark and Registration Number of Vehicle	SJZ6296T	AUTOSAFE *****
2. Name of Policy Holder	NG SIK SUAN	
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment	15 December 2017	Named Drivers Ex Sect. I \$5750.00 Additional Ex Other than Named Drivers: Ex Sect. I - Age <= 25..... \$53,000.00 Ex Sect. I - Age >= 26..... \$5500.00 * Age as at date of accident EX ON WINDSCREEN \$5100.00
4. Date of Expiry of Insurance	14 December 2018	
5. Persons or Classes of Persons entitled to drive*	(a) The Policyholder. (b) Any other person who is driving on the Policyholder's order or with his permission.	
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.		
6. Limitations as to use*	Use for social, domestic and pleasure purposes and for the Policyholder's business. The policy does not cover use for hire or reward tuition driving test racing pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade. Excess whichever is applicable for losses occurring outside Singapore (Constructive Total Loss/Theft) will be doubled. One time Waiver of Excess for the first \$51,000 will apply to the Insured and Named Drivers in the event of Own Damage Claim at our Authorised Workshops for each Policy Year.	
* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.		

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By: VITESSE SOLUTIONS
 Authorised Officer

Authorised Signatory

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8701665Z



Name
NG ZHI-YAN, VALERIE
(HUANG ZHIYAN)
黄智嫣

Race
CHINESE

Date of birth
22-01-1987

Country of birth
SINGAPORE

Sex
F




NRIC No. S8701665Z




Date of issue
18-08-2008

Address
4 KINGSMEAD ROAD
SINGAPORE 267959



Owner Driving Licence Pg. 1



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class	Description	PASS DATE
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	14 Aug 1979



NP 428A

Accident Photo





Merced

ESTIMATE FOR SJZ6296T

Mr NG SIK SUAN

4 Kingsmead Road
Singapore 267959

Mobile: 90018361

WIP No
Reg No/Reg Date
Date In/Mileage
Chassis No
Engine No
Make/Model
Colour/Trim

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	17/09/2018/ 13:53	KO	305 / Alan Quek A
Description of Goods / Services				

- M BPNSUN TRANSFER TRIM AND BALANCING 2 PCS TYRE NETT
- S BPNSUB SUPPLY & INSTALL 1 PC REAR GLASS SOLAR HUPER OPTIK FILM.NETT
- S BPNSUB SUPPLY 1 PC TYRE
- M FRONT BUMPER
- M LH/ RUNNING BOARD
- M LEFT REAR FENDER
- M LH/REAR FENDER INSIDE DAMPING
- M LH/REAR FENDER LINNING
- M LH/REAR FENDER AIR BREATHER
- M LH/REAR FENDER BOTTOM PANEL
- M LH/REAR FENDER INSULATION
- M LH/REAR LAMP BASE FIXTURE PANEL
- M LH/REAR WHEEL HOUSE DAMPING
- M BLIND RIVET
- M FENDER SCREW
- M SCREW
- M [STR] LEFT REAR TAIL LAMP
- M [STR] LH/R BOOT LID TAIL LAMP
- M REAR BUMPER
- M LH/REAR BUMPER GARNISH MOULDING
- M RH/R BUMPER GARNISH MOULDING
- M CTE REAR BUMPER GARNISH MOULDING
- M LH/REAR BUMPER SPRING NUT
- M LH/REAR BUMPER SUPPORT
- M LH/REAR BUMPER GUIDE
- M LH/R FENDER INNER TRIM INSULATION
- M LH/REAR LAMP COVERING
- M [STR] DISK WHEEL LH/F & LH/R
- M LH/F LOWER ARM ADJUSTMENT SCREW
- M LH/F CROSS STRUT ARM

THIS IS NOT AN OFFICIAL ESTIMATE

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencing cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Merced

ESTIMATE FOR SJZ6296T

Mr NG SIK SUAN

4 Kingsmead Road
Singapore 267959

Mobile: 90018361

WIP No
Reg No/Reg Date
Date In/Mileage
Chassis No
Engine No
Make/Model
Colour/Trim

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	17/09/2018/ 13:53	K0	305 / Alan Quek A

Description of Goods / Services

- M LH/E STEERING KNUCKLE
- M LH/FRONT WHEEL HUB
- M LH/F STRUT ARM
- M LH/F SHOCK-ABSORBER STRUT
- M [STR] REAR WINDSCREEN GLASS
- M [MUL] REAR AXLE CARRIER
- M [MUX] STOP PLATE
- M [MUX] STOP PLATE
- M LH/REAR SHOCK ABSORBER
- M LH/REAR DRIVE SHAFT
- M LEFT REAR KNUCKLE ARM
- M LH/REAR FLANGE HUP
- M LH/REAR SPRING CONTROL ARM
- M LEFT REAR CAMBER STRUT
- M LEFT REAR STRUT ARM
- M LEFT/REAR TIE ROD
- M LH/REAR PUSHING STRUT ARM
- M LEFT REAR TORSION BAR ROD
- M REAR TORSION BAR
- M BRAKE FLUID
- M MULTI-GRADE OIL
- M GLAZING REPAIR KIT
- M MERCEDES STAR
- M E250 TYPE DESIGNATION
- M GROMMET
- M RACK AND PINION ASSY

THIS IS NOT AN OFFICIAL

ESTIMATE

Not Applicable For Insurance Claims

FOR C&C USE ONLY

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of work. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

來發(明記)摩多有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	69844
Policy No:	DMPCSN3086821702	Date of Loss:	15/09/2018
Vehicle Reg. No.:	SJZ6296T	Driveable?	
Driver Age/Info:	31 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	NG SIK SUAN		
Driver:	VALERIE NG ZHI-YAN		

Make/Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Vehicle Reg. Date:	15/12/2010
Vehicle Colour:	BROWN	Chassis No:	WDD2120472A347221
Engine No:	27186030157361		
Odometer:	0 KM		

Paint Type:
Total Loss? NO
Est. Duration of Repair (day) 14

Handwritten notes:
26/9/18
Tanjong 97495749
Ex: to be advise
Recovery before paint.
sure@lkauto.com
10 days.
Repair limit \$14,000.

Description of Accident/Loss: PLEASE REFER TO SKETCH PLAN.
Present Location: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) / JASON TAN

COST OF CLAIMS	Amount
Parts	9,602.00
Miscellaneous Items	280.00
Labour	3,083.08
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	12,965.08
+ GST 7.00% (S\$)	907.56
Nett Amount (S\$)	13,872.64

This claim is handled by: JASON TAN 14456.08

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Sep 2018)
 Parts: 143 MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SJZ6296T/25/09/2018 14:02
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*BADGE "CGI"	0.00	0.00 ✓	*39.00 F <i>alc</i>
2	1	NA	*L/F LWR CONTROL ARM	0.00	0.00 ✓	*254.00 F <i>bt</i>
3	1	NA	*L/F SHOCK ABSORBER	0.00	0.00 ✓	*415.00 F <i>bt</i>
4	1	NA	*L/F STEERING KNUCKLE	0.00	0.00 ✓	*635.00 F <i>bt</i>
5	1	NA	*L/F STRUT BEARING	0.00	0.00 ✓	*105.00 F <i>bt</i>
6	1	NA	*L/F TENSION ROD	0.00	0.00	*316.00 F ? <i>X nn</i>
7	1	NA	*L/F WHEEL	0.00	0.00 ✓	*470.00 F <i>cut</i>
8	1	NA	*L/F WHEEL HUB	0.00	0.00 ✓	*360.00 F <i>bt</i>
9	1	NA	*L/INNER BOOT TRIM	0.00	0.00 ✓	*160.00 F ? <i>de</i>
10	1	NA	*L/LOWER INSULATION	0.00	0.00 ✓	*10.00 F ? <i>de</i>
11	1	NA	*L/OUTER TIE ROD BALL	0.00	0.00 ✓	*150.00 F ? <i>bt</i>
12	1	NA	*L/R AXLE STEERING	0.00	0.00 ✓	*95.00 F ? <i>bt</i>
13	1	NA	*L/R BUMPER GUIDE	0.00	0.00 ✓	*20.00 F <i>nr</i>
14	1	NA	*L/R BUMPER SUPPORT	0.00	0.00 ✓	*35.00 F <i>nr</i>
15	1	NA	*L/R CAMBER STRUT	0.00	0.00 ✓	*120.00 F ? <i>bt</i>
16	1	NA	*L/R CONTROL ARM	0.00	0.00	*870.00 F ? <i>X nn</i>
17	1	NA	*L/R INNER LAMP	0.00	0.00 ✓	*230.00 F <i>cut</i>
18	1	NA	*L/R MOULDING	0.00	0.00 ✓	*72.00 F <i>nr</i>
19	1	NA	*L/R OUTER LAMP	0.00	0.00 ✓	*355.00 F <i>nr</i>
20	1	NA	*L/R PROTECT SHIELD	0.00	0.00 ✓	*43.00 F ? <i>de</i>
21	1	NA	*L/R SHOCK ABSORBER	0.00	0.00 ✓	*285.00 F ? <i>bt</i>
22	1	NA	*L/R THRUST ARM	0.00	0.00	*55.00 F ? <i>X nn</i>
23	1	NA	*L/R TIE ROD	0.00	0.00 ✓ <i>105</i>	*110.00 F ? <i>bt</i>
24	1	NA	*L/R TOWING STRUT	0.00	0.00	*95.00 F ? <i>X nn</i>
25	1	NA	*L/R UPP C-ARM COVER	0.00	0.00 ✓	*15.00 F ? <i>de</i>
26	1	NA	*L/R VENT INSERT	0.00	0.00 ✓	*15.00 F <i>de</i>
27	1	NA	*L/R WHEEL	0.00	0.00 ✓	*470.00 F <i>cut</i>
28	1	NA	*L/R WHEEL HUB	0.00	0.00	*110.00 F ? <i>X nn</i>
29	1	NA	*L/R WHL-HOUSE COVER	0.00	0.00 ✓	*85.00 F <i>de</i>
30	1	NA	*L/R WING	0.00	0.00 ✓	*1,140.00 F <i>buc</i>
31	1	NA	*L/SILL PANELLING	0.00	0.00 ✓	*355.00 F <i>cut</i>
32	1	NA	*L/TIE ROD	0.00	0.00 ✓	*93.00 F <i>bt</i>
33	1	NA	*L/UPPER INSULATION	0.00	0.00 ✓	*55.00 F ? <i>de</i>
34	1	NA	*LOWER REAR PANELLING	0.00	0.00	*635.00 F ? <i>X nn</i>
35	1	NA	*R/R MOULDING	0.00	0.00 ✓	*72.00 F <i>nr</i>
36	1	NA	*REAR BADGE	0.00	0.00 ✓	*38.00 F <i>nr</i>
37	1	NA	*REAR BUMPER COVER	0.00	0.00 ✓	*820.00 F <i>dis</i>
38	1	NA	*REAR BUMPER MOULDING	0.00	0.00 ✓	*90.00 F <i>cut</i>
39	1	NA	*REAR SCREEN BOND KIT	0.00	0.00	*40.00 F <i>nr</i>
40	1	NA	*SPARE WHEEL WELL	0.00	0.00 ✓	*145.00 F ? <i>nr</i>
41	1	NA	*STAR EMBLEM	0.00	0.00 ✓	*25.00 F <i>nr</i>
42	1	NA	*SUNDRY PARTS	0	0.00	*100.00 FS ? <i>X nn</i>

F=Franchise part. S=SpcNett.

Lai Huat (Meng Kee) Motor Pte Ltd/SJZ6296T/25/09/2018 14:02. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
Total Parts (S\$)						9,602.00

Lai Huat (Meng Kee) Motor Pte Ltd/SJZ6296T/25/09/2018 14:02. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars		Amount
<u>Miscellaneous Items</u>				
1	1	L/R TYRE	168 ✓	210.00
2	1	REAR W/S SEAL	✓	40.00
3	1	WATER LEAK TEST	✓	30.00
Sub Total (S\$)				280.00

80% punctured ✓
✓
✓

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Total Paint Labour	New	604.80 651.00
2	Total Paint Materials	New	242.26 256.48
3	Total Panel/Mechanical Labour	New	2037.00 2,175.60
Gross Labour Cost (S\$)			3,083.08

1500

Lai Huat (Meng Kee) Motor Pte Ltd/SJZ6296T/25/09/2018 14:02. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

來發(明記)摩多有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

(SUPPLEMENTARY)

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	69844
Policy No:	DMPCSN3086821702	Date of Loss:	15/09/2018
Vehicle Reg. No.:	SJZ6296T	Driveable?	
Driver Age/Info:	31 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	NG SIK SUAN		
Driver:	VALERIE NG ZHI-YAN		
Make/Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Vehicle Reg. Date:	15/12/2010
Vehicle Colour:	BROWN		
Engine No:	27186030157361	Chassis No:	WDD2120472A347221
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN.		
Present Location:	LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) / JASON TAN		

COST OF CLAIMS

	Amount
Parts	351.00
Miscellaneous Items	370.00
Labour	500.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,221.00
+ GST 7.00% (S\$)	85.47
Nett Amount (S\$)	1,306.47
+ Previous Estimates (S\$)	13,872.64
Claim Total (S\$)	15,179.11

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Oct 2018)**Parts:** 143 MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Lai Huat (Meng Kee) Motor Pte Ltd/SJZ6296T/12/10/2018 10:31**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WHEEL SPEED SENSOR LH	0.00 ✓	0.00	dis ✓ *185.00 F ✓
2	1		*L/F BALL JOINT	0.00 ✓	0.00	bt ✓ *73.00 F ✓
3	1		*FRONT ABSORBER BEARING LH	0.00 ✓	0.00	bt ✓ *32.00 F ✓
4	1		*FRONT ABSORBER STOPPER LH	0.00 ✓	0.00	bt ✓ *35.00 F ✓
5	1		*FRONT ABSORBER STOPPER BOOT LH	0.00 ✓	0.00	dis ✓ *26.00 F ✓
						F=Franchise part.
Total Parts (S\$)						351.00

Lai Huat (Meng Kee) Motor Pte Ltd/SJZ6296T/12/10/2018 10:31. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	L/F TYRE	220.00
2	1	REAR WINDSCREEN MOULDING	150.00
Sub Total (S\$)			370.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	REPAIR STEERING LOCK	New / rec ✓	250.00
2	REPROGRAMME STEERING LOCK	New / rec ✓	250.00
Gross Labour Cost (S\$)			500.00

Lai Huat (Meng Kee) Motor Pte Ltd/SJZ6296T/12/10/2018 10:31. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

(SUPPLEMENTARY)

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	69844
Policy No:	DMPCSN3086821702	Date of Loss:	15/09/2018
Vehicle Reg. No.:	SJZ6296T	Driveable?	
Driver Age/Info:	31 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	NG SIK SUAN		
Driver:	VALERIE NG ZHI-YAN		

Make/Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Vehicle Reg. Date:	15/12/2010
Vehicle Colour:	BROWN		
Engine No:	27186030157361	Chassis No:	WDD2120472A347221
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	14

Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN.
Present Location:	LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) / JASON TAN

COST OF CLAIMS	Amount
Parts	88.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	88.00
+ GST 7.00% (S\$)	6.16
Nett Amount (S\$)	94.16
+ Previous Estimates (S\$)	15,179.11
Claim Total (S\$)	15,273.27

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Oct 2018)**Parts:** 143 MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Lai Huat (Meng Kee) Motor Pte Ltd/SJZ6296T/18/10/2018 11:56**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*L/F W-HOUSE CVR REAR	0.00	0.00	<i>de</i> *88.00 F (A)
Total Parts (S\$)						88.00

F=Franchise part.

Lai Huat (Meng Kee) Motor Pte Ltd/SJZ6296T/18/10/2018 11:56. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Lai Huat (Meng Kee) Motor Pte Ltd/SJZ6296T/18/10/2018 11:56. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

(SUPPLEMENTARY)

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	69844
Policy No:	DMPCSN3086821702	Date of Loss:	15/09/2018
Vehicle Reg. No.:	SJZ6296T	Driveable?	
Driver Age/Info:	31 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	NG SIK SUAN		
Driver:	VALERIE NG ZHI-YAN		
Make/Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Vehicle Reg. Date:	15/12/2010
Vehicle Colour:	BROWN		
Engine No:	27186030157361	Chassis No:	WDD2120472A347221
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN.		
Present Location:	LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) / JASON TAN		

COST OF CLAIMS	Amount
Parts	182.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	182.00
+ GST 7.00% (S\$)	12.74
Nett Amount (S\$)	194.74
+ Previous Estimates (S\$)	15,273.27
Claim Total (S\$)	15,468.01

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Apr 2019)**Parts:** 143 MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Lai Huat (Meng Kee) Motor Pte Ltd/SJZ6296T/11/04/2019 17:39**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*RIGHT OUTER TIE ROD BALL	0.00	0.00	*88.00 F <i>ms</i>
2	1		*RIGHT TIE ROD	0.00	0.00	*94.00 F <i>ms</i>
Total Parts (S\$)						182.00

F=Franchise part.

Lai Huat (Meng Kee) Motor Pte Ltd/SJZ6296T/11/04/2019 17:39. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Lai Huat (Meng Kee) Motor Pte Ltd/SJZ6296T/11/04/2019 17:39. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference:
Assessment Number: LHMJ0597
Version: LKKAUTOC/6
Date Calculated: 19/10/2018 10:08

Full Report - V1
Registration: SJZ 6296T
Printed: 19/10/2018 17:09

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	15/09/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMPCSN3086821702	Quote Due Date:	
Other Reference:	OD CLAIM	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	E Class
Sub Model:	E 250 CGI
Model Sheet Number:	3AE 01
Registration:	SJZ 6296T
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

TRIM ELEGANCE



Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	22/09/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		

Claim Reference:
 Assessment Number: LHMJ0597
 Version: LKKAUTOC/6
 Date Calculated: 19/10/2018 10:08

Full Report - V1
 Registration: SJZ 6296T
 Printed: 19/10/2018 17:09



Addresses

Cost Summary

Total Labour	\$2,730.00
Total Paint/Material	\$245.26
Total Parts	\$7,915.00
Total of Additional Costs	\$1,086.00
Excess:	- \$0.00
Grand Total Exc GST:	\$11,976.26
7 % GST:	\$838.34
Grand Total Inc GST:	\$12,814.60

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
 Price/Dent = \$42.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
54-7989 03	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)	2.0	8.40
40-6500 01	ALIGNMENT CPL BEFORE REPAIR	7.0	29.40
88-4705 02	R + R L/F PARTITION REAR SECTION	3.0	12.60
60-1587 01	R + R LEFT REAR OUTER DOOR HANDLE	2.0	8.40
88-9705 02	R + R LEFT ROOF MOULDING	2.0	8.40
60-2175 01	R + R ATTACHED PARTS OF THE REAR PANELLING FOR RENEWAL OF THE L/R WING INCLUDES: R + R ATTACHED PARTS IN THE REPAIR SECTION	58.0	243.60
60-2120 01	R + R ATTACHED PARTS OF THE INTERIOR FOR RENEWAL OF THE SPARE WHEEL WELL INCLUDES: R + R CENTRE BOOT TRIM AND IF NECESSARY REAR AXLE PRESSURE ACCUMULATOR	5.0	21.00
63-1882 01	RENEW L/REAR WING CPL	111.0	466.20
64-1201 01	RENEW SPARE WHEEL WELL	14.0	58.80
88-3501 02	RENEW MERCEDES STAR	2.0	8.40
88-3512 02	R + R REAR TYPE BADGE	4.0	16.80
82-4912 02	R + R LEFT INNER TAILLAMP	3.0	12.60
88-8805 02	DIS + ASS REAR BUMPER (REMOVED)	2.0	8.40
88-8882 ZAX	ADD TO DIS/ASS REAR BUMPER CPL (LUXURY VERSION VEHICLE)	2.0	8.40
91-2157 01	R + R DRIVER AIRBAG	3.0	12.60
68-3051 02)	R + R L/BOOT TRIM	4.0	16.80
40-1580 01	R + R FRONT WHEEL	3.0	12.60
33-3510 03)	R + R L/F STEERING KNUCKLE	20.0	84.00

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference:

Full Report - V1

Assessment Number: LHMJ0597

Registration: SJZ 6296T

Version: LKKAUTOC/6

Printed: 19/10/2018 17:09

Date Calculated: 19/10/2018 10:08

33-3630 03)	R + R FRONT STEERING KNUCKLE ASS WORK	3.0	12.60
32-1955 03)	R + R L/F STRUT	5.0	21.00
32-1908 02)	DISS/ASS L/F SUSPENSION STRUT REMOVED	3.0	12.60
32-1920 02)	DIS + ASS FRONT SPRING STRUT/S (REMOVED)	3.0	12.60
46-7004 01)	R + R LEFT TIE ROD	5.0	21.00
40-2410 01	R + R LEFT FRONT TYRE	3.0	12.60
40-2410 01	R + R LEFT REAR TYRE	3.0	12.60
40-2055 01	L/FRONT WHEEL BALANCE	2.0	8.40
40-2055 01	L/R ROAD WHEEL BALANCE	2.0	8.40
NO NUMBER	LOWER REAR AXLE	14.0	58.80
32-1065 02)	R + R LEFT REAR SHOCK ABSORBER	3.0	12.60
35-7826 02)	R + R LEFT SPRING LINK OF REAR AXLE	8.0	33.60
35-7856 02)	R + R LEFT REAR TIE ROD	2.0	8.40
35-7861 02)	R + R L/R CAMBER STRUT	4.0	16.80
49-6900 ZAX	R + R EXHAUST HEAT SHIELD	4.0	16.80
82-1130 01	ADJUST FRONT LAMP UNITS AND FRONT FOG LAMPS	3.0	12.60
40-6500 01	ALIGN VEHICLE INCLUDES: ALIGN FRONT AND REAR TOE AND CAMBER, CHECK FRONT AND REAR VEHICLE LEVEL	7.0	29.40
40-4064 01	ADJUST FRONT WHEEL TOE (DURING ALIGNMENT)	2.0	8.40
40-4403 01	ADJUST REAR WHEEL TOE (VEHICLE ALIGNMENT)	2.0	8.40
40-6716 01	ADDITIONAL TO OPTICAL ALIGNMENT ADJUST L/FRONT AXLE HALF CAMBER/CASTER	6.0	25.20
7359	REMOVE&REFIT STEERING COLUMN CPL	20.0*	84.00
7400	REMOVE&REFIT STEERING WHEEL	5.0*	21.00
7407	REMOVE&REFIT STRG COLUMN COVER	5.0*	21.00
7417	REMOVE&REFIT COMBI SWITCH MODULE	5.0*	21.00
9852	SHORT TEST ERROR MEMORY	20.0*	84.00
9973	KN TEST DRIVE	10.0*	42.00
2711	REPAIR LOWER REAR PANELLING	40.0*	168.00
4043	REPAIR L/R FLOOR PANEL	20.0*	84.00
4101	REPAIR L/R INNER PILLAR	50.0*	210.00

LABOUR COST

Total Work Units	506.0	
Panel / Mechanical Labour	48.2HRS	\$2,024.40
Visual Alignment Labour	2.4HRS	\$100.80
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	50.6HRS	\$2,125.20
Paint Labour	14.4HRS	\$604.80
Total Labour	65.0HRS	\$2,730.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$42.00/HR

Guide Number	Description	WU	Cost Price (\$)
3481	L/R WING NEW PART PAINTING WITH FRONT SURFACE BELOW DOOR	25.0	
2207	L/SILL PANELLING NEW PART PAINT K1R	7.0	

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference:
Assessment Number: LHMJ0597
Version: LKKAUTOC/6
Date Calculated: 19/10/2018 10:08

Full Report - V1
Registration: SJZ 6296T
Printed: 19/10/2018 17:09

2583	REAR BUMPER COVER NEW PART PAINT K1R	11.0	
283	FRONT BUMPER COVER REPAIR PAINT PLASTIC	14.0	
2101	L/SILL PANEL REPAIR PAINTING <50%	11.0	
2353	L/ROOF COVER PANEL REPAIR PAINTING <50%	9.0	
2711	LOWER REAR PANELLINGREPAIR PAINTING <50%	12.0	
2931	BOOTLID/TAILGATE REPAIR PAINTING <50%	16.0	
1781	L/R DOOR SURFACE PAINT	7.0	
4043	L/R FLOOR PANEL SURFACE PAINT	4.0	
4101	L/R INNER PILLAR SURFACE PAINT	5.0	
LABOUR COST - PAINT			
	TIME(PAINT)	121.0	
	Preparation Main Work Metal	17.0	
	Preparation Comp. Work Plastic	6.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	144.0	
	Total Paintwork Labour	14.4HRS	\$604.80
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$28.84
	New Part Painting - Plastic K1R		\$69.11
	Surface-/Blend Paint		\$23.76
	Repair Painting		\$56.75
	Repair Painting Plastic		\$36.00
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$12.70
	Total Excluding Pearlescent Uplift		\$245.26
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$245.26

PARTS

				Price Valid: 01/06/2015		
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
841	1	L/F W-HOUSE CVR REAR	212 690 3030		0%	88.00*
2207	1	L/SILL PANELLING	212 698 0154 9999		0%	355.00*
2583	1	REAR BUMPER COVER	212 880 4340 9999		0%	820.00*
2593	1	L/R BUMPER GUIDE	212 880 1330		0%	20.00*
2615	1	L/R MOULDING	212 885 2121		0%	72.00*
2616	1	R/R MOULDING	212 885 2221		0%	72.00*
2617	1	REAR BUMPER MOULDING	212 885 2021		0%	90.00*
2619	1	L/R BUMPER SUPPORT	212 880 0103		0%	35.00*
3010	1	STAR EMBLEM	212 817 0016		0%	25.00*
3011	1	REAR BADGE	124 817 6115		0%	38.00*
3023	1	BADGE "CGI"	209 817 0515		0%	39.00*
3160	1	REAR SCREEN BOND KIT	000 670 0100		0%	0.00G
3161	3	REAR SCREEN SUPPORTS	164 742 0097		0%	0.00F
3281	1	L/R OUTER LAMP	212 906 6601		0%	355.00*
3283	1	L/R INNER LAMP	212 906 0158		0%	230.00*
3481	1	L/R WING	212 630 0321		0%	1,140.00*
3525	1	L/UPPER INSULATION	212 682 5300		0%	55.00*
3527	1	L/LOWER INSULATION	212 682 1141		0%	10.00*
3677	1	L/R WHL-HOUSE COVER	212 690 0930		0%	85.00*
3685	1	L/R VENT INSERT	212 830 0242		0%	15.00*
3935	1	SPARE WHEEL WELL	212 610 0075		0%	145.00*

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference:
 Assessment Number: LHMJ0597
 Version: LKKAUTOC/6
 Date Calculated: 19/10/2018 10:08

Full Report - V1
 Registration: SJZ 6296T
 Printed: 19/10/2018 17:09

3939	1	ADHESIVE SEALANT	168 670 0093	0%	0.00F
4981	1	L/INNER BOOT TRIM	212 690 4300 9F08	0%	160.00*
7065	1	L/F BALL JOINT	212 330 0135	0%	73.00*
7071	1	L/F LWR CONTROL ARM	212 330 3900	0%	254.00*
7081	1	L/F STEERING KNUCKLE	212 332 0700	0%	635.00*
7087	1	L/F SHOCK ABSORBER	212 323 5300	0%	415.00*
7091	1	L/F STRUT BEARING	212 323 0020	0%	105.00*
7095	1	L/F SP/STRUT SUPPORT	204 981 0025	0%	32.00*
7101	1	L/UPPER BUFFER	212 321 0106	0%	35.00*
7103	1	L/F S-ABSORB BOOT	212 323 0392	0%	26.00*
7131	1	L/F WHEEL HUB	212 330 0025	0%	360.00*
7201	1	L/F WHEEL	212 401	0%	470.00*
			0002649765		
7251	1	L/F SPEED SENSOR	212 540 0117	0%	185.00*
7309	1	L/TIE ROD	212 330 2103	0%	93.00*
7311	1	L/OUTER TIE ROD BALL	212 330 2303	0%	150.00*
8827	1	L/R PROTECT SHIELD	212 680 0122	0%	43.00*
9201	1	L/R SHOCK ABSORBER	212 320 0630	0%	285.00*
9371	1	L/R CAMBER STRUT	205 350 6103	0%	120.00*
9375	1	L/R TIE ROD	205 350 6503	0%	105.00*
9385	1	L/R AXLE STEERING	204 350 3506	0%	95.00*
9389	1	L/R UPP C-ARM COVER	204 352 1588	0%	15.00*
9551	1	L/R WHEEL	212 401	0%	470.00*
			0002649765		
f: OEM Parts			Saving		\$128.46
g: Original			Sub Total		\$7,815.00
h: Secondhand			Sundry Parts	(Fixed)	\$100.00
p: Parallel			Total Parts		\$7,915.00
x: Exchange					

THIS ASSESSMENT CONTAINS UNPRICED PARTS
 NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description		Betterment	Price
REAR W/S SEAL	SPECIALIST	0%	\$40.00
WATER LEAK TEST	SPECIALIST		\$30.00
L/R TYRE	SPECIALIST	0%	\$168.00
L/F TYRE	SPECIALIST		\$198.00
REAR W/S MOULDING	SPECIALIST	0%	\$150.00
REPAIR STEER_G LOCK	SPECIALIST		\$250.00
PROGRAM STEER_G LOCK	SPECIALIST	0%	\$250.00
Total Extras			\$1,086.00

Final Calculation

Total Parts		\$7,915.00
Labour		
Total Panel/Mechanical	\$2,024.40	
Total Paintwork	\$604.80	
Total Visual Alignment work	\$100.80	
Total Labour		\$2,730.00
Additional Costs		

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference:

Full Report - V1

Assessment Number: LHMJ0597

Registration: SJZ 6296T

Version: LKKAUTO/6

Printed: 19/10/2018 17:09

Date Calculated: 19/10/2018 10:08

Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$1,086.00	
Total of Additional Costs		\$1,086.00
Total Paint/Material Costs		\$245.26
Grand Total Excludes GST		\$11,976.26
GST @ 7 %		\$838.34
Grand Total Includes GST		\$12,814.60

Assessment Notes

Shiau Chan (LKKAuto)

From: Jenny Lim <jenny.lim@laihuat.com.sg>
Sent: Monday, 1 April 2019 5:03 PM
To: Shiau Chan (LKKAuto)
Subject: Finalisation - SJZ 6296T / Mercedes Benz E250
Attachments: SJZ 6296T-Audatex Report.pdf; SJZ 6296T-Supplier Bill.pdf

Dear Shiau Chan

For your confirmation, please:

- Parts: \$ 7,997.00 (include supplementary)
- Sundry: \$ 100.00
- SN: \$ 1,116.00
- L&P: \$ 2,987.86
- Total: \$12,200.86 / Excess: Waived**

Supporting documents are enclosed for your reference.

Thank you.

Kind regards

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267