

INS. CASE OWNER:

Yvonne CC4, ASM 180 17082, 71223

LAK:

IDAC:

70173

Signature

MTH

DOI:

ASSIGNMENT

19/09/18

Date / Time:

18/09/18

Registered in Merimen:

Pre-assign / CCL / FIE

SMC 9047L



Insured Vehicle No.:

Name of Insured:

TAN H YAN, DANIEL

Insured Tel No.:

HP:

Excess Sec II :\$5

D.O.A:

11/09/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

S8mouV 68

Policy No.:

VPA/P 7160732

Make / Model:

Helantra

Place of Accident:

PIE

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SJH 76X



INSRS:

WSP:

Tel:

Liability:

RMKS:

Hitachi



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

2/19

ASM

SJH 76X - CCL / MTH 01 5526 / 14/182 - 00A - 18/11

SMC 9047L - X

16.11.18 @ 10.40

(ALSD) on the Response...

Initial WSP Liability (SMC).

8 MTH - company drop X clear.

before paint photo ✓

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call Of:

16.11.18

After call Itr to Of:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to Of:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

2/18

Sent By:

MTH

FINALIZATION

Date/Time:

Confirm with:

Confirm by: MTH

Repair Cost:

P/R \$36,549.40

(8 days)

Reduction:

49 %

Email

Call

FINAL SETTLEMENT

Date/Time:

26/8/2019

Confirm with:

Jamilah

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

21

If NO or B 28, Ass. Lia:

Repair Cost:

(1/18)

\$5 6,793.43

OI RISE ENDED TV.

Loss of Rental (LOR):

\$5 1,193.40

(8 days)

x \$140.00 + 7% GST

Loss of Use (LOU):

\$5 -

(3 x days)

Loss of Income (LOI):

\$5 -

(3 x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

\$5 2.00

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/ Independent)

Legal Cost:

\$5 -

Total:

\$5 7,993.83

Global Sum \$5:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$350.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5 7,993.83

Name 1:

Hitachi Capital Asia Pacific Pte Ltd

Payee 2: (Strike if N.A.):

\$5 -

Name 2:

Payee 3: (Strike if N.A.):

\$5 -

Name 3:

REF:

AXIA

22003

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S
<input checked="" type="checkbox"/>	

Bal. or Market Value: _____

4/280.

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

% days

Res: _____

Yes or No

Lump Sum: _____

- %

3 Val: _____

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: _____

SJK 76X

Yr Regn: _____

206 / Nov

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: _____

Toyota Corolla Aero

CC

2362

Colour: _____

white

A/C: _____

Insured / Std / NI / NA

Sp. Reading _____

65871

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

ACKS 67132682

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModl: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: _____

F: _____

225/50R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. _____

C

mm

R/Bal. _____

C

mm

L/Bal. _____

C

mm

L/Bal. _____

C

mm

D.O.A. _____

D.O.I. _____

19/9/2000

Survey held at _____

Kilachi Capital

Des. of Damages: ☐ Frt / ☒ Rear / ☐ O/S / ☐ NIS / ☐ UIC / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

P/P: 76349 (BDO: 76191.35 41%)

Date/Time. File Pass to?

☐

: Preli. Report

f)

☐

: Final Report

Date/Time. File Return to?

g)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1. 3-4 RS. 50

1. 2000

1. 2000

1. 2000

TOTAL

Report Format :

Lump Sum / I.B.I: (S)

Add Fee:

☐

Site Insp (S)

☐

Interview (S)

☐

Tech. Invs (S)

☐

Weekend (S)

No. 8 Fourth Lok Yang Road Singapore 629705

Tel : 64663022 Fax : 68966591

Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE

AXA

QUOTE NO :

ACCIDENT DATE : 12/09/2018@1945HRS

VRN :

SJH76X

MODEL :

Toyota Estima

TP VRN :

SMC9047L

ATTN: MOTOR CLAIMS DEPT

PARTS REPLACEMENT1. Body Repair

		<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
1	Rear Bumper	1	\$ 585.00	\$ 585.00	de ✓
2	Rear Bumper Clips	10	\$ 5.50	\$ 55.00	hls ✓
3	Rear Bumper Retainer Outer LH/RH	2	\$ 55.00	\$ 110.00	hls ✓
4	Rear Bumper Retainer Inner LH/RH	2	\$ 55.00	\$ 110.00	hls ✓
5	Towing Cover	1	\$ 25.00	\$ 25.00	mi ✓
6	Rear Bumper Reflector Light LH	1	\$ -	\$ -	230.00 and ✓
7	Rear Bumper Reverse Sensor	1	\$ 200.00	\$ 200.00	q.m. ✓
8	Rear Bumper Inner Sponge LH	1	\$ 65.00	\$ 65.00	X.m ✓
9	End Panel	1	\$ 660.00	\$ 660.00	B.B ✓
10	End Panel Upper Garnish	1	\$ 271.00	\$ 271.00	X.m ✓
11	Rear Fender LH	1	\$ 1,209.00	\$ 1,209.00	Kp ✓
12	Rear Fender Shield LH	1	\$ 95.00	\$ 95.00	X ✓
13	Rear Fender Shield Clips LH	10	\$ 5.50	\$ 55.00	X } NH
14	Rear Fender Inner Trim LH	1	\$ 755.00	\$ 755.00	X ✓
15	Rear Fender Inner Trim Cover LH	1	\$ 325.00	\$ 325.00	X ✓
16	Spare Tyre Compartment	Repair	\$ -	\$ -	
17	Tailgate	1	\$ 1,700.00	\$ 1,700.00	h ✓
18	Tailgate Hinge LH/RH	2	\$ 60.00	\$ 120.00	Ky ✓
19	Tailgate Autodoor Checker	Sample	\$ -	\$ -	475.00 ✓
20	Tailgate Windscreen Moulding	1	\$ 100.00	\$ 100.00	h ✓
21	Tailgate Windscreen Sealant	s/nett	\$ 45.00	\$ 45.00	h ✓
22	Tailgate Toyota Logo	1	\$ 75.00	\$ 75.00	h ✓
23	Tailgate Estima Logo	1	\$ 47.00	\$ 47.00	h ✓
24	Rear Airvent LH	1	\$ 145.00	\$ 145.00	X.m ✓
25	Rear Chassis LH	Repair	\$ -	\$ -	

Discount - 25%

\$ (1,611.75)

TOTAL

\$ 5,080.25

2. Labor Charges

Panel beat, cut, weld, re-align and replace damaged parts
 Spray painting on rear portion of affected area
 Check wiring, re-align taillamp and ensure proper function
 Remove & reinstall bumper sensors
 Cavity Treatment on new parts

1,250. \$ 2,000.00
 1,250 \$ 1,500.00
 30. \$ 80.00
 30. \$ 120.00
 60 \$ 160.00

\$ 3,831.00
 25%
 \$ 2,187.40

S/A \$ 475.00

Realign chassis member	\$ X 2,500.00
Remove & reinstall rear reverse camera	\$40 120.00
Remove & reinstall fuel tank to facilitate cutting and repairing work	\$ X 180.00
Remove & reinstall tailgate windscreen	120 \$20 180.00
Transfer tailgate lock & mechanism to new tailgate	\$60 200.00
Conduct water seepage test	\$40 120.00
Remove & reinstall rear trim compartment to facilitate cutting and repairing	\$60 150.00
Remove & refit tailgate spoiler	Labour \$3000.00 \$60 150.00

Sub Total : \$ 7,460.00

Grand Total : \$ 12,540.25

Add 7% GST : \$ 877.82

Nett Total : \$ 13,418.07

No. of repair days: 10

List \$ 2,874.00
 S/N \$ 475.00
 Labour \$ 3,000.00
 p/p i \$ 6,349.00

CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

Tanfah 97795749
 19/1/18 @ 1800
 Sure (Hantowan)
 86 days
 #Resurvey before/after paint.
 To check p/p or L/S.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are fixed to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplemental claims must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705

Tel : 64663022 Fax : 68966591

Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

Parts - \$3832.00
 -25% = \$958.00
 \$2874.00
 S/M + \$475.00
 Parts Total - \$3349.00
 Labour + \$3000.00
 Total = \$6349.00

VEHICLE ESTIMATE

AXA

ATTN: MOTOR CLAIMS DEPT

QUOTE NO :
 ACCIDENT DATE : 12/09/2018@1945HRS
 VRN : SJH76X
 MODEL : Toyota Estima
 TP VRN : SMC9047L

		<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
PARTS REPLACEMENT					
1. Body Repair					
1 Rear Bumper ✓		585 1	\$ 585.00	\$ 585.00	de ✓
2 Rear Bumper Clips ✓		55 10	\$ 5.50	\$ 55.00	ner ✓
3 Rear Bumper Retainer Outer LH/RH ✓		55 2	\$ 55.00	\$ 110.00	ner ✓
4 Rear Bumper Retainer Inner LH/RH ✓		55 2	\$ 55.00	\$ 110.00	ner ✓
5 Towing Cover ✓		25 1	\$ 25.00	\$ 25.00	mi ✓
6 Rear Bumper Reflector Light LH ✓	s/nett (130)	1	\$ -	\$ -	ner ✓ \$230.00
7 Rear Bumper Reverse Sensor	s/nett	1	\$ 200.00	\$ 200.00	ner ✓
8 Rear Bumper Inner Sponge LH		1	\$ 65.00	\$ 65.00	? ✓
9 End Panel ✓		660 1	\$ 660.00	\$ 660.00	Ky ✓
10 End Panel Upper Garnish		1	\$ 271.00	\$ 271.00	? ✓
11 Rear Fender LH		1	\$ 1,209.00	\$ 1,209.00	Ky ✓
12 Rear Fender Shield LH		1	\$ 95.00	\$ 95.00	x ✓
13 Rear Fender Shield Clips LH		10	\$ 5.50	\$ 55.00	< ✓
14 Rear Fender Inner Trim LH		1	\$ 755.00	\$ 755.00	✓
15 Rear Fender Inner Trim Cover LH		1	\$ 325.00	\$ 325.00	? ✓
16 Spare Tyre Compartment	Repair	1	\$ -	\$ -	
17 Tailgate ✓		1700 1	\$ 1,700.00	\$ 1,700.00	bt ✓
18 Tailgate Hinge LH/RH		2	\$ 60.00	\$ 120.00	Ky ✓
19 Tailgate Autodoor Checker ✓	Sample	225 1	\$ 475.00	\$ 475.00	
20 Tailgate Windscreen Moulding ✓		100 1	\$ 100.00	\$ 100.00	ner ✓
21 Tailgate Windscreen Sealant	s/nett (45)	1	\$ 45.00	\$ 45.00	ner ✓
22 Tailgate Toyota Logo ✓		75 1	\$ 75.00	\$ 75.00	ner ✓
23 Tailgate Estima Logo ✓		47 1	\$ 47.00	\$ 47.00	ner ✓
24 Rear Airvent LH		1	\$ 145.00	\$ 145.00	? ✓
25 Rear Chassis LH	Repair	1	\$ -	\$ -	
Discount - 25%				\$ (1,611.75)	
TOTAL				\$ 5,080.25	

2. Labor Charges

Panel beat, cut, weld, re-align and replace damaged parts	1,250.	\$ 2,000.00
Spray painting on rear portion of affected area	1,250.	\$ 1,500.00
Check wiring, re-align taillamp and ensure proper function	30.	\$ 80.00
Remove & reinstall bumper sensors	30.	\$ 120.00
Cavity Treatment on new parts	60	\$ 160.00

Realign chassis member	\$ X 2,500.00
Remove & reinstall rear reverse camera	\$ 120.00
Remove & reinstall fuel tank to facilitate cutting and repairing work	\$ X 180.00
Remove & reinstall tailgate windscreen	120 \$ 180.00
Transfer tailgate lock & mechanism to new tailgate	\$ 200.00
Conduct water seepage test	\$ 120.00
Remove & reinstall rear trim compartment to facilitate cutting and repairing	\$ 150.00
Remove & refit tailgate spoiler	\$ 150.00

Sub Total : \$ 7,460.00

Grand Total : \$ 12,540.25

Add 7% GST : \$ 877.82

Nett Total : \$ 13,418.07

No. of repair days: 10

CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

Tanjin 97495749
WP

19/1/18 @ 1800

Sur @ 11:00 am.

3 days.

Resuming before/after paint.

To check p/p or L/S.



Service Request Details

Claim

S8M00VG8

Reference

None

Loss Date

September 12, 2018

Request Date

September 18, 2018

Due Date

September 25, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

*7082/en3**JingHaw veh in**18092018 @ 1:45pm**Hitachi Capital v.**8 Fourth Lok Yang Rd**19.09.2018*

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJH76X

Make

TPVD TOYOTA

Model

ESTIMA AERAS 2.4 A

Service Address

Primary Contact/Insured

TAN ZI YAN DANIEL

BLK 566 PASIR RIS STREET 51, #04-118, 510566, Singapore

97852486

danieltanziyan@yahoo.com

Claim Handler

CHAN Kian Chuan

6568804269

kianchuan.chan@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Monday, 26 August 2019 5:24 PM
To: Jamilah, Binte MohdKassim; Hsiao Tong (LKKAuto)
Cc: Admin A; Asher Sng (LKKAuto)
Subject: RE: SJH76X Third party claim against SMC9047L AXA ***LKK REF: CC4/ASM18017082/ea3 - LOD
Attachments: NEW DS SJH 76X.pdf
Importance: High

WITHOUT PREJUDICE

SAVE AS TO COSTS

LKK REF: CC4/ASM18017082/T1pa3
Your Ref: SJH 76X

Dear Jamilah,

We refer to the above matter.

We hereby confirmed settlement as follow:-

1. Cost of Repair (w/gst)	S\$ 6,793.43
2. Loss of Rental (\$140.00 x 8 days)+7%gst	S\$ 1,198.40
3. GIA search fee	S\$ 2.00
	<u>S\$ 7,993.83</u>

Please duly sign the **Direct Settlement Form** enclosed and return with **Authorization to Act** to us (LKK) for payment processing.

Your prompt action will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)




Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

English (default) ▾

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

 SERVICE REQUESTS

MESSAGES

CLAIMS

<<

Re:TP MANDATE IA < S8M00VG8>

Type

 Question

Message

Please proceed

Reply

English (default) ▼

LKK AUTO CONSULTANTS PTE LTD (TP) ▼



SERVICE REQUESTS

MESSAGES

CLAIMS

<<

TP MANDATE IA < S8M00VG8>

Type

🔔 Question

Message

Dear Yvonne, Liability: Insured collided into the rear of third party vehicle as per TP video footage, Liability is down against our insured. We have send letter to OI via e-mail to notify TP claim and NCD issue. Immediate Advice (with mandate) have been uploaded in SMART CLAIM. We hereby seek your approval to offer Third Party repairer M/s "Hitachi Capital Asia Pacific Pte Ltd" is as follows: - 1) COR(w/gst): \$6,793.43 + 2) Loss of Rental (8 days x \$140.00+7%gst): \$1,198.40 + 3) GIA search: \$2.00 = Total: \$7,993.83. **8 days recommendation for repair. **All the relevant documents had been uploaded in SMART CLAIM. For your approval please. PohKin- LKK- 26/08/2019

Print



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Liability: Insured collided into the rear of third party vehicle, Liability is down against our insured. We have send letter to OI via e-mail to notify TP claim and NCD issue.

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 6,793.43	(\$6,349.00 +7%gst)
Loss of use	\$ -	
Loss of rental	\$ 1,198.40	(8 days x \$140.00 +7%gst)
Loss of income	\$ -	
GIA search fees	\$ 2.00	
Others	\$ -	
Proposed Total	\$ 7,993.83	



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 26/8/2019

Survey Details:

Date of loss	12-Sep-18
Date of appointment	18-Sep-18
Date of survey	19-Sep-18
Location of survey	HITACHI CAPITAL (S) PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SJH76X
Make and Model	TOYOTA ESTIMA AERAS 2.4 A - 2362cc
Date of registration	4-Nov-16
Excess	
Market Value	\$ 128,000.00
Part Rebate	\$ 76,850.00
Nett Loss	\$ 51,150.00

Repair details:

Initial Estimate	\$ 12,540.25
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 3,349.00	list price -25%
Check items	\$ -	
Labour	\$ 3,000.00	
Total	\$ 6,349.00	
Lump Sum(if applicable)	\$ -	

Number of days for repair	<u>8</u>
---------------------------	----------

Hitachi Capital Asia Pacific Pte. Ltd.

Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road
Singapore 629705

Date : 30/04/2019

AXA Insurance Pte Ltd
No. 8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Re : Accident involving vehicle no.: SJH76X and vehicle no(s): SMC9047L on 12/09/2018 at PIE towards Tuas

Dear Sir,

Reference to the above accident, we are submitting the following claims on damages to our client's vehicle caused by your insured's vehicle.

<input checked="" type="checkbox"/> Workshop repair bill (Cost of repairs) <u>TP20089948</u>	<u>\$6,793.43</u>
<input type="checkbox"/> Loss of use vehicle for <u>0</u> days at (<u>\$0.00</u> /day)	<u> </u>
<input type="checkbox"/> Medical expenses	<u> </u>
<input type="checkbox"/> Surveyor report fee	<u> </u>
<input checked="" type="checkbox"/> Rental invoice	<u>\$1,198.40</u>
<input type="checkbox"/> Pain & suffering	<u> </u>
<input type="checkbox"/> Traffic police investigation fee	<u> </u>
<input checked="" type="checkbox"/> Search fee	<u>\$2.00</u>
<input type="checkbox"/> Others :	<u> </u>
Grand Total :	<u>\$7,993.83</u>


Please find the following documents enclosed,

- | | |
|------------------------------------------------------------|------------------------------------------------------|
| <input type="checkbox"/> Accident Report | <input type="checkbox"/> Police Investigation Result |
| <input checked="" type="checkbox"/> Repair Bill | <input type="checkbox"/> Medical Receipt |
| <input checked="" type="checkbox"/> Vehicle Rental Receipt | <input type="checkbox"/> Surveyor Bill |
| <input checked="" type="checkbox"/> Search Fee Receipt | <input type="checkbox"/> Excess Bill |
| <input type="checkbox"/> My Insurance Company | |
| <input type="checkbox"/> Policy No | |
| <input type="checkbox"/> Others | |

We look forward to your settlement within 30 days failing which you have to bear all costs incurred for engaging a solicitor to enable us to recover full settlement from your company.

Thank you.

HITACHI CAPITAL ASIA PACIFIC PTE. LTD.


.....
TAKASHI SEKIMOTO (MR)

Hitachi Capital Asia Pacific Pte. Ltd.
Total Vehicle Solutions Department

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Friday, 28 December 2018 9:32 AM
To: 'DANIELTANZIYAN@YAHOO.COM'
Subject: ACCIDENT INVOLVING SMC 9047L AND SJH 76X ALONG PIE PRIOR TO THE STEVENS RD EXIT ON 12/09/2018

28 DEC 2018

TAN ZI YAN, DANIEL

Dear Sir/ Mdm

OUR REF : CC4/ASM18017082/T1ea3

YOUR REF : SMC 9047L

ACCIDENT INVOLVING SMC 9047L AND SJH 76X ALONG PIE PRIOR TO THE STEVENS RD EXIT ON 12/09/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s HITACHI CAPITAL (S) PTE LTD acting on behalf of the owner of SJH 76X against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had rear-ended the Third Party vehicle SJH 76X. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to ashersng@lkkauto.com within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at ashersng@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: ashersng@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

AUTHORISATION TO ACT

I/We, Kho Chuan Hock of S7638366 I
S7H76X, owner of S7H76X hereby
authorized **HITACHI CAPITAL ASIA PACIFIC PTE LTD**, ("The Workshop") to act for me/us with
respect to my/our claim for the repair costs and/or rental and/or loss of use for my/our vehicle number
S7H76X that was damaged pursuant to the accident occurred on 12/9/2018 at
Pte towards Tuar involving vehicle number
S7C904TL.


I/We further authorise the Workshop to settle my/our above mentioned claim in a manner that they deem
fit and The Workshop is further authorised to receive payment further to settlement of my/our claim with
payment cheque being made in favour of **HITACHI CAPITAL ASIA PACIFIC PTE LTD**.

The settlement The Workshop may reach on my/our behalf is on without prejudice and without admission
of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.


Pursuant to Personal Data Protection Act 2012, I/We hereby agree that The Workshop may disclose or
share my personal data to any authorized service providers whom The Workshop would necessarily need
to cooperate, interact or work in one way or another in serving me or meeting my requests.


*If I/we are not able to recover full amount for the repair cost from the 3rd Party's Insurance Company
in 6 (six) months time from Invoice Date, HITACHI CAPITAL ASIA PACIFIC PTE LTD (HCAP)
shall bill to you/your Company for the balance/full amount of the repair cost. HCAP will close this
case without prior notice If we are unable to recover within 2 years*

☐ I/We understood the explanation done by HCAP.


(signature)

Dated this 19 day of 09 (month) 18 (year)


Signed by Claimant
(with Co's stamp for vehicle under Co's name)


Signed by Hitachi Capital Asia Pacific Pte Ltd



AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SMC 9047L (Insd veh)	Model: TOYOTA - ESTIMA AERAS 2.4(A) - 2302cc
	SJH 78X (TP veh)	
Date of Accident/ Time:	13/09/2018	

Repair Estimate	: \$	14,397.12	
Final Repair Cost (w/gst)	: \$	6,793.43	
Loss of Use	: \$	Nil	days at \$ per day
Rental (if any) (w/gst)	: \$	1,188.40	8 days at \$ 148.80 per day
LTA / GIA Search Fee	: \$	2.00	
Others:	: \$	Nil	
Final Settlement Sum	: \$	7,993.83	
Payee Name : Hitachi Capital Asia Pacific Pte Ltd			
Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)			
A)	For Non GIA Registered Workshop:	Agreed Liability _____ (%)	
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: 37	
	BOLA Liability: 100 (%)	Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks:			

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are not received within 7 days of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.


We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.


We confirmed that we have the authority of our client to act for and on their behalf in this accident.

HITACHI CAPITAL ASIA PACIFIC PTE. LTD.


TAKASHI SEKIMOTO (MR)

Signature of workshop representative / Workshop stamp
Name of Representative:
Date: 27/8/2019


Signature of Witness / Workshop stamp (if applicable)
Name of Witness:
Date: 27/8/2019


Signature of AXA's surveyor/representative:
Name of AXA's surveyor/representative:
Date: 27/8/2019

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel: 64663022 Fax: 68966591
Co.Reg.No. 199400399N GST Reg. No. M2-0118999-3

TAX INVOICE

M/S : AXA Insurance Pte Ltd
No. 8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Attn : Motor Claim Dept

Invoice No : TP20089948
Accident Date : 12/09/2018
Veh Regn : SJH76X
Model : Toyota Estima 2.4 Aeris-
Warranty PK SVC
Date : 25/04/2019
Terms : 0 days
Due Date : 25/04/2019
Your Insured : SMC9047L
Total Pages : 1 / 1

	Qty	SSUnit	SSAmt	SSLabor
1. Body Repair				
Parts & Labour Charges				
1 Parts				3,349.00
2 Labour				3,000.00


SubTotal : 0.00 6,349.00

Grand Total : 6,349.00
Add 7 % GST : 444.43
Net Total After GST : 6,793.43

INTEREST OF 1% PER MONTH WILL BE CHARGED ON ANY AMOUNT OUTSTANDING FROM DUE DATE

All cheques should be crossed and made payable to :
Hitachi Capital Asia Pacific Pte. Ltd.

HITACHI CAPITAL ASIA PACIFIC PTE. LTD.


TAKASHI SEKIMOTO (MR)
Manager
Auto Servicing
Total Vehicle Solutions Department

Service Manager

Job done by :

Hitachi Capital Asia Pacific Pte. Ltd.

Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705

Tel: 64663022

Fax: 68966591

Co.Reg.No. 199400399N

GST Reg. No. M2-0118999-3

TAX INVOICE

M/S : Mr Kho Chuan Hock

Blk 726 Jurong West Avenue 5

#06-244

Singapore 640726

Attn : Mr Kho Chuan Hock

Invoice No : NR40089949
Accident Date : 12/09/2018
Veh Regn : SJH76X
Model : Toyota Estima 2.4 Aeras-
4/11/2016-3/11/2019
Date : 25/04/2019
Terms : 0 days
Due Date : 25/04/2019
Your Insured : SMC9047L
Total Pages : 1 / 1

1. Rental Fee

1 Rental of SKB2619L for 8 days

Qty	SSUnit	SSAmt	SSLabor
8.00	140.00	1,120.00	

SubTotal : 1,120.00 0.00

Grand Total : 1,120.00

Add 7 % GST : 78.40

Net Total After GST : 1,198.40

INTEREST OF 1% PER MONTH WILL BE CHARGED ON ANY AMOUNT OUTSTANDING FROM DUE DATE

All cheques should be crossed and made payable to :
Hitachi Capital Asia Pacific Pte. Ltd.

HITACHI CAPITAL ASIA PACIFIC PTE. LTD.



TAKASHI SEKIMOTO (MR)

Manager

Auto Servicing

Service Manager

Job done by :

Replacement Vehicle Report

Particulars of Hirer

Name : Mr Kho Chuan Hock
 Company's Name : Mr Kho Chuan Hock
 Address : Blk 728 Jurong West Avenue 5 #06-244 Singapore 640726
 Vehicle No : SJH76X
 Tel : 91333333
 HP :

Vehicle Particulars

Reason for Replacement :

Vehicle No : SKB2619L
 Maker : Toyota
 Model : Estima 2.4

☒ Accident
☐ Repair
☐ Others

OUT

Petrol: 100

Date : 13/09/2018
 Time : 1345
 Mileage (km) : 20720
 No of Keys (pcs) : 1

50

0

IN

Petrol: 100


Date : 8/10/18
 Time : 1030
 Mileage (km) : 20315
 No of Keys (pcs) : 1

50

0

Others:

Mark "X" on Damage Parts



We hereby confirm our acceptance:

Name: Mr. Alex Ebo
 HP:



For/on behalf of Hitachi Capital Asia Pacific Pte. Ltd.

Name: Alex Ebo
 HP: 91333333



For/on behalf of Hitachi Capital Asia Pacific Pte. Ltd.

- Excess \$1,000 in Singapore / \$1,500 in Malaysia. Additional Excess of \$3,000 for young driver age 25 years & below or driving license less than 2 years.
- In case of vehicle's insurance is under Third Party only, Excess is to cover for any third party damage or injury claims.
- The Lessee shall be responsible for same petrol level (\$25.00 / quarter) and all traffic offences.

Others:

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-142917

Date of Request: 17/09/2018

Your Ref No: Online Purchase

Hitachi Capital Asia Pacific Pte. Ltd
No 8 Fourth Lok Yang Road
Singapore 629705

Dear Sir/Madam,

Enquiry Date 17/09/2018
Enquiry By Ng Jiong How
TP Vehicle No. SMC9047L
Accident Date 12/09/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SMC9047L	AXA Insurance Pte Ltd	27/07/2018-26/07/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-142917

Date of Request: 17/09/2018

Your Ref No: Online Purchase

Hitachi Capital Asia Pacific Pte. Ltd
No 8 Fourth Lok Yang Road
Singapore 629705

Dear Sir/Madam,

Enquiry Date 17/09/2018
Enquiry By Ng Jiong How
TP Vehicle No. SMC9047L
Accident Date 12/09/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:


☒ GIRO ☐ Cash ☐ Cheque

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18017082/T1pa3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:YVONNE			Date : 17-09-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMC 9047L	Veh. Inspected	SJH 76X	
Policy No.	VPA/P2160232	Coverage (\$)	0.00	
Claim No.	S8M00VG8	Excess (\$)	0.00	
Assign From		Assign Date	18/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ESTIMA AERAS	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ACR507132682	Colour	WHITE	
Odometer	65871	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R18	YOKOHAMA	6 mm	
L/H Front Tyre	225/50 R18	YOKOHAMA	6 mm	
R/H Rear Tyre	225/50 R18	YOKOHAMA	6 mm	
L/H Rear Tyre	225/50 R18	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/09/2018	Inspection Date	19/09/2018	
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 76X ✓

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (CONSISTENT)	DEFORMED	✓ 585.00	585.00
10	REAR BUMPER CLIPS @\$5.50 (CONSISTENT)	NECESSARY	✓ 55.00	55.00
2	REAR BUMPER RETAINER OUTER LH/RH @\$55.00 (CONSISTENT)	N/S NECESSARY	✓ 110.00	55.00
2	REAR BUMPER RETAINER INNER LH/RH @\$55.00 (CONSISTENT)	N/S NECESSARY	✓ 110.00	55.00
1	TOWING COVER (CONSISTENT)	MISSING	✓ 25.00	25.00
1	REAR BUMPER INNER SPONGE LH (CONSISTENT)	NOT NECESSARY	✓ 65.00	-
1	END PANEL (CONSISTENT)	BENT	✓ 660.00	660.00
1	END PANEL UPPER GARNISH (CONSISTENT)	NOT NECESSARY	✓ 271.00	-
1	REAR FENDER LH (CONSISTENT)	TO REPAIR SEE LABOUR	✓ 1,209.00	-
1	REAR FENDER SHIELD LH (CONSISTENT)	NOT NECESSARY	✓ 95.00	-
1	SPARE TYRE COMPARTMENT (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	TAILGATE (CONSISTENT)	BENT	✓ 1,700.00	1,700.00
2	TAILGATE HINGE LH/RH @\$60.00 (CONSISTENT)	TO REPAIR SEE LABOUR	✓ 120.00	-
1	TAILGATE AUTODOOR CHECKER (CONSISTENT)	NECESSARY	✓ 475.00	475.00
1	TAILGATE WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	✓ 100.00	100.00
1	TAILGATE TOYOTA LOGO (CONSISTENT)	NECESSARY	✓ 75.00	75.00
1	TAILGATE ESTIMA LOGO (CONSISTENT)	NECESSARY	✓ 47.00	47.00
1	REAR AIRVENT LH (CONSISTENT)	NOT NECESSARY	✓ 145.00	-
1	REAR CHASSIS LH (CONSISTENT) (NPA)	TO REPAIR SEE LABOUR	-	-
LESS 25% DISCOUNT			-1,461.75	-958.00
			4,385.25	2,874.00
SPECIAL NETT ITEMS				
1	REAR BUMPER REFLECTOR LIGHT LH (CONSISTENT) (SN)	CRACKED	✓ 230.00	230.00
1	REAR BUMPER REVERSE SENSOR (CONSISTENT) (SN)	NOT WORKING	✓ 200.00	200.00
10	REAR FENDER SHIELD CLIPS LH @\$5.50 (CONSISTENT)	NOT NECESSARY	✓ 55.00	-
1	REAR FENDER INNER TRIM LH (CONSISTENT)	NOT NECESSARY	✓ 755.00	-

Report Ref No. CC4/ASM18017082/T1pa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER INNER TRIM COVER LH (CONSISTENT)	NOT NECESSARY	✓ 325.00	-
1	TAILGATE WINDSCREEN SEALANT (CONSISTENT) (SN)	NECESSARY	45.00	45.00
			1,610.00	475.00
	LABOUR			
	PANEL BEAT ,CUT ,WELD,RE-ALIGN AND REPLACE DAMAGED PARTS .INCLUSIVE OF THE REPAIR OF REAR FENDER LH ,SPARE TYRE COMPARTMENT,TAILGATE HINGE LH/RH AND REAR CHASSIS LH.		✓ 2,000.00	1,250.00
	SPRAY PAINTING ON REAR PORTION OF AFFECTED AREA.		✓ 1,500.00	1,250.00
	CHECK WIRING ,RE-ALIGN TAILLAMP AND ENSURE PROPER FUNCTION.		✓ 80.00	30.00
	REMOVE & REINSTALL BUMPER SENSOR.		120.00	30.00
	CAVITY TREATMENT ON NEW PARTS.		✓ 160.00	60.00
	REALIGN CHASSIS MEMBER TAILGATE HINGE LH/RH	NOT NECESSARY	✓ 2,500.00	-
	REMOVE & REINSTALL REAR REVERSE CAMERA.		120.00	40.00
	REMOVE & REINSTALL FUEL TANK TO FACILITATE CUTTING AND REPAIRING WORK.	NOT NECESSARY	✓ 180.00	-
	REMOVE & REINSTALL TAILGATE WINDSCREEN.		✓ 180.00	120.00
	TRANSFER TAILGATE LOCK & MECHANISM TO NEW TAILGATE.		✓ 200.00	60.00
	CONDUCT WATER SEEPAGE TEST.		✓ 120.00	40.00
	REMOVE & REINSTALL REAR TRIM COMPARTMENT TO FACILITATE CUTTING AND REPAIRING.		✓ 150.00	60.00
	REMOVE & REFIT TAILGATE SPOILER.		✓ 150.00	60.00
			✓ 7,460.00	3,000.00
GRAND TOTAL			13,455.25	6,349.00
RECOMMENDED COST OF REPAIRS				6,349.00

Report Ref No. CC4/ASM18017082/T1pa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	SBM00VGB
Reference	CCA/ASM18017082/TT103d12
Loss Date	12 September 2018
Report Date	13 Sep 2018 2:29:00 PM
Request Date	18 September 2019
Due Date	

Vendor Name	L&K AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step: Wait for Approve Invoice

Add Invoice

Vehicle Information

Incident Vehicle Registration #	5JH76X
Make	TPVD TOYOTA
Model	ESTIMA AERAS 2.4 A
Service Address	

...

Primary Contact/Insured

TAN ZI YAN DANIEL
BLK 566 PASIR RIS STREET 51, #04-118, S10566, Singapore
97852486
danieltanzyan@yahoo.com

Claim Handler

ANG Yvonne
6568804461
yvonne_ang@axa.com.sg

Additional Instructions









Messages Invoices History Documents Assessment Metrics Notes

Document Type Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
L&KInvoice1 (1).pdf	Invoice	Surveyor/ Assessor expense	L&K AUTO CONSULTANTS PTE LTD (TP)	20 September 2019

NAME LKK PHOTO-3.pdf	Forms / Claim Documents	Sub-TYPE Others	AXA AUTO CONSULTANTS PTE LTD (TP)	DATE 20 September 2019
RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 September 2019
LKKInspection (4).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 September 2019
LKKAdjustment1a (4).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 September 2019
GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 September 2019
PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	20 September 2019
AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	20 September 2019
WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	20 September 2019
Letter to OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	26 August 2019
Immediate Advice (with mandate) dated 26/08.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 August 2019
Rental Tax Invoice.pdf	Forms / Claim Documents	Claim Form	LKK AUTO CONSULTANTS PTE LTD (TP)	26 August 2019
GIA search fee.pdf	Forms / Claim Documents	Claim Form	LKK AUTO CONSULTANTS PTE LTD (TP)	26 August 2019
LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 August 2019
LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 August 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 TP Estimate- Marshall revise.pdf	Reports & Statement	Others	LOK AUTO CONSULTANTS PTE LTD (TP)	26 August 2019
 LKK RESURVEY PHOTO-BEFORE PAINT.pdf	Reports & Statement	Others	LOK AUTO CONSULTANTS PTE LTD (TP)	26 August 2019
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LOK AUTO CONSULTANTS PTE LTD (TP)	1 October 2018
 SJHTAX - 2.jpg4	Evidence	Videos	LOK AUTO CONSULTANTS PTE LTD (TP)	27 September 2018
 SJHTAX - 1.jpg4	Evidence	Videos	LOK AUTO CONSULTANTS PTE LTD (TP)	27 September 2018
 TP PSI FROM WORKSHOP.jpg	Letters and Correspondence	Workshop	DHAKAL Raghav	18 September 2018
 SJHTAX TP GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	18 September 2018
 SMC9047L INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	18 September 2018