

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE

AXA

ATTN: MOTOR CLAIMS DEPT

QUOTE NO :
 ACCIDENT DATE : 12/09/2018@1945HRS
 VRN : SJH76X
 MODEL : Toyota Estima
 TP VRN : SMC9047L

		<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>					
<u>1. Body Repair</u>					
1 Rear Bumper		1	\$ 585.00	\$ 585.00	de
2 Rear Bumper Clips		10	\$ 5.50	\$ 55.00	we
3 Rear Bumper Retainer Outer LH/RH		2	\$ 55.00	\$ 110.00	we
4 Rear Bumper Retainer Inner LH/RH		2	\$ 55.00	\$ 110.00	we
5 Towing Cover		1	\$ 25.00	\$ 25.00	mi
6 Rear Bumper Reflector Light LH	s/nett	1	\$ -	\$ -	we
7 Rear Bumper Reverse Sensor	s/nett	1	\$ 200.00	\$ 200.00	nn
8 Rear Bumper Inner Sponge LH		1	\$ 65.00	\$ 65.00	?
9 End Panel		1	\$ 660.00	\$ 660.00	Ry
10 End Panel Upper Garnish		1	\$ 271.00	\$ 271.00	?
11 Rear Fender LH		1	\$ 1,209.00	\$ 1,209.00	Ry
12 Rear Fender Shield LH		1	\$ 95.00	\$ 95.00	x
13 Rear Fender Shield Clips LH		10	\$ 5.50	\$ 55.00	x
14 Rear Fender Inner Trim LH		1	\$ 755.00	\$ 755.00	x
15 Rear Fender Inner Trim Cover LH		1	\$ 325.00	\$ 325.00	?
16 Spare Tyre Compartment	Repair	1	\$ -	\$ -	
17 Tailgate		1	\$ 1,700.00	\$ 1,700.00	bt
18 Tailgate Hinge LH/RH		2	\$ 60.00	\$ 120.00	Ry
19 Tailgate Autodoor Checker	Sample	1	\$ -	\$ -	
20 Tailgate Windscreen Moulding		1	\$ 100.00	\$ 100.00	we
21 Tailgate Windscreen Sealant	s/nett	1	\$ 45.00	\$ 45.00	we
22 Tailgate Toyota Logo		1	\$ 75.00	\$ 75.00	we
23 Tailgate Estima Logo		1	\$ 47.00	\$ 47.00	we
24 Rear Airvent LH		1	\$ 145.00	\$ 145.00	?
25 Rear Chassis LH	Repair	1	\$ -	\$ -	
Discount - 25%				\$ (1,611.75)	
TOTAL				\$ 5,080.25	

2. Labor Charges

Panel beat, cut, weld, re-align and replace damaged parts	1,250.	\$ 2,000.00
Spray painting on rear portion of affected area	1,250	\$ 1,500.00
Check wiring, re-align taillamp and ensure proper function	30.	\$ 80.00
Remove & reinstall bumper sensors	30.	\$ 120.00
Cavity Treatment on new parts	60	\$ 160.00

Realign chassis member	\$ X 2,500.00
Remove & reinstall rear reverse camera	\$ 40,120.00
Remove & reinstall fuel tank to facilitate cutting and repairing work	\$ X 180.00
Remove & reinstall tailgate windscreen	120 \$ 180.00
Transfer tailgate lock & mechanism to new tailgate	\$ 60 200.00
Conduct water seepage test	\$ 40.120.00
Remove & reinstall rear trim compartment to facilitate cutting and repairing	\$ 60 150.00
Remove & refit tailgate spoiler	\$ 60 150.00

Sub Total : \$ 7,460.00

Grand Total : \$ 12,540.25

Add 7% GST : \$ 877.82

Nett Total : \$ 13,418.07

No. of repair days: 10

CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

Tanjin 97495749
WP
19/1/18 @ 1800
sure (Hantowin).
86 days.
Resurvey before/after paint.
To check p/p or L/S.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: