

ASS. REC. BY:

REF:

CS/CTI18017085/ Gvd3<sup>n2</sup>

Special Instruction:

WV Veror  
Menimen

Guo Chang

ASSIGNMENT (Office)

From (Person):

Chong Boon Sun

of

CTI

Date/Time: 19/9/18 @ 4:39pm.

Estimated Cost:

Bill to:

OL TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SDA 9989K

Insured:

XE 1298R

at Workshop m/s

Yew Hock Motor

Tel:

6747 23 84

of

Blk 9006, Tampines 81-93 # 01-210

Policy No:

DMCVSN1769041700

Claim No:

SNM18D0452/C82

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/09/2018

20/09/2018 @ Morning

H.O.D. Endorsement:

CA / EV / REP. / REV 24 HRS Cup

Date/Time:

4:49pm @ 19/9/18

Person Contacted:

Michelle

Vehicle

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SDA 9989K - NA/UDI18016871/ R3
	XE 1298R - NA/UDI18016871/ R3
	DOA: 12/9/18
	DOA: 12/9/18
9/1/18	Final fig \$ 6326.92 confirmed by email (Ref 2601.25, 2979 CNoLS)

REF: CTS

C119815

(2021)

## ASSIGNMENT

From:

Date:

20/9/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SDA 9989K

at Workshop m/s

New Hock Motor

of Blk 9006, Tampines St. 93 # 01-210

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$44K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. 1-24 HRS <sup>up</sup>

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SDA 9989K

Veh Regn:

19 Aug 2011

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Camry

C.C.

2362

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

112643

T/Radio, Insured / Std / NI / NA

Eng/No:

C/No:

MR053BK 4007046749

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD/A/Rim or

Tyre Size:

F: 215/60R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

20-09-18

Survey held at

W/S

12pm

Des. of Damages ☒ Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$6247.44

RECEIVED 12 NOV 2018

*[Signature]*  
9/11/2018.

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2) 9/11 - typist

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Report Format:

merimen

Lump Sum / I.B.I. (\$)

6306.92

Survey Fee:

Transportation

S + RS (\$)

Photos

Others

TOTAL

220



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18017085/Gvd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 19-09-2018	
		Code : CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	XE 1298R	Veh. Inspected	SDA 9989K
Policy No.	DMCVSN1769041700	Coverage (\$)	0.00
Claim No.	SNM18D04521C02	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	19/09/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	12/09/2018	Inspection Date	20/09/2018
Survey held at	BLK 9006, TAMPINES ST.93# 01-210		
Repairer	YEW HOCK MOTOR		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

**Veron Chen (LKKAUTO)**

**From:** Veron Chen (LKKAUTO)  
**Sent:** Friday, 9 November 2018 4:14 PM  
**To:** 'Yew Hock Motor'  
**Cc:** SUR  
**Subject:** RE: [Spam-pop3] RE: ACCIDENT VEHICLE NUMBER SDA 9989 K DATE OF ACCIDENT : 12 SEPT 2018

Dear Chris,

Noted with thanks @ 5 working days.

**Kindly send Final invoice and all supporting documents to CHINA TAIPING**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Yew Hock Motor <yhmotor@singnet.com.sg>  
**Sent:** Friday, 9 November 2018 1:38 PM  
**To:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Subject:** RE: [Spam-pop3] RE: ACCIDENT VEHICLE NUMBER SDA 9989 K DATE OF ACCIDENT : 12 SEPT 2018

Hi Veron,

We refer to your email dated 08 Nov 2018.

Please be informed that the repair costs of S\$6326.92 is confirmed except the days of repair.

Best Regards,  
Yew Hock Motor  
Chris

**From:** Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]  
**Sent:** Thursday, 8 November, 2018 2:42 PM  
**To:** Yew Hock Motor <yhmotor@singnet.com.sg>  
**Subject:** [Spam-pop3] RE: ACCIDENT VEHICLE NUMBER SDA 9989 K DATE OF ACCIDENT : 12 SEPT 2018

Dear Chris,

**WITHOUT PREJUDICE**

Finalise amount \$6,326.92 @ 5 working days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Yew Hock Motor <yhmotor@singnet.com.sg>

**Sent:** Thursday, 1 November 2018 2:49 PM

**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>

**Subject:** FW: ACCIDENT VEHICLE NUMBER SDA 9989 K DATE OF ACCIDENT : 12 SEPT 2018

Hi Veron,

We refer to our telephone conversation and our email to you since 18 Oct 2018 with attached.

Please let us have your reply soonest possible.

Best Regards,

Yew Hock Motor

Chris

---

**From:** Yew Hock Motor [mailto:yhmotor@singnet.com.sg]

**Sent:** Thursday, 18 October, 2018 1:59 PM

**To:** 'Veron Chen (LKKAuto)' <veronchen@lkkauto.com>

**Subject:** ACCIDENT VEHICLE NUMBER SDA 9989 K DATE OF ACCIDENT : 12 SEPT 2018

Hi Veron,

As spoken, kindly refer to attached.

Best Regards,

Yew Hock Motor

---

**From:** Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

**Sent:** Wednesday, 17 October, 2018 2:08 PM

**To:** Yew Hock Motor <yhmotor@singnet.com.sg>; SUR <sur@lkkauto.com>

**Subject:** [Spam-pop3] RE: ACCIDENT VEHICLE NUMBER SDA 9989 K DATE OF ACCIDENT : 12 SEPT 2018

Dear Chris,

WITHOUT PREJUDICE

Offer \$4729.19 @ 5 working days.

Kindly check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Yew Hock Motor <yhmotor@singnet.com.sg>

**Sent:** Friday, 12 October 2018 3:46 PM

**To:** SUR <sur@lkkauto.com>

**Subject:** FW: ACCIDENT VEHICLE NUMBER SDA 9989 K DATE OF ACCIDENT : 12 SEPT 2018

Hi Veron,

As spoken.

Best Regards,  
Yew Hock Motor  
Chris

---

**From:** Yew Hock Motor [mailto:yhmotor@singnet.com.sg]

**Sent:** Tuesday, 2 October, 2018 1:39 PM

**To:** 'quoqiang@lkkauto.com' <quoqiang@lkkauto.com>

**Subject:** ACCIDENT VEHICLE NUMBER SDA 9989 K DATE OF ACCIDENT : 12 SEPT 2018

Hi Guo Qiang,

We refer to the above matter.

As spoken, we attached herewith the check items and before painting photos for your attention.

Kindly confirm the repair cost of S\$7206.92 ( Before Gst ) soonest possible.

Best Regards,  
Yew Hock Motor  
Chris

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1198K
Vehicle Details	
Vehicle No.:	SDA9989K
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.4 AUTO ABS AIRBAG
Primary Colour:	Grey
Manufacturing Year:	2011
Engine No.:	2AZE226257
Chassis No.:	MR053BK4007046749
Maximum Power Output:	123.0 kW (164 bhp)
Open Market Value:	\$24,155.00
Original Registration Date:	19 Aug 2011
First Registration Date:	19 Aug 2011
Transfer Count:	0
Actual ARF Paid:	\$24,155.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Aug 2021
PARF Rebate Amount:	\$14,493.00
Intended COE Rebate Details	
COE Expiry Date:	18 Aug 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$56,300.00
COE Rebate Amount:	\$16,375.00
<b>Total Rebate Amount:</b>	<b>\$30,868.00</b>

The information contained herein is correct as at 21 Sep 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/09/2018 11:24
Date Of Accident	12/09/2018 14:00
Exact Location Of Accident	387 CHANGI RD PARKING LOT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDA9989K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHEONG BEE PTE LTD
Co Reg No	-
Email Address	CHEONGBE@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-96689743
Alternative Phone No	OFFICE-67421802

### Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY
Exact Purpose for which vehicle was being used at time of accident	PARKED VEH
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	UNITED OVERSEAS INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DHOM110121881206
Cover Note Number	

### Driver

Name of Driver	KHOO TUAN KENG
NRIC No	S2562515C
Date Of Birth	06/07/1951
Occupation	INDOOR
Date Of Driving Pass	17/11/1969
Driving Experience	48 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96689743
Fax Number	
Contact Number	
Email Address	CHEONGBE@SINGNET.COM.SG



Address	3 SIGLAP ROAD #06-17
Postcode	448907
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	SJS7400P
Insurance Company of Driver's Own Vehicle	NTUC INCOME INSURANCE CO-OPERATIVE LTD

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.


#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	NO VIDEO CAPTURED (ENGINE OFF )
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE1298R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	JIMBRAN BIN MAIJOL
NRIC/Passport Number	G7325646T
Contact Number	81062547
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

MY CAR WAS PARKED AT MY OFFICE FRONT  
CARPARK. A LORRY XE 1298R driven by  
Jimbran Bin Majid reversed at collided  
onto my car front portion.  
(Refer To Attached).

Involving Party driver's company:  
m/s Building Resources Industries

DECLARATION

I/We declare the foregoing particulars are true in every respect.

中美(私營)有限公司  
CHEONG BEE PTE LTD  
387 CHANGI RD SINGAPORE 41111  
TEL: 6742 1802 FAX: 6744 3093  
EMAIL: cheongbee@com.net.sg

Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

17/09/18

on: 20/09/18 (Thursday)

Tel: 67472384 Fax: 67482758

Guo Qif 82880282 (LKK)  
20/9/18

18/9/2018

VEHICLE NUMBER : SDA 9989 K  
MODEL : TOYOTA CAMRY 2.4A "2011  
DATE OF ACCIDENT : 12/9/2018  
THIRD PARTY : XE 1298 R

(TAMPINES)

## REPLACEMENT OF PARTS

QTY	DESCRIPTION	UNIT PRICE	TOTAL PRICE
1 PC	FRONT BONNET	1,410.00	1,410.00
2 PCS	FRONT BONNET HINGE @\$60.30	120.60	1,530.60
1 PC	FRONT BONNET LOCK	129.40	1,660.00
1 PC	FRONT BONNET INSULATOR	480.00	2,140.00
11 PCS	FRONT BONNET INSULATOR CLIPS @\$5.00	55.00	2,195.00
1 PC	FRONT BONNET RUBBER	62.00	2,257.00
1 PC	FRONT HEAD LAMP (LH)	3,250.00	5,507.00
1 PC	FRONT HEAD LAMP SUPPORT PANEL	959.70	6,466.70
1 PC	FRONT FENDER	810.00	7,276.70
1 PC	FRONT FENDER COWLING	158.00	7,434.70
10 PCS	FRONT FENDER COWLING CLIPS @\$5.00	50.00	7,484.70
1 SET	FRONT GRILLE WITH MOULDING	549.42	8,034.12
1 PC	FRONT GRILLE LOGO	45.90	8,080.02
1 PC	FRONT BUMPER	570.20	8,650.22
1 PC	FRONT BUMPER CORE	100.00	8,750.22
2 PCS	FRONT BUMPER SIDE BRACKET @\$95.00	190.00	8,940.22
6 PCS	FRONT BUMPER CLIPS @\$5.00	30.00	8,970.22
1 PC	FRONT BUMPER FOG LAMP (LH)	283.50	9,253.72
1 PC	FRONT BUMPER FOG LAMP GARNISH	100.00	9,353.72
	LESS 25%	2,337.68	7,016.04

Signature: \_\_\_\_\_

SWA

6247.44

89 28.17

# YEW HOCK MOTOR

Reg. no: 251827/00C

Blk 9006 Tampines Street 93 #01-210 Singapore 528840

Tel: 67472384 Fax: 67482758

M/S CHEONG BEE PTE LTD  
BLK 9006 TAMPINES STREET 93  
#01-210  
SINGAPORE 528840

DATE: 20/9/2018

## SUPPLEMENTARY

VEHICLE NUMBER : SDA 9989 K  
MODEL : TOYOTA CAMRY 2.4A '2011  
DATE OF ACCIDENT : 12/9/2018  
THIRD PARTY : XE 1298 R

(TAMPINES)

## REPLACEMENT OF PARTS

1 PC	FRONT NUMBER PLATE GANISH	Re	93.50
	LESS 25%		23.38
			<u>70.13</u> (40(SN))
1 PC	FRONT NUMBER PLATE	BT	45.00
		S/NETT	40
	TOTAL BEFORE GST		<u>115.13</u>

YOURS FAITHFULLY,



~~6789.52~~  
~~25%: 592.14~~  
~~6487.14~~  
 4691.69

S/n  
 LC

# 7,749.22  
 1,937.30  
 -----  
 # 5,811.92  
 45.00  
 -----  
 1,350.00  
 -----  
 # 7,206.92

LKK (Nivita)

Called on

19/09/18 @

4-52pm to

Arrange for Survey

on: 20/09/18 (Thursday)

M/S CHEONG BEE PTE LTD  
387 CHANGI ROAD  
SINGAPORE 419836

## YEW HOCK MOTOR

Reg. no: 251827/00C

Blk 9006 Tampines Street 93 #01-210 Singapore 528840

Tel: 67472384 Fax: 67482758

STF21035

5 Days.

part by part.

before part photos.

DATE:

18/9/2018

Give Q's of 8880282 (LKK)

20/9/18

VEHICLE NUMBER : SDA 9989 K  
MODEL : TOYOTA CAMRY 2.4A "2011  
DATE OF ACCIDENT : 12/9/2018  
THIRD PARTY : XE 1298 R

(TAMPINES)

### REPLACEMENT OF PARTS

1 PC	FRONT BONNET	- BT	1,410.00
2 PCS	FRONT BONNET HINGE	@\$60.30 X	120.60 X
1 PC	FRONT BONNET LOCK	X	129.40 X
1 PC	FRONT BONNET INSULATOR	X	480.00 X
11 PCS	FRONT BONNET INSULATOR CLIPS	@\$5.00 - MC	55.00
1 PC	FRONT BONNET RUBBER	?	62.00
1 PC	FRONT HEAD LAMP (LH)	- Cut	3,250.00
1 PC	FRONT HEAD LAMP SUPPORT PANEL		959.70
1 PC	FRONT FENDER	X repair	810.00 X
1 PC	X FRONT FENDER COWLING	?	155.00 X
10 PCS	FRONT FENDER COWLING CLIPS	@\$5.00 ?	50.00
1 SET	FRONT GRILLE WITH MOULDING	- CHA	549.42
1 PC	FRONT GRILLE LOGO	- MC	45.90
1 PC	FRONT BUMPER	- Re ?	570.20
1 PC	FRONT BUMPER CORE	?	100.00
2 PCS	FRONT BUMPER SIDE BRACKET	@\$95.00 ?	190.00
6 PCS	FRONT BUMPER CLIPS	@\$5.00 - MC	30.00
1 PC	FRONT BUMPER FOG LAMP (LH)	?	283.50
1 PC	FRONT BUMPER FOG LAMP GARNISH	?	100.00
			9,350.72
LESS 25%			2,337.68
			7,013.04

**LKK Auto Consultants** Notice to the Repairer of the following:

- To resurvey before/after survey painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be supplied and is subject to final approval from Insurance Company

**ACKNOWLEDGED BY REPAIRER**

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

TO REMOVE AND REPAIR AIR CON.

CHARGES TO REMOVE AND REPLACE ALL

REMOVED PARTS.

SPRAY PAINTING ON AFFECTED AREAS.

TOTAL BEFORE GST

100.00

750.00

950.00

8,813.04

500

750

LKK (MVR 100)

Called on

19/09/18 @

4-52 pm to

Arrange for Survey

on: 20/09/18 (Thursday)

# YEW HOCK MOTOR

Reg no 251827/00C

Bldg 9006 Tampines Street 93 #01-210 Singapore 525640

Tel: 67472384 Fax: 67482756

5 Days

part by part

before paint photos

Quoted by 82880282 (LKK)  
20/9/18

DATE:

18/9/2018

M'S CHEONG BEE PTE LTD

387 CHANGI ROAD

SINGAPORE 419836

VEHICLE NUMBER

MODEL

DATE OF ACCIDENT

THIRD PARTY

SDA 9989 R

TOYOTA CAMRY 2.4A 2011

12/9/2018

XE 1298 R

(TAMPINES)

## REPLACEMENT OF PARTS

1 PC	FRONT BONNET	1 BT	1767.4	110.00	/
2 PCS	FRONT BONNET HINGE @ \$60.30	X		120.60	X
1 PC	FRONT BONNET LOCK	X		129.40	X
1 PC	FRONT BONNET INSULATOR	X		480.00	X
11 PCS	FRONT BONNET INSULATOR CLIPS @ \$5.00	X		55.00	/
1 PC	FRONT BONNET RUBBER	X		67.00	/
1 PC	FRONT HEAD LAMP (LH)	X		5,250.00	X
1 PC	FRONT HEAD LAMP SUPPORT PANEL	X		810.00	X
1 PC	FRONT FENDER	X		155.00	X
1 PC	FRONT FENDER COWLING	X		80.00	/
10 PCS	FRONT FENDER COWLING CLIPS @ \$5.00	X		50.00	/
1 SET	FRONT GRILLE WITH MOULDING	X		45.90	/
1 PC	FRONT GRILLE LOGO	X		70.20	/
1 PC	FRONT BUMPER	X		100.00	/
1 PC	FRONT BUMPER CORE	X		150.00	/
2 PCS	FRONT BUMPER SIDE BRACKET @ \$95.00	X		30.00	/
6 PCS	FRONT BUMPER CLIPS @ \$5.00	X		283.50	/
1 PC	FRONT BUMPER FOG LAMP (LH)	X		100.00	/
1 PC	FRONT BUMPER FOG LAMP GARNISH	X		9,350.72	/
				2,337.68	/
				7,013.04	/
				100.00	/
				750.00	500
				950.00	750
				8,813.04	

LKK Auto Consultants Services include:

The Repairs of the following:

- To survey before/after spray painting
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved by the Insurer
- Is subject to final approval from Insurer

Acknowledged by Repairer

Signature:

Date:



AND REPAIR AIR CON.

CHARGES TO REMOVE AND REPLACE ALL

PARTS

PAINTING OF AFFECTED AREAS.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118017085/GVD3N2

Date: 14/11/2018

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1769041700
Claimant Vehicle No :	SDA9989K	Insured Vehicle No :	XE1298R
Date of Loss:	12/09/2018	Nature of Claim:	TP
		Claim No:	SNM18D04521C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SDA9989K	Engine No:	2AZE226257
Make & Model:	TOYOTA CAMRY, 2.0 (A)	Chassis No:	MR053BK4007046749
Reg. Date:	19/08/2011 (Man. Year: 2011)	Odometer:	112643 km
Colour:	Grey		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,128.16	4,976.91	2,151.25	30.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,350.00	450.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>8,928.16</b>	<b>6,326.91</b>	<b>2,601.25</b>	<b>29.14</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>624.97</b>	<b>442.88</b>	<b>182.09</b>	<b>29.14</b>
<b>Nett Amount (\$\$)</b>	<b>9,553.13</b>	<b>6,769.79</b>	<b>2,783.34</b>	<b>29.14</b>

## INSPECTION

Date of Assignment:	19/09/2018	
Date Inspected:	20/09/2018	Inspected At:
		Yew Hock Motor (Tampines)
		Blk 9006 Tampines Street 93, #01-210
		Singapore 528840
Estimated Period of Repair:	5.0 days	

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$6,326.92



## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 14 Nov 2018)
<b>Parts:</b>	143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SDA9989K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	1,410.00 FL	*1,267.40 FL
2	2		*FRONT BONNET HINGE	Not Necessary	120.60 FL	*- FL
3	1		*FRONT BONNET LOCK	Not Necessary	129.40 FL	*- FL
4	1		*FRONT BONNET INSULATOR	Not Necessary	480.00 FL	*- FL
5	11		*FRONT BONNET INSULATOR CLIPS	Necessary	55.00 FL	*55.00 FL
6	1		*FRONT BONNET RUBBER	Twisted	62.00 FL	*62.00 FL
7	1		*FRONT HEAD LAMP (LH)	Cut	3,250.00 FL	*3,250.00 FL
8	1		*FRONT HEAD LAMP SUPPORT PANEL	Repair	959.70 FL	*- FL
9	1		*FRONT FENDER	Repair	810.00 FL	*- FL
10	1		*FRONT FENDER COWLING	Not Necessary	155.00 FL	*- FL
11	10		*FRONT FENDER COWLING CLIPS	Necessary	50.00 FL	*50.00 FL
12	1		*SET FRONT GRILLE WITH MOULDING	Cracked	549.42 FL	*549.42 FL
13	1		*FRONT GRILLE LOGO	Necessary	45.90 FL	*45.90 FL
14	1		*FRONT BUMPER	Deformed	570.20 FL	*570.20 FL
15	1		*FRONT BUMPER CORE	Cracked	100.00 FL	*100.00 FL
16	2		*FRONT BUMPER SIDE BRACKET	Broken	190.00 FL	*165.80 FL
17	6		*FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
18	1		*FRONT BUMPER FOG LAMP (LH)	Broken	283.50 FL	*283.50 FL
19	1		*FRONT BUMPER FOG LAMP GARNISH	Cracked	100.00 FL	*100.00 FL
20	1		*FRONT NUMBER PLATE GARNISH	Deformed	70.12 FS	*40.00 FS
21	1		*FRONT NUMBER PLATE	Bent	45.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,465.84</b>	<b>6,609.22</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>2,337.68</b>	<b>1,632.31</b>
<b>Total Parts (\$\$)</b>	<b>7,128.16</b>	<b>4,976.91</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIX AIR CON	New	100.00	100.00
2	LABOUR CHARGES TO REMOVE AND REPLACE ALL DAMAGED PARTS	New	750.00	500.00
3	SPRAY PAINTING ON AFFECTED AREAS	New	950.00	750.00
Gross Labour Cost (\$\$)			1,800.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >