

Shrewsbury *P. Alan*

REF: NS/INC18017106/R1A52

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SJK 5027P

Policy No. 5087291133-01 230418 - 220419

Claims No. MT/1011897-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

		N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHB 18614 Yr Regn: 2014 / July

Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) / Prime Mover /
Truck / Trailer or _____

Make: TOYOTA PRINS 1-8 c.c. 1298

Colour: MAROON A/C: Insured / Std / NI / NA

Sp. Reading: 392899 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTOKN36U30S747052

Gen. Cond: Good / (Fair) / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / (SRim) / STD A/Rim or _____

Tyre Size: F: _____ R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or FALKEN

Front: _____ Rear: _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 17/09/18 D.O.I. 19/02/18

Survey held at SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or FRt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SHB 18614 - CS / TLT09006236 / Zj DA: 200309 09/18/2014

SJK 5027P - CS / ATN 10007680 / Rvgj DA: 170310

SJK5027P / NTRC

Lump Sum \$1150f. 3 days
(Red: 2229.10; 59%)

RECEIVED 20 DEC 2018

Date/Time, File Pass to? : Preli. Report

17/12/14 : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:	<input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/>
Transportation:	
\$ + RS _____ \$	
Photos	
Others	
TOTAL	<input type="text"/>

- Add Fee:
- : Site Insp (\$ _____)
 - : Interview (\$ _____)
 - : Tech. Invs (\$ _____)
 - : Weekend (\$ _____)

Report Format : TP
Lump Sum / I.B.I: (\$ 1150)



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18017106/R1tb

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 20-09-2018
189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJK 5027P	Veh. Inspected	SHB 1861U
Policy No.	5087291133-01	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	19/09/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	17/09/2018	Inspection Date	19/09/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Income: Follow-Through Survey

Date : 26/12/2018

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate
1	MT/1023223-002	CITYCAB PTE LTD	SHC 7921K	SMA 7034Y	10/12/2018	\$ 2,703.40
2	MT/1024005-002	COMFORT TRANSPORTATION PTE LTD	SH 7897R	SFU 8029J	16/12/2018	\$ 9,646.26
3	MT/1024171-002	CITYCAB PTE LTD	SHA 9227D	G8E 7717U	14/12/2018	\$ 10,051.12
4	MT/1011897-002	SMRT TAXIS PTE LTD	SHB 1861U	SJK 5027P	17/9/2018	\$ 3,729.10
5	MT/1024163-002	CITYCAB PTE LTD	SHA 8047M	YP 8151P	15/12/2018	\$ 2,094.23

Hello, NAC_PAYA_UBI_800601

Change Language Change Password Log Out

My Desktop
Notice of Loss

Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="17/09/2018 09:51"/>							
Vehicle No.(For Motor)	<input type="text" value="SJK5027P"/>	Certificate Number	<input type="text"/>							
<input type="button" value="Search"/>										
Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5087291133-01		NG SU MIN RACHEL	S9604739H	GPC	drive CLASSIC	SJK5027P	SJK5027P	23/04/2018	22/04/2019
<input type="button" value="Continue"/>										

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/09/2018 13:59
Date Of Accident	17/09/2018 13:00
Exact Location Of Accident	BOON LAY WAY JUNCTION JURONG WEST CTRL 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB1861U
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	
Driver	
Name of Driver	AU BENG CHEOK
NRIC No	S7513667F
Date Of Birth	27/04/1975
Occupation	OUTDOOR
Date Of Driving Pass	30/08/1996
Driving Experience	22 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 967
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING STRAIGHT ALONG BOON LAY WAY AT THE CENTRE LANE. WHEN I WAS APPROACHING THE TRAFFIC JUNCTION, TRAFFIC LIGHT WAS GREEN IN MY FAVOUR AND THUS I CONTINUE PROCEEDED STRAIGHT. WHILE ENTERING THE JUNCTION, THE VEHICLE SJK5027P FROM THE OPPOSITE DIRECTION DID NOT GIVE WAY AND MAKING A RIGHT TURN. AS A RESULT, THE FRONT LEFT PORTION OF THE VEHICLE SJK5027P COLLIDED WITH THE FRONT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: FILE TOO LARGE
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJK5027P
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver DAVID NG
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No: Of Passenger (Including Driver)


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Alu 17/9/2018

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No.: SHB1861U
 Vehicle Type: H10 - Public Transport Taxi (Motor Car)
 Vehicle Attachment 1: Air-Con (Taxi)
 Vehicle Scheme: Taxi (Company)
 Vehicle Make: TOYOTA
 Vehicle Model: PRIUS TAXI (SMRT)
 Chassis No.: JTDM36U305747052
 Propellant: Petrol-Electric
 Engine No.: 2ZR6096499
 Motor No.: 3JM6096499
 Engine Capacity: 1798 cc
 Power Rating: 60.0 kW
 Maximum Power Output: 100.0 kW (134 bhp)
 Maximum Laden Weight: 1805 kg
 Unladen Weight: 1370 kg
 Year Of Manufacture: 2014
 Original Registration Date: 16 Jul 2014
 Lifespan Expiry Date: 15 Jul 2022
 COE Category: A - Car up to 1600cc & 97kW (130bhp)
 PQP Paid: \$53,269.00
 COE Expiry Date: 15 Jul 2022
 Road Tax Expiry Date: 15 Jul 2019
 PARF Eligibility Expiry Date: 15 Jul 2022
 Inspection Due Date: 15 Jul 2019
 Intended Transfer Date: 02 Jan 2019
 CO2 Emission: 92.00 (g/km)
 CEV/VES Rebate Utilised Amount: \$30,000.00
 CO Emission: -
 HC Emission: -
 NOx Emission: -
 PM Emission: -

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print

TP

GIA

SMRT Accident Taxi Repair Estimates

Section A - To be completed by Claims Advisor/Duty Officer at Accident Reporting Centre

Reg. No. : SHB1861U Ref. No. TAX 9 / 18 / 2074

Make / Model : TOYOTA PRIUS Reg. Date : 16/07/2014

Name of Driver : AU BENG CHEOK

Date/Time of Accident : 17/09/2018 13:00

Surveyer is Required ? YES / NO


If Yes, VICOM / LKK / LH Teo / AIS (Please circle one)

Taxi is Towed Back ? YES / NO

Replacement Taxi Issued ? YES / NO

Accident Repair Job Card No. : 24097979

Special Instruction to ARC, if any :



Signed : _____ Date : _____

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U305747052 Mileage : _____

Date Prepared : 18/09/2018 Repair Completed date/time: _____

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	\$ <u>507.00</u>	\$ _____
Total Spray Painting Charges :	\$ <u>558.00</u>	\$ _____
Total Material Charges :	\$ <u>1459.87</u>	\$ _____
Other Charges :	\$ <u>240.00</u>	\$ _____
TOTAL :	\$ <u>2764.87</u> 3729.10	\$ <u>0</u>

No. of Repair Days : [4] days [2] days **4/5**

Signature : Prepared by: MING Adjusted by: [Signature]
 18/09/2018 16:12 17/09/18 @ 1510

[Handwritten signature and date]
 18/09/18

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

QN No. _____ Invoice No. _____ Invoice Date _____

Signed : _____ Date : _____

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	507.00	200
Total Labour	\$ 507.00	\$ -

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	200
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	X
Total Spray Painting & Panel Beating	\$ 558.00	\$ -

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	X
TO WASH AND VACUUM	60.00	X
TO REPLACE SUNDRY PARTS	100.00	X
Total Other Costs	\$ 240.00	\$ -

Part 4 - Spare Parts / Material Usage

Reservation No : _

Page ()

To be completed by Service Advisor, ARC							Surveyor Adj
Part Number	Parts Description	Qty	List Price (\$)	Discount (%)	Final Price (\$)	Repair (R) Replace (/)	Not given (x) Repair (R) Replace (/)
52119-47930	BUMPER FRT	1	482	25%	361.5	/	R
52127-47903	COVER, FR BUMPER HOLE RH	1	18.5	25%	13.88	/	R
53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	1	311.1	25%	233.33	/	X ✓ CWA
53111-47040	GRILLE RADIATOR	1	310.6	25%	232.95	/	X NN
75310-47010	EMBLEM FRONT	1	86.5	25%	64.88	/	✓
	NUMBER PLATE	1	15	0%	15	/	CWA ✓
	NUMBER PLATE FRAME	1	12	0%	12	/	CWA ✓
52114-47140	BRACKET, FR BUMPER	1	110.4	25%	82.8	/	X ✓ net
52021-47023	BUMPER REINFORCEMENT FRT	1	498.4	25%	373.8	/	? ✓ BT
52611-47080	BUMPER ENERGY ABSORBER FRT	1	78.8	25%	59.1	/	? ✓ CWA
57014-47030	ARM SUB-ASSY, FR BUMPER LH	1	250.4	25%	187.8	/	? ✓ BT
57013-47030	ARM SUB-ASSY, FR BUMPER RH	1	250.4	25%	187.8	/	? X PVC
TOTAL MATERIALS					LUMPSUM REPAIR 20%	\$	1,459.87

3729.10



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 50 Woodlands Industrial Park E4, Singapore 757105
 FAX Number : 6365592
 Estimator Telephone Number : 6882623
 Accident Reporting Number : 6992672

Date Generated : 17/12/2018

User ID : PohSuan

Section A - Accident Details

Registration Number	SHB1861U
Case Reference Number	TAX/09/18/2074
Registration Date	16/07/14
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	AU BENG CHEOK
Type of Accident	Head On
Accident Date and Time	17/09/18 1:00 PM
Accident Reported Date and Time	17/09/18 1:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24097979
Special Instruction to ARC, if any	
Prepared Date and Time	14/10/18 11:49 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$558.00	\$200.00
Total Spare Part Cost	\$1,824.84	\$1,028.71
Total Other Cost	\$240.00	(\$278.71)
TOTAL COST	\$3,129.84	\$1,150.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Kim Ming Chin	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date		
Signature	<input type="text"/>	<input type="text"/>
Remarks		



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 50 Woodlands Industrial Park E4, Singapore 757105
 FAX Number : 63685592
 Estimator Telephone Number: 66602023
 Accident Reporting Number : 66652673

Date Generated : 17/12/2018
 User ID : PehBuen

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1812-0375	Invoice Number	
Quotation Date	17.12.2018	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$507.00	\$200.00
Total Labour	\$507.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	\$180.00	\$0.00 X M
Total Spray Painting & Panel Beating	\$558.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00 X M
TO WASH AND VACUUM	\$60.00	\$0.00 X M
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00 X M
Lump Sum Adjustment by Surveyor	\$0.00	(\$278.71)
Total Other Costs	\$240.00	(\$278.71)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6505517		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$0.00	Replace	Repair
			COVER, FR BUMPER HOLE RH	1.00	\$18.50	25.00	\$0.00	Replace	Repair
			BUMPER GRILLE SUB-ASSY, LOWER	1.00	\$311.10	25.00	\$233.33	Replace	Replace
6505573		53111-47040	GRILLE, RADIATOR	0.00	\$310.60	25.00	\$0.00	Replace	Not Given
6505638		75310-47010	EMBLEM FRONT	1.00	\$86.50	25.00	\$64.88	Replace	Replace
			NUMBER PLATE	1.00	\$15.00	0.00	\$15.00	Replace	Replace
			NUMBER PLATE FRAME	1.00	\$12.00	0.00	\$12.00	Replace	Replace
			BRACKET, FR BUMPER	1.00	\$110.40	25.00	\$82.80	Replace	Replace
		52021-47023	BUMPER REINFORCEMENT FRT	1.00	\$498.40	25.00	\$373.80	Replace	Replace
		52611-47080	BUMPER ENERGY ABSORBER FRT	1.00	\$78.80	25.00	\$59.10	Replace	Replace
			ARM SUB-ASSY, FR BUMPER LH	1.00	\$250.40	25.00	\$187.80	Replace	Replace
			ARM SUB-ASSY, FR BUMPER RH	0.00	\$250.40	25.00	\$0.00	Replace	Not Given
Total					\$2,424.10		\$1,028.71		

1028.71
 + 200.00
 + 200.00

 1428.71
 - 202

 1142.97
 415 \$1150/-
 3 days



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18017106/R1tbs2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556	Date: 02-01-2019
	Code: INC4



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJK 5027P	Veh. Inspected	SHB 1861U
Policy No.	5087291133-01	Coverage (\$)	0.00
Claim No.	MT/1011897-002	Excess (\$)	0.00
Assign From		Assign Date	19/09/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS 1.8	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U305747052	Colour	MAROON
Odometer	392899	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	FALKEN	5 mm
L/H Front Tyre	195/65R15	FALKEN	5 mm
R/H Rear Tyre	195/65R15	FALKEN	5 mm
L/H Rear Tyre	195/65R15	FALKEN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/09/2018	Inspection Date	19/09/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No. 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1861U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER GRILLE SUB-ASSY, LOWER (DISC 25%)	CRACKED	311.10	233.33
1	EMBLEM FRONT (DISC 25%)	NECESSARY	86.50	64.88
1	BRACKET, FR BUMPER (DISC 25%)	NECESSARY	110.40	82.80
1	BUMPER REINFORCEMENT FRT (DISC 25%)	BENT	498.40	373.80
1	BUMPER ENERGY ABSORBER FRT (DISC 25%)	CRACKED	78.80	59.10
1	ARM SUB-ASSY, FR BUMPER LH (DISC 25%)	BENT	250.40	187.80
1	NUMBER PLATE (SN)	SCRATCHED	15.00	15.00
1	NUMBER PLATE FRAME (SN)	CRACKED	12.00	12.00
1	ARM SUB-ASSY, FR BUMPER RH	SERVICEABLE	250.40	-
1	GRILLE RADIATOR	NOT NECESSARY	310.60	-
1	BUMPER FRT	TO REPAIR SEE LABOUR	482.00	-
1	COVER, FR BUMPER HOLE RH	TO REPAIR SEE LABOUR	18.50	-
			2,424.10	1,028.71
LABOUR				
PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF BUMPER FRT AND COVER, FR BUMPER HOLE RH.			507.00	200.00
SPRAY PAINT.			558.00	200.00
TO CHECK WIRING AND SYSTEM FUNCTION.		NOT NECESSARY	80.00	-
TO WASH AND VACUUM.		NOT NECESSARY	60.00	-
TO REPLACE SUNDRY PARTS.		NOT NECESSARY	100.00	-
			-	-
			-	-
			-	-
			1,305.00	400.00
GRAND TOTAL			3,729.10	1,428.71
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,150.00

Report Ref No. NS/INC18017106/R1tbs2

Report Ref No. NS/INC18017106/R1tbs2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

A handwritten signature in black ink, appearing to be 'K.K. LAU'.

K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.