

SMRT Accident Taxi Repair Estimates

Section A - To be completed by Claims Advisor/Duty Officer at Accident Reporting Centre

 Reg. No. : SHC 4525R Ref. No. TAX 9 / 18 / 2079

Make / Model : TOYOTA PRIUS Reg. Date : 10/09/2014

Name of Driver : EFFENDI HAMID

Date/Time of Accident : 18/09/2018 09:00

 Surveyer is Required ? YES / NO

If Yes, VICOM / LKK / LH Teo / AIS (Please circle one)

 Taxi is Towed Back ? YES / NO


Replacement Taxi Issued ? YES / NO

Accident Repair Job Card No. : 24097990

Special Instruction to ARC, if any :

Signed : Date :

The damages on the Taxi are as indicated in the following diagram :


Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U905748268 Mileage :

Date Prepared : Repair Completed date/time:

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	\$ 1,352.00	\$
Total Spray Painting Charges :	\$ 2,988.00	\$
Total Material Charges :	\$ 7,773.43	\$
Other Charges :	\$ 1,210.00	\$
TOTAL :	\$ 13,323.43	\$ ()
No. of Repair Days :	[9]	[9 days - 4s]

Signature :

 Prepared by: FOO
 19/09/2018 13:25

 Adjusted by: *Pam*
 19/09/18 01:10

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

QN No. Invoice No. Invoice Date

Signed : Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	338.00	250 150
TO REPAIR REAR PORTION	1014.00	900
Total Labour	\$ 1,352.00	\$

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	200
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	X
TO REPSRAY FRONT HOOD	378.00	X
TO REPSRAY REAR BUMPER	378.00	200
TO RESPRAY REAR PANEL	180.00	100
TO RESPRAY TAIL GATE	378.00	200
TO RESPRAY REAR SPARE TYRE PANEL	180.00	X
TO RESPRAY REAR FENDER LH	378.00	200
TO RESPRAY TROUGH BACK DOOR LH	180.00	X
TO RESRAY REAR DOOR LH	378.00	200
Total Spray Painting & Panel Beating	\$ 2,988.00	\$

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	60 40
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	60
TO WASH AND VACUUM	60.00	X
TO TRANSFER REAR TAILGATE MECHANISM	120.00	60
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	120
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	60
TO REMOVE AND REFIT WIRE HARDESS	250.00	X
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30
TO REPLACE SUNDRY PARTS	100.00	X
Total Other Costs	\$ 1,210.00	\$

Section D - Details of Repair Estimates

Ref. No. TAX 9 / 18 / 2079

Part 4 - Spare Parts / Material Usage

Reservation No : _____

Page (1)

To be completed by Service Advisor, ARC							Surveyor Adj
Part Number	Parts Description	Qty	List Price (\$)	Discount (%)	Final Price (\$)	Repair (R) Replace (/)	Not given (x) Repair (R) Replace (/)
52119-47930	BUMPER FRT	1	482.00	25%	361.50	/	R
52611-47080	BUMPER ENERGY ABSORBER FRT	1	78.80	25%	59.10	/	?
52021-47023	BUMPER REINFORCEMENT FRT	1	498.40	25%	373.80	/	?
57014-47030	ARM SUB-ASSY, FR BUMPER LH	1	250.40	25%	187.80	/	?
57013-47030	ARM SUB-ASSY, FR BUMPER RH	1	250.40	25%	187.80	/	?
52114-47140	BRACKET, FR BUMPER	1	110.40	25%	82.80	/	X
	NUMBER PLATE	1	15.00	0%	15.00	/	BA ✓
	NUMBER PLATE FRAME	1	12.00	0%	12.00	/	Chp ✓
53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25%	233.33	/	X
53111-47040	GRILLE, RADIATOR	1	310.60	25%	232.95	/	X
75310-47010	EMBLEM FRONT	1	86.50	25%	64.88	/	neu ✓
52116-47040	BUMPER SUPPORT F/LH	1	76.40	25%	57.30	/	X
52115-47040	BUMPER SUPPORT F/RH	1	76.40	25%	57.30	/	X
53301-47060	HOOD PANEL	1	748.10	25%	561.08	/	X
52159-47905	BUMPER REAR	1	458.60	25%	343.95	/	DE ✓
52161-16010	BUMPER CLIPS	10	1.61	25%	12.07	/	neu ✓
52023-12240	BUMPER REINFORCEMENT REAR	1	205.70	25%	154.27	/	?
52016-47030	ARM SUB-ASSY, RR BUMPER LH	1	139.60	25%	104.70	/	?
52015-47050	ARM SUB-ASSY, RR BUMPER RH	1	139.60	25%	104.70	/	X
89997-30070	ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10%	141.66	/	X
	SENSOR REVERSE	1	180.00	0%	180.00	/	neu ✓
	PIXEL STICKER	2	60.00	0%	120.00	/	neu ✓
76088-47020	BUMPER LIP COVER RR/LH	1	72.20	25%	54.15	/	sch ✓
76891-47020	BUMPER LIP REAR	1	228.90	25%	171.67	/	sch ✓
52576-47020	BUMPER SIDE RETAINER RR/LH	1	94.80	25%	71.10	/	neu ✓
52575-47020	BUMPER SIDE RETAINER RR/RH	1	94.80	25%	71.10	/	X
52592-47021	BUMPER SEAL, RR LH	1	88.90	25%	66.68	/	?

58308-47011	UNDER COVER SUBASSY, RR FLOOR	1	514.50	25%	385.87	/	?
67005-47241	TAILGATE ASY	1	1007.90	25%	755.92	/	Rt ✓
75574-47020	TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25%	22.05	/	neu ✓
75573-47080	TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25%	22.05	/	neu ✓
75575 -47030	MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25%	22.05	/	neu ✓
	SEALANT W/SCREEN	3	37.00	0%	111.00	/	neu ✓
69350-47030	TAILGATE DOOR LOCK	1	444.10	25%	333.07	/	gX
67881-47022	TAILGATE DOOR WEATHER STRIP	1	353.40	25%	265.05	/	neu ✓
69415-47020	TAILGATE LOCK, COVER	1	15.70	25%	11.77	/	X
69431-47010	STRIKER, BACK DOOR	1	48.90	25%	36.67	/	X
75374-47051	NAME PLATE (HYBRID)	1	51.90	25%	38.92	/	neu ✓
58307-47060	END PANEL	1	602.10	25%	451.57	/	R
58336-12090	REINFORCEMENT, RR	2	34.60	25%	51.90	/	?
4006314	SEALANT SIKAFLEX	1	37.00	0%	37.00	/	X
58311-47071	SPARE TYRE PANEL	1	667.70	25%	500.77	/	X
52563-47010	TAIL LAMP BRACKET, LH	1	30.70	25%	23.02	/	?
81561-47170	TAIL LAMP LH	1	548.40	10%	493.56	/	QA ✓
61622-47030	TROUGH, BACK DOOR LH	1	110.90	25%	83.18	/	X
61602-47091	FENDER RR/LH	1	766.80	25%	575.10	/	Buc ✓
	STICKER SMRT LOGO	1	7.80	0%	7.80	/	neu ✓
	STICKER DECAL 6555 8888	1	21.60	0%	21.60	/	neu ✓
65638-47021	FENDER LINER RR/LH	1	141.30	25%	105.98	/	?
67004-47080	DOOR RR/LH	1	954.50	25%	715.88	/	R
69060-47080	DOOR LOCK RR/LH	1	709.30	25%	531.98	/	X
69410-33010	DOOR LOCK STRIKER	1	40.50	25%	30.38	/	X
TOTAL MATERIALS			LUMP SUM 20%		\$		
					7,773.43		