

## SMRT Accident Taxi Repair Estimates

### Section A - To be completed by Claims Advisor/Duty Officer at Accident Reporting Centre

Reg. No. : SHB 5919L Ref. No. TAX 9 / 18 / 2076

Make / Model : TOYOTA PRIUS 4 Reg. Date : 12/12/2017

Name of Driver : WEE SWEE POH

Date/Time of Accident : 17/09/2018 15:45

Surveyor is Required ? YES / NO

If Yes, VICOM / LKK / LH Teo / AIS (Please circle one)


Taxi is Towed Back ? YES / NO

Replacement Taxi Issued ? YES / NO

Accident Repair Job Card No. : 2409

Special Instruction to ARC, if any :

The damages on the Taxi are as indicated in the following diagram :



Signed : Date :

### Section B - To be Completed by Service Advisor, Accident Repair Centre


Chassis No : JTDKB3FU103576046 Mileage :

Date Prepared : 18/09/2018 Repair Completed date/time:

#### Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	\$ 338.00	\$
Total Spray Painting Charges :	\$ 558.00	\$
Total Material Charges :	\$ 1286.86	\$
Other Charges :	\$ 360.00	\$
<b>TOTAL</b> :	<b>\$ 2542.86</b>	<b>\$ 0 ( )</b>
No. of Repair Days :	[ 3 ] days	[ 3 ] days p/p

Signature : Prepared by: MING  
18/09/2018 10:27

Adjusted by:   
19/09/18 @ 1535

### Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

QN No. : Invoice No. : Invoice Date :

Signed : Date :

## Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	507.00	300
<b>Total Labour</b>	<b>\$ 507.00</b>	<b>\$ -</b>

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY BUMPER BEAM	180.00	X
TO REPSRAY REAR BUMPER	378.00	200
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$ 558.00</b>	<b>\$ -</b>

## Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	60
TO WASH AND VACUUM	60.00	X
TO REPLACE SUNDRY PARTS	100.00	X
<b>Total Other Costs</b>	<b>\$ 360.00</b>	<b>\$ -</b>

## Section D - Details of Repair Estimates

Ref. No. TAX 9 / 18 / 2076

## Part 4 - Spare Parts / Material Usage

Reservation No : \_

Page ( )

To be completed by Service Advisor, ARC							Surveyor Adj
Part Number	Parts Description	Qty	List Price (\$)	Discount (%)	Final Price (\$)	Repair (R) Replace ( / )	Not given (x) Repair (R) Replace ( / )
5215947913	COVER, RR BUMPER ASSY	1	423.9	25%	317.93	/	DE-
5245347010	GUARD, RR BUMPER, LOWER	1	558.3	25%	418.73	/	cut-
5216947020	COVER, GUARD RR BUMPER LOWER	1	14.8	25%	11.1	/	EX
	SENSOR REVERSE	1	180	0%	180	/	?
	PIXEL STICKER	2	60	25%	120	/	nu-
5202347030	REAR BUMPER REINFORCEMENT	1	318.8	25%	239.1	/	?
TOTAL MATERIALS					\$	1,286.86	