

INSURANCE

INS. CASE OWNER

CAROL HANIS

CC

ATG1801

7170

Uph

LKK

IDAC

Surveyor

hanis

DOI

ASSIGNMENT

10/1/18

Date / Time

10/1/18

Registered in Merit

10/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.

SLV 87184

Name of Insured

UP

Insured Tel No.

HP:

Excess Sec II :55

D.O.A:

19/1/18

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

AN CHW 67

Driver Tel No.:

(VAL: YES / NO)

Claim No.

88124711654

Policy No.

999999978

Make / Model

BMW

Place of Accident

OFF THE DAILY FIRM

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SLV 1011A



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Kim Chwee



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting 1st (1st)

Non-Reporting 1st (2nd)

Non-Reporting 1st (Final)

Notification 1st (if non-pickup)

Call OI

After call 1st to OI

10/1/18

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

LTA / GIA

Medical Bill

PIL Against OI

Mandate/Reject Instruction

LOD

Payment Breakdown Form

Post-Repair Photos

Others

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost

UP

\$5 19,000.00

10 days) Reduction:

70

%

Email

Call

FINAL SETTLEMENT

Date/Time:

10/1/18

Confirm with

hanis

Email

Call

Final Liability

%

100

(Assessed) BOLA S/N No.:

21

Repair Cost

65T

\$5 20,330.00

Loss of Rental (LOR)

\$5

60 days)

Loss of Use (LOU)

\$5

60 x 11 days)

Loss of Income (LOI)

\$5

5 x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

\$5

7.45

Medical

\$5

Disbursement

\$5

(e.g. Tow/ Independent)

Legal Cost

\$5

Total:

\$5

20,997.45

Global Sum \$5:

20,990.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

20,990.00

Name 1:

KIM CHWEE MTD FOR LOD

Payee 2: (Strike if N.A.)

\$5

Name 2:

---

Payee 3: (Strike if N.A.)

\$5

Name 3:

---

COPY SENT

08/11/13) wet

ASS. REC. BY: Marcus

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / VVS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLV1991A

at Workshop m/s Kim Chwee

of \_\_\_\_\_

Insured: SLL82186

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 80

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 82309

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLV1991A Yr Regn: 2114

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: BMW 316 i c.c. 1598

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 43461 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WBA3A16030N536391

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 11/9/18 D.O.I. 20/9/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear &amp; R/L

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27A 60284 5 yrs. 8 mth

8/10/18 2/5 19.000 constant with Acc.

Cred: 44,935.15 / 70%

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: \_\_\_\_\_

1) \_\_\_\_\_

☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

2) \_\_\_\_\_

Add Fee: ☐ Site Insp (\$ \_\_\_\_\_)☐ Interview (\$ \_\_\_\_\_)☐ Tech. Invs (\$ \_\_\_\_\_)☐ Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS SI

Photos

Others

TOTAL

Report Format: \_\_\_\_\_

Lump Sum / I.B.I.: (\$ \_\_\_\_\_)





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/LCR18017120/Ujb3		
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 20-09-2018		
		Code : LCR		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLL 8218G	Veh. Inspected	SLV 1991A	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	20/09/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	11/09/2018	Inspection Date	20/09/2018	
Survey held at	KIM CHWEE AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

not authorized  
 x/s #19.000  
 10 dy.

KIM CHWEE AUTO PTE LTD  
 1 KAKI BUKIT AVENUE 6  
 #01-46/48/50  
 SINGAPORE 417883

VEHICLE NO: SLV 1991A

QTY	PARTICULAR			
1 PCS	BOOTLID	1615.80	But/Buc	\$2,118.30
1 PCS	BOOTLID REAR LOGO		ner	\$68.00
1 PCS	BOOTLID OUTER HANDLE GARNISH	68.80	twi	\$165.00
2 PCS	BOOTLID HINGES @\$166.00		n	\$332.00
1 PCS	BOOTLID INNER LOCK		twi	\$299.08
1 PCS	BOOTLID INNER TRIM		de/ton	\$295.43
1 SET	BOOTLID INNER TRIM CLIPS		ner	\$50.00
2 PCS	BOOTLID REFLECTORS @\$920.00	685x2=1390	scr/cne	\$1,840.00
1 PCS	BOOTLID WEATHERSTRIP	266	twi	\$312.00
1 PCS	REAR BUMPER	1233.25	Dis	\$1,850.00
1 PCS	REAR BUMPER LOWER DIFFUSER		nx	\$640.00
1 PCS	REAR BUMPER REINFORCEMENT	715	Dis	\$720.00
2 PCS	REAR BUMPER SIDE HOLDERS @\$210.00	181x2=370	But	\$420.00
1 PCS	REAR BUMPER TOWING COVER		twi	\$30.00
4 PCS	REAR BUMPER PDC SENSORS @\$305.00	285x3=855	cne/shld	\$1,220.00
1 PCS	REAR BUMPER PDC SENSOR WIRE		shld	\$313.54
1 PCS	REAR BUMPER TOP GUIDE		Dis	\$205.00
1 PCS	REAR BUMPER INNER CENTRE GUIDE		Dis	\$282.00
1 SET	REAR BUMPER CLIPS		ner	\$50.00
2 PCS	REAR BUMPER LOWER COVERS @\$115.00		nx	\$230.00
1 PCS	REAR END PANEL	899.20	Sub/OD	\$1,068.00
1 PCS	REAR END PANEL TOP GARNISH		twi	\$290.50
1 PCS	REAR FLOOR PANEL		n	\$1,620.20
1 PCS	REAR FLOOR PANEL TOP BOARD	525.30	unp/pt	\$650.00
1 PCS	REAR FLOOR PANEL CENTRE TRIM GARNISH		nn	\$882.00
2 PCS	REAR FENDERS @\$2150.00		n	\$4,300.00
2 PCS	REAR FENDER INNER TRIMS @\$320.00		de/ton	\$640.00
2 PCS	TAILLAMPS @\$1280.00	750.50x2=1501.00	BLD	\$2,560.00
1 PCS	REAR EXHAUST MUFFLER		n	\$2,480.00
1 PCS	REAR EXHAUST HEAT SHIELD		But	\$311.30
2 PCS	REAR EXHAUST MOUNTINGS @\$45.00		nn	\$90.00
1 PCS	REAR FENDER UNDER COVER N/S	245.	twi	\$880.00
1 PCS	BONNET		n	\$2,135.00
1 PCS	BONNET LOGO	68	ner	\$80.00
2 PCS	BONNET DAMPERS @\$170.00		17	\$340.00
2 PCS	BONNET HINGES @\$140.00		17	\$280.00
1 PCS	BONNET INNER HANDLE W/CABLE		17	\$92.00
1 PCS	BONNET INSULATOR		17	\$193.00
1 SET	BONNET INSULATOR CLIPS		17	\$50.00
1 PCS	BONNET LOCK LEVEL		17	\$190.00
2 PCS	BONNET LOCK CATCHS @\$25.00		17	\$50.00

2 PCS	BONNET MECHANISM LOCK L/R @\$266.00
2 PCS	BONNET RUBBER GUIDE STOPPERS @\$15.00
1 PCS	BONNET WEATHERSTRIP
1 PCS	FRONT BUMPER 1233.25
1 PCS	FRONT BUMPER INNER SPONGE
1 PCS	FRONT BUMPER REINFORCEMENT 695.00
1 PCS	FRONT BUMPER NUMBER PLATE GARNISH
1 PCS	FRONT BUMPER TOW COVER N/S
2 PCS	FRONT BUMPER FOG LAMPS @\$280.00
2 PCS	FRONT BUMPER SIDE HOLDERS @\$115.00
1 SET	FRONT BUMPER CLIPS
1 PCS	FRONT BUMPER CENTRE GRILLE
2 PCS	FRONT BUMPER REINFORCEMENT BRACKETS @\$105.00
1 PCS	FRONT BUMPER TOP RUBBER SEAL
2 PCS	FRONT GRILLES @\$180.00
2 PCS	HEADLAMPS @\$2800.00 2450 x 2 = 4900
2 PCS	HEADLAMP LOWER BRACKETS @\$185.00
1 PCS	HEADLAMP NOZZLE N/S
1 PCS	HEADLAMP TOP BRACKET N/S
1 PCS	FRONT SUPPORT PANEL
1 PCS	FRONT SUPPORT CENTRE GARNISH
1 PCS	AIR CLEANER BOX
2 PCS	ENGINE MOUNTING L/R @\$350.00
1 PCS	FRONT AIR CON CONDENSER AIR GUIDE ASSY
1 PCS	AIR CON CONDENSER
1 PCS	AIR CON SUCTION HOSE
1 PCS	AIR CON DISCHARGE HOSE
1 PCS	AIR CON TEMPERATURE SENSOR
1 PCS	RADIATOR
1 CS	RADIATOR AUXILLIARY FAN ASSY
1 PCS	RADIATOR BYPASS HOSE
1 PCS	RADIATOR LOWER HOSE
1 PCS	RADIATOR TOP HOSE
2 PCS	FRONT FENDERS @\$919.00
2 PCS	FRONT FENDER INNER SHIELDS @\$211.30
1 PCS	FRONT OIL COOLING PIPE

11	\$532.00 X
11	\$30.00 X
11	\$92.00 X
P/O	\$1,615.00
11	\$98.00
11	\$712.00
31	\$110.00
11	\$35.00 X
11	\$560.00 X
11	\$230.00
11	\$50.00
11	\$56.00 X
11	\$210.00 X
11	\$45.00
11	\$360.00
11	\$5,600.00
11	\$370.00 X
11	\$180.00 X
11	\$166.00 X
11	\$627.00 X
11	\$289.30
11	\$766.50 X
11	\$700.00 X
11	\$199.20 X
11	\$1,220.00 X
11	\$295.00 X
11	\$298.00 X
11	\$155.00 X
11	\$922.00 X
11	\$1,550.00 X
11	\$92.00 X
11	\$122.50 X
11	\$133.50 X
11	\$1,838.00 X
11	\$422.60 X
11	\$266.30 X
	\$51,570.25

S.NETT	
1 PCS	REAR LICENCE PLATE W/HOLDER
1 PCS	REAR END PANEL SEALANT
1 PCS	REAR EXHAUST CHROME
1 PCS	REAR FLOOR PANEL CENTRE INSULATOR
1 PCS	FRONT LICENCE PLATE W/HOLDER
1 BOT	RADIATOR COOLANT

11	\$100.00 X
11	\$80.00 50
11	\$200.00 X
11	\$300.00 150
11	\$100.00 50
11	\$80.00 X

#### LABOUR CHARGES:

TO CHECK WIRING	\$100.00 30
TO DISMANTLE & REPLACING PDC SENSOR	\$100.00 50

TOWING CHARGE KING ROLLER	11	\$180.00	X
TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTREY		\$180.00	80
TO DISMANTLE & REFIX BOOTLID MECHANISM		\$180.00	80
TO SPRAY RUSF PROOFING		\$180.00	80
TO MOUNT VEHICLE ON CAR O-LINER	11	\$380.00	X
TO DISMANTLE & REPLACING REAR EXHAUST		\$380.00	80
TO DISMANTLE AIR CON ASSY,VACUUM AND REFILL GAS		\$150.00	100
TO REPROGRAMME & CLEAR FAULT CODE	11	\$200.00	X
LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS		\$3,800.00	1800
TO PUTTY & SPRAY PAINTING		\$2,800.00	1800
TOTAL		\$63,935.15	

4350

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 8230J

Vehicle Details

Vehicle No.: SLV1991A  
Vehicle to be Exported: No  
Intended Deregistration Date: 20 Sep 2018  
Vehicle Make: B.M.W.  
Vehicle Model: 316I 1.6 AT D/AB 4DR ABS HID  
Primary Colour: White  
Manufacturing Year: 2013  
Engine No.: A252J566N13B16A  
Chassis No.: WBA3A16030NS36391  
Maximum Power Output: 100.0 kW (134 bhp)  
Open Market Value: \$31,973.00  
Original Registration Date: 27 Feb 2014  
First Registration Date: 27 Feb 2014  
Transfer Count: 1  
Actual ARF Paid: \$26,763.00 13381

Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 26 Feb 2024  
PARF Rebate Amount: \$20,072.00

Intended COE Rebate Details

COE Expiry Date: 26 Feb 2024  
COE Category: E - Open Category  
COE Period(Years): 10  
QP Paid: \$77,501.00  
COE Rebate Amount: \$40,212.00  
Total Rebate Amount: \$60,284.00

The information contained herein is correct as at 20 Sep 2018

OK



Get your  
\$30 Trading Bonus\*

USAN BOLT  
OFFICIAL SPONSOR

  
www.xm.com

\*T&Cs apply. Trading involves a significant risk and can result in the loss of your invested capital.

Read More

Post an Advertisement  
Sell it yourself! Advertise it at just  
\$58 until it's SOLD!



Ferrari 458 Spider 4.5i A/T A85 D/A8 2WD 2DR Hid.  
Immaculate Condition, Well Maintained.  
Direct Owner - StarAd.

Post an Ad

Advertiser Login

Ways of Selling



VALUE FOR MONEY  
VALUE FOR TIME  
A PEACE OF MIND

HOTLINE: 6741 9997

view our GRS

Browse by Category

Back ( 1 2 ) Next

Sort by Date Posted

20 results/page

30 vehicles

bmw 316

Advanced Search

Submit

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

bmw 316

Any

Any


2014

Any

Any

Any

Available



BMW 3 Series 316i

\$80,800

\$11,790 /yr

13-Jun-2014

1,598 cc

-


Luxury

Available

Road Tax Until Jun 2019! Beautiful Black Exterior On Beige Interior! Well Taken Care By Previous Owner! 100% Accident Free! Price Negotiable For Serious Buyer! Flexible Loan Packages Available! Trade ...

Posted: 19-Sep-2018

Tags: 2014 BMW 316i, BMW 316i, BMW, 316i, Used BMW



BMW 3 Series 316i

\$79,800

\$11,320 /yr

27-Aug-2014

1,598 cc

-


Luxury

Available

1 Owner Only, 100% Accident Free! Serviced By PML, New Road Tax Till Feb 2019. Upgrading To New Mercedes.

Posted: 18-Sep-2018

Tags: 2014 BMW 316i, BMW 316i, BMW, 316i, Used BMW



BMW 3 Series 316i

\$85,000

\$12,550 /yr

09-Jun-2014

1,598 cc

31,500 km

Luxury


Available

Elegant Blue, Just Serviced By Agent In July 2018, Accident Free, One Owner Only, Low Mileage Done, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In House Loan Packages.

Prime Motor & Leasing

Posted: 18-Sep-2018

Tags: 2014 BMW 316i, BMW 316i, BMW, 316i, Used BMW



BMW 3 Series 316i

\$83,288

\$11,400 /yr

23-Dec-2014

1,598 cc

80,000 km

Luxury

Available

100% Fully PML Serviced With Warranty Till Dec 2019. Buy With No Worries Yet At A Cheap Depreciation. Definitely A Good Deal Not To Be Missed. Trade-In And High Loan Available. Call Us Now

Monster Motors Pte Ltd

Posted: 17-Sep-2018

Tags: 2014 BMW 316i, BMW 316i, BMW, 316i, Used BMW

Car Buying

Car Selling

Car Ownership

Buying a pre-owned car, but  
Unsure of its Condition?  
Get, STA Car Evaluation

Car Aftermarket

On The Move

Lifestyle



BMW 3 Series 316i

\$81,800

\$12,080 /yr

10-Jun-2014

1,598 cc

83,000 km


Luxury

Available

Fully Serviced And Maintained By PML. The Most Complete Compact BMW Mid Sized Luxury Sedan. No Single Repairs Needed, 100% Accident Free. Trade In Welcomed, Bank/ High Loan House Finance Can Be Arrang...

Posted: 17-Sep-2018

Tags: 2014 BMW 316i, BMW 316i, BMW, 316i, Used BMW



BMW 3 Series 316i

\$82,800

\$12,000 /yr

14-Jul-2014

1,598 cc

40,614 km

Luxury

Available

Under Utilised! Genuine Low Mileage Done! Beautiful Showroom Condition! Best In The Market! By Appointment! Contact/SMS Our Appointed Sales Person Directly For Enquiry, Viewing And Testing Immediately...

Posted: 17-Sep-2018

Tags: 2014 BMW 316i, BMW 316i, BMW, 316i, Used BMW

BMW 3 Series 316i

\$84,800

\$12,090 /yr

26-Sep-2014

1,598 cc

49,339 km

Luxury

Available

Graded B by

STA

Compare

## Print Received Message

This mail is associated with :

**\*SLV1991A (5877000298SG)  
[SLL8218G]**

TP  
CHEONG DANIEL  
Sep 19 2018 12:00AM  
[LCRF PTE LTD]  
Kim Chwee Auto Pte Ltd

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 18/07/2019 15:46 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$20997.45) - SLV1991A - Claim Handler: Chew, Mavis

Approved:20997.45.

## Vic (LKKAUTO)

---


**From:** Mavis, Chew <Chew.Mavis@aig.com>  
**Sent:** Thursday, 18 July, 2019 3:51 PM  
**To:** Vic (LKKAUTO)  
**Cc:** Admin A  
**Subject:** RE: <SEEK MANDATE>\_Your Ref: 5877000298SG\_ACCIDENT INVOLVING VEHICLES SLL 8218G (OI) AND SLV 1991A (TP) ON 19/09/2018 LKK REF CC6/LCR18017120/Uhb3

Dear Vic

Approval has been granted in Merimen.

Best Regards,  
Ms. Mavis Chew  
AIG  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way, #08-16, Singapore 079120  
Tel +(65) 6419 1970  
[chew.mavis@aig.com](mailto:chew.mavis@aig.com) | [www.aig.sg](http://www.aig.sg)



AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards.  
[Click here to find out more.](#)

### IMPORTANT NOTICE:

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

---

**From:** Vic (LKKAUTO) [mailto:[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)]  
**Sent:** Thursday, July 18, 2019 10:53 AM  
**To:** Mavis, Chew  
**Cc:** Admin A; Vic (LKKAUTO)  
**Subject:** [EXTERNAL] <SEEK MANDATE>\_Your Ref: 5877000298SG\_ACCIDENT INVOLVING VEHICLES SLL 8218G (OI) AND SLV 1991A (TP) ON 19/09/2018 LKK REF CC6/LCR18017120/Uhb3

This message is from an external sender; be cautious with links and attachments.

**Your Ref:** 5877000298SG  
**Our Ref:** CC6/LCR18017120/Uhb3

Dear Mavis,

ACCIDENT INVOLVING VEHICLES SLL 8218G (OI) AND SLV 1991A (TP) ON 19/09/2018

We refer to the subject matter.

It was reported that Insured vehicle was involved in a 3 vehicle chain collision and was the last vehicle and rear-ended TP vehicle.

An email was sent out to the Insured to notify TP claim and NCD issues.

Summary to offer to repairer **KIM CHWEE AUTO PTE LTD** is as follows:

TP CLAIMED		REVISED - TO OFFER
Cost of Repair (w/gst)	\$ 65,334.47	\$ 20,330.00
Loss of Use (\$150 x 11 days)	\$ 1,650.00	\$ 660.00 (\$60 x 11 days)
LTA Search Fee	\$ 7.45	\$ 7.45
<b>TOTAL</b>	<b>\$ 66,991.92</b>	<b>\$ 20,997.45</b>

**TP VEHICLE:**

**MARKET VALUE : \$80,000.00 (est)**

**LTA REBATE : \$60,284.00 (est)**

**NETT VALUE : \$19,716.00 (est)**

**Breakdown of days is as follows:**

Recommended days	10 Days
Weekends / Downtime	1 Day
<b>TOTAL</b>	<b>11 Days</b>

Relevant supporting claim documents are uploaded in merimen for your perusal.

For your approval and/or further instruction please.

Thank you.

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International

Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

Date : 22.10.2018

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn: Motor Claim Department

## ACCIDENT INVOLVING VEHICLE: SLV1991A AND SLL8218G ON 19.09.2018

We are the authorized repair workshop for the owner of motor vehicle no: **SLV1991A**, which was involved in the captioned accident with your insured vehicle no: **SLL8218G**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1) Cost of Repair (inclusive of GST)	\$	20,330.00
2) Loss Of Use (10days + 1sun x \$150)	\$	1,650.00
3) GIA Search Fee	\$	7.45
	<u>\$</u>	<u>21,987.45</u>

We enclosed herewith the following documents to support the claims:

- |                                    |                                  |
|------------------------------------|----------------------------------|
| a) Final Repair Invoice            | b) Vehicle Registration Log Card |
| c) GIA Report                      | d) I/C & Driving Licence         |
| e) Insurance Certificate           | f) GIA Search Result             |
| g) Letter of Authorisation, etc... |                                  |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

**Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.**

Thank you.

Yours faithfully,

Jason Tang (jason@fastechauto.com.sg)

For Kim Chwee Auto Pte Ltd

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC  
Owner ID: 8230J

**Vehicle Details**

Vehicle No.: SLV1991A  
Vehicle to be Exported: Yes  
Intended Deregistration Date: 20 Sep 2018  
Vehicle Make: B.M.W.  
Vehicle Model: 316i 1.6 AT D/AB 4DR ABS HID  
Primary Colour: White  
Manufacturing Year: 2013  
Engine No.: A252J566N13B16A  
Chassis No.: WBA3A16030NS36391  
Maximum Power Output: 100.0 kW (134 bhp)  
Open Market Value: \$31,973.00  
Original Registration Date: 27 Feb 2014  
First Registration Date: 27 Feb 2014  
Transfer Count: 1  
Actual ARF Paid: \$26,763.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 26 Feb 2024  
PARF Rebate Amount: \$20,072.00

**Intended COE Rebate Details**

COE Expiry Date: 26 Feb 2024  
COE Category: E - Open Category  
COE Period(Years): 10  
QP Paid: \$77,501.00  
COE Rebate Amount: \$40,212.00  
**Total Rebate Amount: \$60,284.00**

The information contained herein is correct as at 20 Sep 2018

OK





**SINGAPORE  
POLICE FORCE**

Traffic Police  
10 Ubi Avenue 3  
Singapore 408865  
Tel +65 6547 0000  
Fax +65 6547 4883  
[www.police.gov.sg](http://www.police.gov.sg)

Our Ref : TP/IP/61207/2018  
Date : 16 MAY 2019

CHEONG DANIEL  
BLK 292 BISHAN STREET 22  
#16-81  
SINGAPORE 570292

Dear Sir/Madam

**ROAD TRAFFIC ACCIDENT INVOLVING SLV1991A, SJX6621Z AND SLL8218G ALONG BUKIT  
TIMAH EXPRESSWAY ON 19/09/2018 AT ABOUT 11.35PM**

I refer to the above accident.

Please be informed that we have completed our investigations which revealed that the driver of **SLL8218G** had committed an offence of **Careless Driving under Rule 29 of the Road Traffic Rules**. Action has been initiated against the driver for the said offence.

Yours faithfully

**HEAD INVESTIGATION  
TRAFFIC POLICE  
SINGAPORE POLICE FORCE**

This is a computer-generated letter. No signature is required.

**Joy Irene (LKKAuto)**

---

**From:** Joy Irene (LKKAuto)  
**Sent:** Wednesday, 28 November 2018 4:55 PM  
**To:** 'insurance@lioncityrentals.com.sg'  
**Cc:** Admin A; Hsiao Tong (LKKAuto); Vivian Lau (LKKAuto)  
**Subject:** ACCIDENT INVOLVING SLL 8218G (LCR) & SLV 1991A & OTHERS ON 19/09/2018 (22:40) ALONG BKE BEFORE DAIRY FARM

28 November 2018

**LCRF PTE LTD**

Policy Holder

Your Ref: SLL 8218G  
Our Ref: CC6/LCR18017120/Ujb3

Dear Sir/Madam,

**ACCIDENT INVOLVING SLL 8218G (LCR) & SLV 1991A & OTHERS ON 19/09/2018 (22:40) ALONG BKE BEFORE DAIRY FARM**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from **SLV 1991A** against your insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,

Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.





**AUTHORIZATION TO ACT**  
**(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)**

I, Cheang Daniel ("the third party claimant")  
of BLK 292 Bishan St 22 #16-81 Bishan Heights S570292 (address),  
owner of SLV1991A (vehicle no.) hereby authorize  
Kim Chwee Auto Pte Ltd

("the workshop") to act for me with respect to my claim for repair costs and/or  
rental and/or loss of use ("claim") for my vehicle no. SLV1991A that was  
damaged pursuant to the accident which occurred on 19/9/2018 (date) along  
BKE towards Woodlands (location)  
involving vehicle no/s SLL821867 ("the accident").

I further authorize the workshop to settle the above mentioned claim in a  
manner that they deem fit and the workshop is further authorized to receive  
payment further to settlement of my claim with payment cheque/s being made in  
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my  
behalf is on a without prejudice and without admission of liability basis insofar  
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 20 day of 09 (month) 20 18 (year)

Signed by "the third party claimant"



Signed by "the workshop"



**RELEASE VOUCHER**  
**(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)**

We/I, Kim Chwee Auto Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd, LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 20,990.00 (GLOBAL SUM - ALL IN) (repair costs), S\$ — (loss of use/rental) S\$ — (search fees) for vehicle no. SLV1991A that was damaged pursuant to the accident which occurred on 19/9/18 (date) along AKE Towards woodlands (location) involving vehicle no/s SLV82186

This is pursuant to the inspection conducted on 20/09/18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Cheong Daniel ("third party claimant") of vehicle no. SLV1991A to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLV1991A (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 19 day of 09 (month) 20 19 (year)



CKG

Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"

## TAX INVOICE

### **KIM CHWEE AUTO PTE LTD**

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

Tax Invoice : 20574

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Date: 22.10.2018

Vehicle No: SLV1991A

Make/Model: BMW 316I

Chassis/Eng# :

Accident Date: 19.09.2018

Claim No : 0918-20574

Attn: Motor Claim Department

---

	Amount
To proceed on lump sum repair	SS 19,000.00

---

E. & O. E.

Total : SS 19,000.00

GST @ 7% : SS 1,330.00

*Amount Due* : **SS 20,330.00**

  
for KIM CHWEE AUTO PTE LTD

All Invoices are subjected to GST

[> Back to OneMotoring](#)


Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 20 Sep 2018 / 11:25:36

Receipt Date/Time : 20 Sep 2018 / 11:25:36

## Tax Invoice/Receipt

Receipt No. : ITNET-00000-180920-000910

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLL8218G				
As at 19 Sep 2018/10:35:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLL8218G			
	Enquiry Fee	7.00	0.49	7.49
	20180920112447260325			
	<b>Sub-Total</b>	7.00	0.49	7.49
	<b>Total Before Rounding</b>	7.00	0.49	7.49
	<b>Rounding Difference</b>			0.04
	<b>Total Amount Payable</b>			7.45
Paid By				
	20180920112459860	Direct Debit: eNETS Debit (Internet Banking)		7.45
	<b>Total</b>			7.45
	<b>Cash Change</b>			0.00
	<b>Tendered Amount</b>			7.45
	<b>Excess Refundable Amount</b>			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

[Print Receipt](#)
[OK](#)
[Save as PDF](#)



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane




































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Sep 2018 <a href="#">Edit Reg</a>		20 Sep 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$19,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$19,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>


















































  



















































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>LCRF PTE LTD</b> , Co. Reg. No.: 201624597K, Tel: +6588888888									
Main Claimant: <b>CHEONG DANIEL</b> , ID: S91182301									
Vehicle Reg. No.: <b>SLV1991A</b>		Date of Loss: 19/09/2018 00:00 - :59 [54 Months and 23 Days From LTA Reg Date (Mon Yr)]							
Claim Type: <b>TP / 5877000298SG</b>		Policy/Cover Note No.: 0999994807 (Comprehensive)							
Vehicle Reg. No. (Insured): <b>SLL8218G</b>		Policy No. (Claimant): 5096240466							
		Excess:							
Repairer: <b>Kim Chwee Auto Pte Ltd (HQ)</b>   Kaki Bukit Avenue 6 #01-48, AutoBay@Kaki Bukit, 417883 Eunos - Tel: 67465405/67417244									
Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Chew, Mavis</b> ] Chew.Mavis@aig.com									
Claimant's Insurer: <b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 01/10/2018]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG_EXPRESS (18/07/2019): Alert - Adj Mandate Approved (S\$20997.45) - SLV1991A - Claim Handler: Chew, Mavi...</li> <li>AIG_SG (24/09/2018): Conflicting DOA</li> <li>AIG_SG (21/09/2018): No OI GIA Report (SLL8218G VS SLV1991A)</li> <li>AIG_SG (21/09/2018): Request To Upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



















































## Claim Documents



















































\*SLV1991A (58770002985G)  
[SLL8218G]  
TP  
CHEONG DANIEL  
Sep 19 2018 12:00AM  
[LCRF PTE LTD]  
Kim Chwee Auto Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>   <a href="#">Upload Video</a>   <a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Letters/Correspondences</b>			1 per page <input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	{Draft}	Third Party Express Settlement – Payment Breakdown	 Edit	<input type="checkbox"/>
<b>Photos/Images</b>			3 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/09/18 18:40	Chassis Number	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
2	20/09/18 18:40	Odometer Reading	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
3	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
4	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
5	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
6	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
7	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
8	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
9	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
10	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
11	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
12	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
13	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
14	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
15	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
16	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
17	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
18	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
19	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
20	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
21	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
22	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
23	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
24	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
25	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
26	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
27	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
28	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
29	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
30	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
31	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
32	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
33	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
34	20/09/18 18:41	General View	 Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>













































Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	20/09/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
36	20/09/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
37	20/09/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
38	20/09/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
39	20/09/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
40	20/09/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
41	20/09/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
42	20/09/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
43	20/09/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
44	20/09/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
45	20/09/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
46	20/09/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
47	20/09/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
48	20/09/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
49	20/09/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
50	20/09/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
51	20/09/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
52	20/09/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
53	20/09/18 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
54	20/09/18 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
55	20/09/18 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
56	20/09/18 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
57	20/09/18 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
58	20/09/18 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
59	20/09/18 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
60	20/09/18 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
61	20/09/18 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
62	20/09/18 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
63	20/09/18 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
64	20/09/18 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
65	20/09/18 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
66	20/09/18 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
67	20/09/18 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
68	20/09/18 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
69	20/09/18 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
70	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
71	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
72	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
73	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
74	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
75	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
76	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
77	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
78	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
79	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
80	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
81	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
82	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
83	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
85	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
86	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
87	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
88	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
89	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
90	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
91	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
92	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
93	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
94	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
95	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
96	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
97	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
98	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
99	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
100	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
101	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
102	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
103	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
104	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
105	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
106	20/09/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
107	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
134	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	20/09/18 21:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
161	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
162	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
163	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
164	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
165	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
166	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
167	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
168	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
169	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
170	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
171	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
172	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
173	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
174	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
175	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
176	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
177	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
178	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
179	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
180	20/09/18 21:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
181	20/09/18 22:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
182	20/09/18 22:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
183	20/09/18 22:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
184	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
185	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
186	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
187	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
188	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
189	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
190	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
191	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
192	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
193	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
194	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
195	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
196	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
197	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
198	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
199	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
200	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
201	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
202	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
203	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
204	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
205	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
206	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
207	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
208	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
209	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
210	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
211	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
212	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
213	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
214	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
215	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
216	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
217	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
218	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
219	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
220	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
221	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
222	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
223	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
224	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
225	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
226	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
227	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
228	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
229	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
230	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
231	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
232	20/09/18 22:00	Reinspection Photo		<input checked="" type="checkbox"/>
233	20/09/18 22:02	Reinspection Photo		<input checked="" type="checkbox"/>



Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
234	20/09/18 22:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
235	20/09/18 22:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
236	20/09/18 22:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
237	20/09/18 22:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
238	20/09/18 22:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
239	20/09/18 22:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
240	20/09/18 22:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
241	19/07/19 10:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
242	19/07/19 10:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
243	19/07/19 10:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
244	19/07/19 10:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
245	19/07/19 10:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
246	19/07/19 10:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
247	19/07/19 10:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
248	19/07/19 10:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
249	19/07/19 10:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
250	19/07/19 10:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
251	19/07/19 10:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
252	19/07/19 10:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
253	19/07/19 10:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
254	19/07/19 10:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
255	19/07/19 10:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
256	19/07/19 10:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
257	19/07/19 10:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
258	19/07/19 10:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
259	19/07/19 10:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
260	19/07/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
261	19/07/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
262	19/07/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
263	19/07/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
264	19/07/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
265	19/07/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
266	19/07/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
267	19/07/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/09/18 17:49	TP GIA REPORT	 Load PDF	
2	09/07/19 14:21	LTA SEARCH	 Load PDF	
3	17/07/19 11:15	LETTER OF DEMAND	 Load PDF	
4	17/07/19 11:15	TP GIA-	 Load PDF	
5	17/07/19 11:15	PIR AGAINST INSURED	 Load JPG	<input checked="" type="checkbox"/>
6	05/08/19 09:16	WORKSHOP INVOICE	 Load PDF	
7	05/08/19 09:16	AUTHORISATION TO ACT FORM	 Load PDF	
8	05/08/19 09:16	Release Voucher	 Load PDF	
9	05/08/19 09:16	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	24/09/18 09:02	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
---------------------	-------	------	-------



There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLL8218G (Insd veh)	Model:	BMW 316I 1.6 (A)
	SLV1991A (TP veh)		
Date of Accident:	19/09/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> [ X ] Yes	<input type="checkbox"/> [ ] No	
Repair Estimate	:	\$		85,334.47
Final Repair Cost	:	\$		20,990.00
Loss of Use	:	\$		11.00 days at \$60.00 per day
Rental (if any)	:	\$		days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (Global Sum)	:	\$		20,990.00

Is Third Party Workshop GIA Registered? ☐ [ ] YES ☒ [ X ] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_\_ 100 \_\_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ 100 \_\_\_\_\_ (%)

*\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Kim Chwee Auto Pte Ltd	: \$	20,990.00
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

05 Aug  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18017120/UHB3Q2

Date: 05/08/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994807  
**Claimant Vehicle No :** SLV1991A **Insured Vehicle No :** SLL8218G  
 Date of Loss: 19/09/2018 Nature of Claim: TP Claim No: 5877000298SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV1991A**  
 Make & Model: BMW 316i, 1.6 (A) Engine No: A252J566N13B16A  
 Reg. Date: 27/02/2014 (Man. Year: 2013) Chassis No: WBA3A16030NS36391  
 Colour: White Odometer: 43461 km  
 Engine Capacity: 1598 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	52,430.25	19,817.86	32,612.39	62.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,630.00	4,100.00	4,530.00	52.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>61,060.25</b>	<b>23,917.86</b>	<b>37,142.39</b>	<b>60.83</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>19,000.00</b>		
(S\$)	61,060.25	19,000.00	42,060.25	68.88
<b>+ GST 7.00/7.00% (S\$)</b>	<b>4,274.22</b>	<b>1,330.00</b>	<b>2,944.22</b>	<b>68.88</b>
<b>Nett Amount (S\$)</b>	<b>65,334.47</b>	<b>20,330.00</b>	<b>45,004.47</b>	<b>68.88</b>
<b>+ Loss of Use (11.0 x S\$60.00/day) (S\$)</b>		660.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>20,997.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>20,990.00</b>		

### INSPECTION

Date of Assignment: 20/09/2018  
 Date Inspected: 20/09/2018 Inspected At:

Kim Chwee Auto Pte Ltd (HQ)  
1 Kaki Bukit Avenue 6 #01-48,  
AutoBay@Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 10.0 days

---

**Adjuster:** MARCUS CHUA

**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent / Buckled	2,118.30 F	*1,615.80 FL
2	1		*BOOTLID REAR LOGO	Necessary	68.00 F	*68.00 FL
3	1		*BOOTLID OUTER HANDLE GARNISH	Twisted	165.00 F	*68.80 FL
4	2		*BOOTLID HINGES	Repair	332.00 F	*- FL
5	1		*BOOTLID INNER LOCK	Twisted	299.08 F	*299.08 FL
6	1		*BOOTLID INNER TRIM	Deformed / Torn	295.43 F	*295.43 FL
7	1		*SET BOOTLID INNER TRIM CLIPS	Necessary	50.00 F	*50.00 FL
8	2		*BOOTLID REFLECTORS	Scratched / Cracked	1,840.00 F	*1,390.00 FL
9	1		*BOOTLID WEATHERSTRIP	Twisted	312.00 F	*266.00 FL
10	1		*REAR BUMPER	Distorted	1,850.00 F	*1,233.25 FL
11	1		*REAR BUMPER LOWER DIFFUSER	Not fitted	640.00 F	*- FL
12	1		*REAR BUMPER REINFORCEMENT	Distorted	720.00 F	*715.00 FL
13	2		*REAR BUMPER SIDE HOLDERS	Bent	420.00 F	*370.00 FL
14	1		*REAR BUMPER TOWING COVER	Twisted	30.00 F	*30.00 FL
15	4		*REAR BUMPER PDC SENSORS	Cracked / Shorted (3 PCS ONLY)	1,220.00 F	*855.00 FL
16	1		*REAR BUMPER PDC SENSOR WIRE	Shorted	313.54 F	*313.54 FL
17	1		*REAR BUMPER TOP GUIDE	Distorted	205.00 F	*205.00 FL
18	1		*REAR BUMPER INNER CENTRE GUIDE	Distorted	282.00 F	*282.00 FL
19	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
20	2		*REAR BUMPER LOWER COVERS	Not fitted	230.00 F	*- FL
21	1		*REAR END PANEL	Badly Dented	1,068.00 F	*899.20 FL
22	1		*REAR END PANEL TOP GARNISH	Twisted	290.50 F	*290.50 FL
23	1		*REAR FLOOR PANEL	Repair	1,620.20 F	*- FL
24	1		*REAR FLOOR PANEL TOP BOARD	Warped	650.00 F	*525.30 FL
25	1		*REAR FLOOR PANEL CENTRE TRIM GARNISH	Not Necessary	882.00 F	*- FL
26	2		*REAR FENDERS	Repair	4,300.00 F	*- FL
27	2		*REAR FENDER INNER TRIMS	Deformed / Torn	640.00 F	*640.00 FL
28	2		*TAILLAMPS	Broken	2,560.00 F	*1,501.00 FL
29	1		*REAR EXHAUST MUFFLER	Repair	2,480.00 F	*- FL
30	1		*REAR EXHAUST HEAT SHIELD	Bent	311.30 F	*311.30 FL
31	2		*REAR EXHAUST MOUNTINGS	Not Necessary	90.00 F	*- FL
32	1		*REAR FENDER UNDER COVER N/S	Torn	880.00 F	*245.00 FL
33	1		*BONNET	Repair	2,135.00 F	*- FL
34	1		*BONNET LOGO	Necessary	80.00 F	*68.00 FL
35	2		*BONNET DAMPERS	Not Necessary	340.00 F	*- FL
36	2		*BONNET HINGES	Not Necessary	280.00 F	*- FL
37	1		*BONNET INNER HANDLE W/CABLE	Not Necessary	92.00 F	*- FL
38	1		*BONNET INSULATOR	Not Necessary	193.00 F	*- FL
39	1		*SET BONNET INSULATOR CLIPS	Not Necessary	50.00 F	*- FL
40	1		*BONNET LOCK LEVEL	Not Necessary	190.00 F	*- FL
41	2		*BONNET LOCK CATCHES	Not Necessary	50.00 F	*- FL
42	2		*BONNET MECHANISM LOCK L/R	Not Necessary	532.00 F	*- FL
43	2		*BONNET RUBBER GUIDE STOPPERS	Not Necessary	30.00 F	*- FL
44	1		*BONNET WEATHERSTRIP	Not Necessary	92.00 F	*- FL
45	1		*FRONT BUMPER	Dented / Deformed	1,615.00 F	*1,233.25 FL
46	1		*FRONT BUMPER INNER SPONGE	Torn	98.00 F	*98.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT BUMPER REINFORCEMENT	Dented	712.00 F	*695.00 FL
48	1		*FRONT BUMPER NUMBER PLATE GARNISH	Bent	110.00 F	*110.00 FL
49	1		*FRONT BUMPER TOW COVER N/S	Not Necessary	35.00 F	*- FL
50	2		*FRONT BUMPER FOG LAMPS	Not Necessary	560.00 F	*- FL
51	2		*FRONT BUMPER SIDE HOLDERS	Necessary	230.00 F	*230.00 FL
52	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
53	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	56.00 F	*- FL
54	2		*FRONT BUMPER REINFORCEMENT BRACKETS	Not Necessary	210.00 F	*- FL
55	1		*FRONT BUMPER TOP RUBBER SEAL	Necessary	45.00 F	*45.00 FL
56	2		*FRONT GRILLES	Cracked	360.00 F	*360.00 FL
57	2		*HEADLAMPS	Cracked	5,600.00 F	*4,900.00 FL
58	2		*HEADLAMP LOWER BRACKETS	No such part	370.00 F	*- FL
59	1		*HEADLAMP NOZZLE N/S	Not Necessary	180.00 F	*- FL
60	1		*HEADLAMP TOP BRACKET N/S	Not Necessary	166.00 F	*- FL
61	1		*FRONT SUPPORT PANEL	Repair	627.00 F	*- FL
62	1		*FRONT SUPPORT CENTRE GARNISH	Torn	289.30 F	*289.30 FL
63	1		*AIR CLEANER BOX	Not Necessary	766.50 F	*- FL
64	2		*ENGINE MOUNTING L/R	Not Necessary	700.00 F	*- FL
65	1		*FRONT AIR CON CONDENSER GUIDE ASSY	Not Necessary	199.20 F	*- FL
66	1		*AIR CON CONDENSER	Not Necessary	1,220.00 F	*- FL
67	1		*AIR CON SUCTION HOSE	Not Necessary	295.00 F	*- FL
68	1		*AIR CON DISCHARGE HOSE	Not Necessary	298.00 F	*- FL
69	1		*AIR CON TEMPERATURE SENSOR	Not Necessary	155.00 F	*- FL
70	1		*RADIATOR	Not Necessary	922.00 F	*- FL
71	1		*RADIATOR AUXILLIARY FAN ASSY	Not Necessary	1,550.00 F	*- FL
72	1		*RADIATOR BAYPASS HOSE	Not Necessary	92.00 F	*- FL
73	1		*RADIATOR LOWER HOSE	Not Necessary	122.50 F	*- FL
74	1		*RADIATOR TOP HOSE	Not Necessary	133.50 F	*- FL
75	2		*FRONT FENDERS	Repair	1,838.00 F	*- FL
76	2		*FRONT FENDER INNER SHIELDS	Not Necessary	422.60 F	*- FL
77	1		*FRONT OIL COOLING PIPE	Not Necessary	266.30 F	*- FL
78	1		*REAR LICENCE PLATE W/HOLDER	Not Necessary	100.00 FS	*- FS
79	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
80	1		*REAR EXHAUST CHROME	Not Necessary	200.00 FS	*- FS
81	1		*REAR FLOOR PANEL CENTRE INSULATOR	Necessary	300.00 FS	*150.00 FS
82	1		*FRONT LICENCE PLATE W/HOLDER	Cracked	100.00 FS	*50.00 FS
83	1		*BOT RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>52,430.25</b>	<b>20,847.75</b>
<b>- List Item Discount on L Items 0.00/5.00% (\$\$)</b>	<b>0.00</b>	<b>1,029.89</b>
<b>Total Parts (\$\$)</b>	<b>52,430.25</b>	<b>19,817.86</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	100.00	30.00
2	TO DISMANTLE & REPLACING PDC SENSOR	New	100.00	50.00
3	TOWING CHARGE KING ROLLER	New	180.00	0.00
4	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	180.00	80.00
5	TO DISMANTLE & REFIX BOOTLID MECHANISM	New	180.00	80.00
6	TO SPRAY RUST PROOFING	New	180.00	80.00
7	TO MOUNT VEHICLE ON CAR-O-LINER	New	380.00	0.00
8	TO DISMANTLE & REPLACING REAR EXHAUST	New	380.00	80.00
9	TO DISMANTLE AIR CON ASSY ,VACUUM AND REFILL GAS	New	150.00	100.00
10	TO REPROGRAMME & CLEAR FAULT CODE	New	200.00	0.00
11	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS	New	3,800.00	1,800.00
12	TO PUTTY & SPRAY PAINTING	New	2,800.00	1,800.00
<b>Gross Labour Cost (S\$)</b>			<b>8,630.00</b>	<b>4,100.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >