

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST 201001158E RCB NO 201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 19/09/2018
TP Veh Reg No: SLQ5762U

Estimate No: ES1891076/AMK
Date: 20 Sep 2018
Policy No: 5091916894
Veh Reg No: SKG9325L
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO
Chassis No: MR053REE104149369
Engine No: 1ZRXX230396
Reg. Date: 23/10/2012

Estimate Repair Cost to Vehicle No :SKG9325L

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 FRONT LH DOOR	1,201.70	1 PC	1,201.70	✓
2 FRONT LH DOOR INNER LOCK	411.67	1 PC	411.67	?
3 FRONT LH DOOR POWER WINDOW MOTOR	401.90	1 PC	401.90	?
4 FRONT LH DOOR POWER WINDOW REGULATOR	181.75	1 PC	181.75	?
5 FRONT LH DOOR FRAME STICKER	68.10	1 SET	68.10	✓
6 FRONT LH DOOR INNER RUBBER	178.90	1 PC	178.90	5000
7 FRONT LH DOOR PROTECTOR	95.20	1 PC	95.20	✓
8 FRONT LH DOOR CHROME	34.20	1 PC	34.20	✓
9 REAR LH DOOR	1,091.23	1 PC	1,091.23	✓
10 REAR LH DOOR POWER WINDOW MOTOR	401.91	1 PC	401.91	?
11 REAR LH DOOR REGULATOR	181.75	1 PC	181.75	?
12 REAR LH DOOR CHECKER	171.03	1 PC	171.03	?
13 REAR LH DOOR PROTECTOR	89.80	1 PC	89.80	✓
14 REAR LH DOOR PROTECTOR CHROME	29.80	1 PC	29.80	✓
15 REAR LH DOOR FRAME STICKER	68.10	1 SET	68.10	✓
16 LH CENTRE DOOR PILLAR	409.12	1 PC	409.12	✓
			5,016.16	
	Less 25%		1,254.04	3,762.13
Labour				
17 REMOVE & REFIX BOTH LH DOOR & ATTACHMENTS:TO CUT,WELD & RENEW LH CENTRE DOOR PILLAR:KNOCKING & REPAIR BOTH LH FENDERS & REALIGN THE SAME	1,100.00	1 LA	1,100.00	900
18 PUTTY & RESPRAY BOTH BUMPERS, BOTH LH FENDERS,BOTH LH DOORS,LH CENTRE DOOR PILLAR & ALL AFFECTED AREAS	1,200.00	1 LA	1,200.00	1100
19 REMOVE & REFIX BOTH LH DOOR WINDOW GLASSES AND RESET CENTRAL LOCKING	100.00	1 LA	100.00	✓
20 REMOVE & REFIX LH SEATS,CARPET TO FACILITATE REPAIR	100.00	1 LA	100.00	✓
21 RUSTPROOFING	90.00	1 LA	90.00	✓
			2,590.00	2,590.00

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST 201001158E RCB NO 201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 19/09/2018
TP Veh Reg No: SLQ5762U

Estimate No: ES1891076/AMK
Date: 20 Sep 2018
Policy No: 5091916894
Veh Reg No: SKG9325L
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO
Chassis No: MR053REE104149369
Engine No: 1ZRX230396
Reg. Date: 23/10/2012

Estimate Repair Cost to Vehicle No :SKG9325L

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
			Total	SS 6,352.13
			Add GST @ 7%	444.65
			Total Amount Payable	SS 6,796.78

VEHICLE LYING AT :
NO.10 ANG MO KIO INDUSTRIAL PARK 2A
#01-04 AMK AUTOPOINT
SINGAPORE 568047
TEL : 64812001

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE