



HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street | Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

16 October 2018

India International Insurance Pte Ltd
64 Cecil Street, IOB Building
#04-00 / #05-00
Singapore 049711

Attn: Motor Claims Department

ACCIDENT INVOLVING SLX 6665 Z & SHC 1193 J ON 13/9/2018 AT JEM SHOPPING MALL
PICK UP POINT AT ABOUT 1430 HOURS

Insured : HUA HONG PTE LTD
Vehicle Registration No : SLX 6665 Z
Vehicle Make : HONDA
Vehicle Model : SHUTTLE HYBRID 1.5 AUTO
Vehicle Chassis No : GP71107696
Policy No : 5087272209-01
Date of Accident : 13/9/2018



S/N	Quantity	Description	Type of Claim: Third Party	
			Unit Price S\$	Amount S\$
		To dismantle & refit rear bumper		\$ 200.00 150
		To dismantle & refit rear bumper sensor		\$ 60.00 40
		To spray rear bumper		\$ 600.00 200
				\$ 860.00 390
			7% GST	\$ 60.20
			Total	\$ 920.20



Authorised by Claims Dept
Mrs Tan @ 9639 9195

2 Days.
part by mt.

before and After repair photos.

Gao Qian (82880282)

LKK

13/11/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: