



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 20.09.2018

AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01/02
AXA Tower
Singapore 068811

Attn: Motor Claims Dept

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97445749
WP
20/9/18 @ 1550
02 days
Resurvey After repair
sur E. Murdus. w.h.

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2802Z PRIUS HYBRID 1.8L A (2012)

To Supply

1) 1pc	Rear bumper	\$ de 1,218.00
2) 1pc	Rear bumper right side retainer	\$? 122.25
3) 1pc	Rear bumper left side retainer	\$? 122.25
4) 1set	Rear bumper clip	\$ all 30.00
5) 1pc	Rear bumper under cover	\$ x 494.00

Sub total parts	\$ 1,986.50
Less: 25% discount	\$ (496.62)
	\$ 1,489.88

To supply S.Nett Parts

1) 1pc	Rear bumper advertisement sticker	\$ all 100.00
2) 1pc	Right rear fender advertisement sticker	\$ all 160.00
3) 1pc	Left rear fender advertisement sticker	\$ all 160.00

Sub total S.Nett parts	\$ 420.00
------------------------	-----------

L/charge

1) To remove rear bumper. Knock rear end panel. Replace rear bumper. Align & adjust rear bumper & tail gate.	\$ ²⁰⁰ 450.00
2) To putty, respray painting rear bumper & rear end panel.	\$ ²⁰⁰ 500.00

Sub total L/charges	\$ 950.00
Estimated Grand Total	\$ 2,859.88