

NGS TRADING

Blk 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047
Tel: 64815727 Fax: 64815772 Email: evelynngstrading@gmail.com
Reg No.:51106300L

QUOTATION

No. : QT-09306

FWD SINGAPORE PTE LTD

Your Ref. :

Our Ref : QT-09306/SLZ6255

C. C. :

Date : 20-09-2018

TEL : 6322 2072

FAX :

Page : 1 of 2

Not Withheld

Description	Qty	U/ Price	Amount
		S\$	S
ACCIDENT ON 30/08/2018 INVOLVING SLZ6255M & SKV6541U			
CLAIMS AGAINST SKV6541U			
REPLACEMENT PARTS:			
END PANEL	1	434.40	434.40
REAR BUMPER	1	681.00	681.00
REAR BUMPER RETAINER LH/RH	2	28.00	56.00
REAR BUMPER REINFORCEMENT	1	171.00	171.00
TAILLAMP LH/RH	2	432.00	864.00
CLIPS TAILLAMP(WHITE)	2	8.50	17.00
GROMMET, TAILLAMP	2	8.50	17.00
EXHAUST	1	315.00	315.00
SubTotal			2,555.40
LESS 10%	1	-255.54	-255.54
REVERSE SENSOR S/NETT	1	280.00	280.00
REAR BOOT LOGO S/NETT	1	38.50	38.50
REAR BOOT 'GLX' S/NETT	1	30.50	30.50
REAR BOOT 'LANCER' S/NETT	1	37.00	37.00
REAR BOOT ' C&C' S/NETT	1	25.00	25.00
TO REMOVE ALL DAMAGED PART WITH ALL NECESSARY COMPONENT/ATTACHMENT STRAIGHTEN CHASSIS MEMBER, REPAIR/RESHAPE DENTED BODY PANEL. REPLACE DAMAGED PARTS INTO POSITION.	1	900.00	900.00
SPRAY PAINTING			
CHECK WIRING & PROPER LIGHT FUNCTION			

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2 days

R

Valium

R

SL

SL

na

SL

R

na

na

na

na

na

20

20

15/

NGS TRADING

Blk 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047
Tel: 64815727 Fax: 64815772 Email: evelynngstrading@gmail.com
Reg No.:51106300L

QUOTATION

No. : QT-09306

FWD SINGAPORE PTE LTD

Your Ref. :

Our Ref : QT-09306/SLZ6255

C. C. :

Date : 20-09-2018

Page : 2 of 2

TEL : 6322 2072

FAX :

Description	Qty	U/ Price S\$	Amount S
-------------	-----	-----------------	-------------

Any other parts which necessitate repair or renewal will incur additional charged.
Please contact our Ms Evelyn @ HP 96955547 to arrange for survey. Thank you.

Total **4,260.86**

Yours faithfully,



EVELYN