

ASS. REC. BY:

REF: CS/EGT 18017137/K1fd3n2 Special Instruction:

Surveyor: Kalvin ASSIGNMENT (Office)From (Person): Yee Pei Li of EGT Date/Time: 20/9/18 @ 2:33pm

Estimated Cost: Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SHB 8990J Insured: SKM 39Rat Workshop m/s Premier Automotive Tel: 6544 6682of 23 chengji south Ave 2 # 01-02Policy No: Claim No: SKM 39R / SA / pl

Sum Insured: Excess:

Make of Veh: D.O.A. 19/09/2018  
(Client's Record)CA / REV / REP. / REV 24 HRS lup

H.O.D. Endorsement:

Date/Time: 3:00pm @ 20/9/18 Person Contacted: wee dek Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SHB 8990J - CC3 / III6000234 / H/93n2 DOA: 4/01/2016
	SKM 39R - X
20/9/18 @ 6:30pm	revised to Steve Lim by email.

38/11/3

Surveyor: Kalvin

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insp'd Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHB 8990J Yr Regn: 28 May 2014Type: M.Car / M.Cycle / Bus / Van / Lorry / T~~o~~ / Prime Mover /

Truck / Trailer or

Make: KIA optima c.c. 1685Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 434291 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KNA6M414ME54635KGen. Cond: Good / ~~Fair~~ / Poor / BurntSteering: Inorder / ~~Jammed~~ / Leaked / Burnt orBrake: Inorder / ~~Jammed~~ / Leaked / Burnt orModi: Nil / S/Rim / STD / ~~AR~~ Rim orTyre Size: F: 205/65 R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 19/9/18 D.O.I. 20/9/18Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

d/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

25/9/18 Checked up \$2100 / 4 hrs (red: 573140 / 73%)Ergo4%

RECEIVED 27 SEP 2018

Date/Time, File Pass to?

1) 21/9/18 TP

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Preli. Report☒ : Final ReportDays Of Repair: 4Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)Report Format: TPLump Sum / I.B.I.: (\$ 200)250



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18017137/K1td3

5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
SINGAPORE 038985

Date : 20-09-2018



Code : EGI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKM 39R	Veh. Inspected	SHB 8990J
Policy No.		Coverage (\$)	0.00
Claim No.	SKM39R/SA/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	20/09/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	19/09/2018	Inspection Date	20/09/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: SKM39R/SA/pl

Date: 21<sup>st</sup> September 2018

Our Ref: CS/EG118017137/K1td3

Without Prejudice

The Motor Claims Department  
ERGO Insurance Pte Ltd

Attn: Pei Li

Dear Sirs/Mdm

**PRELIMINARY ADVICE OF VEHICLE NO. SHB 8990J**


We thank you for the instruction on 20/09/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 20/09/2018 at the premises of M/s PREMIER AUTOMOTIVE and have the following to report:-

Workshop Estimate Amount	: S\$ <u>7,831.40</u>
Revised Estimate Amount	: S\$ <u>2,657.20</u>
"Check" Items Amount	: S\$ <u>135.00</u>
Market Value	: S\$ <u>-</u>
Salvage Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the o/s rear portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 4 days.

We have NOT authorise repair.

Yours faithfully

Kalvin Ang  
Automotive Assessor

## Nivitha (LKK Auto)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Thursday, 20 September 2018 2:33 PM  
**To:** 'admin-d@lkkauto.com'  
**Cc:** 'ASSIGNMENTS@LKKAUTO.COM'  
**Subject:** OI : SKM39R / TP : SHB8990J/LKK / DOA : 19/09/2018  
**Attachments:** SHB8990J - SAS n ESTIMATE.pdf; SHB8990J - PRS FORM.pdf

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **PREMIER AUTOMOTIVE SERVICES PTE LTD.**

**ADDRESS** : 23 CHANGI SOUTH AVE 2  
#01-02  
SINGAPORE 486443

**PERSON TO CONTACT** : GOH WEE DEK @ 6544 6682 / 6214 8880 EXT 68

**ERGO OFFICER-IN-CHARGE** : STEVE LIM

***Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.***

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached is TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards,  
Yee Pei Li  
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five  
Singapore 038985  
DID.: +65 6829 9194  
Tel.: +65 6829 9199  
Fax: +65 6829 9247

**ERGO**

[www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

# ERGO

Date: 20.09.2018  
Our Reference: SKM 39R/SA/pl  
Your Reference: SHB 8990J

Sent via Fax

or

Email

weedek.goh@premiertaxi.com /  
gary.shi@premiertaxi.com /  
vincent.chua@premiertaxi.com

To: **PREMIER AUTOMOTIVE SERVICES PTE LTD**

## Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SHB 8990J  
Insured's Vehicle: SKM 39R  
Date Of Accident: 19.09.2018


We acknowledge receipt of your request for PRS on: 20.09.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked \*.

\* **LKK**

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input checked="" type="checkbox"/>	Our Insured's driver has not reported the accident to us todate.
<input checked="" type="checkbox"/>	Others: <u>OFFICER-IN-CHARGE - SITI</u>

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

### Assessor use only:

Assignment Date: \_\_\_\_\_  
Assignment Time: \_\_\_\_\_

Remarks:

### Workshop use only:

#### Assessor attended workshop on:

Date: \_\_\_\_\_  
Time: \_\_\_\_\_  
Inspector: \_\_\_\_\_

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Friday, 21 September 2018 1:31 PM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.); assignments; 'Steve Lim'  
**Cc:** SUR  
**Subject:** RE: SKM39R / TP : SHB8990J/LKK / DOA : 19/09/2018  
**Attachments:** CSEGI18017137K1td3.pdf

Dear Steve,

Enclosed herewith preliminary advice of SHB 8990J.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Thursday, 20 September 2018 3:07 PM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)' <[Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SKM39R / TP : SHB8990J/LKK / DOA : 19/09/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]  
**Sent:** Thursday, 20 September 2018 2:33 PM  
**To:** 'admin-d@lkkauto.com' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Cc:** 'ASSIGNMENTS@LKKAUTO.COM' <[ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)>  
**Subject:** OI : SKM39R / TP : SHB8990J/LKK / DOA : 19/09/2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **PREMIER AUTOMOTIVE SERVICES PTE LTD.**

ADDRESS : 23 CHANGI SOUTH AVE 2  
#01-02

Text size + -

**Enquire Transaction History****Transaction History Details**

Log Date/Time:	28 May 2014 / 09:37:56	Receipt No.:	AACCK001-AX239-140528-000010
Asset Type:	Vehicle	Transaction Amount:	\$73,050.00
Asset ID:	SHB8990J	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20140528093756475034		

Vehicle No.:	SHB8990J
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	28 May 2014
Original Registration Date:	28 May 2014
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414ME5463154
Engine No.:	D4FDDH309736
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2013
Open Market Value:	\$19,996.00
Minimum PARF Benefit:	\$7,497.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	28 May 2014 09:37:56
COE No.:	2014052801000881K
COE Expiry Date:	27 May 2022
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$60,414.00
Lifespan Expiry Date:	27 May 2022
Owner ID Type:	Company



CASH SALE/WORK ORDER No:AK 0994



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL : 6743 1987 ( 3 LINES ) FAX : 6743 0013

Reg No: 200415052W

Date, 1/1/2018

賣號

Messrs:

Premier Taxi

車號

Vehicle No:

8HB 8990 I

車型

Model No:

Omega

由

From:

SRAH STREET

到

To:

OMEGA

其他

Remark:

Acc ① Key.

時間

Time:

21:07 21:40 22:20

AMOUNT:

\$

注意：本公司對所拖之車輛，在進行中如有任何損失或破壞，一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人

Authorised by:

[Signature]

收貨人

Received by:

[Signature]

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

20-Sep-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8990 J

1 pc	Rear o/s air vent <i>X su</i>	\$	30.00
1 pc	Rear o/s fender <i>— <del>Boat</del> Boat</i>	\$	1,205.00
1 pc	Rear o/s fender inner shield <i>X su</i>	\$	120.00
1 pc	Rear windscreen moulding <i>— su</i>	\$	87.00
1 pc	Rear bumper <i>X repair</i>	\$	696.00
1 pc	Rear bumper side bracket o/s <i>X su</i>	\$	29.00
1 pc	Rear o/s lower arm <i>X su</i>	\$	351.00
1 pc	Rear o/s shock absorber <i>X su</i>	\$	313.00
1 pc	Rear o/s trailing arm <i>X su</i>	\$	159.00
1 pc	Rear o/s assist arm <i>X su</i>	\$	163.00
1 pc	Rear o/s bearing <i>X su</i>	\$	349.00
1 pc	Rear o/s upper arm <i>X su</i>	\$	84.00
1 pc	Hub & Bearing Assy- Rear <i>X su</i>	\$	349.00
1 pc	Rear o/s knuckle arm <i>X su</i>	\$	525.00
1 pc	Rear o/s fender inner trim <i>X su</i>	\$	184.00
1 pc	Rear o/s rim <i>X su</i>	\$	246.00
1 pc	Rear o/s wheel cover <i>— <del>hnd</del></i>	\$	116.00
		\$	5,006.00
		Less 10%	\$ 500.60
			\$ 4,505.40

### S/NETT

1 set	Rear bumper clips <i>X 77</i>	\$	48.00
1 set	Rear fender inner shield clips <i>X 77</i>	\$	38.00
1 pc	Rear o/s fender sticker <i>— su</i>	\$	60.00
1 pc	Rear bumper top protector <i>— su</i>	\$	<del>80.00</del> 50
1 pc	Sealant <i>—</i>	\$	50.00

20-Sep-18

**ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8990 J**

Towing Fee	\$ 50.00	/
Sundry <i>rec</i>	\$ <del>50.00</del>	<i>20</i>
To check wheel alignment	\$ <del>80.00</del>	<i>X 44</i>
To dismantle and refit rear windscreen	\$ <del>120.00</del>	<i>100</i>
To dismantle and replace the rear o/s undercarriage	\$ <del>250.00</del>	<i>X 44</i>
To dismantle / refit reverse sensor to new bumper and reset to the same	\$ <del>120.00</del>	<i>X 44</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ <del>180.00</del>	<i>50</i>
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the rear o/s fender inner panel etc	\$ <del>1,000.00</del>	<i>600</i>
To putty and spray painting on rear bumper, rear o/s fender, rear o/s side panel, rear o/s fender inner panel, rear bumper	\$ <del>1,000.00</del>	<i>360</i>
To apply rustproofing on the repaired and replaced panels.	\$ <del>200.00</del>	<i>50</i>
	<u>\$ 7,831.40</u>	

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT  
INCLUDE ANY UNFORESEEN DAMAGES.**

*Kalvi 10/1/18*

*20/9/18 1545hrs*

*4 Days*

*4/5*

*After Repair photo*

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Damaged parts must be resurveyed and approved by the insurance company

Acknowledged by Repairer

Signature:

Date:




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18017137/K1td3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 01-10-2018		
		Code : EGI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKM 39R	Veh. Inspected	SHB 8990J	
Policy No.		Coverage (\$)	0.00	
Claim No.	SKM39R/SA/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	20/09/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KNAGM414ME5463154	Colour	SILVER	
Odometer	434291	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MAXXIS	7 mm	
L/H Front Tyre	205/65 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	19/09/2018	Inspection Date	20/09/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8990J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR O/S AIR VENT	SERVICEABLE	30.00	-
1	REAR O/S FENDER	BENT	1,205.00	1,205.00
1	REAR O/S FENDER INNER SHIELD	SERVICEABLE	120.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	87.00	87.00
1	REAR BUMPER	TO REPAIR SEE LABOUR	696.00	-
1	REAR BUMPER SIDE BRACKET O/S	SERVICEABLE	29.00	-
1	REAR O/S LOWER ARM	SERVICEABLE	351.00	-
1	REAR O/S SHOCK ABSORBER	SERVICEABLE	313.00	-
1	REAR O/S TRAILING ARM	SERVICEABLE	159.00	-
1	REAR O/S ASSIST ARM	SERVICEABLE	163.00	-
1	REAR O/S BEARING	SERVICEABLE	349.00	-
1	REAR O/S UPPER ARM	SERVICEABLE	84.00	-
1	HUB & BEARING ASSY-REAR	SERVICEABLE	349.00	-
1	REAR O/S KNUCKLE ARM	SERVICEABLE	525.00	-
1	REAR O/S FENDER INNER TRIM	SERVICEABLE	184.00	-
1	REAR O/S RIM	SERVICEABLE	246.00	-
1	REAR O/S WHEEL COVER	GRAZED	116.00	116.00
	LESS 10% DISCOUNT		-500.60	-140.80
			4,505.40	1,267.20
<b>SPECIAL NETT ITEMS</b>				
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	SET REAR FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	38.00	-
1	REAR O/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	50.00
1	SEALANT (SN)	NECESSARY	50.00	50.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			326.00	180.00
<b>LABOUR</b>				
	TOWING FEE.		50.00	50.00

Report Ref No. CS/EGI18017137/K1td3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO DISMANTLE AND REFIT REAR WINDSCREEN.		120.00	100.00
	TO DISMANTLE AND REPLACE THE REAR O/S UNDERCARRIAGE.	NOT NECESSARY	250.00	-
	TO DISMANTLE/REFIT REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.	NOT NECESSARY	120.00	-
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS TO HEAT/WELD, CUT-OFF THE REAR O/S FENDER, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE REAR O/S FENDER INNER PANEL ETC. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		1,000.00	600.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER, REAR O/S FENDER, REAR O/S SIDE PANEL, REAR O/S FENDER INNER PANEL, REAR BUMPER.		1,000.00	360.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		200.00	50.00
			3,000.00	1,210.00
<b>GRAND TOTAL</b>			<b>7,831.40</b>	<b>2,657.20</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,100.00</b>

Report Ref No. CS/EGI18017137/K1td3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.