

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1081/2018/PH
Date : 19-Sep-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Kua Ooi Seong
Address : 53 Sunrise Avenue
#03-10
Singapore 806745
Telephone : HP +65 88268937
Type of Claim : Third Party claims
Policy No. : D17/MTPV01006569
Vehicle No : **SCY 9449 M**
Model Code : Audi A3 SEDAN 1.4
Model / Year : May-18
Engine No : CZC 255192
Chassis No : WAUZZZ8V3FA161573
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Sep-18
Place of Accident : Along Driveway Sunrise Garden

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFC 13 B.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,100.00 1250	
3	To respray front bumper and rhs front fender.	\$ 1,500.00 1100	
4	To renew ehs front front rim and carry out wheel alignment.	S/N \$ 280.00 ✗	
5	To carry out diagnostic check	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 4,432.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFC 13 B.

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
1	FRONT BUMPER <i>Deformed</i>	\$ 1,613.00	✓
2	FIXING PARTS FOR FRONT BUMPER	\$ 161.00	X
3	FRONT BUMPER LOWER CENTRE CLOSING ELEMENT <i>3 net</i>	\$ 134.00	X
4	GUIDE SECTION - RH <i>new</i>	\$ 54.00	X
5	AIR GUIDE GRILLE - RH <i>new</i>	\$ 95.00	X
6	FRONT FENDER - RH <i>Dented</i>	\$ 746.00	✓
7	ATTACHMENT PARTS FOR FRONT FENDER - RH <i>new</i>	\$ 62.00	X
8	FRONT FENDER BRACKET - RH ?	\$ 24.00	?
9	FRONT FENDER BRACKET - RH ?	\$ 41.00	?
10	FRONT FENDER BRACE - RH <i>new</i>	\$ 81.00	X
11	FRONT FENDER CLOSING ELEMENT <i>new</i>	\$ 53.00	X
12	WHEEL HOUSING LINER - RH <i>new</i>	\$ 151.00	X
13	ATTACHMENT PARTS FOR WHEEL HOUSING LINER <i>new</i>	\$ 77.00	X
14	FRONT STONE CHIP GUARD - RH <i>new</i>	\$ 63.00	X
15	ADHESIVE TAPE	\$ 49.00	?
16	HEADLIGHT FOR GAS DISCHARGE <i>cut</i>	\$ 1,764.00	✓
17	LIFT CYLINDER FOR HEADLIGHT <i>not new</i>	\$ 174.00	X
18	FRONT RIM - RH <i>26" new</i>	TBC	X
19	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 5,642.00
TOTAL LABOUR CHARGES		:	\$ 4,432.00
GRAND TOTAL		:	\$ 10,074.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling.
Surveyed Date : 08/10/18.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant