



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24  
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com  
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:  
MAKE & MODEL:  
MILEAGE:  
TYRE:  
CHASSIS NUM:

|              |
|--------------|
| JLH 8506     |
| PERODUA MYVI |
|              |
|              |
|              |
|              |

NOT ADJUST  
2/3  
24/5/18  
Tel: 6286 6060

| ATTN: | DESCRIPTION - PARTS                      | QTY | PRICE |
|-------|------------------------------------------|-----|-------|
| NO.   |                                          |     |       |
|       | BOOTLID 3003AD ✓                         |     |       |
|       | BOOTLID LOCK 201 ✓                       |     |       |
|       | BOOTLID CATCH 11X                        |     |       |
|       | BOOTLID WEATHERSTRIP 201 ✓               |     |       |
|       | BOOTLID CENTER GARNISH 11X               |     |       |
|       | BOOTLID LOGO 11X                         |     |       |
|       | BOOTLID EMBLEM - MYVI 11X                |     |       |
|       | BOOTLID INNER TRIM 11X                   |     |       |
|       | BOOTLID DAMPER L+R 11X                   |     |       |
|       | WINDSCREEN MOULDING 11X                  |     |       |
|       | REAR BUMPER 201 ✓                        |     |       |
|       | REAR BUMPER SIDE RETAINER L+R 201 ✓      |     |       |
|       | REAR BUMPER BRACKET L+R 201 X            |     |       |
|       | REAR BUMPER REFLECTOR L+R 201 cnc lpc    |     |       |
|       | REAR BUMPER REINFORCMENT 201 X           |     |       |
|       | REAR BUMPER SPONGE 201 X                 |     |       |
|       | REAR BUMPER TOW COVER 201 ✓              |     |       |
|       | REAR FENDER AIR DUCT 11X                 |     |       |
|       | REAR END PANEL 3003AD ✓                  |     |       |
|       | REAR END PANEL TOP GARNISH 201 ✓         |     |       |
|       | REAR SPARE WHEEL PANEL 201 ✓             |     |       |
|       | REAR SPARE WHEEL PANEL BOARD 201 ✓       |     |       |
|       | REAR FENDER INNER TRIM L+R 201 X         |     |       |
|       | TAILLAMP L+R ?                           |     |       |
|       | TAILLAMP PANEL L+R 201 X                 |     |       |
|       | TAILLAMP CLIPS L+R 201 X                 |     |       |
|       | FRONT BUMPER 201 X nlc                   |     |       |
|       | FRONT BUMPER CLIPS 201 X                 |     |       |
|       | FRONT BUMPER GRILLE 201 X nlc            |     |       |
|       | FRONT BUMPER GRILLE LOGO 201 ✓           |     |       |
|       | FRONT BUMPER LOWER GRILLE 11X            |     |       |
|       | FOG LAMP L+R 11X                         |     |       |
|       | FOG LAMP COVER L+R 11X                   |     |       |
|       | FRONT BUMPER SIDE RETAINER L+R 201 X nlc |     |       |
|       | FRONT BUMPER BRACKET L+R 201 X nlc       |     |       |
|       | FRONT BUMPER REINFORCEMENT 201 X nlc     |     |       |
|       | FRONT SUPPORT PANEL 11X                  |     |       |
|       | FRONT BRACE PANEL 201 X nlc              |     |       |
|       | HORN 11X                                 |     |       |

|                                                             |               |            |              |
|-------------------------------------------------------------|---------------|------------|--------------|
| A/C CONDENSOR                                               | 11X           |            |              |
| A/C LOW PRESSURE PIPE                                       | 17X           |            |              |
| A/C HIGH PRESSURE PIPE                                      | 17X           |            |              |
| A/C DISCHARGE PIPE                                          | 17X           |            |              |
| RADIATOR ASSY                                               | 11X           |            |              |
| RADIATOR FAN MOTOR ASSY                                     | 17X           |            |              |
| RADIATOR FAN COWLING                                        | 17X           |            |              |
| HEADLAMP L+R                                                | em X n/c      |            |              |
| HEADLAMP LOWER BRACKET L+R                                  | 17X           |            |              |
|                                                             |               |            |              |
| SUBTOTAL                                                    |               | \$         | -            |
| LESS 10%                                                    |               | \$         | -            |
| PARTS TOTAL                                                 |               | \$         | -            |
| <b>SPECIAL NETT</b>                                         |               | <b>QTY</b> | <b>PRICE</b> |
| FRONT NUMBER PLATE                                          | set #0 n/c    |            | \$ 80.00     |
| REAR NUMBER PLATE                                           | set 40        |            | \$ 80.00     |
| REVERSE SENSOR                                              | self shut 200 |            | \$ 250.00    |
| REAR END PANEL SEALANT                                      | per 50        |            | \$ 80.00     |
| SPARE WHEEL PANEL SEALANT                                   | 17X           |            | \$ 80.00     |
| SPARE WHEEL                                                 | 17X           |            | \$ 200.00    |
| RADIATOR COOLANT                                            | 17X           |            | \$ 150.00    |
| SPARE WHEEL INSULATOR                                       | 17X           |            | \$ 400.00    |
| FRONT BUMPER CLIPS                                          | APX X         |            | \$ 100.00    |
| FRONT BONNET ISOLATOR CLIPS                                 | 11X           |            | \$ 100.00    |
| FRONT FENDER COWLING CLIPS                                  | 17X           |            | \$ 100.00    |
| REAR BUMPER CLIPS                                           | per 40        |            | \$ 100.00    |
| REAR FENDER COWLING CLIPS                                   | 17X           |            | \$ 100.00    |
| REAR FENDER INNER TRIM CLIPS                                | 11X           |            | \$ 100.00    |
| BOOTLID INNER TRIM CLIPS                                    | 17X           |            | \$ 100.00    |
| REAR END PANEL TOP GARNISH CLIPS                            | 17X           |            | \$ 100.00    |
|                                                             |               |            |              |
| SPECIAL NETT TOTAL                                          |               |            | \$ 2,120.00  |
| <b>LABOUR</b>                                               |               | <b>QTY</b> | <b>PRICE</b> |
| TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN        | Rear 1200     |            | \$ 2,400.00  |
| TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA -Rear           | 1100          |            | \$ 2,200.00  |
| TO RUST PROOF ACCIDENT AFFECTED AREA                        | 80            |            | \$ 160.00    |
| TO RNR REAR WINDSCREEN                                      | 120           |            | \$ 200.00    |
| TO RNR REAR BOOT MECHANISM                                  | 60            |            | \$ 200.00    |
| TO RNR UPHOSTERY,GARNISH AND ATTACHMENT PARTS               | 80            |            | \$ 400.00    |
| TO RNR REVERSE SENSOR & CHECK FUNCTION.                     | 50            |            | \$ 100.00    |
| TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS                  | 17X           |            | \$ 150.00    |
| TO RNR A/C CONDENSOR ASSY AND REFILL GAS                    | 11 X          |            | \$ 150.00    |
| TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS                   | 30            |            | \$ 80.00     |
| TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE. | 17X           |            | \$ 200.00    |
| TO DO WATER LEAK TEST .                                     | 17X           |            | \$ 100.00    |
| TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD          | 17X           |            | \$ 150.00    |

|  |                         |                    |
|--|-------------------------|--------------------|
|  |                         |                    |
|  | <b>LABOUR TOTAL</b>     | <b>\$ 6,490.00</b> |
|  | <b>GRAND TOTAL COST</b> | <b>\$ 8,610.00</b> |
|  |                         |                    |
|  |                         |                    |
|  |                         |                    |
|  |                         |                    |

PAGE 2 OF 2

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: