

ASS. REC. BY:

REF: CS/C7718017149 / U.S.D.3

Typical instruction

Surveyor
meinen

Marion

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

6

(11)

Date/Time: 20/4/2018 @ 3:35pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No. _____

34 5033C

Insured:

STD 9561A

at Workshop m/s

Kah Motor

Tel:

68465671

of

154bi Rd 4

Policy No.

DMPCN1641691802

Claim No.

SNMISDO 4550C02

Sum Insured:

Excess

Make of Veh:

(Client's Record)

D.O.A. 20/09/2018

CA / REV / REP: / REV 24 HRS

(up)

H.O.D. Endorsement

Date/Time

4pm @ 20/9/18

Person Contacted:

try

Vehicle IN/OUT

Date/Time

Action/Instruction	(✓) Estimate
1. <u>Identify the problem</u>	
2. <u>Identify the data</u>	
3. <u>Identify the variables</u>	
4. <u>Identify the relationships</u>	
5. <u>Identify the constraints</u>	
6. <u>Identify the assumptions</u>	
7. <u>Identify the objectives</u>	
8. <u>Identify the stakeholders</u>	
9. <u>Identify the risks</u>	
10. <u>Identify the opportunities</u>	
11. <u>Identify the challenges</u>	
12. <u>Identify the solutions</u>	
13. <u>Identify the implementation</u>	
14. <u>Identify the evaluation</u>	
15. <u>Identify the conclusion</u>	

Sl 5033C-x

SD 9561A - X.

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLJ 5033Cat Workshop m/s lock motor

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: 5 Consistent? : Yes or NoEst. Repairs: 5 days Res.: Yes or NoLum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLJ 5033C Yr Regn: 12/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: Honda Civic c.c. 1498Colour: white A/C: Insured / Std / NI / NASp. Reading: 46824 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRHFC166067000351

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45 R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 2 mm R/Bal. 2 mmL/Bal. 2 mm L/Bal. 2 mmD.O.A. 20/9/18 D.O.I. 20/9/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/5 Lf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

25/10/18 + 4515.08 confirmed with Amy

25/10/18 Confirmed P/P \$ 4,515.08 @ 5 days with Marcus
(+ 2,068.92 Red - 31%)

RECEIVED 25 OCT 2018

Date/Time, File Pass to?

☐ : Prel. Report☒ : Final Report

1) Typist

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 4,515.08 r/p)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Sep 2018		20 Sep 2018 15:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:				
Main Claimant:	LEUNG MENG FOO			
Vehicle Reg. No.:	SLJ5033C	Date of Loss:	20/09/2018 00:00 - :59	
Claim Type:	TP / SNM18D04550C02	Policy/Cover Note No.:	DMPCSN1641691802	
Vehicle Reg. No. (Insured):	SLD9561A	Policy No. (Claimant):		
		Excess:	S\$0.00	
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/10/2018]			
Adj Asg. Remarks:	EST \$6878.98, CASE WITH SJE.			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CS/CTI18017149/Usd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 20-09-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLD 9561A	Veh. Inspected	SLJ 5033C	
Policy No.	DMPCSN1641691802	Coverage (\$)	0.00	
Claim No.	SNM18D04550C02	Excess (\$)	0.00	
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	20/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/09/2018	Inspection Date	20/09/2018	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9390C
Vehicle Details	
Vehicle No.:	SLJ5033C
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.5 TURBO VTIS SR
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	L15B71627398
Chassis No.:	MRHFC1660GT000351
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$26,990.00
Original Registration Date:	14 Dec 2016
First Registration Date:	14 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$24,786.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Dec 2026
PARF Rebate Amount:	\$18,589.00
Intended COE Rebate Details	
COE Expiry Date:	13 Dec 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,002.00
COE Rebate Amount:	\$46,893.00
Total Rebate Amount:	\$65,482.00

The information contained herein is correct as at 21 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/09/2018 11:17
Date Of Accident	20/09/2018 07:00
Exact Location Of Accident	BLK 102A RIVERVALE WALK DECK 3B MSCP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ5033C
Insured/Policyholder	
Name Of Registered Owner	LEUNG MENG FOO
NRIC No	S1309390C
Email Address	FMJLEUNG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97888801
Alternative Phone No	OFFICE-97888801

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-1.5 TURBO VTI-S SR (A)
Exact Purpose for which vehicle was being used at time of accident	P/USED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	16-MV012186-R00
Cover Note Number	

Driver

Name of Driver	LEUNG MENG FOO
NRIC No	S1309390C
Date Of Birth	06/05/1958
Occupation	INDOOR
Date Of Driving Pass	13/11/1984
Driving Experience	33 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97888801
Fax Number	
Contact Number	OFFICE-97888801
Email Address	FMJLEUNG@GMAIL.COM

Vehicle No SLJ 5033C**SKETCH PLAN**

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Blk 102A
Rivervale
Walk Deck 3B
MSCP



A = SLJ5033C
B = SLD9561A

Please continue to Annex E.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE	Document No.	: SQT18003962	Page	1
	3 ANSON ROAD #16-00	Date	: 20. Sep 2018		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: ARY CHUA WAI NGEE		
Registration No	: SLJ5033C	Engine No	: L15B71627398		
Chassis No	: MRHFC1660GT000351	Date Time	: 20. Sep 2018 10:24:19 AM		
Model	: CIVIC 1.5 TURBO VTIS YM2016	Surveyor Name	:		
Owner's Name	: LEUNG MENG FOO	Survey Date	:		
Ins Policy No.	: 16-MV012186-R00	Authorisation Date	:		
Date of Accident	: 20/9/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incld GST
	TP DIRECT SETTLEMENT (J/NO: 71262)						
	OWNER: LEUNG MENG FOO						
	OWNER INSURER: TOKIO MARINE INSURANCE LTD						
	ACC DATE: 20/09/2018@07.50am						
	SURVEYED BY: <i>Marcus Chua</i> 20 SEP 2018 016:16pm						
	REF NO:						
	TP INSURER: CHINA TAIPING INSURANCE PTE LTD						
	TP VEH: SLD9561A (AUDI/A4/BLACK)						
BO-TOW-SW	TOWING SERVICE	1	60.00		60.00	4.20	64.20
					Sum Ext. Service	60.00	4.20
							64.20
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	<i>Days</i> 1	45.00		45.00	3.15	48.15
91505-TM8-003	CLIPBUMPER	<i>Per</i> 14	2.00	25	21.00	1.47	22.47
71101-TEA-T00ZZ	FACEFR.BUMPER	<i>Dis</i> 1	579.90	25	434.92	30.44	465.36
77930-TEA-B11	SENSOR ASSYFR.CRASH	<i>Days</i> 1	69.30	25	51.97	3.64	55.61
34300-TET-H01	LIGHT ASSYR SIDE TURN	<i>Cur</i> 1	32.20	25	24.15	1.69	25.84
33100-TEA-T11	HEADLIGHT ASSY.R.	<i>CAL</i> 1	1155.10	25	866.32	60.64	926.96
33900-TBA-A01	LIGHT ASSYR.FR.FOG	<i>CAL</i> 1	305.90	25	229.42	16.06	245.48
17230-5AA-A00	CHAMBER ASSYRESONATOR	<i>17</i> 1	49.50	X 25	37.12	2.60	39.72
74101-TEA-T10	FENDERR.FR INNER	<i>T10</i> 1	49.60	25	37.20	2.60	39.80
60211-TBA-A00ZZ	PANELR.FENDER	<i>12</i> 1	241.60	X 25	181.20	12.68	193.88
60213-TBA-A00ZZ	BRACKET AR.FR.FENDER	<i>17</i> 1	28.60	X 25	21.45	1.50	22.95
04674-TEA-T00ZZ	EXTENSION SETR.FR.SHOCK ABS	<i>17</i> 1	194.70	X 25	146.02	10.22	156.24
60610-TEA-T00ZZ	MEMBER COMPR.FR.WHEELHOUSE UP	<i>17</i> 1	74.50	X 25	55.87	3.91	59.78
71410-TED-T01	BULKHEAD ASSY.FR.	<i>12</i> 1	510.60	X 25	382.95	26.81	409.76
60628-TEA-305ZZ	BRACKET SETR.FR.BUMPER EXTSN	<i>17</i> 1	72.50	X 25	54.37	3.81	58.18
					Sum Item	2588.96	181.22
							2,770.18
BOSUN	SUNDRIES	<i>20</i> 1	40.00		40.00	2.80	42.80
BML011	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	140.00		140.00	9.80	149.80

washer tank Dis

front bumper tower Dis

big gasket RH Cur

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE	Document No.	: SQT18003962	Page	2
	3 ANSON ROAD #16-00	Date	: 20. Sep 2018		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: ARY CHUA WAI NGEE		
Registration No	: SLJ5033C	Engine No	: L15B71627398		
Chassis No	: MRHFC1660GT000351	Date Time	: 20. Sep 2018 10:24:19 AM		
Model	: CIVIC 1.5 TURBO VTIS YM2016	Surveyor Name	:		
Owner's Name	: LEUNG MENG FOO	Survey Date	:		
Ins Policy No.	: 16-MV012186-R00	Authorisation Date	:		
Date of Accident	: 20/9/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	1800.00	1350-	1800.00	126.00	1926.00
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	1800.00	1120-	1800.00	126.00	1926.00
Sum Labor					3780.00	264.60	4,044.60

Survey By Marcus Loh
Date & Time 20/9/18 @ 4:15pm
Excess Not Authorized
Status Not Authorized
Signature Take photo before repair.
5 day.

Total Amount 6,428.96 450.02 6,878.96
Total (Inclusive of GST) 6,878.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 20/9/2018 12:27:36 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408551, Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: S1309390C / LEUNG MENG FOO
Chassis No: MRHFC1660GT000351
License No: SLJ5033C
Mileage: 46822
Engine No: L15B71627398

Document No: SVO18060125
Printed By: ARYCHUA
Order Date: 11. October 2018
Order Time: 2:50:07 PM
Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incl GST
SUPPLIMENTARY ITEM PARTS & LABOR							
76841-TEA-T01	TANKWASHER	1	25.60	25	19.20	1.34	20.54
71121-TEA-T01	BASE,FR.GRILLE CHROME	1	76.60	25	57.45	4.02	61.47
75700-TBA-A00	EMBLEM	1	14.60	25	10.95	0.77	11.72
90301-ST0-003	NUTPUSH 3MM	2	1.90	25	2.85	0.20	3.05
71103-TEA-T10	GARNISH,FR.BUMPER SIDE	1	13.80	25	10.35	0.72	11.07
71102-TBA-A00	GRILLE, FR.BUMPER LOWER	1	72.40	25	54.30	3.80	58.10
SUM PARTS:					155.10	10.85	165.95
TOTAL SGD					155.10	10.85	165.95

Total Payable (SGD)

165.95

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651, Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING
Chassis No: MRHFC1660GT000351
License No: SLJ5033C
Mileage: 46822
Engine No: L15B71627398

Document No: SVO18060125
Printed By: ARYCHUA
Order Date: 11. October 2018
Order Time: 2:50:07 PM
Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount incld	Amount	GST
	TP DIRECT SETTLEMENT (J/NO: 71262)							
	OWNER: LEUNG MENG FOO							
	OWNER INSURER: TOKIO MARINE INSURANCE LTD							
	ACC DATE: 20/09/2018@07.50am							
	SURVEYED BY: MARCUS CHUA (LKKAUTO)20/09/2018@16.16							
	REF NO: SNM18D04550							
	TP INSURER: CHINA TAIPING INSURANCE PTE LTD							
	TP VEH: SLD9561A (AUDI/A4/BLACK)							
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15	
91505-TM8-003	CLIPBUMPER	14	2.00	25	21.00	1.47	22.47	
71101-TEA-T00ZZ	FACEFR BUMPER	1	579.90	25	434.92	30.44	465.36	
77930-TEA-B11	SENSOR ASSYFR.CRASH	1	69.30	25	51.97	3.64	55.61	
34300-TET-H01	LIGHT ASSYR.SIDE TURN	1	32.20	25	24.15	1.69	25.84	
33100-TEA-T11	HEADLIGHT ASSY,R.	1	1,155.10	25	866.32	60.64	926.96	
33900-TBA-A01	LIGHT ASSYR.FR.FOG	1	305.90	25	229.42	16.06	245.48	
74101-TEA-T10	FENDERR.FR INNER	1	49.60	25	37.20	2.60	39.80	
76841-TEA-T01	TANKWASHER	1	25.60	25	19.20	1.34	20.54	
71121-TEA-T01	BASE,FR.GRILLE CHROME	1	76.60	25	57.45	4.02	61.47	
75700-TBA-A00	EMBLEM	1	14.60	25	10.95	0.77	11.72	
90301-ST0-003	NUTPUSH 3MM	2	1.90	25	2.85	0.20	3.05	
71103-TEA-T10	GARNISHR.FR BUMPER SIDE	1	13.80	25	10.35	0.72	11.07	
71102-TBA-A00	GRILLE, FR.BUMPER LOWER	1	72.40	25	54.30	3.80	58.10	
	SUM PARTS:				1,865.08	130.54	1,995.62	
BOSUN	0672	1	20.00		20.00	1.40	21.40	
	SUNDRIES							
BML011	EXT-YJ	1	100.00		100.00	7.00	107.00	
	INSPECT FR LIGHTING MECHANISMS & FOCUS							
	HEADLIGHTS.(N)							
BKBH01S	EXT-YJ	1	1,120.00		1,120.00	78.40	1,198.40	
	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.							
BP02R	EXT-YBH	1	1,350.00		1,350.00	94.50	1,444.50	
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(2P)							
	SUM LABOUR:				2,590.00	181.30	2,771.30	
BO-TOW-SW	TOWING SERVICE	1	60.00		60.00	4.20	64.20	
	SUM EXT SERVICE:				60.00	4.20	64.20	
	TOTAL SGD				4,515.08	316.04	4,831.12	

Total Payable (SGD)

4,831.12

GST Amount is calculated from individual line(s)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Sep 2018		20 Sep 2018 15:35 Edit Adj Rpt	\$4,515.08 Edit Estimates	\$4,515.08 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	- ID: -								
Main Claimant:	LEUNG MENG FOO								
Vehicle Reg. No.:	SLJ5033C	Date of Loss:	20/09/2018 00:00 - :59 [21 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D04550C02	Policy/Cover Note No.:	DMPCSN1641691802						
Vehicle Reg. No. (Insured):	SLD9561A	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 01/10/2018]								
Adj Asg. Remarks:	EST \$6878.98, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLJ5033C (SNM18D04550C02)
[SLD9561A]
TP
LEUNG MENG FOO
Sep 20 2018 12:00AM
[-]
Kah Motor Co Sdn Bhd

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Photos/Images									3 per page			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	25/10/18 11:04	Odometer Reading								Load JPG	☒			
2	25/10/18 11:04	General View								Load JPG	☒			
3	25/10/18 11:04	Chassis Number								Load JPG	☒			
4	25/10/18 11:04	General View								Load JPG	☒			
5	25/10/18 11:04	General View								Load JPG	☒			
6	25/10/18 11:04	General View								Load JPG	☒			
7	25/10/18 11:04	General View								Load JPG	☒			
8	25/10/18 11:04	General View								Load JPG	☒			
9	25/10/18 11:04	General View								Load JPG	☒			
10	25/10/18 11:04	General View								Load JPG	☒			
11	25/10/18 11:04	General View								Load JPG	☒			
12	25/10/18 11:04	General View								Load JPG	☒			
13	25/10/18 11:04	General View								Load JPG	☒			
14	25/10/18 11:04	General View								Load JPG	☒			
15	25/10/18 11:04	General View								Load JPG	☒			
16	25/10/18 11:04	General View								Load JPG	☒			
17	25/10/18 11:04	General View								Load JPG	☒			
18	25/10/18 11:04	General View								Load JPG	☒			
19	25/10/18 11:04	General View								Load JPG	☒			
20	25/10/18 11:04	General View								Load JPG	☒			
21	25/10/18 11:04	General View								Load JPG	☒			
22	25/10/18 11:04	General View								Load JPG	☒			
23	25/10/18 11:04	General View								Load JPG	☒			
24	25/10/18 11:04	General View								Load JPG	☒			
25	25/10/18 11:04	General View								Load JPG	☒			
26	25/10/18 11:04	General View								Load JPG	☒			
27	25/10/18 11:04	General View								Load JPG	☒			
28	25/10/18 11:04	General View								Load JPG	☒			
29	25/10/18 11:04	General View								Load JPG	☒			
30	25/10/18 11:04	General View								Load JPG	☒			
31	25/10/18 11:04	General View								Load JPG	☒			
32	25/10/18 11:04	General View								Load JPG	☒			
33	25/10/18 11:04	General View								Load JPG	☒			
34	25/10/18 11:04	General View								Load JPG	☒			
35	25/10/18 11:04	General View								Load JPG	☒			
36	25/10/18 11:04	General View								Load JPG	☒			
37	25/10/18 11:04	General View								Load JPG	☒			

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	25/10/18 11:04	General View	 Load JPG	☒
39	25/10/18 11:04	General View	 Load JPG	☒
40	25/10/18 11:04	General View	 Load JPG	☒
41	25/10/18 11:04	General View	 Load JPG	☒
42	25/10/18 11:04	General View	 Load JPG	☒
43	25/10/18 11:04	General View	 Load JPG	☒
44	25/10/18 11:04	General View	 Load JPG	☒
45	25/10/18 11:04	General View	 Load JPG	☒
46	25/10/18 11:04	General View	 Load JPG	☒
47	25/10/18 11:04	General View	 Load JPG	☒
48	25/10/18 11:04	General View	 Load JPG	☒
49	25/10/18 11:04	General View	 Load JPG	☒
50	25/10/18 11:04	General View	 Load JPG	☒
51	25/10/18 11:04	General View	 Load JPG	☒
52	25/10/18 11:04	General View	 Load JPG	☒
53	25/10/18 11:04	General View	 Load JPG	☒
54	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
55	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
56	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
57	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
58	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
59	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
60	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
61	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
62	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
63	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
64	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
65	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
66	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
67	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
68	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
69	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
70	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
71	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
72	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
73	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
74	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
75	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
76	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
77	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
78	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
79	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
80	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
81	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
82	25/10/18 11:04	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/09/18 15:35	PRS	 Load PDF	
2	20/09/18 15:35	REPAIR EST WITH TP GIA	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/10/18 10:46	SUPPLEMENTARY PART	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer.

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118017149/USD3Q2

Date: 26/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1641691802
Claimant Vehicle No:	SLJ5033C	Insured Vehicle No:	SLD9561A
Date of Loss:	20/09/2018	Nature of Claim:	TP
		Claim No:	SNM18D04550C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ5033C	Engine No:	L15B71627398
Make & Model:	HONDA CIVIC, 1.5 TURBO VTI-S SR (A)	Chassis No:	MRHFC1660GT000351
Reg. Date:	14/12/2016 (Man. Year: 2016)	Odometer:	46821 km
Colour:	White		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,784.06	1,885.08	898.98	32.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,800.00	2,630.00	1,170.00	30.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,584.06	4,515.08	2,068.98	31.42
+ GST 7.00/7.00% (S\$)	460.88	316.06	144.82	31.42
Nett Amount (S\$)	7,044.94	4,831.14	2,213.80	31.42

INSPECTION

Date of Assignment:	20/09/2018		
Date Inspected:	20/09/2018	Inspected At:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4 Singapore 408610
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Oct 2018)
Parts:	143	HONDA CIVIC 1.5 TURBO VTI-S SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ5033C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NUMBER PLATE WITH CASING-L	Damaged	45.00 FS	*45.00 FS
2	14		*CLIPBUMPER	Necessary	21.00 FS	*21.00 FS
3	1		*FACEFR.BUMPER	Distorted	434.92 FS	*434.92 FS
4	1		*SENSOR ASSYFR.CRASH	Damaged	51.97 FS	*51.97 FS
5	1		*LIGHT ASSYR.SIDE TURN	Cracked	24.15 FS	*24.15 FS
6	1		*HEADLIGHT ASSY,R	Cracked	866.32 FS	*866.32 FS
7	1		*LIGHT ASSYR,FR.FOG	Cracked	229.42 FS	*229.42 FS
8	1		*CHAMBER ASSYRESONATOR	Not Necessary	37.12 FS	*- FS
9	1		*FENDERR.FR INNER	Torn	37.20 FS	*37.20 FS
10	1		*PANELR.FENDER	Repair	181.20 FS	*- FS
11	1		*BRACKET AR.FR.FENDER	Not Necessary	21.45 FS	*- FS
12	1		*EXTENSION SETR.FR.SHOCK ABS	Not Necessary	146.02 FS	*- FS
13	1		*MEMBER COMPR.FR.WHEELHOUSE UP	Not Necessary	55.87 FS	*- FS
14	1		*BULKHEAD ASSY,FR	Repair	382.95 FS	*- FS
15	1		*BRACKET SETR.FR.BUMPER EXTSN	Not Necessary	54.37 FS	*- FS
16	1		*SUNDRIES	Necessary	40.00 FS	*20.00 FS
17	1		*TANKWASHER	Deformed	19.20 FS	*19.20 FS
18	1		*BASE,FR.GRILLE CHROME	Cracked	57.45 FS	*57.45 FS
19	1		*EMBLEM	Necessary	10.95 FS	*10.95 FS
20	1		*NUTPUSH 3MM (2 PCS)	Necessary	2.85 FS	*2.85 FS
21	1		*GARNISHR.FR.BUMPER SIDE	Distorted	10.35 FS	*10.35 FS
22	1		*GRILLE,FR.BUMPER LOWER	Distorted	54.30 FS	*54.30 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	2,784.06	1,885.08
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING SERVICE	New	60.00	60.00
2	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	140.00	100.00
3	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	1,800.00	1,350.00
4	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS	New	1,800.00	1,120.00
Gross Labour Cost (S\$)			3,800.00	2,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >