

22/03/2002

ASS. REC. BY:

REF:

CS/FCU8017150/Krbnz

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

LWS Karen Tan

of

FCL

Date/Time:

20092018 4:55pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 5287R

Insured:

SHC 8176M

at Workshop m/s

Estem Performance

Tel:

67532112

of

Sik 5033 Amik Ind Park 2 #01-251

Policy No:

Claim No:

D18006414MTSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18092018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

Blk 385 Sin Ming Ave

H.O.D. Endorsement:

Date/Time:

20092018 4:55pm

Person Contacted:

Jess

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLN 5287R - CC3/M3618017104/Rigb

DOA: 180918

SHC 8176M - X

16/11/18

Revert 1A via email

18/11

\$14426.31 Confirm

REF: FCI

ASSIGNMENT

From:

Date: 20092018

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLN 5287R

at Workshop m/s

Esteem Performance

of

385 Sin Ming D/M

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 885k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

14

days

Res.: Yes or No

Lum Sum:

1.B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLN 5287R Yr Regn: 05 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

C.C.

1798

Colour:

2. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading:

89772

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTD KB3FU 9.03556742

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

1P5/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

18/9/18

D.O.I.

20/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

2 R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/9 File ASD to Corham

RECEIVED 15 NOV 2018

Date/Time, File Pass to?



Preli. Report

1) typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 14

Resurvey No. of Trip: 2

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format:

7P

Lump Sum / I.B.I. (\$) 14,426.31

Survey Fee:

Transportation:

) S + P. St

) Photos

) Others

17X15 = 255

170 + 255

50

50 + 50

45

620



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006914MFSH

Date: 16 November 2018

Our Ref: CS/FCI18018936/Urd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLN 5287R

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20/09/2018 at the premises of M/s ESTEEM PERFORMANCE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 24,493.04 .
Revised Estimate Amount	: S\$ 14,426.31 .
"Check" Items Amount	: S\$.
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear and front portion.



Yours faithfully

KENNETH KONG
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	19-09-2018	Our Ref No. D18006914MFSH
Accident Date	18-09-2018	Claim Type. Third Party
Insured Vehicle	SHC8176M	Third Party Vehicle. SLN5287R
Survey Location	BLK 5033 ANG MO KIO, IND PARK 2 #01-251/259	
Contact Person.	SERENCE CHEE	
Contact No.	67532112/ 0	Fax No. 64510394
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ESTEEM PERFORMANCE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Friday, November 16, 2018 3:16 PM
To: 'Claim Workflow System'
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: RE: SURVEY ASSESSMENT - D18006914MFSH/1
Attachments: SLN 5287R.pdf

Dear Sir/ Madam,

Enclosed preliminary revised for SLN 5287R.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, September 20, 2018 4:12 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006914MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 20 September, 2018 4:05 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006914MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7200G
Vehicle Details	
Vehicle No.:	SLN5287R
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2ZR5042187
Chassis No.:	JTDKBB3FU903556742
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	08 May 2017
First Registration Date:	08 May 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 May 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	07 May 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,406.00
COE Rebate Amount:	\$46,936.00
Total Rebate Amount:	\$50,686.00

The information contained herein is correct as at 21 Sep 2018

OK



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLN 5287 R

Parts	(a) Cost / List Price Items	\$	22,577.38
	Plus/Less 25%	\$	5,644.35
	Total of Cost / List	\$	16,933.04
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	340.00
Total Parts Cost		\$	17,273.04
Labour		\$	7,220.00
Total		\$	24,493.04

The above total will be subjected to 7% G.S.T.

Not Authorized
I.B.I
Resurvey By print

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Name of Surveyor : Hennerth

Company : LKK

Survey conducted on : 20/9/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 14 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : De Date: 20/9/18

27109.33



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLN 5287 R**
Make & Model : **TOYOTA PRIUS**
Chassis No. : **JTDKB3FU203556663**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate <i>Bz</i>	1	\$45.00	S.N /	✓
2	Front number plate garnish <i>C M</i>	1	\$129.00	/	✓
3	Bonnet <i>R</i>	1	\$812.40		X
4	Bonnet lock <i>R</i>	1	\$130.00		X
5	Bonnet hinge LH <i>R</i>	1	\$57.80		X
6	Bonnet hinge RH <i>R</i>	1	\$57.80		X
7	Front bumper <i>Bz</i>	1	\$450.80	/	✓
8	Front bumper clip <i>me</i>	10	\$40.00	/	✓
9	Front bumper side retainer RH <i>D, J</i>	1	\$107.20	/	✓
10	Front bumper side retainer LH <i>Sm</i>	1	\$107.20		X
11	Front bumper upper grille <i>C M</i>	1	\$321.90	/	✓
12	Front bumper lower grille <i>D, J</i>	1	\$148.60	/	✓
13	Front bumper emblem <i>me</i>	1	\$87.10	/	✓
14	Front bumper tow cover RH <i>Sm</i>	1	\$25.70		X
15	Front bumper tow cover LH <i>Sm</i>	1	\$25.70		X
16	Front bumper sponge - upper <i>SVC</i>	1	\$89.81		?
17	Front bumper sponge - lower <i>SVC</i>	1	\$135.70		?
18	Rear windscreen moulding <i>me</i>	1	\$97.70	/	✓
19	Rear windscreen sealant <i>me</i>	1	\$50.00	S.N	4052
20	Rear number plate <i>Bz</i>	1	\$45.00	S.N	✓
21	Reverse sensor <i>P301</i>	1	\$200.00	S.N	✓
22	Rear bumper <i>Bz</i>	1	\$497.50	/	✓
23	Rear bumper clip <i>me</i>	10	\$40.00	/	✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLN 5287 R**
 Make & Model : **TOYOTA PRIUS**
 Chassis No. : **JTDKB3FU203556663**

Submit By : **Carmen Lim**
 Year Manufacture : **2017**
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Rear bumper side retainer LH <i>Sn</i>	1	\$112.70		X
25	Rear bumper side retainer RH <i>C M</i>	1	\$112.70		✓
26	Rear bumper reinforcement <i>R₁</i>	1	\$398.90		✓
27	Rear bumper lower garnish centre <i>R₁</i>	1	\$582.60		✓
28	Rear bumper lower garnish LH <i>Mg M</i>	1	\$149.70		✓
29	Rear bumper lower garnish RH <i>Bu</i>	1	\$149.70		✓
30	Rear bumper tow cover <i>NJ</i>	1	\$31.70		✓
31	Rear bumper under cover <i>Reborn</i>	1	\$355.20		✓
32	Rear bumper under cover LH <i>Sn</i>	1	\$187.60		? X
33	Rear bumper under cover RH <i>NJ</i>	1	\$187.60		✓
34	Rear bumper under cover clip <i>Mu</i>	4	\$14.00		✓
35	Tail door <i>R₁</i>	1	\$1,122.50		✓
36	Tail door lock <i>NJ</i>	1	\$487.70		✓
37	Tail door emblem <i>Mu</i>	1	\$61.70		✓
38	Wording "PRIUS" <i>Mu</i>	1	\$51.90		✓
39	Wording "HYBRID" <i>Mu</i>	1	\$55.47		✓
40	Tail door hinge LH <i>R</i>	1	\$87.60		X?
41	Tail door hinge RH <i>R</i>	1	\$87.60		X?
42	Taildoor absorber LH <i>Sn</i>	1	\$296.40		X
43	Taildoor absorber RH <i>Sn</i>	1	\$296.40		X
44	Tail door plate garnish <i>Mit</i>	1	\$782.50		✓
45	Tail door inner trim <i>Sn</i>	1	\$278.90		X?
46	Tail door inner trim clip <i>Mu</i>	10	\$28.00		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLN 5287 R**
 Make & Model : **TOYOTA PRIUS**
 Chassis No. : **JTDKB3FU203556663**

Submit By : **Carmen Lim**
 Year Manufacture : **2017**
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	Tail end panel <i>RT</i>	1	\$596.60	/	✓
48	Tail end panel garnish <i>Br</i>	1	\$151.60	/	✓
49	Tail end panel garnish clip <i>me</i>	10	\$35.00	/	✓
50	Boot weatherstrip <i>Dis / RT</i>	1	\$353.10	/	✓
51	Spare tyre well panel <i>R</i>	1	\$793.15		? X
52	Spare tyre board <i>CM</i>	1	\$566.79	/	✓
53	Spare tyre compartment sponge LH <i>su</i>	1	\$297.67		?
54	Spare tyre compartment sponge RH <i>return</i>	1	\$297.67	/	✓
55	Spare tyre compartment centre <i>su</i>	1	\$251.70	X	?
56	Tail lamp LH - UPPER <i>su</i>	1	\$498.75		X
57	Tail lamp RH - UPPER <i>CM su</i>	1	\$498.75	/	X
58	Tail lamp LH - LOWER <i>su</i>	1	\$511.60		X
59	Tail lamp RH - LOWER <i>CM</i>	1	\$511.60	/	✓
60	Taildoor glass <i>Shotton</i>	1	\$598.70	/	✓
61	Taildoor glass sealant <i>me</i>	1	\$50.00		4010
62	Tail door spoiler <i>su</i>	1	\$1,567.83		?
63	Third brake light <i>su</i>	1	\$359.64		?
64	Exhaust pipe <i>R</i>	1	\$854.10		?
65	Exhaust pipe mouting <i>R</i>	1	\$38.40		?
66	Exhaust insulator <i>nd</i>	1	\$267.40	/	✓
67	Rear Axle <i>su</i>	1	\$2,257.40		X?
68	Rear chassic LH <i>R</i>	1	\$388.90		X
69	Rear chassic RH <i>R</i>	1	\$388.90		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : SLN 5287 R
Make & Model : TOYOTA PRIUS
Chassis No : JTDKB3FU203556663

Submit By : Carmen Lim
Year Manufacture : 2017
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
70	LH rear inner trim <i>SLN</i>	1	\$386.75	<i>X</i>	<i>?</i>
71	RH rear inner trim <i>Re form</i>	1	\$386.75	<i>/</i>	<i>✓</i>
72	Antenna electrical key <i>CM</i>	1	\$155.45	<i>/</i>	<i>✓</i>
73	Rear number plate lamp LH <i>SLN</i>	1	\$98.30	<i>X</i>	<i>?</i>
74	Rear number plate lamp RH <i>SLN</i>	1	\$98.30	<i>X</i>	<i>?</i>
75	Spare tyre lock nut <i>Rt</i>	1	\$35.60	<i>/</i>	<i>✓</i>
76					
77					
78					
79					
80					
81					
82					
83					
84					
85					
86					
87					
88					
89					
90					
91					
92					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLN 5287 R** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER,BONNET,SUPPORT PANEL, REAR BUMPER,TAILOOR,END PANEL,SPARE TYRE WELL PANEL,LHR FENDER,RHR FENDER)	\$2,600.00	1200 /
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER,BONNET,SUPPORT PANEL, REAR BUMPER,TAILOOR,END PANEL,SPARE TYRE WELL PANEL,LHR FENDER,RHR FENDER)	\$2,400.00	1400 /
3	To check wiring & focus headlamp	\$50.00	40 /
4	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	100 /
5	To remove & refit radiator, condenser to assist work load, to top up A/C gas.	\$150.00	h? /
6	To remove & refit rear windscreen.	\$120.00	✓
7	To tuff coat.	\$300.00	90 /
8	To remove & refit taildoor glass to assit work load	\$120.00	80 /
9	To transfer boot mechanism to new boot	\$120.00	60 /

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Submit By : Carmen Lim

Year of Manufacture : 2017

[illegible]

Company Reg No. 200005485N / GST No. 20-0005485-N



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569538.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

4000 (1)
(2) (RFP 2017)

Repair Estimates

SLN 5287 R

Finalised

(a) Cost / List Price Items	\$	22,577.38
Plus/Less 25%	\$	5,644.35
Total of Cost / List	\$	16,933.04
(b) Nett Price Items		
Less		
Total of Nett Item		
(c) Special Nett Items	\$	340.00
Parts Cost	\$	17,273.04
	\$	7,220.00
	\$	24,493.04

14485.08
3608.77
10876.31

Not Authorized
I.B.1
Resurvey B4 print

370

11196.31

3230

14476.31 ✓ ok

Overall total will be subjected to 7% G.S.T.

Name of Surveyor

Kenner

Company

CKK

Survey conducted on

20/9/18

at

15:00

Remarks By Surveyor

The repair of this vehicle is ☒ authorized / Is not authorized until further notice.

Recommended Days of Repair : 14 day(s)

Resurvey : Required / ☒ Not Required

Excess : \$

Signature of surveyor

De

Date:

20/9/18

ESTEEM PERFORMANCE PTE LTD

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

Spare Parts

Vehicle No. :

Make & Model :

Chassis No. :

SLN 5287 R

TOYOTA PRIUS

JTDKB3FU203556663

Submit By :

Year Manufacture :

Engine No. :

Cost / List

CARMEN LIM

2017

Supplementary

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Headlamp RH <i>M-g (M)</i>	1	\$2,531.60	✓	✓
2	Front bumper reinforcement - upper <i>R1</i>	1	\$711.50	✓	✓
3	Front bumper reinforcement - lower <i>R1</i>	1	\$245.30	✓	✓
4					✓
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21		1			
22		1			
23		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

2488.40



ESTEEM PERFORMANCE PTE LTD

Bik 5099 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemparf.com.sg

Parts

e No. : **SLN 5287 R**
& Model : **TOYOTA PRIUS**
Is No : **JTDKB3FU203556663**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :
Cost / List

	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate <i>B₁</i>	1	\$45.00	✓ S.N	✓
2	Front number plate garnish <i>C.M₂</i>	1	\$129.00	✓	✓
3	Bonnet <i>R</i>	1	\$812.40		X
4	Bonnet lock <i>R</i>	1	\$130.00		X
5	Bonnet hinge LH <i>R</i>	1	\$57.80		X
6	Bonnet hinge RH <i>R</i>	1	\$57.80		X
7	Front bumper <i>B₂</i>	1	\$450.80	✓	✓
8	Front bumper clip <i>m</i>	10	\$40.00	✓	✓
9	Front bumper side retainer RH <i>D₁</i>	1	\$107.20	✓	✓
10	Front bumper side retainer LH <i>m</i>	1	\$107.20		X
11	Front bumper upper grille <i>S-10110 & C.M₂</i>	1	\$321.90	✓	✓
12	Front bumper lower grille <i>D₁</i>	1	\$148.60	✓	✓
13	Front bumper emblem <i>m</i>	1	\$87.10	✓	✓
14	Front bumper tow cover RH <i>S₂</i>	1	\$25.70		X
15	Front bumper tow cover LH <i>S₂</i>	1	\$25.70		X
16	Front bumper sponge - upper <i>S₂</i>	1	\$89.81		X
17	Front bumper sponge - lower <i>S₂</i>	1	\$135.70		X
18	Rear windscreen moulding <i>m</i>	1	\$97.70	✓	✓
19	Rear windscreen sealant <i>m</i>	1	\$50.00	✓ S.N	Posn
20	Rear number plate <i>B₁</i>	1	\$45.00	✓ S.N	✓
21	Reverse sensor <i>S₂007</i>	1	\$200.00	✓ S.N	✓
22	Rear bumper <i>B₁</i>	1	\$497.50	✓	✓
23	Rear bumper clip <i>m</i>	10	\$40.00	✓	✓

any of the quoted parts are recommended to be repaired, then an additional labour charge charged accordingly under supplementary.

19.9.80
330 (S.N).

Parts

g No. : **SLN 5287 R**
 & Model : **TOYOTA PRIUS**
 is No : **JTDKB3FU203556663**

Submit By : **Carmen Lim**
 Year Manufacture : **2017**
 Engine No. :
Cost / List

	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
34	Rear bumper side retainer LH <i>Sm</i>	1	\$112.70		X
35	Rear bumper side retainer RH <i>CM</i>	1	\$112.70	✓	✓
36	Rear bumper reinforcement <i>R₁</i>	1	\$398.90	✓	✓
37	Rear bumper lower garnish centre <i>R₁</i>	1	\$582.60	✓	✓
38	Rear bumper lower garnish LH * <i>mgc R₁</i>	1	\$149.70	✓	✓
39	Rear bumper lower garnish RH * <i>R₁</i>	1	\$149.70	✓	✓
40	Rear bumper tow cover <i>Del</i>	1	\$31.70	✓	✓
41	Rear bumper under cover <i>Return</i>	1	\$355.20	✓	✓
42	Rear bumper under cover LH <i>Sm</i>	1	\$187.60		X
43	Rear bumper under cover RH <i>Del</i>	1	\$187.60	✓	✓
44	Rear bumper under cover clip <i>Sm</i>	4	\$14.00	✓	✓
45	Tail door <i>R₁</i>	1	\$1,122.50	✓	✓
46	Tail door lock <i>Del</i>	1	\$487.70	✓	✓
47	Tail door emblem <i>Sm</i>	1	\$61.70	✓	✓
48	Wording "PRIUS" <i>Sm</i>	1	\$51.90	✓	✓
49	Wording "HYBRID" <i>Sm</i>	1	\$55.47	✓	✓
50	Tail door hinge LH <i>R</i>	1	\$87.60		X
51	Tail door hinge RH <i>R</i>	1	\$87.60		X
52	Taildoor absorber LH <i>Sm</i>	1	\$296.40		X
53	Taildoor absorber RH <i>Sm</i>	1	\$296.40		X
54	Tail door plate garnish <i>mi'l</i>	1	\$782.50	✓	✓
55	Tail door inner trim <i>Sm</i>	1	\$278.90		X
56	Tail door inner trim clip <i>Sm</i>	10	\$28.00	✓	✓

any of the quoted parts are recommended to be repaired, then an additional labour charge charged accordingly under supplementary.

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SLN 5287 R

TOYOTA PRIUS

JTDKB3FU203556663

Submit By :
Year Manufacture :
Engine No. :

Carmen Lim

2017

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	Tail end panel	1	\$596.60	✓	✓
48	Tail end panel garnish	1	\$151.60	✓	✓
49	Tail end panel garnish clip	10	\$35.00	✓	✓
50	Boot weatherstrip	1	\$353.10	✓	✓
51	Spare tyre well panel	1	\$793.15		X
52	Spare tyre board	1	\$566.79	✓	✓
53	Spare tyre compartment sponge LH	1	\$297.67		X
54	Spare tyre compartment sponge RH	1	\$297.67	✓	✓
55	Spare tyre compartment centre	1	\$251.70		X
56	Tail lamp LH - UPPER	1	\$498.75		X
57	Tail lamp RH - UPPER	1	\$498.75	✓	✓
58	Tail lamp LH - LOWER	1	\$511.60		X
59	Tail lamp RH - LOWER	1	\$511.60	✓	✓
60	Taildoor glass	1	\$598.70	✓	✓
61	Taildoor glass sealant	1	\$50.00	✓	✓
62	Tail door spoiler	1	\$1,567.83		X
63	Third brake light	1	\$359.64		X
64	Exhaust pipe	1	\$854.10		X
65	Exhaust pipe mounting	1	\$38.40		X
66	Exhaust insulator	1	\$267.40	✓	✓
67	Rear Axle	1	\$2,257.40		X
68	Rear chassis LH	1	\$388.90		X
69	Rear chassis RH	1	\$388.90		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

10368-88

3877-21
40 (S-N)

Spare Parts

Vehicle No. : **SLN 5287 R**

Make & Model : **TOYOTA PRIUS**

Chassis No : **JTDKB3FU203556663**

Submit By : **Carmen Lim**

Year Manufacture : **2017**

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
70	LH rear inner trim <i>Sen</i>	1	\$386.75		X
71	RH rear inner trim <i>Reform</i>	1	\$386.75	✓	✓
72	Antenna electrical key <i>CM</i>	1	\$155.45	✓	✓
73	Rear number plate lamp LH <i>Sen</i>	1	\$98.30		X
74	Rear number plate lamp RH <i>Sen</i>	1	\$98.30		X
75	Spare tyre lock nut <i>Rt</i>	1	\$35.60	✓	✓
76					
77					
78					
79					
80					
81					
82					
83					
84					
85					
86					
87					
88					
89					
90					
91					
92					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/252, 669536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLN 5287 R** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER,BONNET,SUPPORT PANEL, REAR BUMPER,TAILOOR,END PANEL,SPARE TYRE WELL PANEL,LHR FENDER,RHR FENDER)	\$2,600.00	1200
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER,BONNET,SUPPORT PANEL, REAR BUMPER,TAILOOR,END PANEL,SPARE TYRE WELL PANEL,LHR FENDER,RHR FENDER)	\$2,400.00	1400
3	To check wiring & focus headlamp	\$50.00	40
4	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	100
5	To remove & refit radiator, condenser to assist work load, to top up A/C gas.	\$150.00	2
6	To remove & refit rear windscreen.	\$120.00	✓
7	To tuff coat.	\$300.00	90
8	To remove & refit taildoor glass to assit work load	\$120.00	80
9	To transfer boot mechanism to new boot	\$120.00	60

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

3230

2090

Submit By : Carmen Lim
Year of Manufacture : 2017

[illegible]

Company Reg No. 200005485N / GST No. 20-0005485-N



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18017150/Krbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 27-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8176M	Veh. Inspected	SLN 5287R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006914MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	20/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU903556742	Colour	METALLIC SILVER	
Odometer	89772	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	7 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	7 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/09/2018	Inspection Date	20/09/2018	
Survey held at	BLK 385 SIN MING DRIVE			
Repairer	ESTEEM PERFORMANCE PTE LTD			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 5287R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT NUMBER PLATE GARNISH	CRACKED	129.00	129.00
1	BONNET	TO REPAIR SEE LABOUR	812.40	-
1	BONNET LOCK	TO REPAIR SEE LABOUR	130.00	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	57.80	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	57.80	-
1	FRONT BUMPER	BUCKLED	450.80	450.80
10	FRONT BUMPER CLIP	NECESSARY	40.00	40.00
1	FRONT BUMPER SIDE RETAINER RH	DISTORTED	107.20	107.20
1	FRONT BUMPER SIDE RETAINER LH	SERVICEABLE	107.20	-
1	FRONT BUMPER UPPER GRILLE	CRACKED	321.90	321.90
1	FRONT BUMPER LOWER GRILLE	DISTORTED	148.60	148.60
1	FRONT BUMPER EMBLEM	NECESSARY	87.10	87.10
1	FRONT BUMPER TOW COVER RH	SERVICEABLE	25.70	-
1	FRONT BUMPER TOW COVER LH	SERVICEABLE	25.70	-
1	FRONT BUMPER SPONGE -UPPER	SERVICEABLE	89.81	-
1	FRONT BUMPER SPONGE -LOWER	SERVICEABLE	135.70	-
1	REAR WINDSCREEN MOULDING	NECESSARY	97.70	97.70
1	REAR BUMPER	BENT	497.50	497.50
10	REAR BUMPER CLIP	NECESSARY	40.00	40.00
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	112.70	-
1	REAR BUMPER SIDE RETAINER RH	CRACKED	112.70	112.70
1	REAR BUMPER REINFORCEMENT	BENT	398.90	398.90
1	REAR BUMPER LOWER GARNISH CENTRE	BENT	582.60	582.60
1	REAR BUMPER LOWER GARNISH LH	MTG CRACKED	149.70	149.70
1	REAR BUMPER LOWER GARNISH RH	BUCKLED	149.70	149.70
1	REAR BUMPER TOW COVER	DENTED	31.70	31.70
1	REAR BUMPER UNDER COVER	DEFORMED	355.20	355.20
1	REAR BUMPER UNDER COVER LH	SERVICEABLE	187.60	-

Report Ref No. CS/FCI18017150/Krbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER UNER COVER RH	DISTORTED	187.60	187.60
4	REAR BUMPER UNDER COVER CLIP	NECESSARY	14.00	14.00
1	TAIL DOOR	BENT	1,122.50	1,122.50
1	TAIL DOOR LOCK	DENTED	487.70	487.70
1	TAIL DOOR EMBLEM	NECESSARY	61.70	61.70
1	WORDING 'PRIUS'	NECESSARY	51.90	51.90
1	WORDING 'HYBRID'	NECESSARY	55.47	55.47
1	TAIL DOOR HINGE LH	TO REPAIR SEE LABOUR	87.60	-
1	TAIL DOOR HINGE RH	TO REPAIR SEE LABOUR	87.60	-
1	TAILDOOR ABSORBER LH	SERVICEABLE	296.40	-
1	TAILDOOR ABSORBER RH	SERVICEABLE	296.40	-
1	TAIL DOOR PLATE GARNISH	MISSING	782.50	782.50
1	TAIL DOOR INNER TRIM	SERVICEABLE	278.90	-
10	TAIL DOOR INNER TRIM CLIP	NECESSARY	28.00	28.00
1	TAIL END PANEL	BENT	596.60	596.60
1	TAIL END PANEL GARNISH	BUCKLED	151.60	151.60
10	TAIL END PANEL GARNISH CLIP	NECESSARY	35.00	35.00
1	BOOT WEATHERSTRIP	DISTORTED / DENTED	353.10	353.10
1	SPARE TYRE WELL PANEL	TO REPAIR SEE LABOUR	793.15	-
1	SPARE TYRE BOARD	CRACKED	566.79	566.79
1	SPARE TYRE COMPARTMENT SPONGE LH	SERVICEABLE	297.67	-
1	SPARE TYRE COMPARTMENT SPONGE RH	DEFORMED	297.67	297.67
1	SPARE TYRE COMPARTMENT CENTRE	SERVICEABLE	251.70	-
1	TAIL LAMP LH-UPPER	SERVICEABLE	498.75	-
1	TAIL LAMP RH-UPPER	CRACKED	498.75	498.75
1	TAIL LAMP LH -LOWER	SERVICEABLE	511.60	-
1	TAIL LAMP RH -LOWER	CRACKED	511.60	511.60
1	TAILDOOR GLASS	SHATTERED	598.70	598.70
1	TAIL DOOR SPOILER	SERVICEABLE	1,567.83	-
1	THIRD BRAKE LIGHT	SERVICEABLE	359.64	-

Report Ref No. CS/FCI18017150/Krbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXHAUST PIPE	TO REPAIR SEE LABOUR	854.10	-
1	EXHAUST PIPE MOUNTING	TO REPAIR SEE LABOUR	38.40	-
1	EXHAUST INSULATOR	DENTED	267.40	267.40
1	REAR AXLE	SERVICEABLE	2,257.40	-
1	REAR CHASSIS LH	TO REPAIR SEE LABOUR	388.90	-
1	REAR CHASSIS RH	TO REPAIR SEE LABOUR	388.90	-
1	LH REAR INNER TRIM	SERVICEABLE	386.75	-
1	RH REAR INNER TRIM	DEFORMED	386.75	386.75
1	ANTENNA ELECTRICAL KEY	CRACKED	155.45	155.45
1	REAR NUMBER PLATE LAMP LH	SERVICEABLE	98.30	-
1	REAR NUMBER PLATE LAMP RH	SERVICEABLE	98.30	-
1	SPARE TYRE LOCK NUT	BENT	35.60	35.60
1	HEADLAMP RH (ADDITIONAL)	MTG CRACKED	2,531.60	2,531.60
1	FRONT BUMPER REINFORCEMENT-UPPER (ADDITIONAL)	BENT	711.50	711.50
1	FRONT BUMPER REINFORCEMENT -LOWER (ADDITIONAL)	BENT	245.30	245.30
	LESS 25% DISCOUNT		-6,503.95	-3,608.77
			19,511.83	10,826.31
1	TAILDOOR GLASS SEALANT (SN)	NECESSARY	50.00	40.00
	LESS 25% DISCOUNT		-12.50	-
			37.50	40.00
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	BENT	45.00	45.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR NUMBER PLATE (SN)	BENT	45.00	45.00
1	REVERSE SENSOR (SN)	SHORTED	200.00	200.00
			340.00	330.00

Report Ref No. CS/FCI18017150/Krbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO RENEW DAMAED PARTS & KNOCK OUT ACCIDENT REPAIR AREA .(FRONT BUMPER ,BONNET ,SUPPORT PANEL,REAR BUMPER ,TAILDOOR ,END PANEL ,SPARE TYRE WELL PANEL ,LHR FENDER ,RHR FENDER).INCLUSIVE OF THE REPAIR OF BONNET,BONNET LOCK,BONNET HINGE LH ,BONNET HINGE RH,TAIL DOOR HINGE LH ,TAIL DOOR HINGE RH,SPARE TYRE WELL PANEL ,EXHAUST PIPE,EXHAUST PIPE MOUNTING,REAR CHASSIS LH AND REAR CHASSIS RH.		2,600.00	1,200.00
	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (FRONT BUMPER ,BONNET,SUPPORT PANEL,REAR BUMPER ,TAILDOOR,END PANEL ,SPARE TYRE WELL PANEL,LHR FENDER ,RHR FENDER).		2,400.00	1,400.00
	TO CHECK WIRING & FOCUS HEADLAMP.		50.00	40.00
	TO REMOVE & REFIT SPARE TYRE ,SPARE TYRE BOARD ,CARPET TRIM TO ASSIST WORK LOAD.		150.00	100.00
	TO REMOVE & REFIT RADIATOR ,CONDENSER TO ASSIST WORK LOAD,TO TOP UP A/C GAS.	NOT NECESSARY	150.00	-
	TO REMOVE & REFIT REAR WINDSCREEN.		120.00	120.00
	TO TUFF COAT.		300.00	90.00
	TO REMOVE & REFIT INTERIOR GLASS TO ASSIT WORK LOAD.		120.00	80.00
	TO TRANSFER BOOT MECHANISM TO NEW BOOT.		120.00	60.00
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.		120.00	30.00
	TOWING.		60.00	50.00
	TO RE-ALIGN REAR CHASSIC.	NOT NECESSARY	600.00	-
	TO REMOVE & REFIT INNER SEAT & UPHOLSTERY TO ASSIST WORK LOAD.	NOT NECESSARY	280.00	-
	TO REMOVE & REFIT EXHAUST SYSTEM TO ASSIST WORK LOAD.		150.00	60.00
	-		-	-
	-		-	-
	-		-	-
			7,220.00	3,230.00
	GRAND TOTAL		27,109.33	14,426.31

Report Ref No. CS/FC118017150/Krbn2



RECOMMENDED COST OF REPAIRS			14,426.31
-----------------------------	--	--	-----------

Report Ref No. CS/FCI18017150/Krbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.