



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLK7586E

Date of Accident : 14 September 2018

Messrs Asia Pacz Pte Ltd

Date : 17 September 2018

Estimate To Repair GBE7338E - Toyota Dyna 150 Manual
Chassis No : JTFAT35Y30K205903

S/No	Quantity	Description	Amount
		LIST ITEMS	
01	1 pc	front wheel mudguard garnish <i>o/s ground</i>	\$ 194.70
02	1 pc	side gate lis stopper rubber <i>holmis</i>	\$ 28.70
03	1 pc	side gate lid step panel <i>sl</i>	\$ 124.30
04	6 ps	side gate lid hinge pin @ \$12.10 <i>11</i>	\$ 72.60
05	1 pc	rear wheel mudguard front <i>CHS R</i>	\$ 194.40
06	1 pc	rear wheel mudguard rear <i>CHS R</i>	\$ 188.70
07	1 pc	diesel tank <i>R</i>	\$ 745.10
08	1 pc	air cleaner tank <i>11</i>	\$ 394.70
			\$ 1,943.20
		Less 25 %	\$ 485.80
			\$ 1,457.40
		SPECIAL NETT ITEMS	
09	1 pc	side gate lid corporate sticker and address <i>new</i>	\$ 450.00
			\$ 450.00
		LABOUR & MISC. CHARGES	
01		To drop diesel tank and renew the same.	\$ 250.00
02		To install corporate sticker.	\$ 120.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 600.00
04		Putty and spray painting of the affected portion.	\$ 780.00
			\$ 1,750.00
		Total	\$ 3,657.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-347-7
252
260.77
1840.17