



FALCON-AIR

LONPAC INSURANCE BHD  
100 BEACH ROAD #19-00  
SHAW TOWER S189702Attention : Motor Claim Department  
Contact : 62507388 Fax No. : 62962706

Tax Invoice : TI101028

Date : 31/10/2018  
Vehicle Num. : SKQ3937H  
Make/Model : VOLKSWAGEN GOLF  
Chassis/Eng# : WWWZZZAUZFW041392  
Accident Date : 17/09/2018  
Claim No. :  
Reference : TP NTUC VS LONPAC  
Policy No. :

| S/N                                   | Quantity | Particular                 | Unit Price | Amount S\$ |
|---------------------------------------|----------|----------------------------|------------|------------|
| <b>PARTS PURCHASED :</b>              |          |                            |            |            |
| 1.                                    | 1        | TAILGATE                   |            | 750.00     |
| 2.                                    | 1        | TAILGATE LAMP RH           |            | 110.00     |
| 3.                                    | 1        | TAILGATE EMBLEM GOLF       |            | 45.00      |
| 4.                                    | 1        | TAILGATE EMBLEM TSI        |            | 40.00      |
| 5.                                    | 1        | TAILGATE EMBLEM BLUEMOTION |            | 40.00      |
| 6.                                    | 1        | REAR BUMPER                |            | 480.00     |
| 7.                                    | 1        | REAR BUMPER LOWER GARNISH  |            | 165.00     |
| 8.                                    | 4        | REVERSE SENSOR HOLDER      | 18.00      | 72.00      |
| Total Parts Purchased S\$ :           |          |                            |            | 1,702.00   |
| 20.00% Of The Above Parts S\$ :       |          |                            |            | 340.40     |
| Based On Cost Plus S\$ :              |          |                            |            | 2,042.40   |
| <b>SPECIAL NETT ITEMS :</b>           |          |                            |            |            |
| 1.                                    | 1        | SEALANT                    |            | 40.00      |
| 2.                                    |          | REAR BUMPER CLIPS          |            | 30.00      |
| 3.                                    | 1        | REAR NUMBER PLATE          |            | 45.00      |
| Special Nett Total S\$ :              |          |                            |            | 115.00     |
| <b>LABOUR :</b>                       |          |                            |            |            |
| TO REMOVE/REFIX REAR WINDSCREEN GLASS |          |                            |            | 120.00     |

CONTINUE / ...

**FALCON-AIR AUTO SERVICES PTE LTD**

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

**FALCON-AIR AUTO SERVICES PTE LTD**

CO. REG. NO.: 1995-01140-D

GST REG. NO.: 19-9501140-D



FALCON-AIR

LONPAC INSURANCE BHD  
100 BEACH ROAD #19-00  
SHAW TOWER S189702

Attention : Motor Claim Department

Contact : 62507388 Fax No. : 62962706

Tax Invoice : TI101028

Date : 31/10/2018

Vehicle Num. : SKQ3937H

Make/Model : VOLKSWAGEN GOLF

Chassis/Eng# : WWWZZZAUZFW041392

Accident Date : 17/09/2018

Claim No. :

Reference : TP NTUC VS LONPAC

Policy No. :

| S/N | Quantity | Particular                                           | Unit Price | Amount S\$ |
|-----|----------|------------------------------------------------------|------------|------------|
|     |          | SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER |            | 600.00     |
|     |          | TO CHECK REAR WIRING                                 |            | 30.00      |
|     |          | TO REPAIR REAR END PANEL, REAR FENDERS INCLUDES      |            |            |
|     |          | KNOCKING & REPLACEMENT OF PARTS                      |            | 450.00     |
|     |          | Labour Total S\$ :                                   |            | 1,200.00   |

E. &amp; O.E.

Total S\$ : 3,357.40

7% GST S\$ : 235.02

Amount Due S\$ : 3,592.42

=====



*[Handwritten signature]*

for FALCON AIR AUTO SERVICES PTE LTD

**FALCON-AIR AUTO SERVICES PTE LTD**

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg