



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD
CO. REG. No.: 1995-01140-D

TP INSURER:
JARED MENG JUN JIE

Lonpac Insurance Bhd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	17/09/2018
Vehicle Reg. No.:	SKQ3937H	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	VOLKSWAGEN GOLF, 1.4 A7	Vehicle Reg.	26/11/2014
	TSI AT BMT 5G14JZ SR HID (A)	Date:	
Vehicle Colour:	BLUE	Chassis No:	WWWZZZAUZFW041392
Engine No:	CXS217181		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair 5 (day)			
Remarks:	VEHICLE NOT IN WORKSHOP, PLEASE ARRANGE FOR SURVEY WITH ANDY (67795665)		
Present Location:	FALCON-AIR AUTO SERVICES PTE LTD (PANDAN)		

Tan Kah 97495749
wp
27/9/18 @ 11am
Repair before paint
and estimate was
4-5 days

COST OF CLAIMS	Amount
Parts	3,541.00
Miscellaneous Items	0.00
Labour	2,250.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,791.00
+ GST 7.00% (S\$)	405.37
Nett Amount (S\$)	6,196.37

This claim is handled by: GAIL NG

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Sep 2018)
 Parts: 144 VOLKSWAGEN GOLF 1.4 A7 TSI AT BMT 5G14JZ SR HID (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Falcon-Air Auto Services Pte Ltd/SKQ3937H/20/09/2018 11:38
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAILGATE	0.00	0.00	*750.00 F <i>bt</i>
2	1		*TAILGATE LOCK	0.00	0.00	*150.00 F ?
3	1		*TAILGATE WEATHERSTRIP	0.00	0.00	*140.00 F ?
4	1		*SEALANT	0	0.00	*40.00 FS <i>na</i>
5	2		*TAILGATE REFLECTOR	0.00	0.00	*220.00 F ?
6	1		*TAILGATE EMBLEM - GOLF	0.00	0.00	*45.00 F <i>na</i>
7	1		*TAILGATE EMBLEM - TSI	0.00	0.00	*40.00 F <i>na</i>
8	1		*TAILGATE EMBLEM - ACTIVMOTION	0.00	0.00	*480.00 F <i>de</i>
9	1		*REAR BUMPER	0.00	0.00	*40.00 F X
10	2		*REAR BUMPER SIDE RETAINER	0.00	0.00	*15.00 F X
11	1		*REAR BUMPER TOW COVER	0.00	0.00	*240.00 F ?
12	1		*REAR BUMPER REINFORCEMENT	0.00	0.00	*165.00 F <i>int</i>
13	1		*REAR BUMPER LOWER GARNISH	0	0.00	*30.00 FS <i>na</i>
14	10		*REAR BUMPER CLIPS	0.00	0.00	*100.00 F <i>na</i>
15	4		*REVERSE SENSOR HOLDER	0.00	0.00	*250.00 F ?
16	1		*REVERSE SENSOR (INNER)	0.00	0.00	*100.00 F X
17	1		*TAILGATE INNER TRIM	0.00	0.00	*80.00 F X
18	1		*REAR END PANEL GARNISH	0	0.00	*45.00 FS <i>bt</i>
19	1		*REAR NUMBER PLATE			

F=Franchise part. S=SpcNetl.

Sub Total (\$\$)	2,970.00
+ Margin on L,N Items 20.00% (\$\$)	571.00
Total Parts (\$\$)	3,541.00

Falcon-Air Auto Services Pte Ltd/SKQ3937H/20/09/2018 11:38. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CHECK REAR WIRING	New	50.00 30
2	TO REMOVE/REFIX REAR WINDSCREEN	New	120.00 ✓
3	TO STRAIGHTEN REAR END PANEL, LH/RH REAR FENDER, INCLUDES REPLACEMENT OF PARTS	New	800.00 450
4	TO SPRAY PAINT TAILGATE, REAR BUMPER, REAR BUMPER REINFORCEMENT, REAR END PANEL, LH/RH REAR FENDER	New	1,100.00 600
5	TO APPLY BODY SEALANT ON CAR JOINTS	New	80.00 ?
6	TO RUSTPROOF ACCIDENT DAMAGED AREAS	New	100.00 ?
Gross Labour Cost (S\$)			2,250.00

Falcon-Air Auto Services Pte Ltd/SKQ3937H/20/09/2018 11:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD

(A subsidiary of Falcon Air Holdings Pte Ltd)

Head Office : Blk 170 Sin Ming Drive #01-08/07/13, #05-17 Sin Ming Autocare S(525721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7662
Branches : Tampines St 93 Blk 8006 #01-200 S(526840) Tel: 6759-7997 Fax: 6755-7997 • No 8 Pandan Loop S(126226) Tel: 6779-5665 Fax: 6779-1119
Website: www.falconair.com.sg Email: email@falconair.com.sg

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date: