



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

## EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



CITROËN

### ESTIMATE

| Invoice Name & Address  | Owner Name & Vehicle Info |                                   |
|---|---------------------------|-----------------------------------|
| CHINA TAIPING INSURANCE (SINGAPORE)<br>3 Anson Road #16-00<br>Springleaf Tower<br>Singapore 079909<br>Attn: Claims Dept.<br><br>Contact No 63896111 | Cust No/Name              | /Netlink Management Pte. Ltd.     |
|   | Reg No/Reg Date           | GBH5247G / 02/07/2018             |
|   | Date In/Mileage           | 19/09/2018/ 0                     |
|   | Chassis No                | VF77FBHYMHJ760130                 |
|   | Engine No                 | 10JBHW3019358                     |
|   | Make/Model                | CITCV/BERLINGO L2 1.6 BLUEHDI ETG |
|   | Colour/Trim               | WPP / BK                          |

| Account No | Terms  | Date/Time Printed | CSE | Operator      | WIP No |
|------------|--------|-------------------|-----|---------------|--------|
| F0000018   | Credit | 19/09/2018/ 19:02 | DS  | 218 / MarsLer | 10362  |

| Description of Goods / Services   | Qty  | Unit Price | Disc% | Amount  |
|---|------|------------|-------|---------|
| S MIPNT88088<br>TO CHECK LIGHTING AND WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS  |      |            |       | 80.00   |
| S MIPNT88088<br>DIAGNOSTIC / SCANNING   |      |            |       | 250.00  |
| S MIPNT88088<br>TO REPLACE FRONT BUMPER,RHF FENDER,ETC<br>STRAIGHTEN,REFORM,ALIGN ON FRT ACCIDENT AFFECTED AREAS  |      |            |       | 1800.00 |
| S MIPNT88088<br>TO APPLY SEALANT KIT ON PANEL   |      |            |       | 100.00  |
| S MIPNT98088<br>SPRAY PAINTING ON FRT & RHF ACCIDENT AFFECTED AREAS   |      |            |       | 1260.00 |
| M C1613563780<br>FRONT BUMPER   | 1.00 | 856.00     | 0.00  | 856.00  |
| P C7416J2<br>BUMPER SIDE BRACKET  | 1.00 | 56.00      | 0.00  | 56.00   |
| M C1613564780<br>BUMPER MOULDING  | 1.00 | 197.00     | 0.00  | 197.00  |
| M C7841Y2<br>RHF FENDER PANEL   | 1.00 | 348.00     | 0.00  | 348.00  |
| Z NOTES<br>ACCIDENT ON 18/09/2018 ALONG RAEURN PARK<br>OWNER CLAIMING THIRD PARTY<br>REQUIRED REPLACEMENT VEHICLE<br>TP #PC1730P TP INS : CHINA TAIPING |      |            |       |         |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm &amp; accepted by

Authorized signatory and company stamp

|                 |          |
|-----------------|----------|
| Parts           | 1,457.00 |
| Labour          | 0.00     |
| Standard Menu   | 0.00     |
| Specialist Job  | 3,490.00 |
| Others(Lub,etc) | 0.00     |
| Sundry          | 0.00     |
| Total(w/o GST)  | 4,947.00 |

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.