



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18017178/Kga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 29-06-2020



ATTN:RICHARD

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKE 3393P	Veh. Inspected	GBE 3570B
Policy No.		Coverage (\$)	0.00
Claim No.	S8M0095V	Excess (\$)	0.00
Assign From		Assign Date	20/09/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JTFAT35Y90K205033	Colour	SILVER
Odometer	101522	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15X8	FIRENZA	6 mm
L/H Front Tyre	195 R15X8	FIRENZA	6 mm
R/H Rear Tyre	155 R15X8 (D)	FIRENZA	4/4 mm
L/H Rear Tyre	155 R15X8 (D)	FIRENZA	4/4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/02/2018	Inspection Date	20/09/2018
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------