

ASS. REF. BY:

REF: CS/MSG18017182/RI.1652/ Special Instruction:

SURVIVOR: Rasul ASSIGNMENT (Office)
From (Person): Ng Chen How of MSIH Date/Time: 20092018 4:15pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: WC 1594H Insured: WC 2648E

at Workshop m/s Woodlands Transport Tel: 6559 8982

of No. 8 Gul Circle

Policy No: B39088196 MKF Claim No: 570683

Sum Insured: Excess:

Make of Veh: D.O.A. 17092018

(Client's Record)

CA / REV / REP. / REV 24 HRS 1401 H.O.D. Endorsement:

Date/Time: 21092018 9:00am Person Contacted: Mr. Rahman. Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	WC 1594H - CS / LIP / 11001766 / Kan DA: JSD1-11
	WC 2648E - NA / MSG18017182 / ZH DA: 17092018
31/10/18	Revert 1A thru menmen Rasul confirmed L/s \$1800 @ 4 day (red. \$758.00, 29%)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18017182/R1rb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 20-09-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	WC 2648E	Veh. Inspected	WC 1594H
Policy No.	B29088496MKF	Coverage (\$)	0.00
Claim No.	570683	Excess (\$)	0.00
Assign From	MERIMEN (NG CHEN HOW)	Assign Date	20/09/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	17/09/2018	Inspection Date	21/09/2018
Survey held at	WOODLANDS TRANSPORT SERVICE PTE. LTD. 8 GUL CIRCLE SINGAPORE 629564		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Sep 2018		20 Sep 2018 16:45 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS			[Created by insurer]
Insured:	Alliance Concrete Singapore Pte. Ltd., Co. Reg. No.: 200516266D		
Main Claimant:	WOODLANDS TRANSPORT SERVICE PTE LTD, Co. Reg. No.: 198102721M		
Vehicle Reg. No.:	WC1594H	Date of Loss:	17/09/2018 13:00 - :59 [130 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 570683	Policy/Cover Note No.:	B29088496MKF (Comprehensive) Coverage: 01/07/2018 - 30/06/2019
Vehicle Reg. No. (Insured):	WC2648E	Policy No. (Claimant):	
		Excess:	
Repairer:	Woodlands Transport Service Pte Ltd () NO 6 CHIA PING ROAD, 619971 Jurong East - Tel: 65598988		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by NG CHEN HOW - 6643 1391]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/09/2018]		
Driver/Custodian (Insured):	TEO SENG LEE (61 / Male), NRIC: S1275143E		
Adj Asg. Remarks:	Car in. on WP. Please contact us ASAP if you cannot attend this assignment. Workshop wants M/s LKK Auto Consultants to survey. Liability is clear but insured may take over claim.		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													



WTS Engineering Pte Ltd

YOUR REF : WC2648E
OUR REF : JW/0918/583

19 September 2018

MSIG Insurance (Singapore) Pte Ltd
16 Raffles Quay
#24-01, Hong Leong Building
Singapore 048581

By fax: 66431349

Dear Sir

We are instructed by Woodlands Transport Service Pte Ltd to notify you of a road traffic accident on 17/09/2018 about 12:48 hrs at Punggol Timor involving our client's/customer's vehicle registration number WC1594H and vehicle registration number WC2648E driven by you at the material time. A copy of the Singapore accident statement /traffic police report filed is enclosed.

As a result of the accident, our client's /customer's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to repair the vehicle without further reference to you.

Please send your surveyor to our premises at **No. 8 Gul Circle, Singapore 629564.**

Please contact Mr Rahman Tel 6559 8982 for an appointment to view the vehicle.

For your immediate attention and action, please.

Thank you.

Yours faithfully,

Kenji Lee
Claims Department

Direct Line : (65) 6559 8954
Facsimile : (65) 6898 2394
Email : kenjilee@woodlandstransport.com.sg

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: NG CHEN HOW

Date: 31 Oct 2018

Preliminary Advice

Insured Vehicle No	: WC2648E	Accident Date	: 17/09/2018
TP Vehicle No	: WC1594H	Assignment Date	: 20/09/2018
Make	: ISUZU CYH52S	Est. Duration of Repair	: 4.00
Date of Inspection	: 21/09/2018		
Inspection At	: WOODLANDS TRANSPORT SERVICE PTE LTD NO 6 CHIA PING ROAD SINGAPORE 619971		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,558.00
Revised Amount	:S\$	2,258.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,258.00
Lump Sum Repair	:S\$	1,800.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/09/2018 14:58
Date Of Accident	17/09/2018 12:40
Exact Location Of Accident	PUNGGOL TIMOR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	WC1594H
Insured/Policyholder	
Name Of Registered Owner	WOODLANDS TRANSPORT SERVICE PTE LTD
Co Reg No	198102721M
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98383481
Alternative Phone No	OFFICE-65598954

Vehicle Particulars

Manufacturer	ISUZU
Model	CYH52S
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	SD17V11056
Cover Note Number	

Driver

Name of Driver	YEO PHENG SONG
NRIC No	S1123163B
Date Of Birth	04/01/1975
Occupation	OUTDOOR
Date Of Driving Pass	23/07/1979
Driving Experience	39 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96275435
Fax Number	(LOCAL) +65-68982394
Contact Number	OFFICE-65598954
E-Mail Address	NOEMAIL

Accident Photo



8517 8023 Joseph



WTS Engineering Pte Ltd
8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163
Company Registration Number: 200505706E

Surveyor Sign:	<i>[Signature]</i>
Surveyor Name:	RASUL
Date:	21/09/18

Quotation

DATE:	19/09/18	LOCATION:	Gul Workshop
VEHICLE NO:	WC1594H	Q REF No:	Q18/09/931
DRIVER:	YEO PHENG SONG	DEPARTMENT:	WTS Mixer Truck Department
ATTENTION TO:		ACCIDENT DATE:	17/09/18
PREPARED BY:	Winson	REF No:	JW/0918/583

S/N	Description	Qty	Cost per Unit	Amount S\$
Spare Parts				
1	FRONT BUMPER ASSY	1	950	950.00
2	RHS HEAD LAMP BRACKET	1	220	220.00
3	RHS FOG LAMP	1	75	75.00
4	RHS SIGNAL LAMP	1	28	28.00
5	RHS HEAD LAMP ASSY	1	135	135.00
Labour Costs				
1	LABOUR CHARGE FOR DISMANTLE AND REPLACE FRONT BUMPER, HEAD LAMP BRACKET, HEAD LAMP, FOG LAMP & SIGNAL LAMP ASSY.	1	650	650.00 450
Spray Paint				
1	Spray Painting LABOUR CHARGE FOR SPRAY PAINTING FOR NEW FRONT BUMPER AND TOUCH-UP FRONT ACCIDENT POTION.	1	500	500.00 400
TOTAL:				2,558.00
Total Amount				SGD 2,558.00

Remarks:

19.09.2018
Signature of Workshop Dpt

[Signature] 19.9.18
Signature of Department Head

[Signature] 19/9/18
Signature of Claim Department

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer: Winson
Signature: #
Date: 21.09.18

[Signature]
HP 90010068
4 days
4/3
21/09/18 @ HP 10
Revy after repair

Janice

2017 800, 1-2018



WTS Engineering Pte Ltd
8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163
Company Registration Number: 200505706E

Surveyor Sign: [Signature]
 Surveyor Name: RASUL
 Date: 21/09/18

Quotation

DATE: 19/09/18 LOCATION: Gul Workshop
 VEHICLE NO: WC1594H Q REF No: Q18/09/931
 DRIVER: YEO PHENG SONG DEPARTMENT: WTS Mixer Truck Department
 ATTENTION TO: ACCIDENT DATE: 17/09/18
 PREPARED BY: Winson REF No: JW/0918/583

S/N	Description	Qty	Cost per Unit	Amount SS
Spare Parts				
1	FRONT BUMPER ASSY	1	950	950.00
2	RHS HEAD LAMP BRACKET	1	220	220.00
3	RHS FOG LAMP	1	75	75.00
4	RHS SIGNAL LAMP	1	28	28.00
5	RHS HEAD LAMP ASSY	1	135	135.00
Labour Costs				
1	LABOUR CHARGE FOR DISMANTLE AND REPLACE FRONT BUMPER, HEAD LAMP BRACKET, HEAD LAMP, FOG LAMP & SIGNAL LAMP ASSY.	1	650	650.00
Spray Paint				
1	Spray Painting LABOUR CHARGE FOR SPRAY PAINTING FOR NEW FRONT BUMPER AND TOUCH-UP FRONT ACCIDENT POTION.	1	500	500.00
TOTAL:				2,558.00
Total Amount				SGD 2,558.00

s/w
1408
850

Remarks:

Surveyor Sign: _____
 Surveyor Name: _____
 Date: _____

17.09.2018
 Signature of Workshop Dpt

19/9/18
 Signature of Department Head

[Signature]
 19/9/18
 Signature of Claim Department

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Winson
 Signature: #
 Date: 21.09.18

RASUL
 HP 90010068
 4 days
 4/8
 21/09/18 @ HP 10
 Resy after repair

1408.00
 850.00
 2258.00
 208
 1806.40
 4/8 - 1,800
 4 days =

Comp

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Sep 2018		20 Sep 2018 16:45 Edit Adj Rpt	S\$1,800.00 Edit Estimates	S\$1,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	Alliance Concrete Singapore Pte. Ltd., Co. Reg. No.: 200516266D								
Main Claimant:	WOODLANDS TRANSPORT SERVICE PTE LTD, Co. Reg. No.: 198102721M								
Vehicle Reg. No.:	WC1594H	Date of Loss:	17/09/2018 13:00 - :59 [130 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 570683	Policy/Cover Note No.:	B29088496MKF (Comprehensive) Coverage: 01/07/2018 - 30/06/2019						
Vehicle Reg. No. (Insured):	WC2648E	Policy No. (Claimant):							
		Excess:							
Repairer:	Woodlands Transport Service Pte Ltd () NO 6 CHIA PING ROAD, 619971 Jurong East - Tel: 65598988								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by NG CHEN HOW - 6643 1391]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 20/10/2018]								
Driver/Custodian (Insured):	TEO SENG LEE (61 / Male), NRIC: S1275143E								
Adj Asg. Remarks:	Car in. on WP. Please contact us ASAP if you cannot attend this assignment. Workshop wants M/s LKK Auto Consultants to survey. Liability is clear but insured may take over claim.								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
<ul style="list-style-type: none"> MSIG_SG (08/10/2018): Please submit your surveyor report and bill earliest 									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*WC1594H (570683)
[WC2648E]

TP

WOODLANDS TRANSPORT SERVICE PTE LTD

Sep 17 2018 1:00PM

[Alliance Concrete Singapore Pte. Ltd.]

Woodlands Transport Service Pte Ltd

Upload Documents Upload Photos Compose New Letter			View	View in Browser ▾
Video			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/10/18 17:13	Video - Accident 3P video	Load AVI	
Assessment Reports			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/09/18 11:30	Accident Statement From: SC - Reg. No: WC2648E, Claimant: Alliance Concrete Singapore Pte. Ltd.	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/10/18 10:08	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	
2	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	
3	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	
4	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	
5	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	
6	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	
7	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	
8	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	
9	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	
10	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	
11	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	
12	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	
13	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	
14	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	
15	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	
16	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	
17	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	
18	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	
19	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	
20	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	
21	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	
22	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	
23	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	
24	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	
25	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	
26	22/10/18 10:31	General View	Load JPG <input checked="" type="checkbox"/>	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
27	22/10/18 10:31	General View		<input checked="" type="checkbox"/>
28	22/10/18 10:31	General View		<input checked="" type="checkbox"/>
29	22/10/18 10:31	General View		<input checked="" type="checkbox"/>
30	22/10/18 10:31	General View		<input checked="" type="checkbox"/>
31	22/10/18 10:31	General View		<input checked="" type="checkbox"/>
32	22/10/18 10:31	General View		<input checked="" type="checkbox"/>
33	22/10/18 10:31	General View		<input checked="" type="checkbox"/>
34	22/10/18 10:31	General View		<input checked="" type="checkbox"/>
35	22/10/18 10:31	General View		<input checked="" type="checkbox"/>
36	22/10/18 10:31	General View		<input checked="" type="checkbox"/>
37	22/10/18 10:31	General View		<input checked="" type="checkbox"/>
38	22/10/18 10:31	General View		<input checked="" type="checkbox"/>
39	22/10/18 10:31	General View		<input checked="" type="checkbox"/>
40	22/10/18 10:31	General View		<input checked="" type="checkbox"/>
41	22/10/18 10:31	Photo After Spray		<input checked="" type="checkbox"/>
42	22/10/18 10:31	Photo After Spray		<input checked="" type="checkbox"/>
43	22/10/18 10:31	Photo After Spray		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/09/18 11:30	Third Party Accident Report From: SC - Reg. No: WC2648E, Claimant: Alliance Concrete Singapore Pte. Ltd.		<input type="checkbox"/>
2	20/09/18 11:30	QUOTATION From: SC - Reg. No: WC2648E, Claimant: Alliance Concrete Singapore Pte. Ltd.		<input type="checkbox"/>
3	20/09/18 13:29	PRI: 3P workshop wants LKK		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18017182/R1RBS2

Date: 01/11/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B29088496MKF

Claimant Vehicle No: WC1594H

Insured Vehicle No: WC2648E

Date of Loss: 17/09/2018

Nature of Claim: TP

Claim No: 570683

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **WC1594H**

Make & Model: ISUZU CYH52S, 15.7 D (M)

Engine No: 6WG1406659

Reg. Date: 13/11/2007 (Man. Year: 2007)

Chassis No: JALCYH52S77000072

Colour: White

Odometer: 271273 km

Engine Capacity: 15681 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5 (D)

Front Left Side: Chao Yong 8 mm

Rear Left Side: Chao Yong 8/8 mm

Front Right Side: Chao Yong 8 mm

Rear Right Side: Chao Yong 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,408.00	1,408.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	850.00	300.00	26.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,558.00	2,258.00	300.00	11.73
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	2,558.00	1,800.00	758.00	29.63
+ GST 7.00/7.00% (S\$)	179.06	126.00	53.06	29.63
Nett Amount (S\$)	2,737.06	1,926.00	811.06	29.63

INSPECTION

Date of Assignment: 20/09/2018

Date Inspected: 21/09/2018 Inspected At:

Woodlands Transport Service Pte Ltd
8 GUL CIRCLE
SINGAPORE 629564

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL**Manager:** Janice Lee Si Hua*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 01 Nov 2018)	
Parts:	N/A	ISUZU CYH52S 15.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for WC1594H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER ASSY	Bent	950.00 F	*950.00 F	
2	1		*RHS HEAD LAMP BRACKET	Bent	220.00 F	*220.00 F	
3	1		*RHS FOG LAMP	Cracked	75.00 F	*75.00 F	
4	1		*RHS SIGNAL LAMP	Cracked	28.00 F	*28.00 F	
5	1		*RHS HEAD LAMP ASSY	Cracked	135.00 F	*135.00 F	
					Total Parts (S\$)	1,408.00	1,408.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE FOR DISMANTLE AND REPLACE FRONT BUMPER, HEAD LAMP BRACKET, HEAD LAMP, FOG LAMP & SIGNAL LAMP ASSY.	New	650.00	450.00
2	LABOUR CHARGE FOR SPRAY PAINTING FOR NEW FRONT BUMPER AND TOUCH-UP FRONT ACCIDENT PORTION.	New	500.00	400.00
			Gross Labour Cost (\$\$)	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >