

Surveyor:

DOI:

Date / Time:

Pre-assign / CCU / FTE

Registered in Merimen:



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (If non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (If non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mendate/Reject Instruction:

LOD

Payment Breakdown Form:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: MTH

Repair Cost: PIP \$51,483.75 ( 2 days) Reduction: 60 % Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with: Jerni/Wei

Email ☒ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lin:

Repair Cost:

will \$51,581.61

Loss of Rental (LOR):

\$5,800

Loss of Use (LOU):

\$ -

( 2 days) x \$120

Loss of Income (LOI):

\$ -

( 2 days) x \$120

LOR only ☒LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

\$52.00

Medical:

\$ -

Disbursement:

\$ -

(e.g. Tow/ Independent)

Legal Cost

\$ -

Total:

\$51,846.41

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with: Jerni/Wei

Email ☒ Call ☐

Payee 1:

\$51,846.41

Name 1:

HITACHI (APRAL ASIA PACIFIC PTE LTD)

Payee 2: (Strike if N.A.)

\$ -

Name 2:

Payee 3: (Strike if N.A.)

\$ -

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

+ 450

+ 450





Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 18/18/18/VP05/020912  
Our ref: CC4/LPC18017186/T1ja3

Date: 26.09.2018

The Motor Claims Department  
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SLS 534J**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24.09.2018 at the premises of M/s Hitachi Capital Asia Pacific Pte. Ltd have the following to report:-

|                               |       |          |
|-------------------------------|-------|----------|
| Workshop Estimate Amount      | : S\$ | 3,585.25 |
| Revised Estimate Amount       | : S\$ | 1,283.75 |
| "Check" Items Amount          | : S\$ | 1,396.50 |
| Total (Including Check Items) | : S\$ | 2,680.25 |
| Market Value                  | : S\$ | - (est.) |
| LTA Reimbursement Value       | : S\$ | - (est.) |
| Nett Value                    | : S\$ | - (est.) |

**Description of Damage:**

The vehicle sustained damages at the  
Rear Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 2.0 days

Yours faithfully,

MOHD. TAUFIKH  
Licensed Appraiser

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

|                                     |                                       |
|-------------------------------------|---------------------------------------|
| <b>Vehicle Owner Particulars</b>    |                                       |
| Owner ID Type:                      | Singapore NRIC                        |
| Owner ID:                           | 2174H                                 |
| <b>Vehicle Details</b>              |                                       |
| Vehicle No.:                        | SLS534J                               |
| Vehicle to be Exported:             | No                                    |
| Intended Deregistration Date:       | 28 Sep 2018                           |
| Vehicle Make:                       | TOYOTA                                |
| Vehicle Model:                      | C-HR HYBRID 1.8G AUTO                 |
| Primary Colour:                     | Green                                 |
| Manufacturing Year:                 | 2017                                  |
| Engine No.:                         | 2ZR8173706                            |
| Chassis No.:                        | ZYX102066930                          |
| Maximum Power Output:               | 90.0 kW (120 bhp)                     |
| Open Market Value:                  | \$31,616.00                           |
| Original Registration Date:         | 05 Sep 2017                           |
| First Registration Date:            | 05 Sep 2017                           |
| Transfer Count:                     | 0                                     |
| Actual ARF Paid:                    | \$6,263.00                            |
| <b>Intended PARF Rebate Details</b> |                                       |
| PARF Eligibility:                   | Yes                                   |
| PARF Eligibility Expiry Date:       | 04 Sep 2027                           |
| PARF Rebate Amount:                 | \$4,697.00                            |
| <b>Intended COE Rebate Details</b>  |                                       |
| COE Expiry Date:                    | 04 Sep 2027                           |
| COE Category:                       | B - Car above 1600cc or 97kW (130bhp) |
| COE Period(Years):                  | 10                                    |
| QP Paid:                            | \$54,406.00                           |
| COE Rebate Amount:                  | \$48,616.00                           |
| <b>Total Rebate Amount:</b>         | <b>\$53,313.00</b>                    |

The information contained herein is correct as at 24 Sep 2018

OK

No. 8 Fourth Lok Yang Road Singapore 629705

Tel : 64663022 Fax : 68966591

Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

**VEHICLE ESTIMATE**

Lonpac

QUOTE NO :

ACCIDENT DATE : 14/09/2018@1100hrs

VRN : SLS534J

MODEL : Toyota C-HR

TP VRN : SGG1188R

ATTN: MOTOR CLAIMS DEPT

|  | <u>Qty</u> | <u>S\$ Unit</u> | <u>S\$ Amt</u> | <u>S\$ Labor</u> |
|--|------------|-----------------|----------------|------------------|
|--|------------|-----------------|----------------|------------------|

**PARTS REPLACEMENT****1. Body Repair**

|                                    |    |           |             |       |
|------------------------------------|----|-----------|-------------|-------|
| 1 Rear Bumper                      | 1  | \$ 455.00 | \$ 455.00   | ds ✓  |
| 2 Rear Bumper Clips                | 10 | \$ 5.50   | \$ 55.00    | no ✓  |
| 3 Rear Bumper Lower                | 1  | \$ 455.00 | \$ 455.00   | cut ✓ |
| 4 Rear Bumper Retainer Outer LH/RH | 2  | \$ 110.00 | \$ 220.00   | ✓     |
| 5 Rear Bumper Retainer Inner LH/RH | 2  | \$ 40.00  | \$ 80.00    | ✓     |
| 6 Rear Bumper Reverse Sensor       | 4  | \$ 385.00 | \$ 1,540.00 | ?     |
| 7 Rear Bumper Re-inforcement       | 1  | \$ 322.00 | \$ 322.00   | ?     |

Discount - 25% \$ (781.75)

TOTAL \$ 2,345.25

**2. Labor Charges**

|                                                                           |     |           |
|---------------------------------------------------------------------------|-----|-----------|
| Panel beat, cut, weld, re-align and replace damaged parts of rear portion | 250 | \$ 500.00 |
| Spray painting on rear portion of affected area                           | 250 | \$ 500.00 |
| Remove & reinstall bumper sensors                                         | 30  | \$ 120.00 |
| Remove & reinstall rear reverse camera                                    | 30  | \$ 120.00 |

Sub Total : \$ 1,240.00

Grand Total : \$ 3,585.25

Add 7% GST : \$ 250.97

Nett Total : \$ 3,836.22

No. of repair days: 4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CUSTOMER SIGNATURE

Tanphih 97495747  
 -wp  
 24/9/18 11pm  
 Resurvey before paint  
 Survelhants.com  
 02 days

HITACHI CAPITAL ASIA PACIFIC PTE LTD  
(MANAGER)

**Hitachi Capital Asia Pacific Pte. Ltd.**  
**Jun Taiyo Service Centre**

No. 8 Fourth Lok Yang Road Singapore 629705  
 Tel : 64663022 Fax : 68966591  
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

**VEHICLE ESTIMATE**

Lonpac

QUOTE NO :  
 ACCIDENT DATE : 14/09/2018@1100hrs  
 VRN : SLS534J  
 MODEL : Toyota C-HR  
 TP VRN : SGG1188R

ATTN: MOTOR CLAIMS DEPT

|  | <u>Qty</u> | <u>S\$ Unit</u> | <u>S\$ Amt</u> | <u>S\$ Labor</u> |
|--|------------|-----------------|----------------|------------------|
|--|------------|-----------------|----------------|------------------|

**PARTS REPLACEMENT**

**1. Body Repair**

|                                    |    |           |             |        |
|------------------------------------|----|-----------|-------------|--------|
| 1 Rear Bumper                      | 1  | \$ 455.00 | \$ 455.00   | de ✓   |
| 2 Rear Bumper Clips                | 10 | \$ 5.50   | \$ 55.00    | no ✓   |
| 3 Rear Bumper Lower                | 1  | \$ 455.00 | \$ 455.00   | cut ✓  |
| 4 Rear Bumper Retainer Outer LH/RH | 2  | \$ 110.00 | \$ 220.00   | €      |
| 5 Rear Bumper Retainer Inner LH/RH | 2  | \$ 40.00  | \$ 80.00    | €      |
| 6 Rear Bumper Reverse Sensor       | 4  | \$ 385.00 | \$ 1,540.00 | € } mm |
| 7 Rear Bumper Re-inforcement       | 1  | \$ 322.00 | \$ 322.00   | € }    |

Discount - 25% \$ (781.75)

**TOTAL \$ 2,345.25**

**2. Labor Charges**

|                                                                           |     |           |
|---------------------------------------------------------------------------|-----|-----------|
| Panel beat, cut, weld, re-align and replace damaged parts of rear portion | 250 | \$ 500.00 |
| Spray painting on rear portion of affected area                           | 250 | \$ 500.00 |
| Remove & reinstall bumper sensors                                         | 30  | \$ 120.00 |
| Remove & reinstall rear reverse camera                                    | 30  | \$ 120.00 |

Sub Total : \$ 1,240.00

Grand Total : \$ 3,585.25  
 Add 7% GST : \$ 250.97  
 Nett Total : \$ 3,836.22

No. of repair days: 4

P = 965 - W  
 - 25%  
 723.75  
 L = 560 - W  
 SN = 200 - W  
 1,483.75

Tanpiah 97495717  
 WP  
 24/9/18 @ 1pm  
 Repair before paint  
 see elkhants.com  
 2 days

CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD  
 (MANAGER)

**Hitachi Capital Asia Pacific Pte. Ltd.**  
**Jun Taiyo Service Centre**

No. 8 Fourth Lok Yang Road Singapore 629705  
Tel : 64663022 Fax : 68966591  
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

**SUPPLEMENTARY VEHICLE ESTIMATE**

Lonpac

ATTN: MOTOR CLAIMS DEPT

QUOTE NO :  
ACCIDENT D/: 14/09/2018 @ 1100hrs  
VRN : SLS534J  
MODEL : Toyota C-HR  
TP VRN : SGG1188R

**PARTS REPLACEMENT**

**1. Body Repair**

**Special Nett**

1 Coating

| <u>Qty</u> | <u>SS Unit</u> | <u>SS Amt</u> | <u>SS Labor</u> |
|------------|----------------|---------------|-----------------|
| 1          | \$ 200.00      | \$ 200.00     |                 |

Grand Total : \$ 200.00  
Add 7% GST : \$ 14.00  
Nett Total : \$ 214.00

No. of repair days: 4



CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD  
(MANAGER)

# ARTDESHINE

DETAILING CONCEPTS SPECIALISTS

# INVOICE

**Artdeshine**  
7 Soon Lee Street  
#01-40, Ispace  
Singapore, 627608  
Singapore

Mobile: +65 8128 3734  
www.artdeshine.sg

**BILL TO**  
**Hitachi Capital Asia Pacific Pte Ltd**  
Jionghow  
8 Fourth Lok Yang Road  
Singapore, 629705  
Singapore

**Invoice Number:** ADS-0390

**Invoice Date:** November 19, 2018

**Payment Due:** December 19, 2018

**Amount Due (SGD):** \$200.00

| Items                                  | Quantity | Price    | Amount   |
|----------------------------------------|----------|----------|----------|
| <b>Others</b><br>Vehicle No. SLS 534 J | 1        | \$200.00 | \$200.00 |

Stage 1 Polishing  
Coating Re-application:  
- Rear/R Fender  
- Rear/L Fender  
- Rear Bumper

**Total:** \$200.00

**Amount Due (SGD):** \$200.00

## Notes

All cheques crossed and made payable to ARTDESHINE

## FOR BANK TT

Account Payee: ARTDESHINE  
Bank Name: UNITED OVERSEAS BANK LIMITED  
Address: 80 RAFFLES PLACE, UOB PLAZA, SINGAPORE 048624  
Bank Code: 7375  
Branch Code: 035  
Account No.: 363-303-972-9 (UOB CURRENT ACCOUNT)  
Swift Code: UOVBSGSG



## FOR PAYPAL

Account Name: jiahong@artdeshine.com.sg  
Merchant ID: 8RFVUKEARZP92

For enquiries, contact us at [sales@artdeshine.com.sg](mailto:sales@artdeshine.com.sg)



**Nivitha (LKK Auto)**

---

**From:** ONG LI LI <liong@lonpac.com>  
**Sent:** Wednesday, 19 September 2018 3:27 PM  
**To:** JiongHow, Ng; assignments@lkkauto.com; Catherine Chong (LKK Auto)  
**Cc:** MT\_Claim\_SG; Vonn, LM Siow; Jamilah, Binte MohdKassim  
**Subject:** RE: SLS543J Third Party Claim Against SGG1188R Our Ref: 18/18/18/VP05/020912  
**Attachments:** juntaiyo@hcspl.com.sg\_20180919\_115452.pdf

3:31pm @ 19/9/18  
person @ jiong how  
vehicle not in

Without Prejudice

Dear Jiong How

Please liaise with LKK Auto Consultants Pte Ltd for survey.

Dear Nivitha/Catherine

fya

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

---

**From:** JiongHow, Ng [mailto:jionghow.ng@hcspl.com.sg]  
**Sent:** Wednesday, 19 September, 2018 3:19 PM  
**To:** assignments@lkkauto.com  
**Cc:** MT\_Claim\_SG; Vonn, LM Siow; Jamilah, Binte MohdKassim  
**Subject:** SLS543J Third Party Claim Against SGG1188R

Dear all,

Please refer to above subject matter.

Attached GIA report and Estimate for your arrangement.

Kindly Assign Survey, Car In NOT need to arrange with owner

No.8 Fourth lok yang road S/629705

Regards

Ng Jiong How  
Motor Claims Advisor  
Auto Servicing  
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.  
**Jun Taiyo Service Centre (Automobile Leasing & Workshop)**  
8 Fourth Lok Yang Road Singapore 629705  
t: 6833 6282  
e: [jionghow.ng@hcspl.com.sg](mailto:jionghow.ng@hcspl.com.sg)

**DISCLAIMER:**

This email and/or any files and/or attachments transmitted are PRIVATE & CONFIDENTIAL and may be LEGALLY PRIVILEGED.  
This email is intended solely for the attention and use of the name addressee(s).  
If you are not a named addressee, you must not use, disseminate, forward, print or copy this email and all its contents/attachments.  
If you have received this email in error, please notify the sender immediately by email and delete it from your system.

## Mei Kwan (LKKAUTO)

---

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Friday, 21 September, 2018 9:06 AM  
**To:** Mei Kwan (LKKAUTO)  
**Cc:** MT\_Claim\_SG; Admin A; Joy Irene (LKKAUTO); Asher Sng (LKKAUTO)  
**Subject:** RE: SLS543J Third Party Claim Against SGG1188R Our Ref: 18/18/18/VP05/020912  
\*\*\* LKK REF: CC4/LPC18017186/ja3  
**Attachments:** SGG1188R 140918.PDF  
**Categories:** HMK

Hi Mei Kwan

Please see attached for our Insured's GIA report.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

---

**From:** Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]  
**Sent:** Thursday, 20 September, 2018 7:50 PM  
**To:** ONG LI LI  
**Cc:** MT\_Claim\_SG; Admin A; Joy Irene (LKKAUTO); Asher Sng (LKKAUTO)  
**Subject:** RE: SLS543J Third Party Claim Against SGG1188R Our Ref: 18/18/18/VP05/020912 \*\*\* LKK REF: CC4/LPC18017186/ja3

### WITHOUT PREJUDICE

LPC ref: 18/18/18/VP05/020912  
LKK REF: CC4/LPC18017186/ja3

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Mei Kwan | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Wednesday, 19 September, 2018 3:33 PM  
**To:** 'ONG LI LI' <llong@lonpac.com>; assignments <assignments@lkkauto.com>  
**Cc:** 'MT\_Claim\_SG' <mt\_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>  
**Subject:** RE: SLS543J Third Party Claim Against SGG1188R Our Ref: 18/18/18/VP05/020912

Dear Sir/Mdm,

Auto Servicing  
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.  
Jun Taiyo Service Centre (Automobile Leasing & Workshop)  
8 Fourth Lok Yang Road Singapore 629705  
t: 6833 6282  
e: [jlonghow.ng@hcspl.com.sg](mailto:jlonghow.ng@hcspl.com.sg)  
w: [www.hitachi-capital.com.sg](http://www.hitachi-capital.com.sg)

**HITACHI**  
Inspire the Next

**DISCLAIMER:**

This email and/or any files and/or attachments transmitted are PRIVATE & CONFIDENTIAL and may be LEGALLY PRIVILEGED.  
This email is intended solely for the attention and use of the name addressee(s).  
If you are not a named addressee, you must not use, disseminate, forward, print or copy this email and all its contents/attachments.  
If you have received this email in error, please notify the sender immediately by email and delete it from your system.



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                                           |                               |                                                                                     |  |
|----------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------|-------------------------------|-------------------------------------------------------------------------------------|--|
| LONPAC INSURANCE BHD                                                                                                                   |                                                                                                           | Ref : CC4/LPC18017186/T1ea3n2 |                                                                                     |  |
| 300 BEACH ROAD<br>#17-04/07 THE CONCOURSESINGAPORE 199555                                                                              |                                                                                                           | Date : 22-01-2020             |  |  |
|                                                                                                                                        |                                                                                                           | Code : LPC2                   |                                                                                     |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                                           |                               |                                                                                     |  |
| Insured Veh.                                                                                                                           | SGG 1188R                                                                                                 | Veh. Inspected                | SLS 534J                                                                            |  |
| Policy No.                                                                                                                             |                                                                                                           | Coverage (\$)                 | 0.00                                                                                |  |
| Claim No.                                                                                                                              | 18/18/18/VP05/020912                                                                                      | Excess (\$)                   | 0.00                                                                                |  |
| Assign From                                                                                                                            | ONG LI LI                                                                                                 | Assign Date                   | 19/09/2018                                                                          |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                                           |                               |                                                                                     |  |
| Make & Model                                                                                                                           | TOYOTA C-HR HYBRID                                                                                        | c.c                           | 1797                                                                                |  |
| Engine No.                                                                                                                             | HIDDEN                                                                                                    | Year of Reg.                  | 2017                                                                                |  |
| Chassis No.                                                                                                                            | ZYX102066930                                                                                              | Colour                        | GREEN                                                                               |  |
| Odometer                                                                                                                               | 17483                                                                                                     | Steering                      | IN ORDER                                                                            |  |
| Brakes                                                                                                                                 | IN ORDER                                                                                                  | Modification                  | SPORTS RIM                                                                          |  |
| General                                                                                                                                | GOOD                                                                                                      |                               |                                                                                     |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                                           |                               |                                                                                     |  |
|                                                                                                                                        | Size                                                                                                      | Make                          | Balance                                                                             |  |
| R/H Front Tyre                                                                                                                         | 225/50 R18                                                                                                | MICHELIN                      | 6 mm                                                                                |  |
| L/H Front Tyre                                                                                                                         | 225/50 R18                                                                                                | MICHELIN                      | 6 mm                                                                                |  |
| R/H Rear Tyre                                                                                                                          | 225/50 R18                                                                                                | MICHELIN                      | 6 mm                                                                                |  |
| L/H Rear Tyre                                                                                                                          | 225/50 R18                                                                                                | MICHELIN                      | 6 mm                                                                                |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                                           |                               |                                                                                     |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.                                                             |                                                                                                           |                               |                                                                                     |  |
| <b>5. General Information</b>                                                                                                          |                                                                                                           |                               |                                                                                     |  |
| Accident Date                                                                                                                          | 14/09/2018                                                                                                | Inspection Date               | 24/09/2018                                                                          |  |
| Survey held at                                                                                                                         | HITACHI CAPITAL (S) PTE LTD<br>JUN TAIYO SERVICE CENTRE<br>NO. 8 FOURTH LOK YANG ROAD<br>SINGAPORE 629705 |                               |                                                                                     |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                                           |                               |                                                                                     |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                           |                               |                                                                                     |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                                           |                               |                                                                                     |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                                           | <b>2 Working Days</b>         |                                                                                     |  |

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 534J**

| Qty                                | Description of Parts                                                       | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|----------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b>        |                                                                            |               |                           |                   |
| 1                                  | REAR BUMPER                                                                | DEFORMED      | 455.00                    | 455.00            |
| 10                                 | REAR BUMPER CLIPS @\$5.50                                                  | NECESSARY     | 55.00                     | 55.00             |
| 1                                  | REAR BUMPER LOWER                                                          | CUT           | 455.00                    | 455.00            |
| 2                                  | REAR BUMPER RETAINER OUTER LH/RH @\$110.00                                 | NOT NECESSARY | 220.00                    | -                 |
| 2                                  | REAR BUMPER RETAINER INNER LH/RH @\$40.00                                  | NOT NECESSARY | 80.00                     | -                 |
| 4                                  | REAR BUMPER REVERSE SENSOR @\$385.00                                       | NOT NECESSARY | 1,540.00                  | -                 |
| 1                                  | REAR BUMPER RE-INFORCEMENT                                                 | NOT NECESSARY | 322.00                    | -                 |
|                                    | LESS 25% DISCOUNT                                                          |               | -781.75                   | -241.25           |
|                                    |                                                                            |               | 2,345.25                  | 723.75            |
| <b>LABOUR</b>                      |                                                                            |               |                           |                   |
|                                    | PANEL BEAT, CUT, WELD, RE-ALIGN AND REPLACE DAMAGED PARTS OF REAR PORTION. |               | 500.00                    | 250.00            |
|                                    | SPRAY PAINTING ON REAR PORTION OF AFFECTED AREA.                           |               | 500.00                    | 250.00            |
|                                    | REMOVE & REINSTALL BUMPER SENSORS.                                         |               | 120.00                    | 30.00             |
|                                    | REMOVE & REINSTALL REAR REVERSE CAMERA.                                    |               | 120.00                    | 30.00             |
|                                    | COATING (ADDITIONAL).                                                      |               | 200.00                    | 200.00            |
|                                    |                                                                            |               | 1,440.00                  | 760.00            |
| <b>GRAND TOTAL</b>                 |                                                                            |               | <b>3,785.25</b>           | <b>1,483.75</b>   |
| <b>RECOMMENDED COST OF REPAIRS</b> |                                                                            |               |                           | <b>1,483.75</b>   |

Report Ref No. CC4/LPC18017186/T1ea3n2

**MOHAMAD TAUFIKH****M.MATAI, AMSAE-A**

Automotive Assessor

**HO LEONG CHUAN**

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.