

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE

Lonpac

ATTN: MOTOR CLAIMS DEPT

QUOTE NO :
ACCIDENT DATE : 14/09/2018@1100hrs
VRN : SLS534J
MODEL : Toyota C-HR
TP VRN : SGG1188R

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
--	------------	-----------------	----------------	------------------

1. Body Repair

1 Rear Bumper	1	\$ 455.00	\$ 455.00	do ✓
2 Rear Bumper Clips	10	\$ 5.50	\$ 55.00	new ✓
3 Rear Bumper Lower	1	\$ 455.00	\$ 455.00	cut ✓
4 Rear Bumper Retainer Outer LH/RH	2	\$ 110.00	\$ 220.00	x
5 Rear Bumper Retainer Inner LH/RH	2	\$ 40.00	\$ 80.00	x
6 Rear Bumper Reverse Sensor	4	\$ 385.00	\$ 1,540.00	?
7 Rear Bumper Re-inforcement	1	\$ 322.00	\$ 322.00	?

Discount - 25% \$ (781.75)

TOTAL \$ 2,345.25

2. Labor Charges

Panel beat, cut, weld, re-align and replace damaged parts of rear portion	250	\$ 500.00
Spray painting on rear portion of affected area	250	\$ 500.00
Remove & reinstall bumper sensors	30	\$ 120.00
Remove & reinstall rear reverse camera	30	\$ 120.00

Sub Total : \$ 1,240.00

Grand Total : \$ 3,585.25
Add 7% GST : \$ 250.97
Nett Total : \$ 3,836.22

No. of repair days: 4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

CUSTOMER SIGNATURE

Tanfikah 97495449
WP
24/9/18 11pm
Resurvey before paint
survelkhaufs.com
02days

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)